



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2004012
INV Date 19/05/2020
Reference CC4/LPC19003117/Aka3n2
Code LPC2



PROFESSIONAL SERVICE FEE

Vehicle No. SJA 2696E
Insured Veh. SGG 6776K
Claim No. 18/19/19/VP050/21420
Policy No. Z18VP05021256
Accident Date 12/02/2019
Inspection Date 19/02/2019

| Description | Total |
|--------------------------------|---------------|
| Third Party Express Settlement | 450.00 |
| Subtotal | 450.00 |
| GST (7%) | 31.50 |
| Grand Total | 481.50 |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC19003117/Aka3n2

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 19-05-2020



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|----------------------|----------------|------------|
| Insured Veh. | SGG 6776K | Veh. Inspected | SJA 2696E |
| Policy No. | Z18VP05021256 | Coverage (\$) | 0.00 |
| Claim No. | 18/19/19/VP050/21420 | Excess (\$) | 0.00 |
| Assign From | ONG LI LI | Assign Date | 18/02/2019 |

2. Vehicle Particulars & Condition

| | | | |
|--------------|-------------|--------------|--------------------|
| Make & Model | HONDA FREED | c.c | 1496 |
| Engine No. | HIDDEN | Year of Reg. | 2018 |
| Chassis No. | GB71067901 | Colour | BLUE |
| Odometer | 10066 | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | STANDARD ALLOY RIM |
| General | GOOD | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|----------------|------------|--------|---------|
| R/H Front Tyre | 185/55 R15 | DUNLOP | 6 mm |
| L/H Front Tyre | 185/55 R15 | DUNLOP | 6 mm |
| R/H Rear Tyre | 185/55 R15 | DUNLOP | 6 mm |
| L/H Rear Tyre | 185/55 R15 | DUNLOP | 6 mm |

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

| | | | |
|----------------|---|-----------------|------------|
| Accident Date | 12/02/2019 | Inspection Date | 19/02/2019 |
| Survey held at | BW WORKSHOP SERVICES PTE LTD 30 UBI ROAD 4 SINGAPORE 408615 | | |

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **8 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJA 2696E

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|---|----------------------|---------------------------|-------------------|
| <u>REPLACEMENT OF PARTS</u> | | | | |
| 1 | REAR TAILGATE | DISTORTED | 1,450.00 | 1,208.00 |
| 1 | REAR TAILGATE 'FREED' LOGO | NECESSARY | 75.00 | 75.00 |
| 1 | REAR TAILGATE 'HYBRID' LOGO | NECESSARY | 95.00 | 95.00 |
| 1 | REAR TAILGATE LOCK | DAMAGED | 195.00 | 195.00 |
| 1 | REAR BUMPER | DEFORMED | 1,005.00 | 1,005.00 |
| 1 | REAR BUMPER TOW CAP | NOT NECESSARY | 20.00 | - |
| 1 | REAR TAILGATE INNER GARNISH | DEFORMED | 310.00 | 310.00 |
| 1 | REAR TAILGATE WEATHERSTRIP | CUT | 198.00 | 198.00 |
| 1 | REAR END PANEL | DENTED | 630.00 | 630.00 |
| 1 | REAR END PANEL GARNISH -INNER | DEFORMED | 180.00 | 180.00 |
| 1 | REAR TAILGATE CATCH | NECESSARY | 30.00 | 30.00 |
| 1 | REAR FLOOR CARPET | DEFORMED | 850.00 | 485.00 |
| 1 | REAR FLOOR PANEL | TO REPAIR SEE LABOUR | 1,250.00 | - |
| 2 | SETS REAR WINDSCREEN MOULDING | NECESSARY | 140.00 | 140.00 |
| | LESS 20% DISCOUNT | | -1,285.60 | -910.20 |
| | | | 5,142.40 | 3,640.80 |
| <u>SPECIAL NETT ITEMS</u> | | | | |
| 1 | SET REAR BUMPER SENSOR (SN) | DAMAGED | 200.00 | 200.00 |
| 1 | REAR NUMBER PLATE C/W CASING (SN) | DEFORMED | 55.00 | 55.00 |
| 1 | WINDSCREEN SEALANT (SN) | NECESSARY | 80.00 | 60.00 |
| 1 | SUNDRIES (SN) | NECESSARY | 100.00 | 20.00 |
| | | | 435.00 | 335.00 |
| <u>LABOUR</u> | | | | |
| | TO REMOVE ,CUT OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN,REFIT AND TO RENEW AFFECTED PARTS.INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL . | | 2,100.00 | 1,200.00 |
| | TO PUTTY AND RESPRAY ON AFFECTED PORTIONS . | | 1,400.00 | 900.00 |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|---|-----------|---------------------------|-------------------|
| | DISCONNECT AND CHECK ELECTRICAL WIRING ,HARNESS ,WIRE SOCKETS ETC .REMOVE AND REINSTALL DAMAGED PARTS ,TEST AND RECTIFY FOR PROPER FUNCTIONING. | | 120.00 | 30.00 |
| | TO REMOVE AND REFIT REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST. | | 120.00 | 120.00 |
| | TO REMOVE AND REFIT REAR UPHOLSTERY TRIMMING ,ROOF LINING ,SEATS ,SPEAKER BOARD IN ORDER TO FACILITATE REPAIRING WORKS. | | 150.00 | 80.00 |
| | TO APPLY UNDERSEALING. | | 100.00 | 60.00 |
| | TO TRANSFER TAILGATE'S FITTINGS. | | 150.00 | 80.00 |
| | REMOVE AND REPLACE BUMPER SENSOR . | | 120.00 | 60.00 |
| | | | 4,260.00 | 2,530.00 |
| GRAND TOTAL | | | 9,837.40 | 6,505.80 |
| RECOMMENDED COST OF REPAIRS | | | | 6,505.80 |

Report Ref No. CC4/LPC19003117/Aka3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJA 2696E

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJA 2696E

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

