

BW WORKSHOP SERVICES PTE. LTD.
 30 UBI ROAD 4 SINGAPORE 408615
 TEL: 6289 8800 FAX: 6858 2120
 GST. REG NO: 201504834E

Ichunachner

Estimate

To :	LONPAC INSURANCE BHD	DATE :	15/2/2019
Attn :	Claims Officer		
CC :	1499	VEHICLE NO :	SJA 2696 E
YEAR :	2018	CHASSIS NO :	GB71067901
MODEL :	HONDA FREED HYBRID 1.5 G	PAGE :	1 OF 1

Please quote the following items listed.

Third Party Claims

S/NO	ITEMS	Qty	Price
1	Rear tailgate <i>Disturbed</i>	1	¹²⁰⁸ \$1,450.00 ✓
2	Rear tailgate "FREED" logo <i>3pc</i>	1	\$75.00 ✓
3	Rear tailgate "HYBRID" logo	1	\$95.00 ✓
4	Rear tailgate lock <i>Disturbed</i>	1	\$195.00 ✓
5	Rear bumper <i>Disturbed</i>	1	\$1,005.00 ✓
6	Rear bumper tow cap <i>new</i>	1	\$20.00 ✗
7	Rear tailgate inner garnish <i>Disturbed</i>	1	\$310.00 ✓
8	Rear tailgate weathership <i>at</i>	1	\$198.00 ✓
9	Rear end panel <i>Disturbed</i>	1	\$630.00 ✓
10	Rear end panel garnish - inner <i>Disturbed</i>	1	\$180.00 ✓
11	Rear tailgate catch <i>new</i>	1	\$30.00 ✓
12	Rear floor carpat <i>Disturbed</i>	1	\$850.00 485 ✓
13	Rear floor panel <i>Repair</i>	1	\$1,250.00 ✗
14	Rear windscreen moulding - 1sets <i>new</i>	2	\$140.00 ✓
			\$6,428.00
		Discount 20%	\$1,285.60
		TOTAL :	\$5,142.40
S/NO	SPECIAL ITEMS	Qty	Price
1	Rear bumper sensor <i>Disturbed</i>	1set	\$200.00 ✓
2	Rear number plate c/w casing <i>Disturbed</i>	1	\$55.00 ✓
3	Windscreen sealant <i>new</i>	1	\$80.00 60 ✓
4	Sundries <i>new</i>	1	\$100.00 20 ✓
			\$435.00
		Parts Total :	\$5,142.40
		S/P Item :	\$435.00
		TOTAL :	\$5,577.40

BW WORKSHOP SERVICES PTE. LTD.
 30 UBI ROAD 4 SINGAPORE 408615
 TEL: 6289 8800 FAX: 6858 2120
 GST. REG NO: 201504834E

Estimate

To	:	LONPAC INSURANCE BHD	DATE	:	15/2/2019
Attn	:	Claims Officer			
CC	:	1499	VEHICLE NO	:	SJA 2696 E
YEAR	:	2018	CHASSIS NO	:	GB71067901
MODEL	:	HONDA FREED HYBRID 1.5 G	PAGE	:	1 OF 1

Third Party Claims

S/NO	LABOURS	AMOUNT	
1	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIT AND TO RENEW AFFECTED PARTS. @ \$300/Per Days	\$ 2,100.00	1200
2	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS. @ \$280/Per Panel	\$ 1,400.00	800
3	DISCONNECT AND CHECK ELECTRICAL WIRING, HARNESS, WIRE SOCKETS, ETC. REMOVE AND REINSTALL DAMAGED PARTS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	\$ 120.00	30
4	TO REMOVE AND REFIT REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.	\$ 120.00	✓
5	TO REMOVE AND REFIT REAR UPHOLSTERY TRIMMING, ROOF LINING, SEATS, SPEAKER BOARD IN ORDER TO FACILITATE REPAIRING WORKS.	\$ 150.00	80
5	TO APPLY UNDERSEALING.	\$ 100.00	60
6	TO TRANSFER TAILGATE'S FITTINGS.	\$ 150.00	80
7	REMOVE AND REPLACE BUMPER SENSOR.	\$ 120.00	60

Working Days : 12 Days.

NOTE: ALL QUOTED PRICE IS SUBJECT TO 7% GST

TOTAL	:	\$4,260.00
PARTS TOTAL	:	\$5,577.40
GRAND TOTAL	:	\$9,837.40

LK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Adrian Lj
R/p 19/02/19.
08 days.
total: 6505.80.