

ASS. REC. BY:

REF: CS/CTI19003122/GSD3n2 | Special Instruction:

Special Instruction:

Surveyor

ASSIGNMENT (Office)

1945

From (Person): Chong Buan Sen of C7L Date/Time: 19.2.2019

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No: SJ1 1025 Z Insured: PA 91262

at Workshop m/s **SK Automobile** Tel: **Winson 97850992**

of 48 Toh Guan Rd East #01-121

Policy No: _____ Claim No: SNM 1 D 200494

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 4.1.18

(Client's Record)

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement:

Date/Time: _____ Person Contacted: _____ Vehicle IN/OUT

Vehicle IN/OUT

[illegible]

Sponsor

REF:

CS/CT1 190031221 Gsd3

49/8e

XPR.

CTi

ASSIGNMENT

(-2022)

From:

Date:

Veh No:

ST10258

Yr Regn:

16 Apr 2007

Estimated Cost:

Type: ☒ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /OD / ☒ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

Truck / Trailer or

To inspect Vehicle No:

Make:

Honda stream C.C. 1799

Workshop m/s

SK Auto

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp. Reading:

164875

T/Radio:

Insured / Std / NI / NA

Insured:

Eng/No:

RN6 1025377

Policy No.

C/No:

Claims No.

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Sum Insured:

Excess:

Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

(Client's Record)


Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD ☒ A/Rim or

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

\$22k

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

7 & 20

days

Res.: Yes or No

Lum Sum:

3 Val.: Yes or No

Tyre Size:

F:

205/55R16

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

D.O.I.

18-02-19

Survey held at

w/s

4230 pm

Des. of Damages : Frt / Rear / ☒ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

18/2

repair limit \$5500 6000, \$

03/4

\$4000 w/s not don't agree

04/04/19

Unconfirm 45 \$4,000/- @ 6 days

\$5600 confirmed Winson.

C \$12,448.84 Rd-71%)

RECEIVED 04 APR 2019

Date/Time, File Pass to?

04/04/19

1)

Type 4

Date/Time, File Return to?

2)



Preli. Report



Final Report

Days Of Repair:

67

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

220

Report Format :

Lump Sum / I.B.I: (\$ 5,100/- 4/5)

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 21 February 2019 9:06 AM
To: 'Pioneer Workshop'
Cc: SUR
Subject: RE: SJT 1025Z DOA 24/01/2019 (CTI)

Dear Yvonne,

According to our surveyor Guo Qiang, the repair limit is \$ 6,000.00.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Pioneer Workshop [mailto:pioneer@skauto.com.sg]
Sent: Wednesday, 20 February 2019 2:23 PM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Subject: Re: SJT 1025Z DOA 24/01/2019 (CTI)

Dear Shirley ,

Kindly check attachment, the limit should be \$ 6,300.00

On Wed, Feb 20, 2019 at 11:00 AM Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com> wrote:

Hi Yvonne,

As spoken, the repair limit is \$ 5,500.00.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

--

Thanks & Regards,

Yvonne

SK Automobile Pte Ltd
48 Toh Guan Road East #01-121
Enterprise Hub Singapore 608586
Tel: +65-6266 0555
Fax: +65-6266 3155
Email: pioneer@skauto.com.sg

▶ Stream Used Vehicle List (19 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availabi
Honda Stream 1.8A Sunroof (COE till 01/2024)	\$32,800	\$6,670 /yr	21-Jan-2009	1,799 cc	-	GV Credit Pte Ltd	Availal

Office No. - 63443344

Mave - 90099586

2.38% Per Annual, Lowest Interest At \$638 Monthly For Honda Stream. \$0 Admin Fees For All GV Purchase. 2 Years Warranty For Engine And Gearbox.

Honda Stream 1.8A (COE till 12/2021)	\$18,500	\$6,520 /yr	22-Dec-2006	1,799 cc	255,128 km	GV Credit Pte Ltd	Availal
---	-----------------	--------------------	--------------------	-----------------	-------------------	--------------------------	----------------

Best Selling Japanese MPV For All Family. Well Taken Care And Serviced Regularly. Excellent Interior And Exterior Condition. Good Fuel Consumption. Spacious And Comfortable.

Office No. - 63443344

Rishi - 85064696 | Rishi - 83227626 | Kana - 96435365

Honda Stream 1.8A (COE till 02/2022)	\$21,800	\$7,290 /yr	15-Feb-2007	1,799 cc	170,263 km	Benefit Auto Enterprise Pte Ltd	Availal
---	-----------------	--------------------	--------------------	-----------------	-------------------	--	----------------

Well Known Japanese MPV! Economical And Easy To Maintain! Call Now For Viewing And Test Drive Appointment Before The Car Is Gone! Trade In Welcome! Flexible Downpayment Available With Fast And Easy Lo...

Office No. - 68444161

Mark - 98325030 | Tony - 82512499 | Kevin - 90268203

Honda Stream 1.8A (COE till 04/2022)	\$22,777	\$7,140 /yr	30-Apr-2007	1,799 cc	140,000 km	Carland Automobile	Availal
---	-----------------	--------------------	--------------------	-----------------	-------------------	---------------------------	----------------

\$670 For Monthly Installment, Low Mileage Done, Low Depreciation, Excellent Maintained Condition, No Repairs Needed And Comes With 6 Months Warranty.

Office No. - 62912129

Lee - 90044780 | Ken Liu - 90775885

Honda Stream 1.8A (COE till 08/2022)	\$25,200	\$7,160 /yr	28-Aug-2007	1,799 cc	135,000 km		Availal
---	-----------------	--------------------	--------------------	-----------------	-------------------	--	----------------

In Superb Condition, Spacious And Comfortable! No Repairs Needed, Perfect And Genuine Unit Available For Viewing. Road Tax Till January, Change Just Done. Those Who Prefer To Buy From Direct Buyer...

Office No. - -

John - 92302405

Honda Stream 1.8A Style Edition (COE till 11/2022)	\$25,800	\$6,820 /yr	22-Jan-2008	1,799 cc	132,000 km	Jie Heng Motoring	Availal
---	-----------------	--------------------	--------------------	-----------------	-------------------	--------------------------	----------------

100% Loan Approval With Low Interest Rate! Interest As Low As 3.18%, High Paper Value Of \$20K, Definitely Not The Cheapest But For Sure One Of The Better Unit, Lowest Mileage Done At 12,300KM Yearly, ...

Office No. - 64693350

Roy Chua (Hao) - 90121363 | Simpson Tan - 88000787 | Kenneth Chua - 83387618 | Keith Khoo - 97973753

Honda Stream 1.8A (COE till 02/2023)	\$26,838	\$7,000 /yr	21-Feb-2008	1,799 cc	129,000 km	Hoe Beng Auto Trading	Availal
---	-----------------	--------------------	--------------------	-----------------	-------------------	------------------------------	----------------

100% Loan At 2.98%. 5 Years COE. Service Every 10K Km Without Fail! No Repair Needed! 2 Years Free Servicing, We Deliver Our Promise! High Trade In Most Welcome! Loan Up To 54 Months! Flexible Bank/In...

Office No. - 67450138 / 65523003

Agnes - 93680138 | Lee - 98300138 | Eric - 83538778

Honda Stream 1.8A RSZ (COE till 12/2022)	\$28,388	\$7,340 /yr	11-Feb-2008	1,799 cc	130,000 km		Availal
---	-----------------	--------------------	--------------------	-----------------	-------------------	--	----------------

Very Good Condition RSZ Stream. Full Original Bodykit And Paint. 100% Accident-Free. Comes With DVD Entertainment System, Paddle Shift HID Headlights, All Original! All Wear And Tear Parts Replaced O...

Office No. - -

Nelson - 91736493

Honda Stream 1.8A (COE till 10-May-2007)	\$28,800	\$8,950 /yr	10-May-2007	1,799 cc	178,866 km	Prem Roy Motoring	Availal
---	-----------------	--------------------	--------------------	-----------------	-------------------	--------------------------	----------------

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4918C
Vehicle Details	
Vehicle No.:	SJT1025Z
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Feb 2019
Vehicle Make:	HONDA
Vehicle Model:	STREAM 1.8 A
Primary Colour:	Black
Manufacturing Year:	2007
Engine No.:	R18A1728691
Chassis No.:	RN61025377
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$17,226.00
Original Registration Date:	16 Apr 2007
First Registration Date:	16 Apr 2007
Transfer Count:	6
Actual ARF Paid:	\$18,949.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	15 Apr 2022
COE Category:	E - Open Category
COE Period(Years):	5
PQP Paid:	\$26,004.00
COE Rebate Amount:	\$16,420.00
Total Rebate Amount:	\$16,420.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 19 Feb 2019

OK

SK Automobile Pte. Ltd.
(Co Reg. No. 201500047H)
23 Kaki Bukit Ave 4, #03-01
Vicom Inspection Centre (S415933)
Tel: 6789 5155 Fax : 6783 5155

TO	: CHINA TAIPING	DATE	: 14-Feb-19
ATTENTION	: MOTOR CLAIMS DEPARTMENT	JOB TYPE	: T/P CLAIMS
ESTIMATE REPORT	:		
OWNER PARTICULAR		VEHICLE DETAILS	
NAME	:	VEHICLE NO.	: SJT1025Z
ADDRESS	:	MODEL / MAKE	: HONDA STREAM
TEL. NO.	:	CHASSIS NO.	: RN6-1025377
OWNER INSURANCE	: FWD	ACCIDENT DETAIL	
POLICY NO.	: PNPV2018-00004750	DATE	: 24-Jan-19
		TIME	: 17:45hrs
PERSON INCHARGE	:		

QUOTATION SUMMARY PAGE 01

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMER / Re.	1	\$ 635.60	\$ 635.60
2	FRONT BUMPER RETAINER LH / RH RH - Re, 4x1x1	2	\$ 26.70	\$ 53.40
3	FRONT BUMPER FOG LAMP COVER RH X NN	1	\$ 21.50	\$ 21.50
4	FRONT HEADLAMP LH / RH RH - 4x1x1, 4x1x1	2	\$ 855.10	\$ 1,710.20
5	FRONT HEADLAMP LOWER BRACKET LH / RH X NN	2	\$ 55.10	\$ 110.20
6	FRONT GRILLE X	1	\$ 240.60	\$ 240.60
7	FRONT GRILLE CHROME GARNISH X NN	1	\$ 280.80	\$ 280.80
8	FRONT GRILLE LOGO EMBLEM X	1	\$ 25.20	\$ 25.20
9	FRONT DOOR RH / Bue.	1	\$ 922.20	\$ 922.20
10	FRONT DOOR SIDE MIRROR RH ASSY X / Cut	1	\$ 550.00	\$ 550.00
11	FRONT DOOR GLASS RH X / Scr	1	\$ 370.50	\$ 370.50
12	FRONT DOOR GLASS OUTER MOULDING RH X / Scr	1	\$ 88.50	\$ 88.50
13	FRONT DOOR OUTER LOCK HANDLE RH X repair	1	\$ 142.80	\$ 142.80
14	FRONT DOOR OUTER LOCK HANDLE COVER RH X	1	\$ 43.60	\$ 43.60
15	FRONT DOOR OUTER KEY LOCK RH X	1	\$ 103.80	\$ 103.80
16	FRONT DOOR BLACK FRAME STICKER 'VERTICAL' RH X	1	\$ 55.10	\$ 55.10
17	FRONT DOOR BLACK FRAME STICKER 'HORIZONTAL' RH X	1	\$ 67.20	\$ 67.20
18	FRONT DOOR HINGES TOP / LOWER RH X	2	\$ 36.40	\$ 72.80
19	FRONT DOOR CHECKER RH X	1	\$ 44.20	\$ 44.20
20	FRONT DOOR INNER TRIM BOARD RH X	1	\$ 529.50	\$ 529.50
21	FRONT DOOR POWER WINDOW MAIN CONTROL SWITCH RH X	1	\$ 272.30	\$ 272.30
22	FRONT DOOR POWER WINDOW REGULATOR RH X	1	\$ 156.30	\$ 156.30
23	FRONT DOOR POWER WINDOW MOTOR RH X	1	\$ 415.90	\$ 415.90
24	FRONT DOOR POWER WINDOW CHANNEL RH X	1	\$ 90.90	\$ 90.90
25	FRONT DOOR POWER WINDOW CHANNEL WATERSTRIP RH X	1	\$ 109.20	\$ 109.20
26	FRONT DOOR MECHANISM LOCK RH X	1	\$ 225.80	\$ 225.80
27	FRONT DOOR WEATHER STRIP RH X	1	\$ 109.60	\$ 109.60

QUOTATION SUMMARY

PAGE 02

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
28	FRONT DOOR PILLAR PANEL 'OUTER' RH X	1	\$ 696.80	\$ 696.80
29	FRONT DOOR PILLAR PANEL 'INNER' RH X	1	\$ 706.60	\$ 706.60
30	FRONT WINDSCREEN MOULDING X	1	\$ 145.60	\$ 145.60
31	REAR DOOR RH SCREWS BUL	1	\$ 897.80	\$ 897.80
32	REAR DOOR BLACK FRAME STICKER 'VERTICAL' RH X	1	\$ 48.70	\$ 48.70
33	REAR DOOR BLACK FRAME STICKER 'HORIZONTAL' RH X	1	\$ 67.20	\$ 67.20
34	REAR DOOR WEATHER STRIP RH X	1	\$ 109.20	\$ 109.20
35	FRONT FENDER RH BUL / BUL	1	\$ 934.60	\$ 934.60
36	FRONT FENDER SIGNAL LAMP RH BUL / CDS	1	\$ 46.00	\$ 46.00
37	FRONT FENDER INNERSHIELD RH BUL / ee.	1	\$ 198.00	\$ 198.00
38	FRONT FENDER INNERSHIELD VERTICAL RH X	1	\$ 97.60	\$ 97.60
39	FRONT FENDER INNER PANEL RH X	1	\$ 339.20	\$ 339.20
40	FRONT FENDER BRACKET RH X	1	\$ 60.10	\$ 60.10
41	FRONT 16" SPORT RIM RH BUL (local repair) gel	1	\$ 1,456.70	\$ 1,456.70
42	FRONT SUSPENSION SHOCK ASSORBER RH X	1	\$ 560.80	\$ 560.80
43	FRONT SUSPENSION KNUCKLE ARM RH X	1	\$ 490.50	\$ 490.50
44	FRONT SUSPENSION KNUCKLE ARM BEARING RH X	1	\$ 202.80	\$ 202.80
45	FRONT SUSPENSION LOWER ARM RH X	1	\$ 473.90	\$ 473.90

TOTAL PRICE \$ 14,979.80

LESS -20% \$ (2,995.96)

SUB TOTAL PRICE \$ 11,983.84

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIPS SET BUL / BUL	1	\$ 60.00	\$ 30 60.00
2	FRONT HEADLAMP CLIPS SET LH / RH X	2	\$ 20.00	\$ X 40.00
3	FRONT GRILLE CLIPS SET X	1	\$ 30.00	\$ X 30.00
4	FRONT DOOR GLASS SOLAR FIRM RH BUL / BUL	1	\$ 380.00	\$ X 380.00
5	FRONT DOOR SUNVISOR SET BUL / BUL	1	\$ 280.00	\$ X 280.00
6	FRONT DOOR INNER TRIM BOARD CLIPS SET RH BUL / BUL	1	\$ 60.00	\$ 20 60.00
7	FRONT DOOR SPEAKER RH X	1	\$ 280.00	\$ X 280.00
8	FRONT WINDSCREEN SEALANT WITH PRIMER X	1	\$ 100.00	\$ X 100.00
9	FRONT FENDER SIGNAL LAMP BULB RH X	1	\$ 15.00	\$ X 15.00
10	FRONT FENDER INNER SHIELD CLIPS SET RH BUL / BUL	1	\$ 50.00	\$ 20 50.00
11	FRONT FENDER INNER SHIELD VERTICAL CLIPS SET RH X	1	\$ 30.00	\$ X 30.00

TOTAL

\$ 1,325.00

300

QUOTATION SUMMARY

PAGE 03

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 1,400.00	600.	800.
TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$ 1,200.00	1000. 800.	
TO APPLY ANTI-RUST & TUFF KOTE	\$ 160.00	60.	
TO PERFORM LIGHTING & WIRING CHECK	\$ 120.00	30.	
TO DISMANTLE & REPLACED FRONT DOOR INNER COMPONENT MECHANISM RH TO FACILITATE REPAIR WITH CHECKING	\$ 250.00	60	
TO DISMANTLE & REINSTALL REAR DOOR INNER COMPONENT MECHANISM RH TO FACILITATE REPAIR WITH CHECKING	\$ 250.00	X	
TO DISMANTLE & REINSTALL FRONT WINDSCREEN PERFORM WITH WATER LEAK TEST	\$ 150.00	X	
TO DISMANTLE & REPLACED REAR UNDER CARRIAGE COMPONENT LH/RH TO PERFORM FACILITATE REPAIRS	\$ 350.00	X	NN
TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	\$ 280.00	X	
TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	\$ 80.00	X.	

[Signature]
25/2/19
Imp sum repair.

After repair photos.

Guo Qian - 82880282
18/2/19.

7 Days.

TOTAL \$ 4,240.00

1950

6402.08

20% 5100.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

QUOTATION SUMMARY**PAGE 04****ESTIMATE REPORT**

TOTAL PARTS COST	:	\$	13,308.84
TOTAL LABOUR COST	:	\$	4,240.00
TOTAL REPAIR COST	:	\$	<u>17,548.84</u>

APPROVED DETAILS

EXCESS	:
NO. OF REPAIR DAYS	:
RE-SURVEY	:
P / P OR L / S	:

DATE / TIME OF SURVEY	:
SURVEYED BY / FROM	:
CONTACT NUMBER	:
FAX NUMBER	:
EMAIL ADDRESS	:

SK Automobile Pte. Ltd.
(Co Reg. No. 201500047H)
23 Kaki Bukit Ave 4, #03-01
Vicom Inspection Centre (S415933)
Tel: 6789 5155 Fax : 6783 5155

TO : CHINA TAIPING	DATE : 19-Feb-19
ATTENTION : MOTOR CLAIMS DEPARTMENT	JOB TYPE : T/P CLAIMS
ESTIMATE REPORT :	
<u>OWNER PARTICULAR</u>	
NAME :	<u>VEHICLE DETAILS</u>
ADDRESS :	VEHICLE NO. : SJT1025Z
TEL. NO. :	MODEL / MAKE : HONDA STREAM
OWNER INSURANCE : FWD	CHASSIS NO. : RN6-1025377
POLICY NO. : PNPV2018-00004750	<u>ACCIDENT DETAIL</u>
PERSON INCHARGE :	DATE : 24-Jan-19
	TIME : 17:45hrs

QUOTATION SUMMARY PAGE 01
CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT DOOR INSULATOR SOUND MAT 2 LAYER	1	\$ 800.00	\$ 800.00
TOTAL				\$ 800.00

APPROVED DETAILS

DATE / TIME OF RESURVEY :
SURVEYED BY / FROM :
CONTACT NUMBER :
FAX NUMBER :
EMAIL ADDRESS :

Limited Repair \$6,000.00

*Repair done by
Rame on 19/02/19*

Parts	\$	10,411.00
Supplementary	\$	800.00
	\$	11,211.00
Less 20%	\$	2,242.20
	\$	8,968.80
SN	\$	1,010.00
	\$	9,978.80
Labour	\$	2,380.00
	\$	12,358.80
L/s less 20%	\$	1,671.67
	\$	6,686.66

Soon Huat Autoserv Pte Ltd

48 Toh Guan Road East #01-136

Enterprise Hub

Singapore 608586

Phone Number: 8402-5982, 9770-5782

Customer: SK AUTO MOBILE PTE LTD			Date: 2/19/2019 11:25 AM			
Company:			VIN			
License No: SJT1025Z			Technician: AL HONG			
Odometer:			Order No.:			
VEHICLE ALIGNMENT REPORT						
HONDA, STREAM, 2006-2014, RN6, RN8 (2WD, 17" Wheel)						
Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	4°18'	3°20'	5°20'	4°18'
		Right	4°27'	3°20'	5°20'	4°28'
	Camber	Left	0°28'	-0°45'	0°45'	0°20'
		Right	-3°06'	-0°45'	0°45'	-2°45'
	Toe	Left	-4.3	-0.5mm	0.5mm	10.0
		Right	33.8	-0.5mm	0.5mm	20.3
Total		29.5	-1.0	1.0	30.3	
Rear	Camber	Left	-0°38'	-1°45'	-0°15'	-0°36'
		Right	-1°48'	-1°45'	-0°15'	-1°47'
	Toe	Left	0.4	0.3mm	1.1mm	0.7
		Right	-1.0	0.3mm	1.1mm	-0.8
		Total	-0.6	0.5	2.1	-0.1
	Thrust Angle		-0°07'	----	----	-0°07'
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI	Left	12°06'	11°05'	11°05'	12°06'	
	Right	11°16'	11°05'	11°05'	11°16'	
Included Angle	Left	12°34'	----	----	12°26'	
	Right	8°10'	----	----	8°31'	
Toe Out On Turns	Left	----	----	----	----	
	Right	----	----	----	----	
Maximum Turns	Left	----	----	----	----	
	Right	----	----	----	----	
Toe Curve Change	Left	----	----	----	----	
	Right	----	----	----	----	
Setback	Front	5mm	----	----	17mm	
	Rear	4mm	----	----	5mm	
Track Width Diff.		-23mm			-22mm	
Wheel Base Diff.		1mm			12mm	
Front Ride Height	Left	----	----	----	----	
	Right	----	----	----	----	
Rear Ride Height	Left	----	----	----	----	
	Right	----	----	----	----	
Frame Angle					----	

Thank You For Your Business

Soon Huat Autoserv Pte Ltd

48 Toh Guan Road East #01-136

Enterprise Hub

Singapore 608586

Phone Number: 8402-5982, 9770-5782

Customer:	SK AUTO	Date:	2/22/2019 6:23 PM
Company:		VIN	
License No:	SJT1025Z	Technician:	AL HONG
Odometer:		Order No.:	

VEHICLE ALIGNMENT REPORT

HONDA, STREAM, 2006-2014, RN6, RN8 (2WD, 17" Wheel)

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	4°06'	3°20'	5°20'	4°04'
		Right	4°10'	3°20'	5°20'	4°10'
	Camber	Left	0°01'	-0°45'	0°45'	-0°25'
		Right	-0°35'	-0°45'	0°45'	-0°37'
	Toe	Left	-0.6	-0.5mm	0.5mm	0.0
		Right	0.5	-0.5mm	0.5mm	0.0
Total		-0.1	-1.0	1.0	0.0	
Rear	Camber	Left	-1°00'	-1°45'	-0°15'	-1°06'
		Right	-1°25'	-1°45'	-0°15'	-1°23'
	Toe	Left	-2.2	0.3mm	1.1mm	0.3
		Right	0.9	0.3mm	1.1mm	0.3
		Total	-1.3	0.5	2.1	0.6
	Thrust Angle		0°15'	----	----	0°00'
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI	Left		11°00'	11°05'	11°05'	11°00'
	Right		11°20'	11°05'	11°05'	11°20'
Included Angle	Left		11°01'	----	----	10°35'
	Right		10°45'	----	----	10°43'
Toe Out On Turns	Left		----	----	----	----
	Right		----	----	----	----
Maximum Turns	Left		----	----	----	----
	Right		----	----	----	----
Toe Curve Change	Left		----	----	----	----
	Right		----	----	----	----
Setback	Front		1mm	----	----	3mm
	Rear		-7mm	----	----	-6mm
Track Width Diff.			6mm			5mm
Wheel Base Diff.			7mm			9mm
Front Ride Height	Left		----	----	----	----
	Right		----	----	----	----
Rear Ride Height	Left		----	----	----	----
	Right		----	----	----	----
Frame Angle						----

Thank You For Your Business

8 days

SK Automobile Pte. Ltd.
(Co Reg. No. 201500047H)
23 Kaki Bukit Ave 4, #03-01
Vicom Inspection Centre (S415933)
Tel: 6789 5155 Fax : 6783 5155

TO	: CHINA TAIPING	DATE	: 14-Feb-19
ATTENTION	: MOTOR CLAIMS DEPARTMENT	JOB TYPE	: T/P CLAIMS
ESTIMATE REPORT	:		
<u>OWNER PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	:	VEHICLE NO.	: SJT1025Z
ADDRESS	:	MODEL / MAKE	: HONDA STREAM
TEL. NO.	:	CHASSIS NO.	: RN6-1025377
OWNER INSUANCE	: FWD	<u>ACCIDENT DETAIL</u>	
POLICY NO.	: PNPV2018-00004750	DATE	: 24-Jan-19
		TIME	: 17:45hrs
PERSON INCHARGE	:		

QUOTATION SUMMARY PAGE 01

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMER ✓	1	\$ 635.60	\$ 635.60
2	FRONT BUMPER RETAINER LH / RH RH / LH X	2	\$ 26.70	\$ 53.40
3	FRONT BUMPER FOG LAMP COVER RH ✓	1	\$ 21.50	\$ 21.50
4	FRONT HEADLAMP LH / RH RH / LH X	2	\$ 855.10	\$ 1,710.20
5	FRONT HEADLAMP LOWER BRACKET LH / RH ✓	2	\$ 55.10	\$ 110.20
6	FRONT GRILLE ✓	1	\$ 240.60	\$ 240.60
7	FRONT GRILLE CHROME CARNISH ✓	1	\$ 280.80	\$ 280.80
8	FRONT GRILLE LOGO EMBLEM ✓	1	\$ 25.20	\$ 25.20
9	FRONT DOOR RH ✓	1	\$ 922.20	\$ 922.20
10	FRONT DOOR SIDE MIRROR RH ASSY ? *	1	\$ 550.00	\$ 550.00
11	FRONT DOOR GLASS RH ✓	1	\$ 370.50	\$ 370.50
12	FRONT DOOR GLASS OUTER MOULDING RH ✓	1	\$ 88.50	\$ 88.50
13	FRONT DOOR OUTER LOCK HANDLE RH ? *	1	\$ 142.80	\$ 142.80
14	FRONT DOOR OUTER LOCK HANDLE COVER RH X	1	\$ 42.60	\$ 42.60
15	FRONT DOOR OUTER KEY LOCK RH ✓	1	\$ 103.80	\$ 103.80
16	FRONT DOOR BLACK FRAME STICKER 'VERTICAC' RH ✓	1	\$ 55.10	\$ 55.10
17	FRONT DOOR BLACK FRAME STICKER 'HCRIZONTAL' RH X *	1	\$ 67.20	\$ 67.20
18	FRONT DOOR HINGES TOP / LOWER RH ✓	2	\$ 36.40	\$ 72.80
19	FRONT DOOR CHECKER RH ✓	1	\$ 44.20	\$ 44.20
20	FRONT DOOR INNER TRIM BOARD RH X *	1	\$ 529.50	\$ 529.50
21	FRONT DOOR POWER WINDOW MAIN CONTROL SWITCH RH ✓	1	\$ 272.30	\$ 272.30
22	FRONT DOOR POWER WINDOW REGULATOR RH X *	1	\$ 156.30	\$ 156.30
23	FRONT DOOR POWER WINDOW MOTOR RH X *	1	\$ 415.90	\$ 415.90
24	FRONT DOOR POWER WINDOW CHANNEL RH X *	1	\$ 90.90	\$ 90.90
25	FRONT DOOR POWER WINDOW CHANNEL WATERSTRIP RH X *	1	\$ 109.20	\$ 109.20
26	FRONT DOOR MECHANISM LOCK RH X *	1	\$ 225.80	\$ 225.80
27	FRONT DOOR WEATHER STRIP RH X *	1	\$ 109.60	\$ 109.60

26.70

855.10

QUOTATION SUMMARY

PAGE 02

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
28	FRONT DOOR PILLAR PANEL 'OUTER' RH	1	\$ 696.80	\$ 696.80
30	FRONT DOOR PILLAR PANEL 'INNER' RH	1	\$ 706.60	\$ 706.60
30	FRONT WINDSCREEN MOULDING	1	\$ 145.60	\$ 145.60
31	REAR DOOR RH	1	\$ 807.80	\$ 807.80
32	REAR DOOR BLACK FRAME STICKER 'VERTICAL' RH	1	\$ 48.70	\$ 48.70
33	REAR DOOR BLACK FRAME STICKER 'HORIZONTAL' RH	1	\$ 67.20	\$ 67.20
34	REAR DOOR WEATHER STRIP RH	1	\$ 109.20	\$ 109.20
35	FRONT FENDER RH	1	\$ 934.60	\$ 934.60
36	FRONT FENDER SIGNAL LAMP RH	1	\$ 46.00	\$ 46.00
37	FRONT FENDER INNERSHIELD RH	1	\$ 198.00	\$ 198.00
38	FRONT FENDER INNERSHIELD VERTICAL RH	1	\$ 97.60	\$ 97.60
39	FRONT FENDER INNER PANEL RH	1	\$ 330.20	\$ 330.20
40	FRONT FENDER BRACKET RH	1	\$ 60.10	\$ 60.10
41	FRONT 16" SPORT RIM RH	1	\$ 1,456.70	\$ 1,456.70
42	FRONT SUSPENSION SHOCK ASSORBER RH	1	\$ 560.80	\$ 560.80
43	FRONT SUSPENSION KNUCKLE ARM RH	1	\$ 490.50	\$ 490.50
44	FRONT SUSPENSION KNUCKLE ARM BEARING RH	1	\$ 202.80	\$ 202.80
45	FRONT SUSPENSION LOWER ARM RH	1	\$ 473.90	\$ 473.90

TOTAL PRICE \$ 14,979.80 \$10,411.00
 LESS -20% \$ (2,995.96) \$(2,082.20)
 SUB TOTAL PRICE \$ 11,983.84 \$8,328.80

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIPS SET	1	\$ 60.00	\$ 30 60.00
2	FRONT HEADLAMP CLIPS SET LH / RH	2	\$ 20.00	\$ 40.00
3	FRONT GRILLE CLIPS SET	1	\$ 30.00	\$ 30.00
4	FRONT DOOR GLASS SOLAR FIRM RH	1	\$ 380.00	\$ 380.00
5	FRONT DOOR SUNVISOR SET	1	\$ 280.00	\$ 280.00
6	FRONT DOOR INNER TRIM BOARD CLIPS SET RH	1	\$ 60.00	\$ 20 60.00
7	FRONT DOOR SPEAKER RH	1	\$ 280.00	\$ 280.00
8	FRONT WINDSCREEN SEALANT WITH PRIMER	1	\$ 100.00	\$ 100.00
9	FRONT FENDER SIGNAL LAMP BULB RH	1	\$ 15.00	\$ 15.00
10	FRONT FENDER INNER SHIELD CLIPS SET RH	1	\$ 50.00	\$ 20 50.00
11	FRONT FENDER INNER SHIELD VERTICAL CLIPS SET RH	1	\$ 30.00	\$ 30.00

TOTAL \$ 1,325.00 \$1,010.00

QUOTATION SUMMARY

PAGE 03

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 1,400.00	600	
TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$ 1,200.00	1000	
TO APPLY ANTI-RUST & TUFF KOTE	\$ 160.00	60	
TO PERFORM LIGHTING & WIRING CHECK	\$ 120.00	30	
TO DISMANTLE & REPLACED FRONT DOOR INNER COMPONENT MECHANISM RH TO FACILITATE REPAIR WITH CHECKING	\$ 250.00	60	
TO DISMANTLE & REINSTALL REAR DOOR INNER COMPONENT MECHANISM RH TO FACILITATE REPAIR WITH CHECKING	\$ 250.00	X	
TO DISMANTLE & REINSTALL FRONT WINDSCREEN PERFORM WITH WATER LEAK TEST	\$ 150.00	X	
TO DISMANTLE & REPLACED REAR UNDER CARRIAGE COMPONENT LH/RH TO PERFORM FACILITATE REPAIRS	\$ 350.00	X *	
TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	\$ 280.00	? *	
TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	\$ 80.00	X	

TOTAL

\$ 4,240.00

\$2,380.00

QUOTATION SUMMARY

PAGE 04

ESTIMATE REPORT

TOTAL PARTS COST	:	\$	13,308.84
TOTAL LABOUR COST	:	\$	4,240.00
TOTAL REPAIR COST	:	\$	<u>17,548.84</u>

APPROVED DETAILS

EXCESS :
NO. OF REPAIR DAYS :
RE-SURVEY :
P / P OR L / S :

DATE / TIME OF SURVEY :
SURVEYED BY / FROM :
CONTACT NUMBER :
FAX NUMBER :
EMAIL ADDRESS :

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT19003122/GSD3N2

Date: 10/10/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SN30311618000		
Claimant Vehicle No :	SJT1025Z	Insured Vehicle No :	PA9216R		
Date of Loss:	24/01/2019	Nature of Claim:	TP	Claim No:	SNM19D200794C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJT1025Z	Engine No:	R18A1728691
Make & Model:	HONDA STREAM, 1.8 (A)	Chassis No:	RN61025377
Reg. Date:	16/04/2007 (Man. Year: 2007)	Odometer:	164875 km
Colour:	Black		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	13,308.84	4,452.08	8,856.76	66.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,240.00	1,950.00	2,290.00	54.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,548.84	6,402.08	11,146.76	63.52
Approved Total (Overridden) (S\$)		5,100.00		
(S\$)	17,548.84	5,100.00	12,448.84	70.94
+ GST 7.00/7.00% (S\$)	1,228.42	357.00	871.42	70.94
Nett Amount (S\$)	18,777.26	5,457.00	13,320.26	70.94

INSPECTION

Date of Assignment: 04/04/2019

Date Inspected: 18/02/2019 Inspected At:

SK Automobile Pte Ltd (Toh Guan)
48 Toh Guan Road East #01-121,
Enterprise Hub
Singapore 608586

Estimated Period of Repair: 7.0 days

Adjuster: XING GUO QIANG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Oct 2019)
Parts:	M1-MPV	HONDA STREAM 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJT1025Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	635.60 FL	*598.00 FL
2	1		*FRONT BUMPER RETAINER LH/RH	O/s Deformed/N/s Not Necessary	53.40 FL	*26.70 FL
3	1		*FRONT BUMPER FOG LAMP COVER RH	Not Necessary	21.50 FL	*- FL
4	1		*FRONT HEADLAMP LH/RH	O/s Cut/N/s Not Necessary	1,710.20 FL	*760.00 FL
5	2		*FRONT HEADLAMP LOWER BRACKET LH/RH	Not Necessary	110.20 FL	*- FL
6	1		*FRONT GRILLE	Not Necessary	240.60 FL	*- FL
7	1		*FRONT GRILLE CHROME GARNISH	Not Necessary	280.80 FL	*- FL
8	1		*FRONT GRILLE LOGO EMBLEM	Not Necessary	25.20 FL	*- FL
9	1		*FRONT DOOR RH	Buckled	922.20 FL	*922.20 FL
10	1		*FRONT DOOR SIDE MIRROR RH ASSY	Cut	550.00 FL	*550.00 FL
11	1		*FRONT DOOR GLASS RH	Scratched	370.50 FL	*370.50 FL
12	1		*FRONT DOOR GLASS OUTER MOULDING RH	Scratched	88.50 FL	*88.50 FL
13	1		*FRONT DOOR OUTER LOCK HANDLE RH	Repair	142.80 FL	*- FL
14	1		*FRONT DOOR OUTER LOCK HANDLE COVER RH	Not Necessary	43.60 FL	*- FL
15	1		*FRONT DOOR OUTER KEY LOCK RH	Not Necessary	103.80 FL	*- FL
16	1		*FRONT DOOR BLACK FRAME STICKER VERTICAL RH	Necessary	55.10 FL	*55.10 FL
17	1		*FRONT DOOR BLACK FRAME STICKER HORIZONTAL RH	Necessary	67.20 FL	*67.20 FL
18	2		*FRONT DOOR HINGES TOP/LOWER RH	Not Necessary	72.80 FL	*- FL
19	1		*FRONT DOOR CHECKER RH	Not Necessary	44.20 FL	*- FL
20	1		*FRONT DOOR INNER TRIM BOARD RH	Not Necessary	529.50 FL	*- FL
21	1		*FRONT DOOR POWER WINDOW MAIN CONTROL SWITCH RH	Not Necessary	272.30 FL	*- FL
22	1		*FRONT DOOR POWER WINDOW REGULATOR RH	Bent	156.30 FL	*156.30 FL
23	1		*FRONT DOOR POWER WINDOW MOTOR RH	Not Necessary	415.90 FL	*- FL
24	1		*FRONT DOOR POWER WINDOW CHANNEL RH	Not Necessary	90.90 FL	*- FL
25	1		*FRONT DOOR POWER WINDOW CHANNEL WATERSTRIP RH	Not Necessary	109.20 FL	*- FL
26	1		*FRONT DOOR MECHANISM LOCK RH	Not Necessary	225.80 FL	*- FL
27	1		*FRONT DOOR WEATHER STRIP RH	Not Necessary	109.60 FL	*- FL
28	1		*FRONT DOOR PILLAR PANEL OUTER RH	Not Necessary	696.80 FL	*- FL
29	1		*FRONT DOOR PILLAR PANEL INNER RH	Not Necessary	706.60 FL	*- FL
30	1		*FRONT WINDSCREEN MOULDING	Not Necessary	145.60 FL	*- FL
31	1		*REAR DOOR RH	Buckled	897.80 FL	*897.80 FL
32	1		*REAR DOOR BLACK FRAME STICKER VERTICAL RH	Not Necessary	48.70 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
33	1		*REAR DOOR BLACK FRAME STICKER HORIZONTAL RH	Not Necessary	67.20 FL	*-FL
34	1		*REAR DOOR WEATHER STRIP RH	Not Necessary	109.20 FL	*-FL
35	1		*FRONT FENDER RH	Buckled	934.60 FL	*486.40 FL
36	1		*FRONT FENDER SIGNAL LAMP RH	Cracked	46.00 FL	*46.00 FL
37	1		*FRONT FENDER INNERSHIELD RH	Deformed	198.00 FL	*165.40 FL
38	1		*FRONT FENDER INNERSHIELD VERTICAL RH	Not Necessary	97.60 FL	*-FL
39	1		*FRONT FENDER INNER PANEL RH	Not Necessary	339.20 FL	*-FL
40	1		*FRONT FENDER BRACKET RH	Not Necessary	60.10 FL	*-FL
41	1		*FRONT SUSPENSION SHOCK ABSORBER RH	Not Necessary	560.80 FL	*-FL
42	1		*FRONT SUSPENSION KNUCKLE ARM RH	Not Necessary	490.50 FL	*-FL
43	1		*FRONT SUSPENSION KNUCKLE ARM BEARING RH	Not Necessary	202.80 FL	*-FL
44	1		*FRONT SUSPENSION LOWER ARM RH	Not Necessary	473.90 FL	*-FL
45	1		*FRONT 16 SPORT RIM RH (LOCAL REPAIR)	Scratched	1,165.36 FS	*100.00 FS
46	1		*SET FRONT BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
47	2		*FRONT HEADLAMP CLIPS SET LH/RH	Not Necessary	40.00 FS	*-FS
48	1		*SET FRONT GRILLE CLIPS	Not Necessary	30.00 FS	*-FS
49	1		*FRONT DOOR GLASS SOLAR FIRM RH	Necessary	380.00 FS	*80.00 FS
50	1		*SET FRONT DOOR SUNVISOR	Necessary	280.00 FS	*50.00 FS
51	1		*FRONT DOOR INNER TRIM BOARD CLIPS SET RH	Necessary	60.00 FS	*20.00 FS
52	1		*FRONT DOOR SPEAKER RH	Not Necessary	280.00 FS	*-FS
53	1		*FRONT WINDSCREEN SEALANT WITH PRIMER	Not Necessary	100.00 FS	*-FS
54	1		*FRONT FENDER SIGNAL LAMP BULB RH	Not Necessary	15.00 FS	*-FS
55	1		*FRONT FENDER INNER SHIELD CLIPS SET RH	Necessary	50.00 FS	*20.00 FS
56	1		*FRONT FENDER INNER SHIELD VERTICAL CLIPS SET RH	Not Necessary	30.00 FS	*-FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,013.46	5,490.10
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,704.62	1,038.02
Total Parts (\$\$)	13,308.84	4,452.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	New	1,400.00	800.00
2	TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	New	1,200.00	1,000.00
3	TO APPLY ANTI-RUST & TUFF KOTE	New	160.00	60.00
4	TO PERFORM LIGHTING & WIRING CHECK	New	120.00	30.00
5	TO DISMANTLE & REPLACED FRONT DOOR INNER COMPONENT MECHANISM RH TO FACILITATE REPAIR WITH CHECKING	New	250.00	60.00
6	TO DISMANTLE & REINSTALL REAR DOOR INNER COMPONENT MECHANISM RH TO FACILITATE REPAIR WITH CHECKING	New	250.00	0.00
7	TO DISMANTLE & REINSTALL FRONT WINDSCREEN PERFORM WITH WATER LEAK TEST	New	150.00	0.00
8	TO DISMANTLE & REPLACED REAR UNDER CARRIAGE COMPONENT LH/RH TO PERFORM FACILITATE REPAIRS	New	350.00	0.00
9	TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	New	280.00	0.00
10	TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	New	80.00	0.00
Gross Labour Cost (S\$)			4,240.00	1,950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >