

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd. From: LKK Auto Consultants Pte Ltd
3 Anson Road 51 Ubi Ave 1 #01-25
#16-00 Springleaf Tower Paya Ubi Industrial Park
Singapore 079909 Singapore 408933

Attn: Elaine Cheong Date: 20 Feb 2019

Preliminary Advice

Vehicle No	: GBH3975B	Accident Date	: 14/02/2019
Make	: PEUGEOT PARTNER	Policy No.	: DMCVSN3035471800
Assignment Date	: 18/02/2019	Excess	: S\$500.00
Date of Inspection	: 18/02/2019	Est. Duration of Repair	: 2 days
Inspection At	: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity Singapore 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	: \$	3,300.00 (INCLUSIVE SUPPLEMENTARY \$500.00)
Revised Amount	: \$	400.00
Check Items (Estimated)	: \$	0.00
Total	: \$	400.00
Lump Sum Repair		: \$

Total Loss Consideration

New for Old Value	: \$	
Pre-Accident Value	: \$	52,000.00
COE / PARF Rebate	: \$	28,076.00
Salvage Value	: \$	
Margin for Repair	: \$	23,924.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Damage on rear left fender related to this accident or other damage not related.