

13/03/2003

ASS. REC. BY:

REF: CS3/LPC18022275/Rsd3-1

Special Instruction:

Surveyor: Rasu

ASSIGNMENT (Office)

From (Person): Ong Li Li

of LPC

Date/Time: 19/2/2019

Estimated Cost:

Bill to:

OD TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLL 9593R

Insured:

SLE 3877Z

at Workshop m/s

Kuo Ah Wai

Tel:

9954 8055

of

5 Soon Lee Street #06-03

Policy No:

Claim No:

18/18/18/VPOS/02/202

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

10/12/2018

CA / REV / REP. / REV 24 HRS

hps

12/12/18

H.O.D. Endorsement:

Date/Time:

3:20pm @ 11/12/18

Person Contacted

Mr. Kuo

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SLL 9593R - X

SLE 3877Z - X.

Pending Insd. GIA.

9/04/19

Submit HS \$ 2,900/- @ 5 days  
(\$ 900/- Red - 24%)

  
28/3/2019

RECEIVED 01 APR 2019

REF:

98344

COE XPIR 2019/11/12

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No. **SLL9593R**at Workshop m/s **Koro AH WUAR**of **5, Soon Lee St #06-03**  
Insured **LPC**

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

**18K**

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res: Yes or No

Lump Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS up

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No

**SLL9593R**Vt Page: **2001 AAP**Type: ☒ M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make

**NISSAN TERRA 2.5 CVT** **2496**

Colour

**WHITE**

A/C Insured / Std / NI / NA

Sp Reading:

**228527**

T/Radio Insured / Std / NI / NA

Eng/No

C/No

**JN1BBUJ32Z 0001319.**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ Good / Jammed / Leaked / Burnt orBrake: ☒ Good / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

**215/55R17**

R:

BS: ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

**6**

mm

R/Bal:

**6**

mm

L/Bal:

**6**

mm

L/Bal:

**6**

mm

D.O.A

**10/12/18**

D.O.I

**12/12/18**

Survey held at

**Koro AH WUAR****11.09**Des. of Damages: Frt / ☒ Rear / O/S / NI / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

**Submit PRS report**

RECEIVED 17 DEC 2018

Date/Time File Pass to?

**14/12/18**

(1)

**Typist**

Date/Time File Return to?

(2)

☐

Prel. Report

☐

Final Report

Days Of Repair:

Resurvey No. of Trip:

**1**

Survey Fee

Transportation

1. S-PK 10

2. Photo

3. Other

Add Fee:

☐

Site Insp. \$

☐

Interview \$

☐

Tech Serv \$

☐

Weekend \$

Report Format:

**PRS**

Lump Sum / I.B.I. \$

**450**

## Nivitha (LKK Auto)

---

**From:** ONG LI LI <llong@lonpac.com>  
**Sent:** Tuesday, 19 February 2019 11:18 AM  
**To:** Admin-D (LKKAuto); assignments  
**Cc:** MT\_Claim\_SG; SUR  
**Subject:** RE: Our Ref : 18/18/18/VP05/021202 2ND PRS - Notice to conduct Pre-Prepair Survey - Your insured'svehicle: SLE 3877Z and our ref: SLL 9593R/KAW/jp/cl [External General]  
**Attachments:** 21202 TPD SURVEY REPORT.pdf

### Lonpac External - General

Dear Catherine/Nivitha


Attached is the TP survey report.

Please let us have your surveyor's comment/report.

Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road #17-04/07 The Concourse Singapore 199555  
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



*Lonpac External - General data is for internal / external use.*

---

**From:** Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]  
**Sent:** Tuesday, 11 December, 2018 3:20 PM  
**To:** ONG LI LI; assignments  
**Cc:** MT\_Claim\_SG; SUR  
**Subject:** RE: Our Ref : 18/18/18/VP05/021202 RE: 2ND PRS - Notice to conduct Pre-Prepair Survey - Your insured'svehicle: SLE 3877Z and our ref: SLL 9593R/KAW/jp/cl

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed repairer agreed survey on 12/12/2018.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** ONG LI LI [mailto:llong@lonpac.com]  
**Sent:** Tuesday, 11 December 2018 1:02 PM  
**To:** Accident@kscgp.com; assignments@lkkauto.com; Admin-D (LKKAuto) <admin-d@lkkauto.com>  
**Cc:** MT\_Claim\_SG <mt\_claim@lonpac.com>

**Subject:** Our Ref : 18/18/18/VP05/021202 RE: 2ND PRS - Notice to conduct Pre-Prepair Survey - Your insured's vehicle: SLE 3877Z and our ref: SLL 9593R/KAW/jp/cl

Without Prejudice  
Save as to Costs


Dear Calshie

We are not agreeable to your proposed list of surveyors, we shall appoint LKK Auto Consultants Pte Ltd to conduct the survey.

Dear Catherine/Nivitha

fya

Regards,  
Ong Li Li  
Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road #17-04/07 The Concourse Singapore 199555  
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



**From:** [Accident@kscgp.com](mailto:Accident@kscgp.com) [<mailto:Accident@kscgp.com>]  
**Sent:** Tuesday, 11 December, 2018 12:59 PM  
**To:** GERALD POH WEE BIN  
**Cc:** MT\_Claim\_SG  
**Subject:** 2ND PRS - Notice to conduct Pre-Prepair Survey - Your insured's vehicle: SLE 3877Z and our ref: SLL 9593R/KAW/jp/cl

Dear Gerald,

Please find attached our 2ND PRS Notice to conduct Pre-Prepair Survey, for your attention.

Thank you.

Wishing you a Merry Christmas and a Happy New Year! 🎄

Regards,  
Calshie LIM  
for and on behalf of Mr Gurdeep Singh Sekhon  
KSCGP Juris LLP  
10 Hoe Chiang Road  
#13-03A Keppel Towers  
Singapore 089315  
Tel: 6538 3611 / DID: 3152 0989 / Fax: 6538 3708  
Email: [accident@kscgp.com](mailto:accident@kscgp.com)

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

----- Original Message -----

**From:** GERALD POH WEE BIN [mailto:geraldpoh@lonpac.com]

**To:** [Accident@kscgp.com](mailto:Accident@kscgp.com)

**Cc:** [mt\\_claim@lonpac.com](mailto:mt_claim@lonpac.com)

**Sent:** Tue, 11 Dec 2018 03:54:35 +0000

**Subject:**

WITHOUT PREJUDICE

Our Ref : 18/18/18/VP05/021202

Dear Calshie,

Please see attached and revert to us.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



---

**From:** [Accident@kscgp.com](mailto:Accident@kscgp.com) [mailto:Accident@kscgp.com]

**Sent:** Tuesday, 11 December, 2018 11:42 AM

**To:** MT\_Claim\_SG

**Cc:** [jiapei@kscgp.com](mailto:jiapei@kscgp.com)

**Subject:** 1ST PRS - Notice to conduct Pre-Prepair Survey - Your insured's vehicle: SLE 3877Z and our ref: SLL 9593R/KAW/jp/d

Dear Sirs,

Please find enclosed our 1ST PRS Notice to conduct Pre-Prepair Survey, for your attention and necessary action.

Thank you.

Wishing you a Merry Christmas and a Happy New Year! 🎅

Regards,

Calshie LIM

for and on behalf of Mr Gurdeep Singh Sekhon

KSCGP Juris LLP

10 Hoe Chiang Road

#13-03A Keppel Towers


Singapore 089315

Tel: 6538 3611 / DID: 3152 0989 / Fax: 6538 3708

Email: [accident@kscgp.com](mailto:accident@kscgp.com)

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege.

If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.



This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)



**PRO  
PLUS  
AUTOMOBILE  
ENGINEERS**

221 Balestier Road #10-01, Rocca Balestier, Singapore 329928  
Tel: +65 6707 8932 Fax: +65 6352 6802  
Mobile: +65 9673 0595 / +65 9788 9809  
E-mail: ethtan88@singnet.com.sg Email: ethtan88@gmail.com  
Company Registration No: 40156500M

*Consultants to Motor Industry, Automobile  
Engineers, Claims Investigators, Accident  
Reconstruction Specialists, Insurance Loss  
Assessors / Adjusters, Valuers And  
Licensed Appraisers.*

## VEHICLE INSPECTION REPORT

To : Mr Sundra s/o Retnam  
c/o 5 Soon Lee Road  
#06-03 Pioneer Point  
Singapore 627607

Insured :  
Policy Number :  
Claim Number :  
Our Reference : PP/ET/CT.9593.TP.1-19  
Own Damage/Sum Insured :  
Excess :  
Third Party/Insco Company :  
Date : 28 January 2019

Instructed By : Mr Sundra s/o Retnam  
Date of Assignment : 10 December 2018  
Date of Accident : 10 December 2018  
Date of Inspection : 11 December 2018  
Name of Workshop : Khor Ah Whar  
Place of Inspection : 5 Soon Lee Road  
#06-03 Pioneer Point  
Singapore 627607

### PARTICULARS OF DAMAGED VEHICLE

Registration Number	: SLL 9593 R	Odometer Reading	: 228 527 Km
Make/Model	: Nissan Teana 2.5 CVT	Radio/Cassette/CD	: Fitted
Year of Manuf/Reg	: 2009	Air Conditioner	: Fitted
Engine Number	: VQ25411214A	View Mirrors	: Fitted -O/s & n/s
Chassis Frame Number	: JNIBBUJ32Z0001319	Seat Belts	: Fitted -Front & rear
Class/Type	: Passenger ( Saloon )	Other Accessories	
Colour	: White	(Specify)	:

### PRE-ACCIDENT CONDITION OF VEHICLE

General Condition	: Good	Any Apparent Engine	
Paintwork	: Good	Modification/s	:
Footbrakes	: Serviceable	Market Value	: -
Steering	: Serviceable	Scrap Value (PARF/OMV)	: -
Undercarriage (Front)	: Serviceable		
Undercarriage (Rear)	: Serviceable		

### TYRE CONDITIONS ON VEHICLE

		NEAR SIDE	OFF SIDE
		70%	70%
Front (Size)	: 215/55R17		
MAKE	: Dunlop		
Rear (Size)	: 215/55R17	70%	70%
MAKE	: Dunlop		
SPARE (Size)	: -	-	
MAKE	: -		
Type of Road Wheels	: Alloy		

NOTE: The above percentages represent the estimated remaining life of the tyre threads  
\* Denotes damaged component/s




## PRO PLUS AUTOMOBILE ENGINEERS

### IMPACT OF VEHICLE

Direction of Impact (←→)

Damages sustained were consistent with the subject vehicle being involved in a collision with another vehicle and the impact was delivered onto the rear portion of the vehicle.



### SYNOPSIS OF DAMAGES RESULTANT FROM THE ACCIDENT



 Damage Area/s

Damages sustained were the bootlid & its inner reinforcement- dented/bent, bootlid hinge n/s- bent/misaligned, bootlid inner lock/striker- bent inwards/shifted/disrupted, rear end panel- thrust inwards/buckled, rear bumper assembly, rear fender n/s- buckled, rear door lock pillar/dog leg n/s- buckled/sandwiched with n/s rear door assembly resulting in its inner lock- shifted/misaligned, rear compartment floor/tyre well panel- buckled etc.----

*Note : Follow-up reinspection of damaged components & works-in-progress on 14 December 2018.*

*Follow-up reinspection of vehicle on 20 December 2018 after spray painting & noted that the listed components as per our recommendations were replaced and repaired accordingly.*

### ESTIMATE

The estimate submitted by **M/s Khor Ah Whar** as per schedule attached has been revised and scrutinised, and in our opinion, we consider it to be fair and reasonable. The repairers have agreed to undertake the repairs to the owner's satisfaction at our revision. As instructed, we have/have not authorised the repairs.

	Repairer's Estimate	Our Recommendation	
Spare Parts :	6717.70	2841.15	Estimated number of days for repairs: 5
Labour Charges :	1250.00	800.00	
Paint Work :	1250.00	850.00	
Towing Charges :			Number of photographs taken at time of static inspection: 39
Others :	670.00	240.00	
TOTAL	9887.70	4731.15	

**Remarks:** The repairer has agreed to undertake the repairs on a contract lump sum of \$3,800.00 NETT corresponding to supply of parts, labour and spray painting charges. Invariably, the motor repairer has the prerogative/option for the recommended replacement components to either be repaired or be replaced.

*NOTE: The revised estimate was made from a visual inspection. Any discrepancies or unseen damage/s should be notified with the company within 7 (seven) days from the date thereof. Otherwise, the revised amount should deem to be valid.*



# APPRAISEMENT SCHEDULE

Registration No: SLL 9593 R

Your Reference:

S/No	Qty	Descriptions	Comments/ Condition	Repairer's Estimate \$	Revised Amount \$
<b><u>PARTS REPLACEMENT- LIST ITEMS</u></b>					
1	1 pc	Bootlid	Dented/bent	1044.70	Repair
2	1 pc	Bootlid rear handle [ chrome ]	Serviceable	323.10	Rejected
3	1 pc	Bootlid inner lock	Bent/malfunctioned/ erratic	97.90	97.90 <i>X SVC</i>
4	1 pc	Bootlid draught weatherstrip	Essential	118.10	118.10 <i>X SVC</i>
5	1 pc	Rear end panel	Thrustud inwards/buckled	446.40	446.40
6	1 pc	Rear end panel inner garnish	Serviceable	78.60	Rejected
7	1 pc	Rear bumper	Dented/distorted	844.30	844.30
8	1 pc	Rear bumper reinforcement [ plastic ]	Cracked/warped	364.80	364.80
9	2 pcs	Rear bumper side retainer @\$40.40	O/s intact n/s cracked	80.80	40.40
				3398.70	1911.90
<b>Less : 30% by Pro Plus Automobile Engineers</b>					573.57
				3398.70	1338.33
<b><u>PARTS REPLACEMENT- NETT ITEMS</u></b>					
1	1 pc	Bootlid ' NISSAN ' emblem	Essential <i>rec</i>	35.00	35.00
2	1 pc	Bootlid ' TEANA ' emblem	Essential <i>rec</i>	52.70	52.70
3	1 pc	Bootlid ' 250X ' emblem	Essential <i>rec</i>	52.70	52.70
4	1 pc	Bootlid ' V8 ' emblem	Essential <i>rec</i>	32.80	32.80
5	1 pc	Bootlid lower moulding [ chrome ]	Serviceable	173.00	Rejected
6	1 pc	Bootlid striker	Bent	50.60	Repair
7	2 pcs	Taillamp assembly @\$419.40	O/s intact n/s base cracked/displaced	838.80	419.40
8	2 pcs	Rear bumper corner moulding @\$154.40	Essential <i>LH-crack RH-SVC</i>	308.80	154.40 308.80
			Sub - Total	1544.40	901.40

APPRAISEMENT SCHEDULE

Registration No: SLL 9593 R

Your Reference:

S/No	Qty	Descriptions	Comments/ Condition	Repairer's Estimate \$ ¢	Revised Amount \$ ¢
			B/F	1544.40	901.40
		<u>PARTS REPLACEMENT- NETT ITEMS (CONT'D)</u>			
9	1 pc	Rear bumper beam	Bent/buckled	268.40	268.40
10	1 pc	Exhaust muffler/tailpipe	Bent	783.60	Refer labour charge
11	2 pcs	Exhaust muffler/tailpipe mounting @\$28.80	Serviceable	57.60	Rejected
		<u>Less : 10% by Pro Plus Automobile Engineers</u>	1052.82	2654.00	1169.80 116.98
				2654.00	1052.82
		<u>PARTS REPLACEMENT- SPECIAL NETT ITEMS</u>			
1	1 set	Bootlid inner trim clip/fastener	Unnecessary <i>AN</i>	50.00	Rejected
2	1 set	Rear end panel inner garnish clip/fastener	Essential <i>REC</i>	40.00	20.00
3	1 set	Rear bumper clip/fastener	Essential <i>MC</i>	50.00	30.0
4	1 set	Rear bumper reverse sensor	Malfunctioned <i>AN</i>	320.00	220 280.00
5	2 pcs	Terostat @\$80.00	Essential <i>MC</i>	160.0	60 120.00
6	1 pc	Rear licence plate c/w holder	Serviceable	45.00	Rejected
					330
			Sub - Total	6717.70	2841.15

# PRO PLUS AUTOMOBILE ENGINEERS

Continuation Sheet No: 3

## APPRAISEMENT SCHEDULE

Registration No: SLL 9593 R

Your Reference:

S/No	Qty	Descriptions	Comments/ Condition	Repairer's Estimate \$    ¢	Revised Amount \$    ¢
			B/F	6717.70	2841.15
		<u>LABOUR &amp; MISC. CHARGES</u>			
1		To disconnect rear wire harness of electrical components to facilitate repairs, reconnect & check functions .		50.00	20.00 ✓
2		To disconnect rear wire harness of rear bumper reverse sensors to facilitate repairs, reconnect & check functions including to replace/recalibrate rear bumper reverse sensors to specifications.		80.00	40.00 ✓
3		To dismantle/transfer/rebuild bootlid fittings/uncillary accessories etc to new bootlid.		150.00	Rejected
4		To dismantle/install rear luggage fittings/uncillary attachments, trims, garnishes, spare tyre, tools etc to facilitate repairs.		160.00	80.00 X m
5		To dismantle/renew exhaust muffler/ tailpipe including heat cut/weld & align system & to check for carbon monoxide leakages	[ to align ]	80.00	max 20.00
6		To check diagnostics of vehicle management/control units , reset memories to specification etc.	[ essential ]	150.00	40 80.00 ✓
7		To dismantle/renew the rear accident damaged portion. To heat, cut/weld rear end panel including to heat, knock-out, reshape, straighten, orientate & align bootlid & its inner reinforcement, bootlid hinge n/s, bootlid striker, taillamp panel n/s, rear fender n/s, rear door lock pillar/dog leg n/s, rear door inner lock n/s, n/s rear door & their inner reinforcement, rear compartment floor/tyre well panel etc to symmetrical dimensions.		1250.00	500 800.00 ✓
Sub - Total				8637.70	3881.15

# PRO PLUS AUTOMOBILE ENGINEERS

Continuation Sheet No: 4

## APPRAISEMENT SCHEDULE

Registration No: SLL 9593 R

Your Reference:

S/No	Qty	Descriptions	Comments/ Condition	Repairer's Estimate \$ £	Revised Amount \$ £
			B/F	8637.70	3881.15
		<u>LABOUR &amp; MISC. CHARGES</u> <u>(CONT'D)</u>			
8		To putty/primer application and spray painting including touch-up affected areas with polyurethane paint.	) ) ) ) ) ) )		
9		To rustproofing & cavities preservation to the replaced and repaired panels.	) ) ) ) ) ) )	1250.00	<del>850.00</del>
		1187.13 1052.82 330.00 1260.00 <u>3829.95</u> 20% 3063.96 <u>45-3,050</u>	5 days		
Grand - Total				9887.70	4731.15

Note: The repairer has agreed to undertake the repairs at a contract lump sum of \$3,800.00 NETT, corresponding to supply of parts, labour and spray painting charges. Invariably, the motor repairer has the prerogative/option for the recommended replacement components to either be repaired or be replaced.

Pro Plus Automobile Engineers

  
ERROL TAN

B.A.Econ (Hons).UK

Dip. Auto Engr. & Motor Trade Management, UK  
Automobile Engineer & Licensed Appraiser

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	10/12/2018 13:14
Date Of Accident	10/12/2018 10:20
Exact Location Of Accident	BUKIT BATOK WEST AVE 6 INTO CARPARK
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLL9593R
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SUNDRAM S/O RETNAM
NRIC No	S7249834H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97307206
Alternative Phone No	OFFICE-97307206
<b>Vehicle Particulars</b>	
Manufacturer	NISSAN
Model	TEANA-2.5 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please indicate action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5090598552.0 (CLASSIC)
Cover Note Number	
<b>Driver</b>	
Name of Driver	SUNDRAM S/O RETNAM
NRIC No	S7249834H
Date Of Birth	09/08/1972
Occupation	INDOOR
Date Of Driving Pass	04/04/1996
Driving Experience	22 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97307206
Fax Number	
Contact Number	OFFICE-97307206
Email Address	NOEMAIL

Address	112 BUKIT BATOK WEST AVE 6
	#04-160
Postcode	S650112
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

SD

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLE3877Z
Vehicle Make/Model/Colour	HONDA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CS3/LPC18022275/R1sd3n2-1

300 BEACH ROAD  
#17-04/07 THE CONCOURSE SINGAPORE 199555

Date : 02-04-2019



Code : LPC2

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLE 3877Z	Veh. Inspected	SLL 9593R
Policy No.		Coverage (\$)	0.00
Claim No.	18/18/18/VP05/021202	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	19/02/2019

### 2. Vehicle Particulars & Condition

Make & Model	NISSAN TEANA 2.5 CVT	c.c	2496
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	JN1BBUJ32Z0001319	Colour	WHITE
Odometer	228527	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55 R17	DUNLOP	6 mm
L/H Front Tyre	215/55 R17	DUNLOP	6 mm
R/H Rear Tyre	215/55 R17	DUNLOP	6 mm
L/H Rear Tyre	215/55 R17	DUNLOP	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

### 5. General Information

Accident Date	10/12/2018	Inspection Date	12/12/2018
Survey held at	5 SOON LEE STREET#06-03		
Repairer	KOO AH WHAR		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 9593R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	BOOTLID	TO REPAIR SEE LABOUR	1,044.70	-
1	BOOTLID REAR HANDLE (CHROME)	SERVICEABLE	323.10	-
1	BOOTLID INNER LOCK	SERVICEABLE	97.90	-
1	BOOTLID DRAUGHT WEATHERSTRIP	SERVICEABLE	118.10	-
1	REAR END PANEL	THRUSTED INWARDS / BUCKLED	446.40	446.40
1	REAR END PANEL INNER GARNISH	SERVICEABLE	78.60	-
1	REAR BUMPER	DENTED / DISTORTED	844.30	844.30
1	REAR BUMPER REINFORCEMENT (PLASTIC)	CRACKED / WARPED	364.80	364.80
2	REAR BUMPER SIDE RETAINER @\$40.40	O/S INTACT / N/S CRACKED	80.80	40.40
	LESS 30% DISCOUNT		-	-508.77
			3,398.70	1,187.13
<b>NETT ITEMS</b>				
1	BOOTLID "NISSAN" EMBLEM (N)	NECESSARY	35.00	35.00
1	BOOTLID "TEANA" EMBLEM (N)	NECESSARY	52.70	52.70
1	BOOTLID "250X" EMBLEM (N)	NECESSARY	52.70	52.70
1	BOOTLID "V8" EMBLEM (N)	NECESSARY	32.80	32.80
1	BOOTLID LOWER MOULDING (CHROME)(N)	SERVICEABLE	173.00	-
1	BOOTLID STRIKER (N)	TO REPAIR SEE LABOUR	50.60	-
2	TAILLAMP ASSEMBLY @\$419.40 (N)	O/S INTACT/N/S BASE CRACKED/DISPLACED	838.80	419.40
2	REAR BUMPER CORNER MOULDING @\$154.40 (N)	N/S CRACKED / O/S SERVICEABLE	308.80	154.40
1	REAR BUMPER BEAM (N)	BENT / BUCKLED	268.40	268.40
1	EXHAUST MUFFLER/TAIPIPE (N)	TO REPAIR SEE LABOUR	783.60	-



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	EXHAUST MUFFLER/TAILOPIPE MOUNTING @\$28.80 (N)	SERVICEABLE	57.60	-
	LESS 10% DISCOUNT		-	-101.54
			2,654.00	913.86
	<b>SPECIAL NETT ITEMS</b>			
1	SET BOOTLID INNER TRIM CLIP/FASTENER (SN)	NOT NECESSARY	50.00	-
1	SET REAR END PANEL INNER GARNISH CLIP/FASTENER (SN)	NECESSARY	40.00	20.00
1	SET REAR BUMPER CLIP/FASTENER (SN)	NECESSARY	50.00	30.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	NOT WORKING	320.00	220.00
2	TEROSTAT @\$80.00 (SN)	NECESSARY	160.00	60.00
1	REAR LICENCE PLATE C/W HOLDER (SN)	SERVICEABLE	45.00	-
			665.00	330.00
	<b>LABOUR</b>			
	TO DISCONNECT REAR WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS.RECONNECT & CHECK FUNCTIONS.		50.00	20.00
	TO DISCONNECT REAR WIRE HARNESS OF REAR BUMPER REVERSE SENSORS TO FACILITATE REPAIRS,RECONNECT & CHECK FUNCTIONS INCLUDING TO REPLACE/RECALIBRATE REAR BUMPER REVERSE SENSORS TO SPECIFICATIONS.		80.00	40.00
	TO DISMANTLE/TRANSFER,REBUILD BOOTLID FITTINGS/UNCILLARY ACCESSORIES ETC TO NEW BOOTLID.	NOT NECESSARY	150.00	-
	TO DISMANTLE/INSTALL REAR LUGGAGE FITTINGS/UNCILLARY ATTACHMENTS,TRIMS,GARNISHES,SPARE TYRE,TOOLS ETC TO FACILITATE REPAIRS.	NOT NECESSARY	160.00	-
	TO DISMANTLE/RENEW EXHAUST MUFFLER/TAILOPIPE INCLUDING HEAT CUT/WELD & ALIGN SYSTEM & TO CHECK FOR CARBON MONOXIDE LEAKAGES.	NOT NECESSARY	80.00	-
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.		150.00	40.00

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISMANTLE/RENEW THE REAR ACCIDENT DAMAGED PORTION.TO HEAT,CUT/WELD REAR END PANEL INCLUDING TO HEAT,KNOCK-OUT,RESHAPE,STRAIGHTEN, ORIENTATE & ALIGN BOOTLID & ITS INNER REINFORCEMENT,BOOTLID HINGE N/S,BOOTLID STRIKER,TAILLAMP PANEL N/S,REAR FENDER N/S REAR DOOR LOCK PILLAR/DOG LEG N/S,REAR DOOR INNER LOCK N/S,N/S REAR DOOR & THEIR INNER REINFORCEMENT,REAR COMPARTMENT FLOOR/TYRE WELL PANEL ETC TO SYMMETRICAL DIMENSIONS.INCLUSIVE OF THE REPAIR OF EXHAUST MUFFLER/TAIPIPE.		1,250.00	500.00
	TO PUTTY/PRIMER APPLICATION AND SPRAY PAINTING INCLUDING TOUCH-UP AFFECTED AREAS WITH POLYURETHANE PAINT. }		1,250.00	600.00
	TO RUSTPROOFING & CAVITIES PRESERVATION TO THE REPLACED AND REPAIRED PANELS. }		-	-
			3,170.00	1,200.00
<b>GRAND TOTAL</b>			<b>9,887.70</b>	<b>3,630.99</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>2,500.00</b>

Report Ref No. CS3/LPC18022275/R1sd3n2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.