

AIG Aisa Pacific Insurance Pte Ltd
AIG Building
78 Shenton Way #07-16
Singapore 079120

3RD PARTY CLAIM ESTIMATION

Vehicle number	SKK7766P
Make / Model	HONDA/FIT
Chassis number	GE61007352
Accident date	02 Fenruary 2019
Reference	1902-14

Qty	Particulars	Unit Price - SGD \$	
<u>PARTS REPLACEMENT - LIST ITEMS</u>			
1	END PANEL NW	565.90 X	
1	END PANEL TOP GARNISH NW	107.80 X	
2	REAR TAILLAMP O/S CRASH W/S NW	414.50 ✓	
2	REAR FENDER INNER TRIM NW	589.00 X	
1	TAILGATE	908.00 X	
1	TAILGATE WEATHERSTRIP NW	92.30 X	
1	TAILGATE LOCK NW	186.20 X	
1	TAILGATE LOCK STRIKER NW	28.00 X	
1	TAILGATE INNER TRIM NW	151.00 X	
1	TAILGATE GLASS MOLDING NW	86.00 X	
1	SPARE TYRE TOP BOARD NW	291.00 X	
		3419.70	
		Less 20%	683.94
		Subtotal	2735.76
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>			
Balance B/F		2735.76	
1 SET	REAR REVERSE SENSOR Dem	400.00 220/-	
1 SET	REAR BUMPER CLIP Hec	40.00 30/-	
1	REAR BUMPER (AFTER MARKET) distributed	1200.00 800/-	
1	REAR BUMPER UNDER GARNISH (AFTER MARKET) distributed	800.00 500/-	
1	JOINT SEALANT NW	150.00 X	
1	WINDSCREEN SEALANT NW	150.00 X	
		Subtotal	2740.00
Balance C/F		5475.76	
<u>LABOUR AND MISCELLANEOUS CHARGES</u>			
Balance B/F		5475.76	
1	CHECK REAR WIRING AND LIGHTNING SYSTEM	60.00 30/-	
2	REMOVE AND RENEW REAR REVERSE SENSOR	150.00 40/-	
3	REMOVE AND REFIT REAR LINING, TRIM AND GARNISH	200.00 NW	
4	REMOVE AND STRAIGHTEN REAR EXHAUST	150.00 NW	
5	REMOVE AND REFIT REAR WINDSCREEN	150.00 NW	
6	TRANSFER PARTS, ATTACHMENT FROM OLD TAILGATE TO NEW	200.00 NW	
7	PANEL BEATING ON AFFECTED AREAS	1400.00 300/-	
8	SPRAY PAINTING ON AFFECTED AREAS	1400.00 300/-	
9	REMOVE AND RENEW WRAPPING ON AFFECTED AREAS	800.00 450/-	
		Subtotal	4510.00
20/02/2019 e 1700m NW Antura 2/5mm		4 days.	
		Grand total	9985.76

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: