



Stew (LKK) WH Pte Ltd
26/3/19 10.00 am

AIG Asia Pacific Insurance Pte. Ltd
78 Shenton Way
#08-16
Singapore(079120)

P/P
Ry b/f 6 AL Spg
3 days

Teamwork Garage Pte Ltd
53 Ubi Avenue 1 #01-23/24 Spore 408934
Paya Ubi Industrial Park
Tel : 6844 2475
E-mail : claims@teamworkgarage.com
Register number : 201015366H
ROC number : 201015366H
3RD PARTY CLAIM ESTIMATION

Vehicle number	SMC1818G
Make / Model	TOYOTA ALPHARD
Chassis number	JN1BAAC11Z0007196
Accident date	25 January 2019
Reference	1902-17

Qty	Particulars	Unit Price - SGD \$
PARTS REPLACEMENT - LIST ITEMS		
1	REAR BUMPER / DD	609.90 /
1	END PANEL - OUTER X R	728.30 X
1	END PANEL - INNER X NN	594.20 X
1	REAR TAILLAMP PANEL X NN	364.80 X
2	REAR BUMPER RETAINER / NEC RH - LH /	70.40 / 70.39
2	REAR BUMPER BRACKET X NN	90.80 X
1	END PANEL TOP GARNISH X NN	173.10 X
1	REAR TAILLAMP X NN	519.30 X
1	REAR PDC SENSOR WIRE X NN	445.68 X
1	REAR BUMPER SIDE COVER RH X NN	601.45 X
		680.30 - 25% 510.22
		4197.93
	Less 25 %	1049.48
	Subtotal	3148.45
	Balance C/F	3148.45
PARTS REPLACEMENT - SPECIAL NETT ITEMS		
	Balance B/F	3148.45
1 SET	REAR BUMPER CLIP / NEC	30 / 40.00
1 SET	REAR REVERSE SENSOR ? X NN	400.00 X
	Subtotal	440.00
	Balance C/F	3588.45
LABOUR AND MISCELLANEOUS CHARGES		
	Balance B/F	3588.45
1	CHECK REAR WIRING AND LIGHTING	60.00 30
2	REMOVE AND REFIT REAR LINING, TRIM AND GARNISH	200.00 50
4	REMOVE AND REFIT REAR REVERSE SENSOR	150.00 30
9	PANEL BEATING ON AFFECTED AREAS	1200.00 400
10	SPRAY PAINTING ON AFFECTED AREAS	1000.00 500
11	APPLY ANTI RUST ON AFFECTED AREAS	150.00 20
	Subtotal	2760.00
	Grand total	6348.45



Teamwork Garage Pte Ltd
 53 Ubi Avenue 1 #01-23/24 Spore 408934
 Paya Ubi Industrial Park
 Tel : 6844 2475
 E-mail : claims@teamworkgarage.com
 Register number : 201015366H
 ROC number : 201015366H
3RD PARTY CLAIM ESTIMATION

AIG Asia Pacific Insurance Pte. Ltd
 78 Shenton Way
 #08-16
 Singapore(079120)

Vehicle number	SMC1818G
Make / Model	TOYOTA ALPHARD
Chassis number	JN1BAAC11Z0007196'
Accident date	25 January 2019
Reference	1902-17

Qty	Particulars	Unit Price - SGD \$
	<u>PARTS REPLACEMENT - LIST ITEMS</u>	
1	TAILGATE / 011	2100.00 1957 ✓
1	WINDSCREEN MOUDLING / MC	189.10 /
		2289.10
	Less 25 %	714.10
	Subtotal	1575.00
	<u>LABOUR AND MISCELLANEOUS CHARGES</u>	
	Balance B/F	1575.00
1	REMOVE AND REFIT REAR WINDSCREEN	200.00 190 ✓
	Subtotal	200.00
	Grand total	1775.00

1799.57 ✓

P- 519.22
 Supp- 1799.57
 AI - 30
 L- 1030
3279.79

Steve Chen (LKK Auto)

From: claims@teamworkgarage.com
Sent: Tuesday, September 10, 2019 11:07 AM
To: Steve Chen (LKK Auto)
Cc: 'TEAMWORK GARAGE CLAIMS'
Subject: RE: SMC1818G TOYOTA ALPHARD

Hi steve ,

We confirm COR \$3,279.79 & DOR @ 3 days.

Thank you and have a nice day! ☺

Letitia

Teamwork Garage Pte Ltd

Blk 53 Ubi Avenue 1 #01-24 Paya Ubi Industrial Park
Singapore (408934)
Tel: 6844 2475 | Fax: 6844 2474

From: Steve Chen (LKK Auto) [mailto:SteveChen@lkkauto.com]
Sent: Wednesday, July 10, 2019 7:11 PM
To: Darren <claims@teamworkgarage.com>
Subject: SMC1818G TOYOTA ALPHARD

Dear Darren,

Kindly refer our finalize \$3,279.79 (P/P, before GST). 3 days.

Kindly confirm.

Thanks

Best Regards,

Steve Chen | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Darren [mailto:claims@teamworkgarage.com]
Sent: Tuesday, July 09, 2019 6:36 PM
To: Steve Chen (LKK Auto)
Subject: SMC1818G TOYOTA ALPHARD

Hi Steve,

FYNA