



Steve (LKK) with Pte Ltd
26/3/19 10.00 am

AIG Asia Pacific Insurance Pte. Ltd
78 Shenton Way
#08-16
Singapore(079120)

P/P
Ry b of 6 AL Spg
7 days

Teamwork Garage Pte Ltd
53 Ubi Avenue 1 #01-23/24 Spore 408934
Paya Ubi Industrial Park
Tel : 6844 2475
E-mail : claims@teamworkgarage.com
Register number : 201015366H
ROC number : 201015366H
3RD PARTY CLAIM ESTIMATION

Vehicle number	SMC1818G
Make / Model	TOYOTA ALPHARD
Chassis number	JN1BAAC11Z0007196'
Accident date	25 January 2019
Reference	1902-17

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	REAR BUMPER / DD	609.90
1	END PANEL - OUTER X R	728.30
1	END PANEL - INNER X NM	594.20
1	REAR TAILLAMP PANEL X NM	364.80
2	REAR BUMPER RETAINER - NEC RH - LH	70.40
2	REAR BUMPER BRACKET X NM	90.80
1	END PANEL TOP GARNISH X NM	173.10
1	REAR TAILLAMP X NM	519.30
1	REAR PDC SENSOR WIRE X NM	445.68
1	REAR BUMPER SIDE COVER RH X NM	601.45
	≠ Tailgate DD	
		4197.93
	Less 25 %	1049.48
	Subtotal	3148.45
	Balance C/F	3148.45
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
	Balance B/F	3148.45
1 SET	REAR BUMPER CLIP / NEC	30 40.00
1 SET	REAR REVERSE SENSOR ?	400.00
	Subtotal	440.00
	Balance C/F	3588.45
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
	Balance B/F	3588.45
1	CHECK REAR WIRING AND LIGHTING	60.00 30
2	REMOVE AND REFIT REAR LINING, TRIM AND GARNISH	200.00 50
4	REMOVE AND RENEW REAR REVERSE SENSOR	150.00 30
9	PANEL BEATING ON AFFECTED AREAS	1200.00 400
10	SPRAY PAINTING ON AFFECTED AREAS	1000.00 500
11	APPLY ANTI-RUST ON AFFECTED AREAS	150.00 10
	Subtotal	2760.00
	Grand total	6348.45
	Signature: Repairer	