



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SMC9538L

NTUC INCOME INS CO-OPERATIVE LTD

ATTN: MOTOR CLAIMS DEPARTMENT
73 BRAS BASAH ROAD #05-01
NTUC TRADE UNION HOUSE
SINGAPORE 189556
67886616

Vehicle & Document Information

WIP No **30671**
Reg No/Reg Date **SMC9538L / 11/02/2015**
Date In/Mileage **19/02/2019/ 73516**
Chassis No **WDD2120342B132491**
Engine No **27492030357334**
Make/Model **MB/E 200 2.0 CGI SEDAN (W212**
Colour/Trim **021 197 Obsidian B1/ 042 211 Leather bla**

Account No	Terms	Date/Time Printed	CSE	Operator	Description of Goods / Services	Qty	Unit Price	Disc%	Amount
WI000549	Credit	04/04/2019/ 10:55	CH	371 / Go Chee Han					
Z REQUEST					Customer Request				
M BPNSUN					POLICY NO/ACC DATE : SI18V05417 // 1-2-2019				
					DRIVE IN/TP VEH : 1-2-2019 // SLA4490U - NTUC				
					DATE IN/DATE SURVEY: 19-2-2019 1430 // Taufik - LKK				
					BY/AUTHORIZED ON : 14-2-2019 // Azhari - NTUC				
A BPILAB					STRAIGHTEN, REMOVE SUPPORT ASSY FROM FRAME IMPACT				3840.00
					DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.				
A BPIRES					RESPRAY REAR BUMPER & TRUNK LID & END PANEL				1800.00
A BPILAB					USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO			0.10	380.00
					IDENTIFICATION STANDARD. NETT				
A BPILAB					CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT				120.00
A BPILAB					PLACE VEHICLE ON-TO CELLETTE BENCH & CONDUCT CHASSIS ALIGNMENT. NETT			0.07	1000.00
A BPILAB					REMOVE & REFIT LUGGAGE COMPARTMENT, TRIM, GARNISH-				960.00
					CARPET FOR NECESSARY REPAIR. NETT				
A BPILAB					TO STRAIGHTEN & ALIGN REAR EXHAUST SYSTEM. NETT				420.00
A BPILAB					REMOVE REAR CARRIAGE ASSY FROM FRAME, IMPACT. REPLACE AND ASSEMBLE				1920.00
					WHEEL BASE & ADJUST TO VEHICLE.				
A BPILAB					TO INSPECT & CONDUCT WHEEL ALIGNMENT. NETT				540.00
A BPILAB					SEALANT PANEL JOINT			0.49	80.00
S BPNSUB					SUPPLY 1 PC NO PLATE				60.00

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Mercedes-Benz are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SMC9538L

NTUC INCOME INS CO-OPERATIVE LTD

ATTN: MOTOR CLAIMS DEPARTMENT
73 BRAS BASAH ROAD #05-01
NTUC TRADE UNION HOUSE
SINGAPORE 189556
67886616

Vehicle & Document Information

WIP No **30671**
Reg No/Reg Date **SMC9538L / 11/02/2015**
Date In/Mileage **19/02/2019/ 73516**
Chassis No **WDD2120342B132491**
Engine No **27492030357334**
Make/Model **MB/E 200 2.0 CGI SEDAN (W212**
Colour/Trim **021 197 Obsidian Bl/ 042 211 Leather bla**

Account No	Terms	Date/Time Printed	CSE	Operator
WI000549	Credit	04/04/2019/ 10:55	CH	371 / Go Chee Han

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X REAR BUMPER	1.00	1663.18	00.00	1663.18
X LH/REAR BUMPER CHROME MOULDING	1.00	132.65	00.00	132.65
X RH/REAR BUMPER CHROME MOULDING	1.00	132.65	00.00	132.65
X SPACER RING	6.00	6.42	00.00	38.52
X TRUNK LID	1.00	2790.99	00.00	2790.99
X TRUNK LID WEATHERSTRIP	1.00	181.83	00.00	181.83
X TRUNK LID CHROME MOULDING	1.00	117.11	00.00	117.11
X GROMMET	3.00	2.29	00.00	6.87
X MERCEDES STAR	1.00	48.25	00.00	48.25
X E200 MODEL PLATE	1.00	83.60	00.00	83.60
X REAR END PANEL	1.00	1265.29	00.00	1265.29
X REAR CROSS MEMBER	1.00	817.08	00.00	817.08
X SPARE WHEEL WELL	1.00	289.40	00.00	289.40
X BASIC MOUNTING FOR BUMPER	1.00	218.99	00.00	218.99
X RIVETED NUT	4.00	3.75	00.00	15.00
X STOP	2.00	9.73	00.00	19.46
X SPHERICAL COLLAR BOLT	4.00	10.59	00.00	42.36
X RIVET	16.00	2.54	00.00	40.64
X RIGHT REAR LAMP COMBINATION	1.00	712.05	00.00	712.05
X LICENSE PLATE LAMP	1.00	27.05	00.00	27.05

Finalization

Confirmed & accepted by

Nett **19,762.97**
7% GST on **19762.97** **1383.41**

Authorized signatory and company stamp

Total Payable **21,146.38**

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SMC9538L

NTUC INCOME INS CO-OPERATIVE LTD

ATTN: MOTOR CLAIMS DEPARTMENT
73 BRAS BASAH ROAD #05-01
NTUC TRADE UNION HOUSE
SINGAPORE 189556
67886616

Vehicle & Document Information

WIP No **30671**
Reg No/Reg Date **SMC9538L / 11/02/2015**
Date In/Mileage **19/02/2019 / 73516**
Chassis No **WDD2120342B132491**
Engine No **27492030357334**
Make/Model **MB/E 200 2.0 CGI SEDAN (W212**
Colour/Trim **021 197 Obsidian Bl/ 042 211 Leather bla**

Account No	Terms	Date/Time Printed	CSE	Operator
WI000549	Credit	04/04/2019/ 10:53	CH	371 / Go Chee Han

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE : SI18V05417 // 1-2-2019 DRIVE IN/TP VEH : 1-2-2019 // SLA4490U - NTUC DATE IN/DATE SURVEY: 19-2-2019 1430 // Taufik - LKK BY/AUTHORIZED ON : 14-2-2019 // Azhari - NTUC				
S BPNSUB SUPPLY 1 PC NO PLATE				60.00
X RIVETED NUT	4.00	3.75	00.00	15.00
X STOP	2.00	9.73	00.00	19.46
X SPHERICAL COLLAR BOLT	4.00	10.59	00.00	42.36
X RIVET	16.00	2.54	00.00	40.64
X RIGHT REAR LAMP COMBINATION	1.00	712.05	00.00	712.05
X LICENSE PLATE LAMP	1.00	27.05	00.00	27.05

SUPPLEMENTARY

Confirmed & accepted by

Nett 916.56
7% GST on 916.56 64.16
Total Payable 980.72

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg