

ASS. REC. BY:

REF: CS/INC/9003148/R/Sd3n2

Special Instruction:

Surveyor

Rashu

ASSIGNMENT (Office)

From (Person): Cynthia Ang

of INC

Date/Time: 10:38 am 9/12/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GIBF 4854X

Insured: GBH 336 IP

at Workshop m/s BP Auto

Tel: 6266 0555

of 18 toh Green Rd East #01-121

Policy No:

Claim No: MT/1032127-002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 14/12/19

CA / REV / REP. / REV 24 HRS

hup

H.O.D. Endorsement

Date/Time: 11:04 am 9/12/19

Person Contacted: YWNE

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate	
	GIBF 4854X - NA/INC 19003148/K4	D.O.A. 14/12/19
	GBH 336 IP - NA/INC 19003148/K4	D.O.A. 14/12/19
24/07/19	83,700 / 6 days (con combined)	
	(+ 8,603.32 Red - 70%)	

Form

107

5952A

INSURANCE

Make: _____

Model: _____

Year: _____

Color: _____

Engine: _____

Transmission: _____

Drive: _____

Insurance: _____

Policy No.: _____

Claim No.: _____

Sum Insured: _____

Excess: _____

Make of Vehicle: _____

Remark: The veh had commenced its repair at the time of inspection.

Estimate: _____

Days: _____


Cost: _____

CA / REV / REP: _____

Date: _____

Person Contacted: _____

Vehicle: IN / OUT



Vehicle: G6F 4854X

Type: M/Car / H/Cycle / Bus / Van / Lorry / Taxi / Private Motor / Truck / Trailer or

Make: NISSAN CASSINI 3.0 SM

Color: Grey

Sp. Reading: 93478

Engine: JN18C2F 24208 590 28

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Smooth / Jammed / Leaked / Burnt or

Brake: Smooth / Jammed / Leaked / Burnt or

Mod: H / S/Rim / STD A/Rim or

Tyre Size: F: 175/80R15
R: 155R13

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / OKW or

Front: R/Bal 7 mm
L/Bal 7 mm
D.O.A. 14/02/19

Rear: R/Bal 5 mm
L/Bal 5 mm
D.O.L. 19/02/19

Survey held at: SK AUTO 11.56am

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Insured amount \$5,450 / 6 days 4/5
(\$8,506.99 Rd - 61%)

14/8/2019

RECEIVED 15 AUG 2019

Expiry Date: 14/08/19

Type: _____

Days Of Repair: _____

Resurvey No. of Trip: 1

Survey Fee: _____

Add Fee: _____

Report Format: _____

Stamp: 5.450/- 4/5

250

Nivitha (LKK Auto)

From: Cynthia Ang <Cynthia.Ang@income.com.sg>
Sent: Tuesday, 19 February 2019 10:38 AM
To: assignments@lkkauto.com
Subject: RE: TP CASES FARMED OUT TO LKK ON 19/2/2019

Dear Veron / Nivitha,

Resend with the following details.

With Regards

Cynthia Ang
Admin Assistant
Motor Insurance
T +65 6430 7900
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.

Find out more at Income.com.sg/careers

in with you

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

From: Cynthia Ang
Sent: Tuesday, 19 February 2019 9:38 AM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>
Cc: Teng Ken Leong <kenleong.teng@income.com.sg>; Daniel Koh <daniel.koh@income.com.sg>; Thio Tse Kiat <tsekiat.thio@income.com.sg>
Subject: TP CASES FARMED OUT TO LKK ON 19/2/2019

Dear Veron / Nivitha,

Please assist to survey the vehicles as per Mr Teng's instruction :-

SN	Surveyor	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Type	Survey Time	Of Veh	DOA	Additional Remarks
1	Marcus Xiao	MT/1028540-002	GBF4771B	BP AUTO	48 TOH GUAN ROAD EAST #01-121 ENTERPRISE HUB SINGAPORE 608586	Yvonne / 6266 0555	Physical Survey		YN7967U	16/01/2019	
2	Jared Liu	MT/1032127-002	GBF4854X	BP AUTO	48 TOH GUAN ROAD EAST #01-121 ENTERPRISE HUB SINGAPORE 608586	/ 6266 0555	Physical Survey		GBH3381P	14/02/2019	
3	Azhari	MT/1030557-002	5MC9538L	CYCLE & CARRIAGE INDUSTRIES PTE LTD	188 PANDAN LOOP SINGAPORE 128378	GO CHEE HAN / 9181 7717	Physical Survey	10:00- 12:00	SLA4490U	01/02/2019	
4	Charlotte Chew	MT/1032277-002	SMD9595R	GOLD AUTO WORKS PTE LTD	48 TOH GUAN ROAD EAST #01-119 ENTERPRISE HUB	SIMON TAN / 8199-9149	Physical Survey		SJK2343X	15/02/2019	
5	Juliana Lee	MT/1032093-002	GBC4953J	LEE KUAN HWA MOTOR SERVICE	24 SUNGEI KADUT STREET 4 SUNGEI KADUT INDUSTRIAL ESTATE SINGAPORE 729050	Siew Chen / 6369 9192	Physical Survey		SJP7498Z	11/02/2019	
6	Fiona Shen	MT/1031900-002	SKC197U	MUNICH AUTOMOBILES PTE LTD	30 TEBAN GARDENS CRESCENT SINGAPORE 608927	Tan Kok Ting / 9051 5581	Physical Survey	10:00- 11:00	SLS3819T	11/02/2019	

Please contact workshops.

Please ack.

Thank You

With Regards

Cynthia Ang
Admin Assistant
Motor Insurance
T +65 6430 7900
www.income.com.sg

income

made different



in with
you

At Income, we are 'In with You' on Performance, Growth,
Innovation and Impact. These attributes reflect what we promise
as an employer and what we want our people to exemplify.

Find out more at Income.com.sg/careers

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

Shirley Hiew (LKK Auto)

From: bpauto <bpauto@yahoo.com>
Sent: Tuesday, 6 August 2019 3:05 PM
To: Rasul (LKKAuto)
Cc: Shirley Hiew (LKK Auto)
Subject: Re: Arrange for Pre-repair Inspection for GBF4854X (YOUR Insured: GBH3381P)
DOA 14 Feb 2019

Hi Rasul,

OK, COR confirm.

Thanks & Regards,

Yvette Zhao

BP Auto
48 Toh Guan Road East #01-121
Enterprise Hub Singapore 608586
Tel: +65-6266 0555
Fax: +65-6266 3155
Email: bpauto_wkshp@yahoo.com

On Tuesday, 6 August 2019, 12:11:17 pm SGT, Rasul (LKKAuto) <Rasul@lkkauto.com> wrote:

Hi Yvette,

Finalised amount is \$ 5,450 / 6 days of lump sum repair

Kindly confirm

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Veron Chen (LKKAUTO)

From: bpauto <bpauto@yahoo.com>
Sent: Friday, 2 August 2019 12:09 PM
To: Rasul (LKKAUTO)
Cc: Shirley Hiew (LKK Auto)
Subject: Re: Arrange for Pre-repair Inspection for GBF4854X (YOUR Insured: GBH3381P)
DOA 14 Feb 2019
Attachments: GBF4854X Estimate.pdf

Hi Rasul,

The Estimate attached. Kindly assist.

Thanks & Regards,

Yvette Zhao

BP Auto
48 Toh Guan Road East #01-121
Enterprise Hub Singapore 608586
Tel: +65-6266 0555
Fax: +65-6266 3155
Email: bpauto_wkshp@yahoo.com

On Wednesday, 31 July 2019, 5:21:26 pm SGT, Rasul (LKKAUTO) <Rasul@lkkauto.com> wrote:

Hi Yvette,

Kindly re-do the estimate for this case on the parts prices nett discount change to 10% instead of 30% and forward to me

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Shirley Hiew (LKK Auto)

From: Rasul (LKKAuto) <Rasul@lkkauto.com>
Sent: Wednesday, 24 July 2019 9:54 AM
To: bpauto
Cc: Shirley Hiew (LKK Auto)
Subject: RE: Arrange for Pre-repair Inspection for GBF4854X (YOUR Insured: GBH3381P) DOA 14 Feb 2019

Hi Yvonne,

I disagree with the finalisation
Anyway, I will submit as per usual subject to insurance approval

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: bpauto [mailto:bpauto@yahoo.com]
Sent: Tuesday, 23 July, 2019 3:05 PM
To: Rasul (LKKAuto)
Cc: Shirley Hiew (LKK Auto)
Subject: Re: Arrange for Pre-repair Inspection for GBF4854X (YOUR Insured: GBH3381P) DOA 14 Feb 2019

Hi Rasul,

Kindly re-confirm the parts price,

We check with our supplier, those is NETT PRICE, base on NTUC INCOME ANNEX1, Nett price discount 10% only.

Attached Estimate and Price List, please check and get back to us ASAP.

Thanks & Regards,

Yvette Zhao

BP Auto
48 Toh Guan Road East #01-121
Enterprise Hub Singapore 608586
Tel: +65-6266 0555
Fax: +65-6266 3155
Email: bpauto_wkshp@yahoo.com

On Tuesday, 23 July 2019, 11:56:32 am SGT, Rasul (LKKAuto) <Rasul@lkkauto.com> wrote:

Hi Yvonne,

Kindly assist confirm this finalise amount


Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Rasul (LKKAuto)
Sent: Thursday, 13 June, 2019 2:14 PM
To: BP Auto
Cc: Shirley Hiew (LKK Auto)
Subject: RE: Arrange for Pre-repair Inspection for GBF4854X (YOUR Insured: GBH3381P) DOA 14 Feb 2019

Hi Yvonne,

Refer to attachment

Finalised amount is \$ 3,700 / 6 days lump sum

Kindly confirm


Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: BP Auto [<mailto:bpauto@yahoo.com>]

Sent: Saturday, 2 March, 2019 4:55 PM

To: Rasul (LKKAuto)

Subject: Fw: Arrange for Pre-repair Inspection for GBF4854X (YOUR Insured: GBH3381P) DOA 14 Feb 2019

Dear Mr Rasul,

Kindly help top finalized below vehicle. The after photo attached.

MT/1032127-002 (TP NTUC)	GBF4854X	Lumpsum Repair	\$5,000.00
--------------------------	----------	----------------	------------

Repair days 7 days

Thanks & Regards,

Yvonne

BP Auto

48 Toh Guan Road East #01-121

Enterprise Hub Singapore 608586

Tel: +65-6266 0555
Fax: +65-6266 3155

On Tuesday, 19 February 2019, 9:20, "MTCL@income.com.sg" <mtcl@income.com.sg> wrote:

Hi all,

Claim created. MT/1032127-002

OIC - JARED

With Regards

Junainah
Senior Admin Assistant

Motor Insurance

www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers

in wit'
yo

From: BP Auto [<mailto:bpauto@yahoo.com>]
Sent: Monday, 18 February 2019 4:20 PM
To: MTSurvey <MTSurvey@income.com.sg>; NTUC Income Motor Dept <motor@income.com.sg>;
MTCL@income.com.sg
Subject: Arrange for Pre-repair Inspection for GBF4854X (YOUR Insured: GBH3381P) DOA 14 Feb 2019

Request For Surveyor

Dear Motor Claim Department,

We would like to request a vehicle in-house surveyor for the following:

Our client vehicle (GBF4854X) is currently at

48 Toh Guan Road East,

#01-121 Enterprise Hub,

Singapore 608586

Contact : 6266 0555

Your Insured: GBH3381P

Accident Date: 14 Feb 2019

Location: Bukit Batok West Ave 6

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/02/2019 14:57
Date Of Accident	14/02/2019 10:00
Exact Location Of Accident	KALLANG WAY & LORONG BAKAR BATU
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBF4854X
Insured/Policyholder	
Name Of Registered Owner	NGE
Co Reg No	53225952A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91513620
Alternative Phone No	OFFICE-91513620

Vehicle Particulars

Manufacturer	NISSAN
Model	CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5086037902-02
Cover Note Number	

Driver

Name of Driver	WEE POON LIP
NRIC No	S0207952F
Date Of Birth	14/06/1953
Occupation	OUTDOOR
Date Of Driving Pass	29/05/1980
Driving Experience	38 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91513620
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 330 SERANGOON AVENUE 03 #03-367
 Postcode 550330
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident SIDE SWIPE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN:

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBH3381P
 Vehicle Make/Model/Colour TOYOTA DYNA 150 5MT
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name NTUC INCOME INSURANCE CO-OPERATIVE LTD
 Nature Of Damage
 No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name WEE POON LIP

Approximate Age

Injuries Sustain

Injured person in which vehicle?

GBF4854X

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

Address

330 SERANGOON AVENUE 03 #03-367

Postcode

550330

SKETCH PLAN



IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


14 FEB 2013

IDAC KAKI BUKIT (VAC)

Reporting Centre
Name: IDAC KAKI BUKIT
Singapore 415933
Tel: 67416697
Fax: 67492305
Email: vackbugsingnet.com.sg

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 14.02.2013 at about 10:00hrs I was travelling along Kallang Road as I was heading straight, all of a sudden a white 6BH 3381Y on my left make a sudden swerve to his right and collided with my front left side portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

14 FEB 2013
IDAC KAKI BUKIT(VAC)
23 KAKI BUKIT AVE 4
Singapore 415933
Tel: 67416677
Fax: 67492305
Email: vacb@singnet.com.sg

BP Auto
(UEN No. 53378133K)
48 Toh Guan Road Esat #01-121
Enterprise Hub S(608586)
Tel: 6266 0555 Fax : 6266 3155

TO : NTUC Income	DATE : 18-Feb-19
ATTENTION : MOTOR CLAIMS DEPARTMENT	JOB TYPE : T/P CLAIMS
ESTIMATE REPORT :	
OWNER PARTICULAR	
NAME :	VEHICLE DETAILS
ADDRESS :	VEHICLE NO. : GBF4854X
TEL. NO. :	MODEL / MAKE : NISSAN CABSTAR
OWNER INSURANCE : NTUC Income	CHASSIS NO. : JN1SC2F24Z0859028
POLICY NO. : 5086037902-02	ACCIDENT DETAIL
PERSON INCHARGE :	DATE : 14-Feb-19
	TIME : 10:00hrs

QUOTATION SUMMARY PAGE 01

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT DOOR LH <i>TORN</i>	1	\$ 1,696.50	\$ 1,696.50
2	FRONT DOOR GLASS OUTER MOULDING LH <i>ne</i>	1	\$ 136.20	\$ 136.20
3	FRONT DOOR HINGES (TOP & LOWER) <i>SCA (Lower)</i>	1pc @	\$ 61.70	\$ 61.70
3	FRONT DOOR SIGNAL LAMP LH <i>SCA</i>	1	\$ 53.40	\$ 53.40
4	FRONT DOOR CHECKER LH <i>X</i>	1	\$ 40.10	\$ 40.10
5	FRONT DOOR LOWER RUBBER SEAL LH <i>X</i>	1	\$ 35.60	\$ 35.60
6	FRONT DOOR WEATHERSTRIP LH <i>X</i>	1	\$ 151.10	\$ 151.10
7	FRONT DOOR INNER AIR VENT LH <i>CRA</i>	1	\$ 67.20	\$ 67.20
9	FRONT DOOR STEP PANEL GARNISH LH <i>CRA</i>	1	\$ 139.40	\$ 139.40
10	FRONT DOOR PILLAR PANEL 'OUTER' LH <i>repair</i>	1	\$ 1,846.40	\$ 1,846.40
11	FRONT DOOR PILLAR PANEL 'INTER' LH <i>X</i>	1	\$ 207.60	\$ 207.60
12	FRONT CORNER SIDE PANEL LH <i>PA</i>	1	\$ 389.90	\$ 389.90
13	FRONT PANEL <i>repair</i>	1	\$ 1,417.70	\$ 1,417.70
14	FRONT PANEL CABSTAR EMBLEM <i>ne</i>	1	\$ 55.10	\$ 55.10
15	FRONT PANEL RUBBER SEAL LH/RH <i>LH-ne / RH-X</i>	2	\$ 24.70	\$ 49.40
16	FRONT GRILLE <i>CRA</i>	1	\$ 678.60	\$ 678.60
17	FRONT GRILLE LOGO EMBLEM <i>ne</i>	1	\$ 55.10	\$ 55.10
18	FRONT BUMPER <i>DE</i>	1	\$ 945.10	\$ 945.10
19	FRONT BUMPER REINFORCEMENT <i>PA</i>	1	\$ 339.60	\$ 339.60
20	FRONT HEADLAMP LH <i>CRA</i>	1	\$ 473.40	\$ 473.40
21	FRONT HEADLAMP APRON GARNISH LH <i>CRA</i>	1	\$ 75.60	\$ 75.60
22	FRONT SIDE MIRROR ARM LH <i>CRA</i>	1	\$ 191.90	\$ 191.90
23	FRONT SIDE MIRROR ARM COVER LH <i>CRA</i>	1	\$ 24.10	\$ 24.10
24	FRONT SIDE MIRROR ARM COVER TOP GARNISH LH <i>ne</i>	1	\$ 113.50	\$ 113.50
25	FRONT SIDE MIRROR ARM TOP COVER LH <i>X</i>	1	\$ 24.90	\$ 24.90
26	AIR CON CONDENSOR <i>X</i>	1	\$ 692.20	\$ 692.20
27	AIR CON CONDENSOR BRACKET <i>PA</i>	1	\$ 373.90	\$ 373.90

3967.30

QUOTATION SUMMARY

PAGE 02

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
28	AIR CON CONDENSOR AIR GUIDE <i>NA</i>	1	\$ 33.60	\$ 33.60
29	AIR CON FAN COWLING WITH MOTOR ASSY <i>NA</i>	1	\$ 452.70	\$ 452.70
30	FRONT WINDSCREEN RUBBER MOULDING <i>X</i>	1	\$ 179.40	\$ 179.40

TOTAL PRICE \$ 11,062.60 \$6,381.20
 LESS -30% \$ (3,318.78) \$(1,914.36)
 SUB TOTAL PRICE \$ 7,743.82 \$4,466.84

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT DOOR SUNVISOR SET <i>NA</i>	1	\$ 280.00	\$ 80 280.00
2	FRONT DOOR COMPANY DETAIL STICKER SET <i>NA</i>	1	\$ 80.00	\$ 30 80.00
3	FRONT DOOR INNER TRIM BOARD CLIPS SET LH <i>NA</i>	1	\$ 60.00	\$ 40 60.00
4	FRONT GRILLE CLIPS SET <i>NA</i>	1	\$ 50.00	\$ 30 50.00
5	FRONT BUMPER CLIPS SET <i>NA</i>	1	\$ 50.00	\$ 30 50.00
6	FRONT HEADLAMP CLIPS LH <i>NA</i>	1	\$ 20.00	\$ 10 20.00

TOTAL \$ 540.00 \$420.00

QUOTATION SUMMARY

PAGE 03

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 1,200.00	600 700	
TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$ 1,000.00	500	
TO APPLY ANTI-RUST & TUFF KOTE	\$ 60.00	40	
TO PERFORM LIGHTING & WIRING CHECK	\$ 80.00	30	
TO DISMANTLE & REINSTALL FRONT DOOR INNER COMPONENT MECHANISM LH TO FACILITATE REPAIR WITH CHECKING	\$ 250.00	80	
TO DISMANTLE & REINSTALL FRONT WINDSCREEN PERFORM WITH WATER LEAK TEST	\$ 150.00	X	
TO DISMANTLE & REINSTALL AIR CON CONDENSOR WITH REFILL AIRCON GAS	\$ 120.00	X	
TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	\$ 280.00	60 60	
TO DISMANTLE & REPLACED FRONT DASHBOARD, EVAPORATOR UNIT, WIRE HARNESS SET, RADIO COMPONENT WITH OTHER ATTACHMENT PARTS	\$ 800.00	X	
TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	\$ 80.00	X	

TOTAL

\$ 4,020.00

\$1,410.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 8,283.82
 TOTAL LABOUR COST : \$ 4,020.00
 TOTAL REPAIR COST : \$ 12,303.82

APPROVED DETAILS

EXCESS :
 NO. OF REPAIR DAYS : 6 days
 RE-SURVEY :
 P / P OR L / S : L/S

DATE / TIME OF SURVEY : 19/02/19 @ 1245
 SURVEYED BY / FROM : PASUL (LKK)
 CONTACT NUMBER : 90010068
 FAX NUMBER :
 EMAIL ADDRESS :

Resy after repair

3024.91
 220.00
 1410.00
4654.91
 20%
 3723.92
45-3,700

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before the spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Parts	\$	6,381.20
Less 30%	\$	1,914.36
	\$	4,466.84
SN	\$	420.00
	\$	4,886.84
Labour	\$	1,410.00
	\$	6,296.84
L/s less 20%	\$	1,259.37
	\$	5,037.47

6 days

BP Auto
(UEN No. 53378133K)
48 Toh Guan Road Esat #01-121
Enterprise Hub S(608586)
Tel: 6266 0555 Fax : 6266 3155

TO	: NTUC Income	DATE	: 18-Feb-19
ATTENTION	: MOTOR CLAIMS DEPARTMENT	JOB TYPE	: T/P CLAIMS
ESTIMATE REPORT :			
<u>OWNER PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	:	VEHICLE NO.	: GBF4854X
ADDRESS	:	MODEL / MAKE	: NISSAN CABSTAR
TEL. NO.	:	CHASSIS NO.	: JN1SC2F24Z0859028
OWNER INSURANCE	: NTUC Income	<u>ACCIDENT DETAIL</u>	
POLICY NO.	: 5086037902-02	DATE	: 14-Feb-19
		TIME	: 10:00hrs
PERSON INCHARGE	:		

QUOTATION SUMMARY PAGE 01

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE	
1	FRONT DOOR LH <i>TORA /</i>	1	\$ 1,696.50	\$ 1,696.50	1396
2	FRONT DOOR GLASS OUTER MOULDING LH <i>ne /</i>	1	\$ 136.20	\$ 136.20	
3	FRONT DOOR HINGES (TOP & LOWER) <i>32 / (Lower) 1pc 2</i>	1	\$ 61.70	\$ 123.40	6510
3	FRONT DOOR SIGNAL LAMP LH <i>SCA /</i>	1	\$ 53.40	\$ 53.40	48.50
4	FRONT DOOR CHECKER LH <i>X</i>	1	\$ 40.10	\$ 40.10	X
5	FRONT DOOR LOWER RUBBER SEAL LH <i>X 2 SCA</i>	1	\$ 35.60	\$ 35.60	X
6	FRONT DOOR WEATHERSTRIP LH <i>X</i>	1	\$ 151.10	\$ 151.10	X
7	FRONT DOOR INNER AIR VENT LH <i>X CRA /</i>	1	\$ 67.20	\$ 67.20	144.50
9	FRONT DOOR STEP PANEL GARNISH LH <i>CRA /</i>	1	\$ 139.40	\$ 139.40	
10	FRONT DOOR PILLAR PANEL 'OUTER' LH <i>repar /</i>	1	\$ 1,846.40	\$ 1,846.40	X
11	FRONT DOOR PILLAR PANEL 'INTER' LH <i>X SCA</i>	1	\$ 207.60	\$ 207.60	X
12	FRONT CORNER SIDE PANEL LH <i>PA /</i>	1	\$ 389.90	\$ 389.90	
13	FRONT PANEL <i>repar /</i>	1	\$ 1,417.70	\$ 1,417.70	X
14	FRONT PANEL CABSTAR EMBLEM <i>ne /</i>	1	\$ 55.10	\$ 55.10	
15	FRONT PANEL RUBBER SEAL LH/RH <i>2 LH-ne / RH X SCA</i>	2	\$ 24.70	\$ 49.40	24.70
16	FRONT GRILLE <i>X CRA /</i>	1	\$ 678.60	\$ 678.60	438.40
17	FRONT GRILLE LOGO EMBLEM <i>ne /</i>	1	\$ 55.10	\$ 55.10	65.70
18	FRONT BUMPER <i>DE /</i>	1	\$ 945.10	\$ 945.10	
19	FRONT BUMPER REINFORCEMENT <i>PA /</i>	1	\$ 339.60	\$ 339.60	272.50
20	FRONT HEADLAMP LH <i>CRA /</i>	1	\$ 473.40	\$ 473.40	393.60
21	FRONT HEADLAMP APRON GARNISH LH <i>CRA /</i>	1	\$ 75.60	\$ 75.60	78
22	FRONT SIDE MIRROR ARM LH <i>CRA /</i>	1	\$ 191.90	\$ 191.90	
23	FRONT SIDE MIRROR ARM COVER LH <i>CRA /</i>	1	\$ 24.10	\$ 24.10	23.90
24	FRONT SIDE MIRROR ARM COVER TOP GARNISH LH <i>ne /</i>	1	\$ 113.50	\$ 113.50	111.30
25	FRONT SIDE MIRROR ARM TOP COVER LH <i>X SCA</i>	1	\$ 24.90	\$ 24.90	X
26	AIR CON CONDENSOR <i>X SCA</i>	1	\$ 692.20	\$ 692.20	X
27	AIR CON CONDENSOR BRACKET <i>PA /</i>	1	\$ 373.90	\$ 373.90	148

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
28	AIR CON CONDENSOR AIR GUIDE <i>na /</i>	1	\$ 33.60	\$ 33.60 <i>32</i>
29	AIR CON FAN COWLING WITH MOTOR ASSY <i>na / CR</i>	1	\$ 452.70	\$ 452.70 <i>650</i>
30	FRONT WINDSCREEN RUBBER MOULDING <i>X na</i>	1	\$ 179.40	\$ 179.40 <i>X</i>
TOTAL PRICE				\$ 11,062.60
LESS -30%				\$ (3,318.78)
SUB TOTAL PRICE				<u>\$ 7,743.82</u>

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT DOOR SUNVISOR SET <i>na / grille?</i>	1	\$ 280.00	\$ 280.00 <i>80</i>
2	FRONT DOOR COMPANY DETAIL STICKER SET <i>na /</i>	1	\$ 80.00	\$ 80.00 <i>30</i>
3	FRONT DOOR INNER TRIM BOARD CLIPS SET LH <i>na /</i>	1	\$ 60.00	\$ 60.00 <i>40</i>
4	FRONT GRILLE CLIPS SET <i>na /</i>	1	\$ 50.00	\$ 50.00 <i>30</i>
5	FRONT BUMPER CLIPS SET <i>na /</i>	1	\$ 50.00	\$ 50.00 <i>30</i>
6	FRONT HEADLAMP CLIPS LH <i>na /</i>	1	\$ 20.00	\$ 20.00 <i>10</i>
TOTAL				<u>\$ 540.00</u>

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 1,200.00	600 700	
TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$ 1,000.00	500	
TO APPLY ANTI-RUST & TUFF KOTE	\$ 60.00	40	
TO PERFORM LIGHTING & WIRING CHECK	\$ 80.00	30	
TO DISMANTLE & REINSTALL FRONT DOOR INNER COMPONENT MECHANISM LH TO FACILITATE REPAIR WITH CHECKING	\$ 250.00	80	
TO DISMANTLE & REINSTALL FRONT WINDSCREEN PERFORM WITH WATER LEAK TEST	\$ 150.00	X n n	
TO DISMANTLE & REINSTALL AIR CON CONDENSOR WITH REFILL AIRCON GAS	\$ 120.00	X n n	
TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	\$ 280.00	60	
TO DISMANTLE & REPLACED FRONT DASHBOARD, EVAPORATOR UNIT, WIRE HARNESS SET, RADIO COMPONENT WITH OTHER ATTACHMENT PARTS	\$ 800.00	X n n	
TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	\$ 80.00	X n n	

TOTAL \$ 4,020.00

ESTIMATE REPORT

TOTAL PARTS COST	:	\$	8,283.82
TOTAL LABOUR COST	:	\$	4,020.00
TOTAL REPAIR COST	:	\$	<u>12,303.82</u>

APPROVED DETAILS

EXCESS :
NO. OF REPAIR DAYS : 6 days
RE-SURVEY :
P / P OR L / S : 4/5


20/2/19

DATE / TIME OF SURVEY : 19/02/19 @ 12.45
SURVEYED BY / FROM : RASUL (LKK)
CONTACT NUMBER : 90010068
FAX NUMBER :
EMAIL ADDRESS :

Ready after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal modification(s) is allowed
- The agreement (if any) must be resurveyed and
- Subject to LKK assessment/insurance Company

Acknowledged by Repairer:
Signature:
Date:

BP Auto
(UEN No. 53378133K)
48 Toh Guan Road Esat #01-121
Enterprise Hub S(608586)
Tel: 6266 0555 Fax : 6266 3155

TO	: NTUC Income	DATE	: 18-Feb-19
ATTENTION	: MOTOR CLAIMS DEPARTMENT	JOB TYPE	: T/P CLAIMS
ESTIMATE REPORT	:		
OWNER PARTICULAR		VEHICLE DETAILS	
NAME	:	VEHICLE NO.	: GBF4854X
ADDRESS	:	MODEL / MAKE	: NISSAN CABSTAR
TEL. NO.	:	CHASSIS NO.	: JN15C2F24Z0859028
OWNER INSURANCE	: NTUC Income	ACCIDENT DETAIL	
POLICY NO.	: 5086037902-02	DATE	: 14-Feb-19
		TIME	: 10:00hrs
PERSON INCHARGE	:		

QUOTATION SUMMARY PAGE 01

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT DOOR LH <i>TOP</i>	1	\$ 1,396.50	\$ 1,396.50 ✓
2	FRONT DOOR GLASS OUTER MOULDING LH <i>new</i>	1	\$ 136.20	\$ 136.20 ✓
3	FRONT DOOR HINGES (TOP & LOWER) <i>new</i>	<i>1pc 2</i>	\$ 65.10	\$ 130.20 ✓
3	FRONT DOOR SIGNAL LAMP LH <i>new</i>	1	\$ 48.50	\$ 48.50 ✓
4	FRONT DOOR CHECKER LH <i>new</i>	1	\$ 40.10	\$ 40.10 X
5	FRONT DOOR LOWER RUBBER SEAL LH <i>new</i>	1	\$ 35.60	\$ 35.60 X
6	FRONT DOOR WEATHERSTRIP LH <i>new</i>	1	\$ 151.10	\$ 151.10 X
7	FRONT DOOR INNER AIR VENT LH <i>new</i>	1	\$ 144.50	\$ 144.50 ✓
9	FRONT DOOR STEP PANEL GARNISH LH <i>new</i>	1	\$ 139.40	\$ 139.40 ✓
10	FRONT DOOR PILLAR PANEL 'OUTER' LH <i>new</i>	1	\$ 1,846.40	\$ 1,846.40 X
11	FRONT DOOR PILLAR PANEL 'INTER' LH <i>new</i>	1	\$ 207.60	\$ 207.60 X
12	FRONT CORNER SIDE PANEL LH <i>new</i>	1	\$ 389.90	\$ 389.90 ✓
13	FRONT PANEL <i>repair</i>	1	\$ 1,417.70	\$ 1,417.70 X
14	FRONT PANEL CABSTAR EMBLEM <i>new</i>	1	\$ 55.10	\$ 55.10 ✓
15	FRONT PANEL RUBBER SEAL LH/RH <i>LH-new/RH-new</i>	2	\$ 24.70	\$ 49.40 ✓
16	FRONT GRILLE <i>new</i>	1	\$ 438.40	\$ 438.40 ✓
17	FRONT GRILLE LOGO EMBLEM <i>new</i>	1	\$ 65.70	\$ 65.70 ✓
18	FRONT BUMPER <i>new</i>	1	\$ 945.10	\$ 945.10 ✓
19	FRONT BUMPER REINFORCEMENT <i>new</i>	1	\$ 272.50	\$ 272.50 ✓
20	FRONT HEADLAMP LH <i>new</i>	1	\$ 393.60	\$ 393.60 ✓
21	FRONT HEADLAMP APRON GARNISH LH <i>new</i>	1	\$ 78.00	\$ 78.00 ✓
22	FRONT SIDE MIRROR ARM LH <i>new</i>	1	\$ 191.90	\$ 191.90 ✓
23	FRONT SIDE MIRROR ARM COVER LH <i>new</i>	1	\$ 29.90	\$ 29.90 ✓
24	FRONT SIDE MIRROR ARM COVER TOP GARNISH LH <i>new</i>	1	\$ 111.30	\$ 111.30 ✓
25	FRONT SIDE MIRROR ARM TOP COVER LH <i>new</i>	1	\$ 24.90	\$ 24.90 X
26	AIR CON CONDENSOR <i>new</i>	1	\$ 692.20	\$ 692.20 X
27	AIR CON CONDENSOR BRACKET <i>new</i>	1	\$ 148.00	\$ 148.00 ✓

QUOTATION SUMMARY

PAGE 02

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
28	AIR CON CONDENSOR AIR GUIDE <i>re /</i>	1	\$ 32.00	\$ 32.00 ✓
29	AIR CON FAN COWLING WITH MOTOR ASSY <i>re /</i>	1	\$ 650.00	\$ 650.00 ✓
30	FRONT WINDSCREEN RUBBER MOULDING <i>re /</i>	1	\$ 179.40	\$ 179.40 X
		TOTAL PRICE		\$ 10,441.10
		LESS -10%		\$ (1,044.11)
		SUB TOTAL PRICE		<u>\$ 9,396.99</u>

5756.30
10%
5180.67

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT DOOR SUNVISOR SET <i>re /</i>	1	\$ 280.00	\$ 280.00 80
2	FRONT DOOR COMPANY DETAIL STICKER SET <i>re /</i>	1	\$ 80.00	\$ 80.00 30
3	FRONT DOOR INNER TRIM BOARD CLIPS SET LH <i>re /</i>	1	\$ 60.00	\$ 60.00 40
4	FRONT GRILLE CLIPS SET <i>re /</i>	1	\$ 50.00	\$ 50.00 30
5	FRONT BUMPER CLIPS SET <i>re /</i>	1	\$ 50.00	\$ 50.00 30
6	FRONT HEADLAMP CLIPS LH <i>re /</i>	1	\$ 20.00	\$ 20.00 10

TOTAL \$ 540.00 220

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 1,200.00	700	
TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$ 1,000.00	500	
TO APPLY ANTI-RUST & TUFF KOTE	\$ 60.00	40	
TO PERFORM LIGHTING & WIRING CHECK	\$ 80.00	30	
TO DISMANTLE & REINSTALL FRONT DOOR INNER COMPONENT MECHANISM LH TO FACILITATE REPAIR WITH CHECKING	\$ 250.00	80	
TO DISMANTLE & REINSTALL FRONT WINDSCREEN PERFORM WITH WATER LEAK TEST	\$ 150.00	X <i>na</i>	
TO DISMANTLE & REINSTALL AIR CON CONDENSOR WITH REFILL AIRCON GAS	\$ 120.00	X <i>na</i>	
TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	\$ 280.00	60	
TO DISMANTLE & REPLACED FRONT DASHBOARD, EVAPORATOR UNIT, WIRE HARNESS SET, RADIO COMPONENT WITH OTHER ATTACHMENT PARTS	\$ 800.00	X <i>na</i>	
TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	\$ 80.00	X <i>na</i>	

TOTAL \$ 4,020.00 1,410.00

ESTIMATE REPORT

TOTAL PARTS COST	:	\$	9,936.99
TOTAL LABOUR COST	:	\$	4,020.00
TOTAL REPAIR COST	:	\$	<u>13,956.99</u>

APPROVED DETAILS

EXCESS :
NO. OF REPAIR DAYS :
RE-SURVEY :
P / P OR L / S :

5180.67

220.00

1410.00

6810.67

20%

5448.53

415-5,450

DATE / TIME OF SURVEY :
SURVEYED BY / FROM :
CONTACT NUMBER :
FAX NUMBER :
EMAIL ADDRESS :

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19003148/R1sd3n2

73 BRAS BASAH ROAD

Date: 15-08-2019

#05-01 NTUC TRADE UNION HOUSESINGAPORE

189556



ATTN: JARED LIU

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBH 3381P	Veh. Inspected	GBF 4854X
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1032127-002	Excess (\$)	0.00
Assign From	CYNTHIA ANG	Assign Date	19/02/2019

2. Vehicle Particulars & Condition

Make & Model	NISSAN CABSTAR 3.0 5M	c.c	2953
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JN1SC2F24Z0859028	Colour	GREY
Odometer	93478 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175/80 R15	YOKOHAMA	7 mm
L/H Front Tyre	175/80 R15	YOKOHAMA	7 mm
R/H Rear Tyre	155 R13	YOKOHAMA	5 mm
L/H Rear Tyre	155 R13	YOKOHAMA	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	14/02/2019	Inspect Date / Time	19/02/2019 (11:56 AM)
Survey held at	BP AUTO 48 TOH GUAN ROAD EAST #01-121 ENTERPRISE HUB SINGAPORE 608586		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 4854X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT DOOR LH	TORN	1,396.50	1,396.50
1	FRONT DOOR GLASS OUTER MOULDING LH	NECESSARY	136.20	136.20
2	FRONT DOOR HINGES (TOP & LOWER) @\$65.10	SCRATCHED (1 PC ONLY)	130.20	65.10
1	FRONT DOOR SIGNAL LAMP LH	SCRATCHED	48.50	48.50
1	FRONT DOOR CHECKER LH	SERVICEABLE	40.10	-
1	FRONT DOOR LOWER RUBBER SEAL LH	SERVICEABLE	35.60	-
1	FRONT DOOR WEATHERSTRIP LH	SERVICEABLE	151.10	-
1	FRONT DOOR INNER AIR VENT LH	CRACKED	144.50	144.50
1	FRONT DOOR STEP PANEL GARNISH LH	CRACKED	139.40	139.40
1	FRONT DOOR PILLAR PANEL "OUTER" LH	SERVICEABLE	1,846.40	-
1	FRONT DOOR PILLAR PANEL "INNER" LH	SERVICEABLE	207.60	-
1	FRONT CORNER SIDE PANEL LH	BENT	389.90	389.90
1	FRONT PANEL	TO REPAIR SEE LABOUR	1,417.70	-
1	FRONT PANEL CABSTAR EMBLEM	NECESSARY	55.10	55.10
2	FRONT PANEL RUBBER SEAL LH/RH @\$24.70	N/S NECESSARY / O/S SERVICEABLE	49.40	24.70
1	FRONT GRILLE	CRACKED	438.40	438.40
1	FRONT GRILLE LOGO EMBLEM	NECESSARY	65.70	65.70
1	FRONT BUMPER	DEFORMED	945.10	945.10
1	FRONT BUMPER REINFORCEMENT	BENT	272.50	272.50
1	FRONT HEADLAMP LH	CRACKED	393.60	393.60
1	FRONT HEADLAMP APRON GARNISH LH	CRACKED	78.00	78.00
1	FRONT SIDE MIRROR ARM LH	CRACKED	191.90	191.90
1	FRONT SIDE MIRROR ARM COVER LH	CRACKED	29.90	29.90
1	FRONT SIDE MIRROR ARM COVER TOP GARNISH LH	MISSING	111.30	111.30
1	FRONT SIDE MIRROR ARM TOP COVER LH	SERVICEABLE	24.90	-
1	AIR CON CONDENSOR	SERVICEABLE	692.20	-
1	AIR CON CONDENSOR BRACKET	BENT	148.00	148.00
1	AIR CON CONDENSOR AIR GUIDE	NECESSARY	32.00	32.00
1	AIR CON FAN COWLING WITH MOTOR ASSY	CRACKED	650.00	650.00

Report Ref No. CS/INC19003148/R1sd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT WINDSCREEN RUBBER MOULDING	NOT NECESSARY	179.40	-
	LESS 10% DISCOUNT		-1,044.11	-575.63
			9,396.99	5,180.67
	SPECIAL NETT ITEMS			
1	SET FRONT DOOR SUNVISOR (SN)	NECESSARY	280.00	80.00
1	SET FRONT DOOR COMPANY DETAIL STICKER (SN)	NECESSARY	80.00	30.00
1	FRONT DOOR INNER TRIM BOARD CLIPS SET LH (SN)	NECESSARY	60.00	40.00
1	SET FRONT GRILLE CLIPS (SN)	NECESSARY	50.00	30.00
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	FRONT HEADLAMP CLIPS LH (SN)	NECESSARY	20.00	10.00
			540.00	220.00
	LABOUR			
	TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE AFFECTED PORTION.INCLUSIVE OF THE REPAIR OF FRONT PANEL.		1,200.00	700.00
	TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA.		1,000.00	500.00
	TO APPLY ANTI-RUST & TUFF KOTE.		60.00	40.00
	TO PERFORM LIGHTING & WIRING CHECK.		80.00	30.00
	TO DISMANTLE & REINSTALL FRONT DOOR INNER COMPONENT MECHANISM LH TO FACILITATE REPAIR WITH CHECKING.		250.00	80.00
	TO DISMANTLE & REINSTALL FRONT WINDSCREEN PERFORM WITH WATER LEAK TEST.	NOT NECESSARY	150.00	-
	TO DISMANTLE & REINSTALL AIR CON CONDENSOR WITH REFILL AIRCON GAS.	NOT NECESSARY	120.00	-
	TO DISMANTLE & REINSTALL INTERIOR CARAPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR.		280.00	60.00
	TO DISMANTLE & REPLACED FRONT DASHBOARD,EVAPORATOR UNIT,WIRE HARNESS SET,RADIO COMPONENT WITH OTHER ATTACHMENT PARTS.	NOT NECESSARY	800.00	-
	TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION.	NOT NECESSARY	80.00	-
			4,020.00	1,410.00

Report Ref No. CS/INC19003148/R1sd3n2



GRAND TOTAL		13,956.99	6,810.67
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			5,450.00

Report Ref No. CS/INC19003148/R1sd3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.