

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5952D**AAD1902-125***Not Authored
1/2 up @ 4400h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 5952D

VF1ABL15AUC281590

RENAULT

LATITUDE

17.2.2019

AIG

8/5/2015

PART**LIST**

1	DOOR PANEL FRT LH	\$	<i>N</i>	2,844.66	} X
1	DOOR HINGE UPPER LH	\$	<i>N</i>	261.28	
1	DOOR HINGE LOWER LH	\$	<i>N</i>	300.55	
1	DOOR CHECK FRT LH	\$	<i>SL</i>	194.77	
1	DOOR LOCK FRT LH	\$	<i>N</i>	908.75	
1	DOOR CATCH FRT LH	\$	<i>N</i>	131.23	
1	DOOR HANDLE OUTER FRT LH	\$	<i>SL</i>	477.76	
1	DOOR HANDLE COVER FRT LH	\$	<i>SL</i>	13.22	
1	DOOR HANDLE MODULE FRT LH	\$	<i>SL</i>	133.60	
1	DOOR REGULATOR FRT LH	\$	<i>N</i>	505.19	
1	DOOR REGULATOR MOTOR FRT LH	\$	<i>N</i>	796.46	} X
1	DOOR REGULATOR GUIDE FRT LH	\$	<i>SL</i>	120.97	
1	DOOR PANEL REAR LH	\$	<i>BT/way</i>	2,844.66	
1	DOOR GUIDE REAR LH	\$	<i>SL</i>	176.82	
1	DOOR HINGE UPPER LH	\$	<i>N</i>	274.50	
1	DOOR HINGE LOWER LH	\$	<i>N</i>	300.55	
1	DOOR CHECK REAR LH	\$	<i>SL</i>	203.06	
1	DOOR LOCK REAR LH	\$	<i>N</i>	908.75	
1	DOOR HANDLE OUTER REAR LH	\$	<i>SL</i>	126.49	
1	DOOR HANDLE CAP REAR LH	\$	<i>SL</i>	35.52	
1	DOOR HANDLE SEAL REAR LH	\$	<i>SL</i>	7.89	} X
1	DOOR HANDLE COVER REAR LH	\$	<i>SL</i>	13.22	
1	DOOR HANDLE MODULE REAR LH	\$	<i>SL</i>	133.60	
1	DOOR REGULATOR REAR LH	\$	<i>N</i>	1,135.10	
1	DOOR REGULATOR MOTOR REAR LH	\$	<i>SL</i>	893.75	
1	DOOR REGULATOR NUT REAR LH	\$	<i>SL</i>	12.43	
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	<i>SL</i>	6.31	
1	DOOR FINISHER REAR LH	\$	<i>SL</i>	423.10	
1	DOOR MOULDING REAR LH	\$	<i>SL</i>	176.82	

Trans-cab Auto Services Pte Ltd

AAD1902-125

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5952D

1	DOOR MOULDING CLIP L70Y	\$	na	5.92	}
1	DOOR MOULDING SCREW L70Y	\$	na	6.91	
1	DOOR CASING REAR LH	\$	sh	1,509.06	
1	DOOR WATER SHIELD REAR LH	\$	sh	30.39	
1	DOOR CASING CLIP	\$	na	12.63	
1	DOOR CASING LIGHT L70Y	\$	sh	48.74	
1	DOOR FINISHER INNER REAR LH	\$	sh	323.44	
1	DOOR FINISHER BRACKET INNER REAR LH	\$	n	46.97	
1	DOOR FINISHER BRACKET INNER REAR LH	\$	n	20.33	
1	DOOR FINISHER BRACKET INNER REAR LH	\$	n	20.33	
1	DOOR FINISHER BRACKET INNER REAR LH	\$	n	20.33	
1	DOOR GRAB HANDLE REAR LH	\$	sh	210.96	
1	DOOR BLIND REAR LH	\$	sh	741.80	
1	DOOR WHEATHESTRIIP REAR LH	\$	sh	410.66	
1	DOOR SEAL REAR LH	\$	sh	162.02	
1	DOOR GLASS RUNNER SEAL REAR LH	\$	sh	229.31	}
1	DOOR WAIST SEAL OUTER REAR LH	\$	sh	334.69	
1	DOOR WAIST SEAL INNER REAR LH	\$	sh	115.64	
1	DOOR MIRROR ASSY LH	\$	cm	1,483.40	
1	ROCKER PANEL INNER GARNISH LH	\$	sh	466.51	
1	ROCKER PANEL INNER LH	\$	n	1,024.79	
1	ROCKER PANEL CENTER LH	\$	n	990.25	
1	FENDER PANEL REAR LH	\$	n	3,299.13	
1	FENDER PANEL INNER TRIM REAR	\$	sh	671.45	
1	WHEELARCH REAR LH	\$	sh	543.47	

	\$	27,090.14
10%	\$	2,709.01
	\$	24,381.13

Special Nett

1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00	X
2	FRAME FULL SUPPORT PANEL NUT	\$	na	20.00	X
2	FRAME FULL SUPPORT PANEL STUD	\$	na	30.00	X
1SET	WHEELARCH CLIP FRT LH	\$	na	30.50	X
1	FRONT DOOR STICKER 'Trans-cab'	\$	na	80.00	60sm
1	FRONT DOOR STICKER 'Chassis'	\$	na	50.00	15sm
1	REAR DOOR STICKER '6555 3333'	\$	na	80.00	60sm

Trans-cab Auto Services Pte Ltd**AAD1902-125**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5952D

1	DOOR CHECK BOLT	\$	SH 22.69	}	X
1	DOOR GUIDE SCREW	\$	SH 10.85		
1	DOOR HINGE BOLT	\$	SH 10.85		
1	DOOR HINGE NUT RH	\$	SH 14.60		
1	DOOR CHECK BOLT	\$	SH 22.69		
1	DOOR CHECK NUT	\$	SH 3.75		
1	DOOR LOCK SCREW L70Y	\$	SH 6.12		
1	DOOR CATCH SCREW L70Y	\$	SH 10.06		
1	LEFT REAR RIM	\$	SH 380.00	}	
1	LEFT REAR TYRE	\$	SH 330.00		
TOTAL		\$	1,172.13		

TOTAL PARTS \$ 25,553.26**LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,200.00	500
Putty and spray painting of the affected portion.	\$	4,200.00	800
To rust-proofing of the affected areas.	\$	170.00	30
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	SH 380.00	X
To check steering geometry and computer wheel alignment	\$	SH 220.00	X
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	SH 380.00	X
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	SH 380.00	X
To transfer of tire, rim and on wheel balancing.	\$	SH 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	20

Trans-cab Auto Services Pte Ltd

AAD1902-125

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5952D

To transfer of front fender fittings, attachment and
perform water seepage test.

\$ *nn* 380.00 *X*

To transfer of front door fittings, attachment and
perform water seepage test.

\$ *nn* 380.00 *X*

To transfer of Rear door fittings, attachment and
perform water seepage test.

\$ 380.00 *601*

TOTAL	\$	11,410.00
--------------	-----------	------------------

Over All Total	\$	36,963.26
-----------------------	-----------	------------------

LUMP SUM (REPAIR DAY)**20 DAYS***3 day*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: