

AUTO WHEELS

MOTORWORKS PTE LTD

48 TOH GUAN ROAD EAST ENTERPRISE

#04-142 SINGAPORE 608586

ATTN: LONPAC INSURANCE

DATE: 2/19/2019

VEHICLE NO: SMF4320P

MODEL: MERCEDES E200

ACCIDENT DATE: 2/14/2019

CLAIM ADVISOR: LOUIS (91928963)

EMAIL: louisongautowheels@yahoo.com

ESTIMATION

DESCRIPTION	QTY	LIST PRICE
PARTS		
RH HEADLAMP	1	\$1,971.20 <i>arb</i>
RH HEADLAMP LOWER BRACKET	1	\$249.60 <i>?</i>
FRONT BUMPER	1	\$1,654.20 <i>de</i>
RH FRONT BUMPER RETAINER	1	\$113.10 <i>?</i>
RH FRONT BUMPER INNER PAD	1	\$278.40 <i>x</i>
RH FRONT BUMPER BRACKET	1	\$255.60 <i>?</i>
RH FRONT BUMPER CHROME MOULDING	1	\$355.40 <i>x</i>
RH FRONT BUMPER GRILLE	1	\$295.40 <i>x</i>
RH FOG LAMP CHROME RING	2	\$430.40 <i>x</i>
TOWING COVER	1	\$188.40 <i>x</i>
FRONT BUMPER SPONGE	2	\$214.60 <i>x</i>
FRONT REINFORCEMENT	1	\$546.20 <i>x</i>
FRONT SENSOR	2	\$522.80 <i>?</i>
FRONT SENSOR HOLDER	2	\$110.60 <i>net</i>
RH FRONT FENDER	1	RESTORE

TOTAL: \$7,185.90

DISCOUNT 10%: \$718.59

\$6,467.31

LABOUR

PRICE

LABOUR FOR FACILITATE REPAIR - FRONT PORTION

\$1,000.00 *250*

TO RESPRAY AFFECTED AREAS - FRONT BUMPER

\$300.00 *220*

AUTO WHEELS

MOTORWORKS PTE LTD

48 TOH GUAN ROAD EAST ENTERPRISE

#04-142 SINGAPORE 608586

ATTN: LONPAC INSURANCE

DATE: 2/19/2019
VEHICLE NO: SMF4320P
MODEL: MERCEDES E200
ACCIDENT DATE: 2/14/2019
CLAIM ADVISOR: LOUIS (91928963)
EMAIL: louisongautowheels@yahoo.com

ESTIMATION

TO RESPRAY AFFECTED AREAS - RH FRONT FENDER
TO CHECK AND RECONNECT ALL NECESSARY WIRING
TO REMOVE AND REFIT FRONT SENSOR
SUNDARIES
RUST PROOFING

\$300.00 X
\$50.00 30.
\$100.00 30.
\$80.00 20.
\$100.00 X

TOTAL: \$1,930.00

TOTAL: \$8,397.31
7% GST: \$587.81
\$8,985.12

Tanphie 97495749
'wp' lumps
Resin after repair
su@lkkauto.com

2-3 days
26/2/19 @ 1240.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: