

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 8014Y

DATE 19/2/2019 9:43

MAKE :

MODEL : MERCEDES BENZ

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <i>Rehul</i>			\$ 1,510.00
	Rear Bumper Reinforcement <i>Xm</i>			\$ 1,150.00
	Rear Bumper Bracket Lower (LH/RH) <i>is in</i>		\$ 135.00	\$ 270.00
	Rear Bumper Bracket Top (LH/RH) <i>Xm</i>		\$ 125.00	\$ 250.00
	Rear Bumper Retainer Mounting (LH/RH) <i>Xm</i>		\$ 115.00	\$ 230.00
	Rear Bumper Lower Cover <i>cut</i>			\$ 325.00
	<i>Per part lid X repair</i>			
	SUB TOTAL			\$ 3,735.00
	LESS 20%			\$ 747.00
	DISCOUNTED TOTAL			\$ 2,988.00
	Rear Bumper Sensor <i>shul</i>			\$ 388.00 Nett
	Labour Charge			
	Panel Beating			\$ 200 \$ 400.00
	Spray Painting Charge			\$ 500 \$ 400
	Wiring Charge			\$ 30.00 Xm
	Remove/Refix Reverse Sensor			\$ 120.00 20
	TOTAL LABOUR			\$ 850.00
	ESTIMATE TOTAL			\$ 4,226.00
	<i>Ka hui 16/1/19</i>			
	<i>19/2/19 1125L</i>			
	<i>2 Dgs</i>			
	<i>4s</i>			
	<i>After Repair photo</i>			
<div> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Work Order" basis No illegal modification Supplies are subject to inspection </div>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				