

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 777R**AAD1902-123***Not Autharish**Re survey B4 paint**@300h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHF 777R

VF1ABL15AUC283281

RENAULT

LATITUDE

16.2.2019

AIG

30/6/2016

PART**LIST**

1	1 BUMPER COVER REAR	\$	<i>n</i>	1,108.46	}	<i>X</i>
2	1 BUMPER LOWER REAR	\$	<i>sn</i>	768.84		
3	1 BUMPER BRACKET CTR REAR	\$	<i>sn</i>	113.47		
4	1 BUMPR BRACKET SIDE RH REAR	\$	<i>sn</i>	135.97		
5	1 BUMPR RETAINER RH REAR	\$	<i>sn</i>	44.99		
6	1 BUMPER REFLECTOR RH	\$	<i>sn</i>	43.61		
7	1 BUMPR BRACKET SIDE LH REAR	\$	<i>sn</i>	135.97		
8	1 BUMPER RETAINER LH REAR	\$	<i>sn</i>	44.99		
9	1 BUMPER REFLECTOR LH	\$	<i>sn</i>	43.61		
10	1 BUMPER BEAM REAR	\$	<i>n</i>	777.52		
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>n</i>	225.95		
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>n</i>	225.95		
13	1 OUTER PANEL REAR (End Panel)	\$	<i>n</i>	1,471.77		
14	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>sn</i>	404.56		
15	1 BOOT REAR	\$	<i>n</i>	2,872.68		
16	1 TAILLAMP RH	\$	<i>sn</i>	552.55		
17	1 TAILLAMP PANEL RH	\$	<i>n</i>	986.70		
18	1 TAILLAMP LH	\$	<i>sn</i>	552.55		
19	1 TAILLAMP PANEL LH	\$	<i>n</i>	986.70		

\$ 11,496.85**10% \$ 1,149.69****\$ 10,347.17****Special Nett**

1	1SET PARKING AID	\$	<i>sn</i>	700.00	<i>X</i>
2	1SET REAR BUMPER CLIP	\$	<i>sn</i>	66.00	<i>X</i>
3	1SET BUMPER BRACKET CTR CLIP	\$	<i>sn</i>	33.00	<i>X</i>

Trans-cab Auto Services Pte Ltd**AAD1902-123**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 777R

4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	<i>na</i>	10.00	} X
5	1SET BUMPER RETAINER RH CLIP RR	\$	<i>na</i>	20.00	
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	<i>na</i>	10.00	
7	1SET BUMPER RETAINER CLIP LH RR	\$	<i>na</i>	20.00	
8	1SET BUMPER LOWER REAR RIVET	\$	<i>na</i>	22.00	
9	1SET BUMPER LOWER REAR CLIP	\$	<i>na</i>	66.00	
10	1 EXHAUST MOUNTING REAR	\$	<i>na</i>	17.82	
11	2 REAR WINDSCREEN SELANT	\$	<i>na</i>	80.00	
12	1 WINDSCREEN MOULDING	\$	<i>na</i>	100.00	
13	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i>	100.00	
14	1 REAR BOOT STICKER 'Trans-cab'	\$	<i>na</i>	80.00	
15	1 REAR BOOT STICKER '6555-3333'	\$	<i>na</i>	80.00	
TOTAL		\$		605.82	
TOTAL PARTS		\$		10,952.99	

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	<i>2201</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	<i>801</i>
To Rust-Proofing Of The Affected Areas.	\$	<i>na</i> 170.00	X
To reinstall rear bumper parking sensor.	\$	<i>na</i> 170.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>na</i> 170.00	X
To repair and realign rear exhaust pipe.	\$	<i>na</i> 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>na</i> 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>na</i> 170.00	X

Trans-cab Auto Services Pte Ltd**AAD1902-123**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 777R

To transfer of rear windscreen fittings and conduct
water seepage test.

\$ *nn* 170.00 X

To check steering geometry and computer wheel
alignment

\$ *nn* 220.00 X**TOTAL \$ 7,410.00****Over All Total \$ 28,710.15****(PART-BY-PART)****Repair Days****~~10 DAYS~~***1 day*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: