

INSURANCE

INS. CASE OWNER:

CC 6 / AIG1900 2168, 128239

LKK:
IDAC:

Surveyor:

Kasm

DOI:

ASSIGNMENT

21/2/14

Date / Time:

20/2/14

Registered in Merimen:

20/2/14

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLR 3392M

Name of Insured:

BOH LAY KENG

Insured Tel No.:

HP:

27/1/14

Excess Sec II : \$

D.O.A:

Claim No.:

086870908654

Policy No.:

180046524

Make / Model:

Subaru

Place of Accident:

7-mn b/w JAW TUBA

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

GBE 8710



INSRS:

WSP:

Tel:

Liability:

RMKS:

Rong Sheng



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

GBE 8710 21/2/14

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

20/11-4-19

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

X

After call ltr to OI:

X

Authorisation To Act:

X

Release Voucher:

X

Final Repair Bill:

X

Car Rental Invoice:

X

Towing Invoice:

X

LTA / GIA:

X

Medical Bill:

X

PIR:

X

Mandate/Reject Instruction:

X

LOD

X

Payment Breakdown Form:

X

Post-Repair Photos:

X

Others:

X

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

27

If NO or B 28. Ass. Lia:

Repair Cost:

\$

2,400 x 2

Loss of Rental (LOR):

\$

(days)

Loss of Use (LOU):

\$

320 (S 80 x 4 days)

Loss of Income (LOI):

\$

- (S x days)

LOR only

LOU only

LOR + LOU

LOR + LO

(Tick only one)

GIA/LTA Search

\$

7.45

Medical:

\$

-

Disbursement:

\$

-

(e.g. Tow/ Independent)

Legal Cost

\$

-

Total:

\$

2,727.45

Global Sum \$:

2,700 x 2

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$

2,700 x 2

Name 1:

RONG SHENG AUTO ENGINEERING (MADRID)

Payee 2: (Strike if N.A.)

\$

-

Name 2:

X

Payee 3: (Strike if N.A.)

\$

-

Name 3:

X

RONG SHENG AUTO ENGINEERING TRADING

NO 42 TOH GUAN ROAD EAST

01-79 ENTERPRISE HUB

SINGAPORE 608583

TEL : 8239 0099

REG NO : 53181821K

QUOTATION/ESTIMATE

VEHICLE NO : GBE871C

RE: REPAIR VEHICLE ON TOYOTA DYNA

DATE : 18/02/2019

TO : AIG ASIA PACIFIC INSURANCE PTE LTD

REFER NO : RSA/2019/02/0008

PARTS DESCRIPTION	QTY	UNTIL PRICE	AMOUNT
-------------------	-----	-------------	--------

LIST ITEMS

1	LH REAR TAILLAMP	X ^{new}	1	\$352.60	\$352.60
2	LH REAR TAILLAMP PANEL	X ^{new}	1	\$156.70	\$156.70
3	RH REAR TAILLAMP	CR1	1	\$352.60	\$352.60
4	RH REAR TAILLAMP PANEL	PA	1	\$156.70	\$156.70
5	REAR NUMBER PLATE BRACKET	PA	1	\$181.65	\$181.65
6	REAR NUMBER PLATE LAMP	X ^{new}	2	\$38.40	\$76.80
7	REAR SPARE TYRE BRACKET	X ^{new}	1	\$236.95	\$236.95
8	REAR TAILGATE HING LH	X ^{new}	1	\$143.60	\$143.60
9	REAR TAILGATE HING RH	RELOCKER PA	1	\$143.60	\$143.60
10	REAR TAILGATE RUBBER STOPPER LH	X ^{new}	1	\$38.90	\$38.90
11	REAR TAILGATE RUBBER STOPPER RH	SC	1	\$38.90	\$38.90
12	REAR EXHUAUST MUFFLER	PA	1	\$589.20	\$589.20

TOTAL :	\$2,429.80	\$2,468.20
---------	------------	------------

LESS 25 % :	\$607.45	\$617.05
-------------	----------	----------

TOTAL PARTS :	\$1,822.35	\$1,851.15
---------------	------------	------------

S/NETT ITEMS

13	REAR NUMBER PLATE	PA	1	\$45.00	\$45.00 ³⁵
14	REAR REVERSE SENSOR	new	1	\$250.00	\$250.00 ²⁰⁰
15	RAER TAILGATE COMPANY STICKER	new	1	\$120.00	\$120.00
16	EMBLEM DYNA STICKER		1	\$58.00	\$58.00
17	8 PAX STICKER		1	\$20.00	\$20.00
18	70KM/H STICKER		1	\$20.00	\$20.00

TOTAL :	\$513.00	\$513.00
---------	----------	----------

TOTAL SPARE PARTS :	\$2,335.35	\$2,364.15
---------------------	------------	------------

supplementary

1) Rear tailgate - \$250.00

VEHICLE NO : GBE871C

LABOUR DESCRIPTION

AMOUNT

- 1 LABOUR FOR PANEL BEATING
- 2 LABOUR FOR SPRAYPAINTING
- 3 TO RUST PROOF ON REAR ACCIDENT AREAS
- 4 WIRING CHECK
- 5 TO REPAIR AND STRAIGHTEN REAR EXHUAUST PIPE

~~\$800.00~~ 500
~~\$500.00~~ 300
~~\$120.00~~ 60
~~\$80.00~~ 30
~~\$250.00~~ 120

TOTAL LABOUR :

\$1,750.00

TOTAL PARTS AND LABOUR :

\$4,114.15


① Parts = \$1699.60

② less 25% = \$424.90

③ Total = \$1274.70

④ S/A/ett = \$703.00

⑤ Total Parts = \$1977.70

⑥ Labour = \$1010.00

⑦ Total = \$2987.70

⑧ L/sun = \$2597.54
20%

⑨ Total = \$2390.16

20% 2450.00




Hy 90010068

4 days

2/5

21/02/19 @ 1120

Resy after repair

RONG SHENG AUTO ENGINEERING TRADING

NO 42 TOH GUAN ROAD EAST

01-79 ENTERPRISE HUB

SINGAPORE 608583

TEL : 8239 0099

REG NO : 53181821K

QUOTATION/ESTIMATE

VEHICLE NO : GBE871C

RE: REPAIR VEHICLE ON TOYOTA DYNA

DATE : 21/02/2019

TO : AIG ASIA PACIFIC INSURANCE PTE LTD

REFER NO : RSA/2019/02/0008

PARTS DESCRIPTION

QTY UNTIL PRICE AMOUNT

SUPPLEMENTARY ITEMS

S/NETT ITEMS

1 REAR TAILGATE

1 \$250.00 \$250.00



TOTAL :

\$250.00 \$250.00

TOTAL SPARE PARTS :

\$250.00 \$250.00

RONG SHENG AUTO ENGINEERING TRADING

NO 42 TOH GUAN ROAD EAST

01-79 ENTERPRISE HUB

SINGAPORE 608583

TEL : 8239 0099

REG NO : 53181821K

QUOTATION/ESTIMATE

VEHICLE NO : GBE871C

RE: REPAIR VEHICLE ON TOYOTA DYNA

DATE : 18/02/2019

TO : AIG ASIA PACIFIC INSURANCE PTE LTD

REFER NO : RSA/2019/02/0008

PARTS DESCRIPTION

QTY

UNTIL PRICE

AMOUNT

LIST ITEMS

1	LH REAR TAILLAMP X	1	\$352.60	\$352.60
2	LH REAR TAILLAMP PANEL X	1	\$156.70	\$156.70
3	RH REAR TAILLAMP CRA	1	\$352.60	\$352.60
4	RH REAR TAILLAMP PANEL RA	1	\$156.70	\$156.70
5	REAR NUMBER PLATE BRACKET PA	1	\$181.65	\$181.65
6	REAR NUMBER PLATE LAMP X	2	\$38.40	\$76.80
7	REAR SPARE TYRE BRACKET	1	\$236.95	\$236.95
8	REAR TAILGATE HING LH X	1	\$143.60	\$143.60
9	REAR TAILGATE HING RH (LOCK) RA	1	\$143.60	\$143.60
10	REAR TAILGATE RUBBER STOPPER LH X	1	\$38.90	\$38.90
11	REAR TAILGATE RUBBER STOPPER RH SC	1	\$38.90	\$38.90
12	REAR EXHUAUST MUFFLER PA	1	\$589.20	\$589.20

TOTAL :	\$2,429.80	\$2,468.20
LESS 25 % :	\$607.45	\$617.05
TOTAL PARTS :	\$1,822.35	\$1,851.15

S/NETT ITEMS

13	REAR NUMBER PLATE PA	1	\$45.00	\$45.00 35
14	REAR REVERSE SENSOR RA	1	\$250.00	\$250.00 200
15	RAER TAILGATE COMPANY STICKER RA	1	\$120.00	\$120.00
16	EMBLEM DYNA STICKER	1	\$58.00	\$58.00
17	8 PAX STICKER	1	\$20.00	\$20.00
18	70KM/H STICKER	1	\$20.00	\$20.00

TOTAL :	\$513.00	\$513.00
---------	----------	----------

TOTAL SPARE PARTS :	\$2,335.35	\$2,364.15
---------------------	------------	------------

VEHICLE NO : GBE871C

LABOUR DESCRIPTION	AMOUNT
1 LABOUR FOR PANEL BEATING	\$800.00 500
2 LABOUR FOR SPRAYPAINTING	\$500.00 300
3 TO RUST PROOF ON REAR ACCIDENT AREAS	\$120.00 60
4 WIRING CHECK	\$80.00 30
5 TO REPAIR AND STRAIGHTEN REAR EXHAUST PIPE	\$250.00 120
TOTAL LABOUR :	<u>\$1,750.00</u>


TOTAL PARTS AND LABOUR : \$4,114.15


Same
Hy 90010068

4 days

2/5

21/02/19 @ 1120

Resy after repair

The Auto Consultants hence notify
 the repairs of the following:
 • To ensure safety  spray painting
 • To ensure operation of parts during handling
 • Parts must be replaced as recommended
 • That parts supplied are of "Warranted Protection" quality
 • To ensure recommended standards
 • Supplied parts are of the highest quality and
 is subject to the manufacturer's warranty.

Acknowledged by Customer:

Signature:

Date:

Nivitha (LKK Auto)

From: Eric Kee <rsauto_eng@yahoo.com.sg>
Sent: Monday, 18 February 2019 1:53 PM
To: Assignments
Subject: Direct TP (Direct settlement)GBE871C against SLZ3392U
Attachments: GBE871C ESTIMATE 02182019.pdf; GBE871C GIA REPORT02182019.pdf

Hi Celine

Kindly arrange to survey for the mentioned vehicle below :

- 1) Our customer vehicle No : GBE871C
- 2) Your Insured vehicle No :SLZ3392U
- 3)Accident date : 27/01/2019
- 4) workshop at : Rong Sheng Auto Engineering Trading
No 42 Toh Guan Road East #01-79
Enterprise Hub
Singapore 608583
- 5) Vehicle NOT in workshop (Kindly arrange the survey on 20/02/2019 after 10am)
- 6)Contact person : Eric Kee 8239 0099

We would like to do direct TP claim (direct settlement) for this case

Please see attach file for GIA report and our estimate

Kindly let us know the officer in charge of this case and the liability

Thank you

Regards
Eric kee

A/G

RONG SHENG AUTO ENGINEERING TRADING

(Reg No : 53181821K)

No 42 TOH GUAN ROAD EAST #01-79

ENTERPRISE HUB

SINGAPORE 608583

TEL :8239 0099

Letter Of Demand

Dear Sir ,

We act on behalf of the owner of vehicle No : GBE871C
Ms Tee Guan Tyre & Battery Co Pte Ltd to claim against you
insured vehicle no SLZ3392U on accident date 27/01/2019

The below following is :

- 1)Cost Of Repair =\$2400.00
- 2)Loss Of Use(04 days x \$80.00)=\$320.00
- 3)LTA Search fee =\$7.45

Total =\$ 2727.45

Regards

Eric Kee

8239 0099

A handwritten signature in black ink, appearing to be 'Eric Kee', is written over a circular company stamp. The stamp contains the text 'RONG SHENG AUTO ENGINEERING TRADING', 'Reg No 53181821K', and 'SINGAPORE 608583'.

Joy Irene (LKKAuto)

From: Joy Irene (LKKAuto)
Sent: Thursday, 11 April 2019 10:00 AM
To: reiranchu@gmail.com
Cc: Admin A
Subject: ACCIDENT INVOLVING SLZ 3392U AND GBE 871C ON 27/01/2019

Our ref: CC6/AIG19003168/R1jb3

GOH LAY KEONG

Policy Holder

Dear Sir/Madam,

ACCIDENT INVOLVING SLZ 3392U AND GBE 871C ON 27/01/2019

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us.

We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

RONG SHENG AUTO ENGINEERING TRADING

No 42 Toh Guan Road East

Enterprise Hub #01-79

SINGAPORE 608583

(REG NO : 53181821K)

TEL: 8239 0099

LETTER OF AUTHORISATION

I, TEE Kuan Tyre & Battery Co. Pte Ltd ("the third-party claimant"),
of _____ (address)
of the owner of ABE871C (vehicle no), hereby authorise
Rong sheng Auto Engineering Trading
("the workshop") to act for me with respect to my claim for repair costs and/or rental
and/or loss of use ("the claim") for my vehicle no. ABE871C that was
damaged involving in the accident which occurred on 27/01/2019 (date)
along Junction of JLN TIGA X PINE LANE (location)
involving vehicle/s no. SLZ3392U ("the accident").

I further authorise the workshop to settle my above mentioned claim in a manner that
they are deem fit and the workshop is further authorised to receive payment to
settlement of my claim with payment cheque/s being made in favour to the
workshop.

I further acknowledge that any settlement the workshop may reach with your
company on my behalf is on a without prejudice and without admission of liability
basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this on 20 day of Feb (month) 2019 (year).

Signature

(the third-party claimant)



Signature with Company's stamp

(Workshop)



RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, RONG SHENG AUTO ENGINEERING TRADING ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for SS2,700.00 (Global Sum, all-in) for vehicle no. GBE 871C that was damaged pursuant to the accident which occurred on 27/01/2019 (date) along JALAN TIGA/PINE LANE (location) involving vehicle no/s SLZ 3392U. This is pursuant to the inspection conducted on 21/02/2019 (date) at "the workshop".


We/I confirm that we/I are/am authorized by the owner TEE GUAN TYRE & BATTERY CO PTE LTD ("the third party claimant") of vehicle no. GBE 871C make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".


We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to GBE 871C (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 12 (day) of April (month) 2019 (year)


Signed by appointed surveyor


Signed by "the workshop" (with chop)

荣昇汽车贸易

RONG SHENG AUTO ENGINEERING TRADING

Blk 42 Toh Guan Road East #01-79 Enterprise Hub Singapore 608583

H/P: 9239 9009 / 8239 0099

(Reg. No. 53181821K)

CASH / INVOICE

INVOICE NO: 04400

Name / Address: <i>Alfa Asia Pacific Insurance Pte Ltd</i>	Date: <i>25/02/2019</i>
	Vehicle No: <i>6BE 871C</i>
	Make of Vehicle: <i>TOYOTA</i>
	Model of Vehicle: <i>DYNA</i>
	Your ref: <i>-</i>
	My ref: <i>-</i>

S/N	Qty	Descriptions	Unit Price	Amount S\$
<i>01</i>	<i>-</i>	<i>Cost of Repair</i>	<i>-</i>	<i>\$2400.00</i>
Remarks:			Total S\$	<i>2400.00</i>



RONG SHENG AUTO ENGINEERING TRADING

Recipient Signature



[Handwritten Signature]

> Back to OneMotoring



Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 18 Feb 2019 / 13:13:16

Receipt Date/Time : 18 Feb 2019 / 13:13:16

Tax Invoice/Receipt

Receipt No. : ITNET-00000-190218-001646

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
	Result of Insurance Enquiry - SLZ3392U As at 27 Jan 2019/10:45:00 Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.			
1	Insurance Enquiry - SLZ3392U Enquiry Fee 20190218131124443760	7.00	0.49	7.49
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
	Paid By			
	20190218131147645 Direct Debit: eNETS Debit (Internet Banking)			7.45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Jan 2019 Edit Reg		21 Feb 2019 00:00 Edit Adj Rpt	S\$2,400.00 Edit Estimates	S\$2,400.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	GOH LAY KEONG, ID: 57412015F								
Main Claimant:	TEE GUAN TYRE & BATTERY CO PTE LTD, Co. Reg. No.: 200918306H								
Vehicle Reg. No.:	GBE871C	Date of Loss:	27/01/2019 10:00 - :59 [40 Months and 25 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 0868709686SG	Policy/Cover Note No.:	1800046529 (Comprehensive) Coverage: 28/04/2018 - 27/04/2019						
Vehicle Reg. No. (Insured):	SL23392U	Policy No. (Claimant):	DMCVSN176521801						
		Excess:							
Repairer:	Rong Sheng Auto Engineering Trading (Toh Guan Rd East) No 42 Toh Guan Road East, #01-79 Enterprise Hub, 608583 Jurong East - Tel: 92399009								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com								
Claimant's Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 01/03/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBE871C (0868709686SG)
[SLZ3392U]
TP
TEE GUAN TYRE & BATTERY CO PTE LTD
Jan 27 2019 10:00AM
[GOH LAY KEONG]
Rong Sheng Auto Engineering Trading

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Letters/Correspondences			1 per page <input type="checkbox"/> <input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown		Edit
Photos/Images			3 per page <input type="checkbox"/> <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/04/19 10:04	General View		Load JPG <input checked="" type="checkbox"/>
2	11/04/19 10:04	General View		Load JPG <input checked="" type="checkbox"/>
3	11/04/19 10:04	General View		Load JPG <input checked="" type="checkbox"/>
4	11/04/19 10:04	General View		Load JPG <input checked="" type="checkbox"/>
5	11/04/19 10:04	General View		Load JPG <input checked="" type="checkbox"/>
6	11/04/19 10:04	General View		Load JPG <input checked="" type="checkbox"/>
7	11/04/19 10:04	General View		Load JPG <input checked="" type="checkbox"/>
8	11/04/19 10:04	General View		Load JPG <input checked="" type="checkbox"/>
9	11/04/19 10:04	General View		Load JPG <input checked="" type="checkbox"/>
10	11/04/19 10:04	General View		Load JPG <input checked="" type="checkbox"/>
11	11/04/19 10:04	General View		Load JPG <input checked="" type="checkbox"/>
12	11/04/19 10:04	General View		Load JPG <input checked="" type="checkbox"/>
13	11/04/19 10:04	General View		Load JPG <input checked="" type="checkbox"/>
14	11/04/19 10:04	General View		Load JPG <input checked="" type="checkbox"/>
15	11/04/19 10:04	General View		Load JPG <input checked="" type="checkbox"/>
16	11/04/19 10:04	General View		Load JPG <input checked="" type="checkbox"/>
17	11/04/19 10:04	General View		Load JPG <input checked="" type="checkbox"/>
18	11/04/19 10:04	General View		Load JPG <input checked="" type="checkbox"/>
19	11/04/19 10:04	General View		Load JPG <input checked="" type="checkbox"/>
20	11/04/19 10:04	General View		Load JPG <input checked="" type="checkbox"/>
21	11/04/19 10:04	General View		Load JPG <input checked="" type="checkbox"/>
22	11/04/19 10:04	General View		Load JPG <input checked="" type="checkbox"/>
23	11/04/19 10:04	General View		Load JPG <input checked="" type="checkbox"/>
24	11/04/19 10:04	General View		Load JPG <input checked="" type="checkbox"/>
25	11/04/19 10:04	General View		Load JPG <input checked="" type="checkbox"/>
26	11/04/19 10:04	General View		Load JPG <input checked="" type="checkbox"/>
27	11/04/19 10:04	General View		Load JPG <input checked="" type="checkbox"/>
28	11/04/19 10:04	General View		Load JPG <input checked="" type="checkbox"/>
29	11/04/19 10:04	General View		Load JPG <input checked="" type="checkbox"/>
30	11/04/19 10:04	General View		Load JPG <input checked="" type="checkbox"/>
31	11/04/19 10:04	General View		Load JPG <input checked="" type="checkbox"/>
32	11/04/19 10:04	General View		Load JPG <input checked="" type="checkbox"/>
33	11/04/19 10:04	General View		Load JPG <input checked="" type="checkbox"/>
34	11/04/19 10:04	General View		Load JPG <input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	11/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
36	11/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
37	11/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
38	11/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
39	11/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
40	11/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
41	11/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
42	11/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
43	11/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
44	11/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/02/19 14:48	TP ESTIMATE	 Load PDF	
2	20/02/19 14:49	TP GIA REPORT	 Load PDF	
3	25/02/19 09:45	TP ESTIMATE- MARKED	 Load PDF	
4	16/04/19 09:29	WORKSHOP INVOICE	 Load PDF	
5	16/04/19 09:29	AUTHORISATION TO ACT FORM	 Load PDF	
6	16/04/19 09:29	Release Voucher	 Load PDF	
7	16/04/19 09:29	LTA SEARCH	 Load PDF	
8	16/04/19 09:29	LETTER TO OI	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	21/02/19 10:22	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLZ3392U (Insd veh)	Model:	TOYOTA DYNA 150 3.0 D (M)
	GBE871C (TP veh)		
Date of Accident:	27/01/2019		

Global Sum Settlement	:	<input checked="" type="checkbox"/> [X] Yes	<input type="checkbox"/> [] No	
Repair Estimate	:	\$		4,364.15
Final Repair Cost	:	\$		2,700.00
Loss of Use	:	\$		4.00 days at \$80.00 per day
Rental (if any)	:	\$		days
LTA / GIA Search Fee	:	\$		
Others:	:	\$		
	:	\$		
Final Settlement Sum (Global Sum)	:	\$		2,700.00

Is Third Party Workshop GIA Registered? ☐ [] YES ☒ [X] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Rong Sheng Auto Engineering Trading	:	2,700.00
2)		:	
3)		:	

JOANNE LEE KHANG MIN

16 Apr
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19003168/R1JB3Q2

Date: 16/04/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800046529
Claimant Vehicle GBE871C **Insured Vehicle No :** SLZ3392U
No :
 Date of Loss: 27/01/2019 Nature of Claim: TP Claim No: 0868709686SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBE871C**
 Make & Model: TOYOTA DYNA 150, 3.0 D (M) Engine No: 1KD2496351
 Reg. Date: 02/09/2015 (Man. Year: 2015) Chassis No: JTFAT35Y70K204592
 Colour: Blue Odometer: 135005 km
 Engine Capacity: 2982 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 155 R12C (D)
 Front Left Side: Maxmiler 7 mm Rear Left Side: Maxmiler 5/5 mm
 Front Right Side: Maxmiler 7 mm Rear Right Side: Maxmiler 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,614.15	1,977.70	636.45	24.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,750.00	1,010.00	740.00	42.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,364.15	2,987.70	1,376.45	31.54
Approved Total (Overridden) (S\$)		2,400.00		
Nett Amount (S\$)	4,364.15	2,400.00	1,964.15	45.01
+ Loss of Use (4.0 x S\$80.00/day) (S\$)		320.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,727.45		
Global Sum Settlement (S\$)		2,700.00		

INSPECTION

Date of Assignment: 21/02/2019
 Date Inspected: 21/02/2019 Inspected At: Rong Sheng Auto Engineering Trading
 (Toh Guan Rd East)
 No 42 Toh Guan Road East, #01-79

Enterprise Hub
Singapore 608583

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH REAR TAILLAMP	Not Necessary	352.60 FL	*- FL
2	1		*LH REAR TAILLAMP PANEL	Not Necessary	156.70 FL	*- FL
3	1		*RH REAR TAILLAMP	Cracked	352.60 FL	*352.60 FL
4	1		*RH REAR TAILLAMP PANEL	Bent	156.70 FL	*156.70 FL
5	1		*REAR NUMBER PLATE BRACKET	Bent	181.65 FL	*181.65 FL
6	2		*REAR NUMBER PLATE LAMP	Not Necessary	76.80 FL	*- FL
7	1		*REAR SPARE TYRE BRACKET	Necessary	236.95 FL	*236.95 FL
8	1		*REAR TAILGATE HING LH	Not Necessary	143.60 FL	*- FL
9	1		*REAR TAILGATE HING RH (LOCK)	Bent	143.60 FL	*143.60 FL
10	1		*REAR TAILGATE RUBBER STOPPER LH	Not Necessary	38.90 FL	*- FL
11	1		*REAR TAILGATE RUBBER STOPPER RH	Scratched	38.90 FL	*38.90 FL
12	1		*REAR EXHAUST MUFFLER	Bent	589.20 FL	*589.20 FL
13	1		*REAR NUMBER PLATE	Bent	45.00 FS	*35.00 FS
14	1		*REAR REVERSE SENSOR	Not Working	250.00 FS	*200.00 FS
15	1		*REAR TAILGATE COMPANY STICKER	Necessary	120.00 FS	*120.00 FS
16	1		*EMBLEM DYNA STICKER	Necessary	58.00 FS	*58.00 FS
17	1		*8 PAX STICKER	Necessary	20.00 FS	*20.00 FS
18	1		*70KM/H STICKER	Necessary	20.00 FS	*20.00 FS
19	1		*REAR TAILGATE	Bent	250.00 FS	*250.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc

Sub Total (\$\$)	3,231.20	2,402.60
- List Item Discount on L Items 25.00/25.00% (\$\$)	617.05	424.90

Total Parts (\$\$)	2,614.15	1,977.70
--------------------	----------	----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR FOR PANEL BEATING	New	800.00	500.00
2	LABOUR FOR SPRAYPAINTING	New	500.00	300.00
3	TO RUST PROOF ON REAR ACCIDENT AREAS	New	120.00	60.00
4	WIRING CHECK	New	80.00	30.00
5	TO REPAIR AND STRAIGHTEN REAR EXHAUST PIPE	New	250.00	120.00
Gross Labour Cost (S\$)			1,750.00	1,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >