RONG SHENG AUTO ENGINEERING TRADING

NO 42 TOH GUAN ROAD EAST # 01-79 ENTERPRISE HUB SINGAPORE 608583 TEL: 8239 0099

REG NO: 53181821K

QUOTATION	/ESTIMATE
UUUTATION	LOTHVIMIL

VEHICLE NO :GBE871C

RE: REPAIR VEHICLE ON TOYOTA DYNA

DATE: 18/02/2019

TO A A SIA PACIFIC INSURANCE PTE LTD

REFER NO: RSA/2019/02/0008

IG ASIA PACIFIC INSURANCE FILE EID	C INSURANCE PTE LTD REFER NO : RSA/2019/02/0008		
S DESCRIPTION	QTY	UNTIL PRICE	AMOUNT
LIST ITEMS			
LH REAR TAILLAMP ×	1		\$352.60
LH REAR TAILLAMP PANEL	1	\$156.70	\$156.70
RH REAR TAILLAMP CRA	1	\$352.60	\$352.60
RH REAR TAILLAMP PANEL 84	1		\$156.70
REAR NUMBER PLATE BRACKET #	1	\$181.65	\$181.65
REAR NUMBER PLATE LAMP	2	\$38.40	\$76.80
REAR SPARE TYRE BRACKET	1	\$236.95	\$236.95
REAR TAILGATE HING LH X	1	\$143.60	\$143.60
REAR TAILGATE HING RH KLOW RI	1	\$143.60	\$143.60
REAR TAILGATE RUBBER STOPPER LH	1	\$38.90	\$38.90
REAR TAILGATE RUBBER STOPPER RH 50	1	\$38.90	\$38.90
REAR EXHUAST MUFFLER 34/	1	\$589.20	\$589.20
	TOTAL:	\$2,429.80	\$2,468.20
	LESS 25 %:	\$607.45	\$617.05
	TOTAL PARTS:	\$1,822.35	\$1,851.15
S/NETT ITEMS			12
REAR NUMBER PLATE	1	\$45.00	\$45.00
REAR REVERSE SENSOR ^ /	1	\$250.00	\$45.00 3 \$250.00 2
RAER TAILGATE COMPANY STICKER **	1	\$120.00	\$120.00
EMBLEM DYNA STICKER	1	\$58.00	\$58.00
8 PAX STICKER	1	\$20.00	\$20.00
70KM/H STICKER	1	\$20.00	\$20.00 ~
TOTAL:		\$513.00	\$513.00
	LIST ITEMS LH REAR TAILLAMP LH REAR TAILLAMP PANEL RH REAR TAILLAMP PANEL RH REAR TAILLAMP PANEL RH REAR TAILLAMP PANEL REAR NUMBER PLATE BRACKET REAR SPARE TYRE BRACKET REAR TAILGATE HING LH REAR TAILGATE RUBBER STOPPER LH REAR TAILGATE RUBBER STOPPER RH REAR EXHUAST MUFFLER S/NETT ITEMS REAR REVERSE SENSOR RAER TAILGATE COMPANY STICKER 8 PAX STICKER	LIST ITEMS LH REAR TAILLAMP LH REAR TAILLAMP PANEL RH REAR TAILLAMP PANEL RH REAR TAILLAMP PANEL RH REAR TAILLAMP PANEL REAR NUMBER PLATE BRACKET REAR NUMBER PLATE LAMP REAR TAILGATE HING LH REAR TAILGATE HING RH REAR TAILGATE RUBBER STOPPER LH REAR TAILGATE RUBBER STOPPER RH TOTAL: LESS 25 %: TOTAL PARTS: S/NETT ITEMS REAR REVERSE SENSOR REAR TAILGATE COMPANY STICKER PAX STICKER REAR TOKM/H STICKER 1	LIST ITEMS LH REAR TAILLAMP

TOTAL SPARE PARTS: \$2,335.35

\$2,364.15

VEHICLE NO: GBE871C

LABOUR DESCRIPTION

- 1 LABOUR FOR PANEL BEATING
- 2 LABOUR FOR SPRAYPAINTING
- 3 TO RUST PROOF ON REAR ACCIDENT AREAS
- 4 WIRING CHECK
- 5 TO REPAIR AND STRAIGTHEN REAR EXHUAST PIPE

AMOUNT

\$800.00 500 \$500.00 300 \$120.00 0 \$80.00 30 \$250.00 120

TOTAL LABOUR:

\$1,750.00



TOTAL PARTS AND LABOUR:

\$4,114.15

Carme
Hep 20010068

4 days
2/s
21/02/12@1120

Pasy after more

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date: