



SOUTHERN MOTOR

Black 1000 Bala Motor, June 2, 2014
Singapore 159762 Tel 63730309 Fax 63746614

Repair & Dealing in New & Second-hand Motor-cycles, Scooters & Insurance Agent

Asher

Date: 13th February 2018

Motor Claims Department
AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way #07-16
AIG Building
Singapore 078120

Dear Sirs

Re: Cost of repair to Yamaha FZ-16 - FRF 7949L

1 pc of meter	SCA ✓	350.00	
"	Top brake pump	125.00	
"	Brake lever	12.00	
"	Handle bar	38.00	
"	Mirror	24.00	1626
"	Head lamp	160.00	
"	Front mudguard	15.00	10%
"	Fuel tank cover	220.00	
"	Front head lamp bracket	65.00	1463.40
"	Exhaust pipe cover	45.00	
"	Front fork complete	540.00	
		1681.00	
		169.10	
		1521.90	

Steve
7/6/19

Less 10%

Nett

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Yours faithfully,
SOUTHERN MOTOR

Transport

No plate

Labour

Paul

198 } 20.00 ✓
15.00 SCA ✓
200.00 150
1766.90

Hf 90010068

4 days

45

18/02/19 @ 1725

Resurvey after repair

1463.40

195.00

1658.40

20%

1326.72

45-

Tel 64193000

Fax 64153727

1300

4 day