



南方摩哆  
SOUTHERN MOTOR

Block 1006, Bukit Merah Lane 2, #01-10  
Singapore 159762 Tel: 62730369 Fax: 62746614

Repair & Dealing in New & Second-hand Motor-cycles, Scooters & Insurance Agent

Date: 13th February 2018

Motor Claims Department  
AIG Asia Pacific Insurance Pte Ltd  
78 Shenton Way #07-16  
AIG Building  
Singapore 079120  
Dear Sirs

Re: Cost of repair to Yamaha FZ-16 - 7BF7949L

|               |                         |               |
|---------------|-------------------------|---------------|
| 1 pc of motor | SCA                     | 310.00        |
| "             | Top brake pump          | 125.00        |
| "             | Brake lever             | 12.00         |
| "             | Handle bar              | 32.00         |
| "             | Mirror                  | 25.00         |
| "             | Head lamp               | 160.00        |
| "             | Front mudguard          | 150.00        |
| "             | Fuel tank cover         | 220.00        |
| "             | Front head lamp bracket | 65.00         |
| "             | Exhaust pipe cover      | 45.00         |
| "             | Front forks complete    | 580.00        |
|               |                         | <hr/> 1681.00 |
|               |                         | 168.10        |
|               |                         | <hr/> 1521.90 |

Less 10%

Net

Transport

20.00

No plate

15.00

Labour

Repair

200.00

150

1766.90

4 days

18/02/18 @ 1725

Resurvey after repair

Tel 64193000  
Fax 64153727

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Yours faithfully,  
SOUTHERN MOTOR