

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO.201001158E

M/S: AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG/AMK

Claim Type: Third Party

Accident Date: 31/01/2019

TP Veh Reg No: SCY1312B

Estimate No: ES1991190/AMK

Date: 25 Feb 2019

Policy No: 5026669951-10

Veh Reg No: SGS1969R

Make/Model: TOYOTA CAMRY 2.0
 AUTO

Chassis No: MR053BK4107004891

Engine No: 1AZE017246

Reg. Date: 07/03/2007

Estimate Repair Cost to Vehicle No :SGS1969R

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 FRONT BUMPER	486.77	1 PC	486.77	✓
2 FRONT BUMPER SPONGE	97.00	1 PC	97.00	✓
3 FRONT BUMPER CHROME MOULDING	101.90	2 PC	203.80	✓
4 FRONT GRILLE	446.00	1 PC	446.00	✓
5 FRONT GRILLE LOGO	60.00	1 PC	60.00	✓
6 REAR BUMPER	530.50	1 PC	530.50	✓
7 REAR BUMPER REINFORCEMENT	420.00	1 PC	420.00	✓
8 REAR BUMPER RH SIDE REFLECTOR	56.90	1 PC	56.90	✓
9 REAR BUMPER RH SIDE RETAINER (LONG)	57.10	1 PC	57.10	✓
10 REAR BUMPER CLIP	3.50	5 PC	17.50	✓
11 REAR BOOT LOGO	70.24	1 PC	70.24	✓
12 REAR BOOT EMBLEM 'CAMRY'	49.98	1 PC	49.98	✓
13 REAR BOOT EMBLEM '2.0'	83.39	1 PC	83.39	✓
14 REAR BOOT INNER RUBBER	204.10	1 PC	204.10	50% ✓
15 REAR END PANEL	602.00	1 PC	602.00	✓
16 REAR END PANEL INNER TOP GARNISH	353.00	1 PC	353.00	✓
			3,738.28	
		Less 25%	934.57	2,803.71
Special Net				
17 FRONT NUMBER PLATE	35.00	1 PC	35.00	✓
18 REVERSE SENSOR	200.00	1 SET	200.00	✓
			235.00	235.00
Labour				
19 REMOVE & REFIX FRT BUMPER,GRILLE:KNOCKING & REPAIR FRT PANEL & REALIGN THE SAME	400.00	1 LA	400.00	300 ✓
20 PUTTY & RESPRAY FRT BUMPER,FRT PANEL & REALIGN THE SAME	450.00	1 LA	450.00	380 ✓
21 REMOVE & REFIX REAR BUMPER,TAILLAMP:TO CUT,WELD & RENEW REAR END PANEL:KNOCKING & REPAIR REAR FENDERS & REALIGN REAR BOOT THE SAME	700.00	1 LA	700.00	600 ✓
22 PUTTY & RESPRAY REAR BUMPER,REAR BOOT,REAR END PANEL & ALL AFFECTED AREAS	700.00	1 LA	700.00	600 ✓
23 RUSTPROOFING	60.00	1 LA	60.00	✓
			2,310.00	2,310.00

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST: 201001158E RCB NO: 201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department

WS Ref: TP/AIG/AMK
Claim Type: Third Party
Accident Date: 31/01/2019
TP Veh Reg No: SCY1312B

Estimate No: ES1991190/AMK
Date: 25 Feb 2019
Policy No: 5026669951-10
Veh Reg No: SGS1969R
Make/Model: TOYOTA CAMRY 2.0
AUTO
Chassis No: MR053BK4107004891
Engine No: 1AZE017246
Reg. Date: 07/03/2007

Estimate Repair Cost to Vehicle No :SGS1969R

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
			Total	S\$ 5,348.71
			Add GST @ 7%	374.41
			Total Amount Payable	<u>S\$ 5,723.12</u>

* SURVEY VEHICLE AT ANG MO KIO WORKSHOP.

For Cheng Hoe Motor Pte Ltd

DORLYN LI

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: