

Estimate Report

Page 1 of 4

ETHOZ

INSURER: FWD Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	PNPV2017-00001620-01	Date of Loss:	17/02/2019
Vehicle Reg. No.:	SJW1409J	Driveable?	
Driver Age/Info:	24 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	TEOH KEAN HUAT		
Driver:	JEREMY TEOH		
Make/Model:	HONDA CIVIC, 1.3 IMA CVT (A)	Vehicle Reg. Date:	04/03/2010
Vehicle Colour:	GREY		
Engine No:	LDA24017754	Chassis No:	JHMFD36209S205095
Odometer:	84186 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Description of Accident/Loss	REFER TO ATTACHMENT		
Remarks:	VEHICLE IN ETHOZ TAMPINES		
Present Location:	ETHOZ PROTECT PTE LTD (TAMPINES)		

NOT Affected
WAL
4/5
5/5
Excess \$3000
the ph. After repair

COST OF CLAIMS

	Amount
Parts	5,975.00
Miscellaneous Items	60.00
Labour	1,900.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (\$\$)	7,935.00
- Excess (\$\$)	800.00
(\$\$)	7,135.00
+ GST 7.00% (\$\$)	499.45
Nett Amount (\$\$)	7,634.45

This claim is handled by: JIMMY GOH - 9040 4688

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Estimate Report

Page 2 of 4

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Feb 2019)
 Parts: 143 HONDA CIVIC 1.3 IMA CVT (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SJW1409J)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BONNET <i>Buc</i>	0.00	0.00	*420.00 F //
2	1		*BONNET HINGE LH <i>Ref</i>	0.00	0.00	*45.00 F //
3	1		*BONNET HINGE RH <i>Ref</i>	0.00	0.00	*45.00 F //
4	2		*BONNET WEATHER STRIP <i>Ref</i>	0.00	0.00	*72.00 F //
5	1		*BONNET INSULATOR <i>Ref</i>	0.00	0.00	*65.00 F //
6	10		*BONNET INSULATOR CLIPS <i>Ref</i>	0.00	0.00	*35.00 F //
7	1		*BONNET LOCK <i>Ref/Ref</i>	0.00	0.00	*75.00 F //
8	1		*FRONT GRILLE BASE <i>Ref</i>	0.00	0.00	*95.00 F //
9	1		*FRONT GRILLE CHROME MOULDING <i>Ref</i>	0.00	0.00	*105.00 F //
10	1		*FRONT GRILLE LOGO <i>Ref</i>	0.00	0.00	*38.00 F //
11	4		*FRONT GRILLE CLIPS <i>11</i>	0.00	0.00	*8.00 F //
12	1		*FRONT BUMPER <i>Ref</i>	0.00	0.00	*280.00 F //
13	1		*FRONT BUMPER SIDE RETAINER LH <i>Ref</i>	0.00	0.00	*30.00 F //
14	1		*FRONT BUMPER SIDE RETAINER RH <i>Ref</i>	0.00	0.00	*30.00 F //
15	1		*FRONT BUMPER REINFORCEMENT <i>Ref</i>	0.00	0.00	*195.00 F //
16	1		*FRONT BUMPER LOWER AIR GRILLE <i>Ref</i>	0.00	0.00	*70.00 F //
17	1		*FRONT BUMPER NUMBER PLATE BASE <i>Ref</i>	0.00	0.00	*65.00 F //
18	10		*FRONT BUMPER CLIPS <i>Ref</i>	0.00	0.00	*30.00 F //
19	1		*HEADLAMP LH <i>Ref</i>	0.00	0.00	*320.00 F //
20	1		*HEADLAMP LOWER BRACKET LH <i>Ref</i>	0.00	0.00	*35.00 F //
21	1		*HEADLAMP RH <i>Ref</i>	0.00	0.00	*320.00 F //
22	1		*HEADLAMP LOWER BRACKET RH <i>Ref</i>	0.00	0.00	*35.00 F //
23	1		*FRONT SUPPORT PANEL <i>Ref/Ref</i>	0.00	0.00	*480.00 F //
24	1		*FRONT SUPPORT TOP GARNISH <i>Ref</i>	0.00	0.00	*78.00 F //
25	10		*FRONT SUPPORT TOP GARNISH CLIPS <i>Ref</i>	0.00	0.00	*30.00 F //
26	1		*HORN LH <i>11</i>	0.00	0.00	*50.00 F X
27	1		*HORN RH <i>11</i>	0.00	0.00	*50.00 F X
28	1		*AIRCON CONDENSOR ASSY <i>Ref</i>	0.00	0.00	*490.00 F //
29	1		*AIRCON CONDENSOR AIR GUIDE LH <i>11</i>	0.00	0.00	*28.00 F X
30	1		*AIRCON CONDENSOR AIR GUIDE RH <i>11</i>	0.00	0.00	*28.00 F X
31	1		*AIRCON PIPE (COND TO COMP) <i>11</i>	0.00	0.00	*190.00 F X
32	1		*AIRCON PIPE (COND TO COIL) <i>11</i>	0.00	0.00	*180.00 F X
33	1		*AIRCON FAN MOTOR	0.00	0.00	*195.00 F >
34	1		*AIRCON FAN BLADE	0.00	0.00	*55.00 F >
35	1		*AIRCON FAN COWLING	0.00	0.00	*110.00 F >
36	1		*RADIATOR ASSY <i>holder one/phase</i>	0.00	0.00	*460.00 F //
37	1		*RADIATOR TOP BRACKET LH <i>Ref</i>	0.00	0.00	*25.00 F //
38	1		*RADIATOR TOP BRACKET RH <i>Ref</i>	0.00	0.00	*25.00 F //

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

Estimate Report

Page 3 of 4

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
39	1		*RADIATOR FAN MOTOR	0.00	0.00	*290.00 F ?
40	1		*RADIATOR FAN BLADE	0.00	0.00	*75.00 F ?
41	1		*RADIATOR FAN COWLING	0.00	0.00	*110.00 F ?
42	1		*RADIATOR RESERVOIR TANK	0.00	0.00	*48.00 F ?
43	1		*FRONT FENDER LH	0.00	0.00	*195.00 F ?
44	1		*FRONT FENDER INNER SHIELD LH	0.00	0.00	*75.00 F ?
45	1		*FRONT FENDER RH	0.00	0.00	*195.00 F ?
46	1		*FRONT FENDER INNER SHIELD RH	0.00	0.00	*75.00 F ?
47	10		*FRONT FENDER INNER SHIELD CLIPS	0.00	0.00	*25.00 F ?
Total Parts (S\$)						5,975.00

F=Franchise part.

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

3923

615

Estimate Report

Page 4 of 4

Estimates on Miscellaneous Items

No Qty Particulars

Miscellaneous Items			Amount
1	1	COOLANT <i>all</i>	25.00
2	1	FRONT NUMBER PLATE & HOLDER <i>buy</i>	35.00
Sub Total (\$\$)			60.00

Estimates on Labour

No Particulars

Labour Items		Lab.Type	Amount
1	LABOUR TO FACILITATE REPAIR	New	700 850.00
2	TO REMOVE & INSTALL AIRCON CONDENSOR INCLUDING CHARGE UP GAS	New	100 120.00
3	TO APPLY ANTI RUST COATING ON AFFECTED AREAS	New	NZ X 100.00 X
4	TO CHECK & RECONNECT ALL NECESSARY WIRINGS	New	30.00
5	TO SPRAY PAINT ON AFFECTED AREAS	New	660 800.00
Gross Labour Cost (\$\$)			1,800.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

ETHOZ PROTECT PTE LTD

Company Registration No. 199005791M

30 Bukit Batok Crescent, SINGAPORE 658075 . Website : <http://www.orix.com.sg>

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: