

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.  
6 Temasek Boulevard  
#18-01 Suntec Tower 4  
Singapore 038986

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Josey Loh

Date: 20 Feb 2019

**Preliminary Advice**

Vehicle No	: SJW1409J	Accident Date	: 17/02/2019
Make	: HONDA CIVIC	Policy No.	: PNPV2017-00001620-01
Assignment Date	: 19/02/2019	Excess	: S\$3,000.00
Date of Inspection	: 20/02/2019	Est. Duration of Repair	: 5.00
Inspection At	: ETHOZ PROTECT PTE LTD (BUKIT BATOK) 30 BUKIT BATOK CRESCENT SINGAPORE 658075		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,935.00
Revised Amount	:S\$	5,468.00
Check Items (Estimated)	:S\$	883.00
Total	:S\$	6,351.00

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	19,500.00
COE / PARF Rebate	:S\$	13,765.00
Salvage Value	:S\$	
Margin for Repair	:S\$	5,735.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Repairer agree Lump Sum repair not exceeding Nett Value. Kindly re-confirmed on policy excess.