

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khal@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0202/2019/NK
Date	:	15-Feb-19

Vehicle in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	M/S Erbe Singapore Pte Ltd
Address	:	25 International Business Park #02-55/56 German Centre Singapore 609916
Telephone	:	HP +65 97537561
Type of Claim	:	Own Damage Claims
Policy No.	:	1800120277
Vehicle No	:	SME 8293 M
Model Code	:	Audi Q5 SPORT 2.0 TFSI
Model / Year	:	18/10/2018
Engine No	:	DAX041384
Chassis No	:	WAUZZZF2J2197223
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	3-Feb-19
Place of Accident	:	Sin Ming HDB Carpark

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SME 8293 M

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall rear parking aid and rear lid kick sensor. Check function.	S/N \$ 360.00 ✓	
2	To dismantle and renew rear bumper assy. Reorganise crash management components. Reinstall all parts removed.	\$ 1,050.00 500	
3	To respray rear upper bumper, rear lower bumper and both rear wheel arch covers.	\$ 2,300.00 1375	
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
SUB- TOTAL LABOUR CHARGES		: \$ 3,902.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SME 8293 M

S/N	Parts Description		Damaged Par S/Nett
1	REAR BUMPER	\$	2,648.00 <i>do ✓</i>
2	SPACE HOLDER	\$	13.00 <i>?</i>
3	REAR BUMPER SPOILER	\$	754.00 <i>do ✓</i>
4	REAR BUMPER TOW EYE COVER	2 \$	69.00 <i>X</i>
5	REAR BUMPER CLOSING ELEMENTS LH/ RH	2 \$	172.00 <i>?</i>
6	REAR BUMPER TRIM LH / RH	2 \$	426.00 <i>X</i>
7	TAILLIGHT RH / LH	2 \$	1,254.00 <i>LH-ntw, RH X</i>
8	CONTROL UNIT FOR BOOTLID OPENING	\$	387.00 <i>?</i>
9	REAR BUMPER REINFORCEMENT	\$	831.00 <i>?</i>
10	REAR BUMPER HOLDING STRAP	\$	151.00 <i>X</i>
11	REAR BUMPER GUIDE SECTION LH / RH	2 \$	152.00 <i>?</i>
12	REAR BUMPER FOAM LH / RH	2 \$	112.00 <i>?</i>
13	REAR BUMPER SENSOR	2 \$	462.00 <i>?</i>
14	REAR BUMPER SENSOR RING	\$	12.00 <i>X</i>
15	REAR BUMPER WHEEL COVER REAR LH / RH	2 \$	974.00 <i>? - photo</i>
16	SUNDRIES	\$	400.00 <i>?</i>
TOTAL SPARE PARTS CHARGES		:	\$ 8,817.00
TOTAL LABOUR CHARGES		:	\$ 3,902.00
GRAND TOTAL		:	\$ 12,719.00

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Tan Hin 97495744
17/2/92 1140
Authorise (below SK)
Repair before paint
sure 114auto.com
103 days
Ex \$ to be advise.

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant