

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

VEHICLE NO : SHD 3948E

DATE 20/2/2019 9:24

MAKE :

MODEL : HYUNDAI SONATA

AXIA-FZ
L8um

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid <i>Rest</i>			\$ 1,349.50
	Boot Lid Rubber <i>X su</i>			\$ 110.90
	Boot Lid Lock Upper <i>X su</i>			\$ 132.10
	Boot Lid Lock Lower <i>X su</i>			\$ 30.30
	Boot Lid Sonata Plate <i>- me</i>			\$ 43.60
	Boot Lid Hyundai Plate <i>- me</i>			\$ 24.20
	Boot Lid 'H' Emblem <i>- me</i>			\$ 26.10
	Boot Lid CRDI Plate <i>- me</i>			\$ 22.70
	Rear Bumper <i>Rest</i>			\$ 578.40
	Rear Bumper Reinforcement <i>X su</i>			\$ 483.30
	Rear Bumper Clip <i>- me</i>			\$ 22.00
	Rear Bumper Sponge <i>X su</i>			\$ 137.40
	Rear Bumper Under Cover <i>X su</i>			\$ 185.80
	Rear Bumper Protector (RH) <i>X su</i>			\$ 38.00
	Rear Panel <i>X su</i>			\$ 391.80
	Rear Panel Garnish <i>X su</i>			\$ 95.80