

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5713H**AAD1902-120***Not Authored
L1Pny & 3000*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHC 5713H

VF1ABL15AUC280316

RENAULT

LATITUDE

15.2.2019

AXA

28/11/2014

PART**LIST**

- 1 1 BUMPER COVER REAR
- 2 1 BUMPER LOWER REAR
- 3 1 BUMPER BRACKET CTR REAR
- 4 1 BUMEP R BRACKET SIDE RH REAR
- 5 1 BUMEP R RETAINER RH REAR
- 6 1 BUMPER REFLECTOR RH
- 7 1 BUMEP R BRACKET SIDE LH REAR
- 8 1 BUMEP R RETAINER LH REAR
- 9 1 BUMPER REFLECTOR LH
- 10 1 BUMPER BEAM REAR
- 11 1 BUMPER BEAM BRACKET LH REAR
- 12 1 BUMPER BEAM BRACKET RH REAR
- 13 1 BOOT REAR
- 14 1 BOOT FINISHER
- 15 1 BOOT WHEATERSTRIP
- 16 1 BOOT REFLECTOR LAMP LH
- 17 1 BOOT REFLECTOR LAMP RH
- 18 1 BOOT BADGE 'RENAULT'
- 19 1 BOOT BADGE
- 20 1 BOOT STRUT LH
- 21 1 BOOT STRUT RH
- 22 1 BOOT HINGE LH
- 23 1 BOOT HINGE RH
- 24 1 BOOT INNER TRIM
- 25 1 BOOT SWITCH
- 26 1 BOOT LOCK
- 27 1 BOOT LOCK CATCH
- 28 2 LICENCE PLATE LAMP
- 29 2 BOOT RUBBER PLUG

- | | | | |
|----|---------------|----------|-----|
| \$ | <i>Bu</i> | 1,108.46 | ✓ |
| \$ | <i>nd/dri</i> | 768.84 | ✓ |
| \$ | <i>SL</i> | 113.47 | X |
| \$ | <i>SL</i> | 135.97 | X |
| \$ | <i>SL</i> | 44.99 | X |
| \$ | <i>SL</i> | 43.61 | X |
| \$ | <i>SL</i> | 135.97 | X |
| \$ | <i>SL</i> | 44.99 | X |
| \$ | <i>SL</i> | 43.61 | X |
| \$ | <i>Bu</i> | 777.52 | ✓ |
| \$ | <i>Bu</i> | 225.95 | X |
| \$ | <i>Bu</i> | 225.95 | X |
| \$ | <i>N</i> | 2,872.68 | X |
| \$ | <i>SL</i> | 470.06 | } X |
| \$ | <i>SL</i> | 323.05 | |
| \$ | <i>SL</i> | 493.35 | |
| \$ | <i>SL</i> | 493.35 | |
| \$ | <i>na</i> | 225.36 | |
| \$ | <i>na</i> | 225.36 | |
| \$ | <i>SL</i> | 276.08 | |
| \$ | <i>SL</i> | 276.08 | |
| \$ | <i>N</i> | 367.84 | |
| \$ | <i>N</i> | 367.84 | |
| \$ | <i>SL</i> | 586.45 | |
| \$ | <i>SL</i> | 168.13 | |
| \$ | <i>N</i> | 202.67 | |
| \$ | <i>N</i> | 74.40 | |
| \$ | <i>SL</i> | 50.52 | |
| \$ | <i>SL</i> | 221.81 | |

Trans-cab Auto Services Pte Ltd**AAD1902-120**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5713H

30	1 FENDER PANEL REAR LH	\$	R	3,299.13	}
31	1 WHEELARCH REAR LH	\$	Sh	543.47	
32	1 FENDER PANEL INNER TRIM REAR LH	\$	Sh	671.45	
33	1 WHEEL HOUSING PANEL REAR LH	\$	R	4,682.09	
34	1 TAILLAMP LH	\$	Sh	552.55	
35	1 TAILLAMP PANEL LH	\$	R	986.70	
36	1 TAILLAMP RH	\$	Sh	552.55	
37	1 TAILLAMP PANEL RH	\$	R	986.70	
38	1 OUTER PANEL REAR (End Panel)	\$	R	1,471.77	
39	1 OUTER PANEL REAR (End Panel)TRIM	\$	Sh	404.56	
40	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	2,189.88	
41	1 SPARE WHEEL PANEL TRIM	\$	Sh	612.21	
42	1 EXHAUST REAR	\$	R	7,489.05	
43	1 EXHAUST CAP REAR	\$	R	230.49	

TOTAL	\$	36,036.98
10%	\$	3,603.70
	\$	32,433.28

Specical Nett

1	1SET PARKING AID	\$	Sh	700.00	X
2	1SET REAR BUMPER CLIP	\$	na	66.00	—
3	1SET BUMPER BRACKET CTR CLIP	\$	na	33.00	—
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X
5	1SET BUMPR RETAINER RH CLIP RR	\$	na	20.00	X
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	na	10.00	X
7	1SET BUMPR RETAINER CLIP LH RR	\$	na	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	na	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	na	66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	na	17.82	X
11	1SET BOOT FINISHER CLIP	\$	na	24.20	X
12	1 REAR BOOT STICKER 'Trans-cab'	\$	na	80.00	X
13	1 REAR BOOT STICKER '6555-3333'	\$	na	80.00	X

Trans-cab Auto Services Pte Ltd**AAD1902-120**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5713H

14 1SET FENDER WHEELARCH REAR RH CLIP	\$	na	35.00	}	X
15 1SET FENDER WHEELARCH REAR LH CLIP	\$	na	35.00		
16 1 FENDER INNER TRIM CLIP LH	\$	na	28.00		
17 1 FENDER INNER TRIM CLIP LH	\$	na	28.00		
18 1 TAILLAMP CLIP RH	\$	na	5.00		
19 1 TAILLAMP CLIP LH	\$	na	5.00		
20 2 REAR WINDSCREEN SELANT	\$	na	80.00		
21 1 WINDSCREEN MOULDING	\$	na	100.00		
22 1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00		
23 1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	sz na	385.00		
24 1 SPARE TYRE	\$	sz	330.00		

TOTAL \$ 2,280.02**TOTAL PARTS \$ 34,713.30****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	400l
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	300l
To Rust-Proofing Of The Affected Areas.	\$	170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	60l
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	na 170.00	X
To repair and realign rear exhaust pipe.	\$	na 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	na 170.00	X

Trans-cab Auto Services Pte Ltd**AAD1902-120**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5713H

To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	X
To supply and re-do rear luggage floor panel insulation padding.	\$	<i>nn</i> 380.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>nn</i> 170.00	X
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00	X

TOTAL \$ 14,340.00**Over All Total \$ 49,053.30****(LUMP SUM)****Repair Days*****20 DAYS******2 day***

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: