

15/5/2010

INS. CASE OWNER:

C2

CC 3/15m AXA1900 3188, Kgh.

LKK:

IDAC:

Surveyor:

KSL

DOI:

ASSIGNMENT

16/5/19

Date / Time:

16/5/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SFV 807C

Name of Insured:

AMB TDOW THAIN

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

16/5/19

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

S9M01EB7 / 9A9N

Policy No.:

6A1055

Make / Model:

MERCEDES

Place of Accident:

Sembawang East Ave

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

SHC 5891B

INSRS:
WSP:
Tel:
Liability:
RMKS:Trans
CabINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time		STAGE	DATE / PIC
17/8	SHC 5891B - x	Non-Reporting ltr (1st):	
	SFV 807C - x	Non-Reporting ltr (2nd):	
	Req of AVP from both parties.	Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
		Call OI:	
		After call ltr to OI:	
		Documentation Check List: Handler	Typist
		Notification ltr (if non-pickup)	☒
		After call ltr to OI:	☒
		Authorisation To Act:	☒
		Release Voucher:	☒
		Final Repair Bill:	☒
		Car Rental Invoice:	☒
		Towing Invoice	☒
		LTA / GIA:	☒
		Medical Bill:	☒
		PIR:	☒
		Mandate/Reject Instruction:	☒
		LOD	☒
		Payment Breakdown Form:	☒
		Post-Repair Photos:	☒
		Others:	☒

PRELIMINARY ADVICE	Date/Time:	Sent By:	Confirm by: Kenneth
FINALIZATION	Date/Time:	Confirm with:	Confirm by: Kenneth
Repair Cost: 46	SS 6200.00	(6 days) Reduction: \$30,163.26 % 82	Email ☐ Call ☐
FINAL SETTLEMENT	Date/Time: 14/4/2020	Confirm with: Wai Yim	Email ☐ Call ☐
Final Liability: % 50	(Agreed / Assessed) BOLA S/N No.:	NIL	If NO or B 28, Ass. Lia:
Repair Cost: 47276	SS 3638.00	(w/ GST)	* conflicting version.
Loss of Rental (LOR): 496.60	SS 248.30	(5 days) x \$99.32	
Loss of Use (LOU):	SS -	(S x days)	
Loss of Income (LOI):	SS -	(S x days)	
LOR only ☐ LOU only ☐	LOR + LOU ☐	LOR + LOU ☐	[Tick only one]
GLA / LTA Search	SS 7.49		
Medical:	SS -		
Disbursement:	SS -	(e.g. Tow/ Independent)	
Legal Cost	SS -		
Total:	SS 2893.79	Global Sum SS: 3890.00	
FINAL PAYMENT	Date/Time:	Confirm with:	Email ☐ Call ☐
Payee 1:	SS 3890.00	Name 1: Trans-cab Auto Services Pte Ltd	
Payee 2: (Strike if N.A.)	SS	Name 2:	
Payee 3: (Strike if N.A.)	SS	Name 3:	

✓ GIA

ASS. REC. BY:

REF:

ATA/

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S14C 5891B Yr Regn: 12, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Longitude c.c. 1995

Colour:

n. white 1R1 A/C: Insured / Std / NI / NA

Sp. Reading

342030 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VF1ABL 15AUC 280975

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NII / S/Rlm / STD A/Rlm or

Tyre Size:

F:

R:

215/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Giti

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

16/2/19

D.O.A.

19/2/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

File pass to
1 Rm & 6800

(Red = \$30,163.26 / 821.7)

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5891B**AAD1902-141***Not Authorized*
11 Sep 868006

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHC 5891B

VF1ABL15AUC280975

RENAULT

LATITUDE

16.2.2019

AXA

18/12/2014

PART**LIST**

1	DOOR PANEL FRT LH	\$	B ₁ 2,844.66 ✓
1	DOOR HINGE UPPER LH	\$	11 261.28
1	DOOR HINGE LOWER LH	\$	11 300.55
1	DOOR CHECK FRT LH	\$	11 194.77
1	DOOR LOCK FRT LH	\$	11 908.75
1	DOOR CATCH FRT LH	\$	11 131.23
1	DOOR HANDLE OUTER FRT LH	\$	11 477.76
1	DOOR HANDLE COVER FRT LH	\$	11 13.22
1	DOOR HANDLE MODULE FRT LH	\$	11 133.60
1	DOOR REGULATOR FRT LH	\$	11 505.19
1	DOOR REGULATOR MOTOR FRT LH	\$	11 796.46
1	DOOR REGULATOR GUIDE FRT LH	\$	11 120.97
1	DOOR PANEL REAR LH	\$	B ₁ 2,844.66 ✓
1	DOOR GUIDE REAR LH	\$	11 176.82
1	DOOR HINGE UPPER LH	\$	11 274.50
1	DOOR HINGE LOWER LH	\$	11 300.55
1	DOOR CHECK REAR LH	\$	11 203.06
1	DOOR LOCK REAR LH	\$	11 908.75
1	DOOR HANDLE OUTER REAR LH	\$	11 126.49
1	DOOR HANDLE CAP REAR LH	\$	11 35.52
1	DOOR HANDLE SEAL REAR LH	\$	11 7.89
1	DOOR HANDLE COVER REAR LH	\$	11 13.22
1	DOOR HANDLE MODULE REAR LH	\$	11 133.60
1	DOOR REGULATOR REAR LH	\$	11 1,135.10
1	DOOR REGULATOR MOTOR REAR LH	\$	11 893.75
1	DOOR REGULATOR NUT REAR LH	\$	11 12.43
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	11 6.31
1	DOOR FINISHER REAR LH	\$	11 423.10
1	DOOR MOULDING REAR LH	\$	11 176.82

Trans-cab Auto Services Pte Ltd

AAD1902-141

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5891B

1	DOOR MOULDING CLIP L70Y	\$	na	5.92	}
1	DOOR MOULDING SCREW L70Y	\$	sn	6.91	
1	DOOR CASING REAR LH	\$	sn	1,509.06	
1	DOOR WATER SHIELD REAR LH	\$	sn	30.39	
1	DOOR CASING CLIP	\$	na	12.63	
1	DOOR CASING LIGHT L70Y	\$	sn	48.74	
1	DOOR FINISHER INNER REAR LH	\$	sn	323.44	
1	DOOR FINISHER BRACKET INNER REAR LH	\$	n	46.97	
1	DOOR FINISHER BRACKET INNER REAR LH	\$	n	20.33	
1	DOOR FINISHER BRACKET INNER REAR LH	\$	n	20.33	
1	DOOR FINISHER BRACKET INNER REAR LH	\$	n	20.33	
1	DOOR GRAB HANDLE REAR LH	\$	sn	210.96	
1	DOOR BLIND REAR LH	\$	sn	741.80	
1	DOOR WHEATHESTRIP REAR LH	\$	sn	410.66	
1	DOOR SEAL REAR LH	\$	sn	162.02	
1	DOOR GLASS RUNNER SEAL REAR LH	\$	sn	229.31	
1	DOOR WAIST SEAL OUTER REAR LH	\$	sn	334.69	
1	DOOR WAIST SEAL INNER REAR LH	\$	sn	115.64	
1	DOOR MIRROR ASSY LH	\$	sn	1,483.40	}
1	ROCKER PANEL INNER GARNISH LH	\$	sn	466.51	
1	ROCKER PANEL INNER LH	\$	n	1,024.79	
1	ROCKER PANEL CENTER LH	\$	n	990.25	
1	FENDER PANEL REAR LH	\$	n	3,299.13	
1	FENDER PANEL INNER TRIM REAR	\$	sn	671.45	
1	WHEELARCH REAR LH	\$	sn	543.47	X

\$	27,090.14
----	-----------

10% \$	2,709.01
--------	----------

\$	24,381.13
----	-----------

Special Nett

1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00	X
2	FRAME FULL SUPPORT PANEL NUT	\$	na	20.00	X
2	FRAME FULL SUPPORT PANEL STUD	\$	na	30.00	X
1SET	WHEELARCH CLIP FRT LH	\$	na	30.50	X
1	FRONT DOOR STICKER 'Trans-cab'	\$	na	80.00	60sn
1	FRONT DOOR STICKER 'Chassis'	\$	na	50.00	15sn
1	REAR DOOR STICKER '6555 3333'	\$	na	80.00	60sn

Trans-cab Auto Services Pte Ltd**AAD1902-141**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5891B

1	DOOR CHECK BOLT	\$	S _h 22.69	}
1	DOOR GUIDE SCREW	\$	S _h 10.85	
1	DOOR HINGE BOLT	\$	S _h 10.85	
1	DOOR HINGE NUT RH	\$	S _h 14.60	
1	DOOR CHECK BOLT	\$	S _h 22.69	
1	DOOR CHECK NUT	\$	S _h 3.75	
1	DOOR LOCK SCREW L70Y	\$	S _h 6.12	
1	DOOR CATCH SCREW L70Y	\$	S _h 10.06	
1	LEFT REAR RIM	\$	S _h 380.00	}
1	LEFT REAR TYRE	\$	S _h 330.00	
TOTAL		\$	1,172.13	

TOTAL PARTS	\$	25,553.26
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,200.00	800l
Putty and spray painting of the affected portion.	\$	4,200.00	1100l
To rust-proofing of the affected areas.	\$	170.00	90l
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	80l
To check steering geometry and computer wheel alignment	\$	220.00	60l
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	380.00	80l
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	20l

Trans-cab Auto Services Pte Ltd**AAD1902-141**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5891B

To transfer of front fender fittings, attachment and
perform water seepage test.

\$ 380.00 X

To transfer of front door fittings, attachment and
perform water seepage test.

\$ 380.00 601

To transfer of Rear door fittings, attachment and
perform water seepage test.

\$ 380.00 601

TOTAL \$ 11,410.00**Over All Total \$ 36,963.26****LUMP SUM (REPAIR DAY)****20 DAYS**

6 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHC5891B
Vehicle to be Exported:	Yes
Intended Deregistration Date:	18 Feb 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C002283
Chassis No.:	VF1ABL15AUC280975
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	18 Dec 2014
First Registration Date:	18 Dec 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Dec 2022
PARF Rebate Amount:	\$9,373.00

Intended COE Rebate Details

COE Expiry Date:	17 Dec 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$51,668.00
COE Rebate Amount:	\$24,729.00
Total Rebate Amount:	\$34,102.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 18 Feb 2019

OK



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 20/02/2020

Survey Details:

Date of loss	16-Feb-19
Date of appointment	19-Feb-19
Date of survey	19-Feb-19
Location of survey	TRANS-CAB AUTO SERVICES PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SHC 5891B
Make and Model	RENAULT LATITUDE
Date of registration	18/12/2014
Excess	
Market Value	\$0
Parf Rebate	\$0
Nett Loss	\$0

Repair details:

Initial Estimate	\$ 36,963.26
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 6,146.61
Check items (estimate)	\$ -
Labour	\$ 2,350.00
Total	\$ 8,496.61
Lump Sum(if applicable)	\$ 6,800.00

Number of days for repair	6
---------------------------	---



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

CONFLICTING VERSION - 50%

Mandate:

Liability(TP)	50%	
Proposed repair cost	\$ 3,638.00	W/GST
Loss of use	\$ -	
Loss of rental	\$ 248.30	5days x \$99.32
Loss of income	\$ 125.00	5days x \$50
LTA search fees	\$ 7.49	
Others	\$ -	
Proposed Total	\$ 4,018.79	



<MANDATE IA> - S9M01EB7 {ACCIDENT INVOLVING SFV 807C (OI) & SHC 5891B (TP) ON 16/02/2019}

Type

🔗 Question

Message

LIABILITY: 50% CONFLICTING VERSION - INFORMED OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$4018.79 (CLAIMING LOR & LOI). MANDATE IA HAS BEEN UPLOADED IN SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION. THANKS - CCL
20/02/2020

Reply



**Re:<MANDATE IA> - S9M01EB7 {ACCIDENT INVOLVING
SFV 807C (OI) & SHC 5891B (TP) ON 16/02/2019}**

Type

Question

Message

MANDATE APPROVE \$3893.79 (ALL IN). EXCLUDED LOSS OF INCOME BECAUSE HAD SETTLED IN HIS
INJURY CLAIM VIA LAWYER. THANKS

Reply

Joy

Trans-Cab Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

Our Ref : AAD1902-141

Your Ref : SFV807C

LKK

Date : 10.April 2019

AXA INSURANCE S PTE LTD

Dear Sir/Madam,

ACCIDENT INVOLVING SHC5891B AND SFV807C ON 16/02/19 09:30 AM ALONG Sengkang East Avenue

It appears that the above accident was caused by your insured's negligence. We, therefore seeking compensation from you for our financial loss as itemized below :-

1.	Cost of Repair (inclusive of 7% GST)	\$	7,276.00
2.	Loss of Rental for <u>5</u> days @ \$ <u>99.32</u> per day	\$	496.60
3.	Loss of Income for <u>5</u> days @ \$ <u>50</u> per day	\$	250.00
4.	LTA Search Fee	\$	7.49
5.	Survey Fee	\$	0.00
	Total	\$	8,030.09

We enclose a copy of the following documents for your consideration :-

GIA report lodged by our driver

Rental rate and mileage records

Certificate of Insurance

Authorization To Act

Original final repair bill

LTA Search Fee

Kindly let us have the discharge voucher within the next 14 days, failing which we shall proceed to hand over the conduct of this matter to our solicitors without further reference to you.

Yours Faithfully

Trans-Cab Services Pte Ltd



Jasmine Tan

General Manager

Tel No. : 6603 1250 (DID)

Note : Please email any further correspondence to claims@transcab.com.sg (6603 1259)

Trans-Cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel: 6287 6666**Fax:** 6287 7764**Co. Reg. No.:** 201019626G**GST Reg. No.:** 201019626G**Tax Invoice / Debit Note**

TO: AXA INSURANCE PTE LTD 8 SHENTON WAY, #27-01 AXA TOWER 068811 SINGAPORE ATTENTION:	INVOICE NO. : INV1903-315 DATE : 31. March 2019 REFERENCE NO : AAD1902-141 TERMS : DUE DATE : 31. March 2019 PAGE : 1
--	--

NO.	CODE	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
1.	6050101	REPAIR-SHC5891B;DOA 16.02.19(LUMP SUM-19)	1	7,276.00	7,276.00

Total SGD Excl. GST :	6,800.00
7% GST :	476.00
Total SGD Incl. GST :	7,276.00

****** SEVEN THOUSAND TWO HUNDRED SEVENTY SIX SGD ONLY ******

- 1) All cheques should be crossed and made payable to "Trans-Cab Auto Services Pte Ltd"
- 2) Please quote our Invoice Number during payment.
- 3) We reserve the right to charge interest @ 1.5% per month on overdue invoice.
- 4) Any dispute as to the accuracy, charges etc of this invoice must be communicated within 10 days from the date hereof failing which it shall be deemed to have been unconditionally accepted.

E. & O. E.**THIS IS A COMPUTER GENERATED INVOICE WHICH REQUIRES NO SIGNATURE**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC3/ASM19003188/Kga3s2

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811
ATTN: CYNTHIA LOH

Date : 09-03-2020



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SFV 807C	Veh. Inspected	SHC 5891B
Policy No.	GA10555	Coverage (\$)	0.00
Claim No.	S9M01EB7	Excess (\$)	0.00
Assign From		Assign Date	19/02/2019

2. Vehicle Particulars & Condition

Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	VF1ABL15AUC280975	Colour	METALLIC WHITE / RED
Odometer	342030	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	GITI	9 mm
L/H Front Tyre	215/60 R16	GITI	9 mm
R/H Rear Tyre	215/60 R16	GITI	9 mm
L/H Rear Tyre	215/60 R16	GITI	9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	16/02/2019	Inspection Date	19/02/2019
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5891B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	DOOR PANEL FRT LH (CONSISTENT)	BENT	2,844.66	2,844.66
1	DOOR HINGE UPPER LH (CONSISTENT)	TO REPAIR SEE LABOUR	261.28	-
1	DOOR HINGE LOWER LH (CONSISTENT)	TO REPAIR SEE LABOUR	300.55	-
1	DOOR CHECK FRT LH (CONSISTENT)	SERVICEABLE	194.77	-
1	DOOR LOCK FRT LH (CONSISTENT)	TO REPAIR SEE LABOUR	908.75	-
1	DOOR CATCH FRT LH (CONSISTENT)	TO REPAIR SEE LABOUR	131.23	-
1	DOOR HANDLE OUTER FRT LH (CONSISTENT)	SERVICEABLE	477.76	-
1	DOOR HANDLE COVER FRT LH (CONSISTENT)	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE FRT LH (CONSISTENT)	SERVICEABLE	133.60	-
1	DOOR REGULATOR FRT LH (CONSISTENT)	TO REPAIR SEE LABOUR	505.19	-
1	DOOR REGULATOR MOTOR FRT LH (CONSISTENT)	TO REPAIR SEE LABOUR	796.46	-
1	DOOR REGULATOR GUIDE FRT LH (CONSISTENT)	SERVICEABLE	120.97	-
1	DOOR PANEL REAR LH (CONSISTENT)	BENT	2,844.66	2,844.66
1	DOOR GUIDE REAR LH (CONSISTENT)	SERVICEABLE	176.82	-
1	DOOR HINGE UPPER LH (CONSISTENT)	TO REPAIR SEE LABOUR	274.50	-
1	DOOR HINGE LOWER LH (CONSISTENT)	TO REPAIR SEE LABOUR	300.55	-
1	DOOR CHECK REAR LH (CONSISTENT)	SERVICEABLE	203.06	-
1	DOOR LOCK REAR LH (CONSISTENT)	TO REPAIR SEE LABOUR	908.75	-
1	DOOR HANDLE OUTER REAR LH (CONSISTENT)	SERVICEABLE	126.49	-
1	DOOR HANDLE CAP REAR LH (CONSISTENT)	SERVICEABLE	35.52	-
1	DOOR HANDLE SEAL REAR LH (CONSISTENT)	SERVICEABLE	7.89	-
1	DOOR HANDLE COVER REAR LH (CONSISTENT)	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE REAR LH (CONSISTENT)	SERVICEABLE	133.60	-
1	DOOR REGULATOR REAR LH (CONSISTENT)	TO REPAIR SEE LABOUR	1,135.10	-

Report Ref No. CC3/ASM19003188/Kga3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR REGULATOR MOTOR REAR LH (CONSISTENT)	SERVICEABLE	893.75	-
1	DOOR REGULATOR NUT REAR LH (CONSISTENT)	SERVICEABLE	12.43	-
1	DOOR REGULATOR MOTOR SCREW REAR L70Y (CONSISTENT)	SERVICEABLE	6.31	-
1	DOOR FINISHER REAR LH (CONSISTENT)	SERVICEABLE	423.10	-
1	DOOR MOULDING REAR LH (CONSISTENT)	SERVICEABLE	176.82	-
1	DOOR MOULDING CLIP L70Y (CONSISTENT)	NOT NECESSARY	5.92	-
1	DOOR MOULDING SCREW L70Y (CONSISTENT)	SERVICEABLE	6.91	-
1	DOOR CASING REAR LH (CONSISTENT)	SERVICEABLE	1,509.06	-
1	DOOR WATER SHIELD REAR LH (CONSISTENT)	SERVICEABLE	30.39	-
1	DOOR CASING CLIP (CONSISTENT)	NOT NECESSARY	12.63	-
1	DOOR CASING LIGHT L70Y (CONSISTENT)	SERVICEABLE	48.74	-
1	DOOR FINISHER INNER REAR LH (CONSISTENT)	SERVICEABLE	323.44	-
1	DOOR FINISHER BRACKET INNER REAR LH (CONSISTENT)	TO REPAIR SEE LABOUR	46.97	-
1	DOOR FINISHER BRACKET INNER REAR LH (CONSISTENT)	TO REPAIR SEE LABOUR	20.33	-
1	DOOR FINISHER BRACKET INNER REAR LH (CONSISTENT)	TO REPAIR SEE LABOUR	20.33	-
1	DOOR FINISHER BRACKET INNER REAR LH (CONSISTENT)	TO REPAIR SEE LABOUR	20.33	-
1	DOOR GRAB HANDLE REAR LH (CONSISTENT)	SERVICEABLE	210.96	-
1	DOOR BLIND REAR LH (CONSISTENT)	SERVICEABLE	741.80	-
1	DOOR WEATHERSTRIP REAR LH (CONSISTENT)	SERVICEABLE	410.66	-
1	DOOR SEAL REAR LH (CONSISTENT)	SERVICEABLE	162.02	-
1	DOOR GLASS RUNNER SEAL REAR LH (CONSISTENT)	SERVICEABLE	229.31	-
1	DOOR WAIST SEAL OUTER REAR LH (CONSISTENT)	SERVICEABLE	334.69	-
1	DOOR WAIST SEAL INNER REAR LH (CONSISTENT)	SERVICEABLE	115.64	-
1	DOOR MIRROR ASSY LH (CONSISTENT)	SERVICEABLE	1,483.40	-
1	ROCKER PANEL INNER GARNISH LH (CONSISTENT)	SERVICEABLE	466.51	-
1	ROCKER PANEL INNER LH (CONSISTENT)	TO REPAIR SEE LABOUR	1,024.79	-
1	ROCKER PANEL CENTER LH (CONSISTENT)	BENT	990.25	990.25
1	FENDER PANEL REAR LH (CONSISTENT)	TO REPAIR SEE LABOUR	3,299.13	-

Report Ref No. CC3/ASM19003188/Kga3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FENDER PANEL INNER TRIM REAR (CONSISTENT)	SERVICEABLE	671.45	-
1	WHEELARCH REAR LH (CONSISTENT)	SERVICEABLE	543.47	-
	LESS 10% DISCOUNT		-2,708.99	-667.96
			24,381.15	6,011.61
	SPECIAL NETT ITEMS			
1	SET FRAME FULL SUPPORT PANEL CLIP (SN) (CONSISTENT)	NOT NECESSARY	70.00	-
2	FRAME FULL SUPPORT PANEL NUT (SN) (CONSISTENT)	NOT NECESSARY	20.00	-
2	FRAME FULL SUPPORT PANEL STUD (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
1	SET WHEELARCH CLIP FRT LH (SN) (CONSISTENT)	NOT NECESSARY	30.50	-
1	FRONT DOOR STICKER 'TRANS-CAB' (SN) (CONSISTENT)	NECESSARY	80.00	60.00
1	FRONT DOOR STICKER 'CLASSIC' (SN) (CONSISTENT)	NECESSARY	50.00	15.00
1	REAR DOOR STICKER '6555 3333' (SN) (CONSISTENT)	NECESSARY	80.00	60.00
1	DOOR CHECK BOLT (SN) (CONSISTENT)	SERVICEABLE	22.69	-
1	DOOR GUIDE SCREW (SN) (CONSISTENT)	SERVICEABLE	10.85	-
1	DOOR HINGE BOLT (SN) (CONSISTENT)	SERVICEABLE	10.85	-
1	DOOR HINGE NUT RH (SN) (CONSISTENT)	SERVICEABLE	14.60	-
1	DOOR CHECK BOLT (SN) (CONSISTENT)	SERVICEABLE	22.69	-
1	DOOR CHECK NUT (SN) (CONSISTENT)	SERVICEABLE	3.75	-
1	DOOR LOCK SCREW L70Y (SN) (CONSISTENT)	SERVICEABLE	6.12	-
1	DOOR CATCH SCREW L70Y (SN) (CONSISTENT)	SERVICEABLE	10.06	-
1	LEFT REAR RIM (SN) (CONSISTENT)	SERVICEABLE	380.00	-
1	LEFT REAR TYRE (SN) (CONSISTENT)	SERVICEABLE	330.00	-
			1,172.11	135.00
	LABOUR			
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF DOOR HINGE UPPER LH, DOOR HINGE LOWER LH, DOOR LOCK FRT LH, DOOR CATCH FRT LH, DOOR REGULATOR FRT LH, DOOR REGULATOR MOTOR FRT LH, DOOR LOCK REAR LH, DOOR REGULATOR REAR LH, DOOR FINISHER BRACKET INNER REAR LH, ROCKER PANEL INNER LH AND FENDER PANEL REAR LH.		4,200.00	800.00

Report Ref No. CC3/ASM19003188/Kga3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		4,200.00	1,100.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	90.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.		380.00	80.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		220.00	60.00
	TO TRANSFER OF FRONT BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		380.00	80.00
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO TRANSFER OF FRONT FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF FRONT DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		380.00	60.00
	TO TRANSFER OF REAR DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		380.00	60.00
			11,410.00	2,350.00
	GRAND TOTAL		36,963.26	8,496.61
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,800.00

Report Ref No. CC3/ASM19003188/Kga3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.