

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5891B**AAD1902-141**

Not Authorised
11 Rm 868001

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHC 5891B

VF1ABL15AUC280975

RENAULT

LATITUDE

16.2.2019

AXA

18/12/2014

PART**LIST**

1	DOOR PANEL FRT LH	\$	B1 2,844.66 ✓
1	DOOR HINGE UPPER LH	\$	N 261.28
1	DOOR HINGE LOWER LH	\$	N 300.55
1	DOOR CHECK FRT LH	\$	S2 194.77
1	DOOR LOCK FRT LH	\$	N 908.75
1	DOOR CATCH FRT LH	\$	N 131.23
1	DOOR HANDLE OUTER FRT LH	\$	S2 477.76
1	DOOR HANDLE COVER FRT LH	\$	S2 13.22
1	DOOR HANDLE MODULE FRT LH	\$	S2 133.60
1	DOOR REGULATOR FRT LH	\$	N 505.19
1	DOOR REGULATOR MOTOR FRT LH	\$	N 796.46
1	DOOR REGULATOR GUIDE FRT LH	\$	S2 120.97
1	DOOR PANEL REAR LH	\$	B1 2,844.66 ✓
1	DOOR GUIDE REAR LH	\$	S2 176.82
1	DOOR HINGE UPPER LH	\$	N 274.50
1	DOOR HINGE LOWER LH	\$	N 300.55
1	DOOR CHECK REAR LH	\$	S2 203.06
1	DOOR LOCK REAR LH	\$	N 908.75
1	DOOR HANDLE OUTER REAR LH	\$	S2 126.49
1	DOOR HANDLE CAP REAR LH	\$	S2 35.52
1	DOOR HANDLE SEAL REAR LH	\$	S2 7.89
1	DOOR HANDLE COVER REAR LH	\$	S2 13.22
1	DOOR HANDLE MODULE REAR LH	\$	S2 133.60
1	DOOR REGULATOR REAR LH	\$	N 1,135.10
1	DOOR REGULATOR MOTOR REAR LH	\$	S2 893.75
1	DOOR REGULATOR NUT REAR LH	\$	S2 12.43
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	S2 6.31
1	DOOR FINISHER REAR LH	\$	S2 423.10
1	DOOR MOULDING REAR LH	\$	S2 176.82

Trans-cab Auto Services Pte Ltd

AAD1902-141

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5891B

1	DOOR MOULDING CLIP L70Y	\$	na	5.92	}
1	DOOR MOULDING SCREW L70Y	\$	sn	6.91	
1	DOOR CASING REAR LH	\$	sn	1,509.06	
1	DOOR WATER SHIELD REAR LH	\$	sn	30.39	
1	DOOR CASING CLIP	\$	na	12.63	
1	DOOR CASING LIGHT L70Y	\$	sn	48.74	
1	DOOR FINISHER INNER REAR LH	\$	sn	323.44	
1	DOOR FINISHER BRACKET INNER REAR LH	\$	n	46.97	
1	DOOR FINISHER BRACKET INNER REAR LH	\$	n	20.33	
1	DOOR FINISHER BRACKET INNER REAR LH	\$	n	20.33	
1	DOOR FINISHER BRACKET INNER REAR LH	\$	n	20.33	
1	DOOR GRAB HANDLE REAR LH	\$	sn	210.96	
1	DOOR BLIND REAR LH	\$	sn	741.80	
1	DOOR WHEATHESTRIIP REAR LH	\$	sn	410.66	
1	DOOR SEAL REAR LH	\$	sn	162.02	
1	DOOR GLASS RUNNER SEAL REAR LH	\$	sn	229.31	
1	DOOR WAIST SEAL OUTER REAR LH	\$	sn	334.69	
1	DOOR WAIST SEAL INNER REAR LH	\$	sn	115.64	
1	DOOR MIRROR ASSY LH	\$	sn	1,483.40	}
1	ROCKER PANEL INNER GARNISH LH	\$	sn	466.51	
1	ROCKER PANEL INNER LH	\$	n	1,024.79	
1	ROCKER PANEL CENTER LH	\$	sn	990.25	
1	FENDER PANEL REAR LH	\$	n	3,299.13	
1	FENDER PANEL INNER TRIM REAR	\$	sn	671.45	
1	WHEELARCH REAR LH	\$	sn	543.47	

\$ 27,090.1410% **\$ 2,709.01****\$ 24,381.13****Specical Nett**

1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00	X
2	FRAME FULL SUPPORT PANEL NUT	\$	na	20.00	X
2	FRAME FULL SUPPORT PANEL STUD	\$	na	30.00	X
1SET	WHEELARCH CLIP FRT LH	\$	na	30.50	X
1	FRONT DOOR STICKER 'Trans-cab'	\$	na	80.00	60sn
1	FRONT DOOR STICKER 'Chassis'	\$	na	50.00	15sn
1	REAR DOOR STICKER '6555 3333'	\$	na	80.00	60sn

Trans-cab Auto Services Pte Ltd

AAD1902-141

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5891B

1	DOOR CHECK BOLT	\$	S ₂ 22.69	}	X
1	DOOR GUIDE SCREW	\$	S ₂ 10.85		
1	DOOR HINGE BOLT	\$	S ₂ 10.85		
1	DOOR HINGE NUT RH	\$	S ₂ 14.60		
1	DOOR CHECK BOLT	\$	S ₂ 22.69		
1	DOOR CHECK NUT	\$	S ₂ 3.75		
1	DOOR LOCK SCREW L70Y	\$	S ₂ 6.12		
1	DOOR CATCH SCREW L70Y	\$	S ₂ 10.06		
1	LEFT REAR RIM	\$	S ₂ 380.00		
1	LEFT REAR TYRE	\$	S ₂ 330.00		
TOTAL		\$	1,172.13		

TOTAL PARTS	\$	25,553.26
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,200.00	800L
Putty and spray painting of the affected portion.	\$	4,200.00	1100L
To rust-proofing of the affected areas.	\$	170.00	90L
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	80L
To check steering geometry and computer wheel alignment	\$	220.00	60L
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	380.00	nn X
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	380.00	80L
To transfer of tire, rim and on wheel balancing.	\$	170.00	nn X
To Check Electrical Lighting Concerned.	\$	170.00	20L

Trans-cab Auto Services Pte Ltd**AAD1902-141**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5891B

To transfer of front fender fittings, attachment and
perform water seepage test.

\$ *in* 380.00 *X*

To transfer of front door fittings, attachment and
perform water seepage test.

\$ 380.00 *bol*

To transfer of Rear door fittings, attachment and
perform water seepage test.

\$ 380.00 *bol***TOTAL \$ 11,410.00****Over All Total \$ 36,963.26****LUMP SUM (REPAIR DAY)****~~20~~ DAYS***6 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: