Menmen From Ferson	Rauline Tham	ASSIGNM	HENT (Office MS(&		nte/Time 19/2/19@ 4-45F
Estimated Co	at		Bill to:		
To Inspect V	S/TP RES / OD RES /	8kk 910		Insured:	SLA 6936E
at Workshop		Massive -	ruding.	Tel:	91082728
of	BIC 5038 # 01	405 Ind - 1	role 2		
Policy No:_	29071835QM	×	Claim No:		
Sum Insured			Excess:		
Make of Veh (Client's Recor				D.	O.A 17/02/2019
CA / REV	REP. / REV 24 HRS				ILO.D. Enderstment:
Date/Time	2 2 days	Person Contacted:	Ante		ici Nour
Date/Time	Side 9105] -		e		
	814 6956E-1				DOA: 18/3/2016

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

LAIM SUB	FOLDER TRA	CKING								
Case:	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Sat	mitted	Ins Autroed	Status		
Main	18 Feb 2019		19 Feb 2019 16:45 Assign					gotesennistic	New Assignment Cancel Case	
	Main	Re	ference		Claim Details		Docume	nts	Sh	IIA wor
CLAIM SU	BFOLDER DE	TAILS				[Create	ed by insurer]			-
Insured:	Chan Eng	Leong Edwin,	D: S1698061G							
Main Claimant:	LIN JIAN	NING, ID: 5707	6148C							
Vehicle Reg No.:	SKK910	K9105J			Date of Loss:		019 15:00 - :59 oths and 5 Days F	rom LTA Re	g Date (Mar	n Yr)]
Claim Type	: TP				Policy/Cover Note No.:	29071835QMX Coverage: 11/03/2018 - 10/03/2019				
Vehicle Reg No. (Insured):	SLA69561	E			Policy No. (Claimant):					
					Excess:					
Repairer:	Massive T	rading & Auto ()	Blk 5038 #01~	405, Ang Mo	Kio Industrial P	k 2, 5695	41 Ang Mo Kio - Ti	el:		
Handling Insurer:	MSIG Ins	urance (Singapo	re) Pte. Ltd. (H	(Q) - Tei: +	65 6827 7888	[Handled	by Pauline Than	n - 6594 2	545]	
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel:	6256-3561	[Imm.Adv	ice due	20/02/2019]			
Adj Asg. Remarks:	Unable to 2728 Anth	comment on liabili ony	ty. OI reported t	o wrong insi	urer. TP agree wi	th SJE - a	ssign LKK Auto Co	onsultants i	Pte Ltd. cont	tact: 910
ASSOCIAT	TED MAIL RE	CEIVED						View All	Compose 0	Case Mail
There are n	no mail for this	case.								
ALL ASSO	CIATED TAS	ks∃				View A	II Search Tasks	I contra	iew Task	Complete

Completed On

Created On

Due Date Priority Type Task Group Subject Handler Assigned By

No results.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Pauline Tham Attn:

Date: 21 Feb 2019

Preliminary Advice

Insured Vehicle No : SLA6956E

TP Vehicle No

: SKK9105J

Accident Date

: 17/02/2019

Make

: FORD FOCUS

Assignment Date

: 19/02/2019

Date of Inspection

: 19/02/2019

Est. Duration of Repair

: 4 days

Inspection At

: Massive Trading & Auto

Blk 5038 #01-405, Ang Mo Kio Industrial Pk 2

Singapore 569541

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,301.00
Revised Amount	:S\$	3,598.60
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,598.60
Lump Sum Repair	:S\$	2,800.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

- Pre repair inspection request - SLF695X VS GBD3069M (OI) DOA: 30/08/2018

From: Aplen, Byazardina

To. admin a@likkauto.com, assignments@likkautis.com

Dr. Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Manesa, Md Ishak, Mohd Invan, Lim, Sheng Yang, Mithoosingh, Asshweenjeetkaur, Chan, Yoke Shi, Kaur, Baljit, Hur, Yinnul

Sent: 15/2/2019 2 14:19 PM 1mi/5372.tif

Attach

HL.

Please refer to the enclosed request from CK TEO & CO.

Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know. Kindly assist to assign Kenneth Kong as Single Joint Expert as requested.

Thanks and regards.

Syaza Intina Azlan

AIG

Express Claims Adjuster H. Singapore FNOL: Claims Operations - Auto

SG Claims Operations. | AlG Shared Services

Systemina Azien@percom I www.arp.so

From: Willow Tueng [mailto:wtueng@gmail.com]

Sent: Friday, February 15, 2019 1:03 PM

To: Azlan, Systairdina

Subject: Re: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GB03069M AND SLF695X ON 30/08/2018

Dear Sir / Mdm

We refer to your email of even date.

We are agreeable of appointing KENNETH KONG (LKK AUTO) as a Single Joint Expert.

Our client's vehicle is available for pre-repair survey at:

Venue	7	Guan Motor Works 176 Sin Ming Drive #02-03 Sin Ming AutoCare	
		Singapore 575721 Tel: 6453 6111 (AH HENG)	

Error! Filename not specified.Regards

Tuang Willow CK TEO & CO Tel: 65354788

Fax: 65354245

On Fri, Feb 15, 2019 at 10:50 AM Azian, Systaintina Systaictina Azian@aig.com> wrote:

This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息、如要阅读此信息、请开启时件、

นี้คือภารรักษาครามปลอดภัยชื่อความที่เข้าหรือลับ เพื่อสานปนให้เปิดใหม่ที่ SALES T

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 침부 파일을 입니다.

ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

Click here by 2019-02-22 10:49 +08 to read your message. After that, open the attachment.

Disclaimer: This remail and its interest are autilitized and intended solely for the use of the minimum. Force confly the conductify prochare increased this aread in contact prophysicists

Secured by Produces European, Copunglis & 2009-3017 Produces, mr. All rights

The information in this armail (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this small in error, please intrinsialistly notify me by "Repty" command and any attachments are believed to be fixe of any virus or other defect that might affect any computer system into which it is received and operate, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage are raising in any why from its use.

From: Byazartine Azien@aig.com
To: whiterp@grad.com
Co: Andy-5Y-Feng@aig.com LeeYing Chin@aig.com , NoorMariesa AbuKassim@aig.com , imran.lshak@aig.com ,ShangYang Lim@aig.com ,Azshwaanjaetiaur.Mithocangh@aig.com ,yekeshi.chan@aig.com ,Baijit.Kaun@aig.com ,Yin
Bubyect.AIGENCRYFT - FRE-REPAIR INSPECTION - ACCIDENT INVOLVING DUR INSURED VEHICLE GROSSISM AND SLFISSX ON 30Y08/2018
Date: Fri. 15 Feb 2019 02:49:50 +0000

Without Prejudice

Your Reference Our Reference

SLF695X GBD3069M

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor aurveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Loni	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards,

Systa Irdina Azian

AIG

Express Claims Adjuster II, Singapore FNOL, Claims Operations - Auto

SG Clams Operations | AlG Shared Services

Systambra Acandhag con: I now ag so

From: Chin, Ann

Sent: Thursday, February 14, 2019 3:28 PM

To: PRDSG.FNOL

Cc: Azlan, Syazairdina; Abu Kassim, Noor Mariesa; Lim, Sheng Yang; Chan, Yoke Shi; Mithoosingh, Aashweenjeetkaur; Md Ishak, Mohd Imran; Ho, Choon-Poh; Tan, Lily (AIG);

Quek, Joyceline-CH; Zhou, Alping; Hor, Yinrul Subject: 05#G8D3069M#00Z,00Z#DEFAULT

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

design to the second second	ACCIDENT STATEMENT
Date Of Report	17/02/2019 18:29
Date Of Accident	17/02/2019 15:00
Exact Location Of Accident	NEWTON CIRCLE
Country/State of Loss	SINGAPORE
D	ETAILS OF OWN VEHICLE
Vehicle Registration Number	SKK9105J
Insured/Policyholder	
Name Of Registered Owner	LIN JIANNING
NRIC No	S7076148C
Email Address	JIANNINGLIN@GMAIL.COM
Mobile Phone No	(LOCAL) +65-87220981
Alternative Phone No	OFFICE-87220981
Vehicle Particulars	AND RESIDENCE OF THE PARTY OF T
Manufacturer	FORD
Model	FOCUS 1.6
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	the second state of the second state of
Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE, LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MTPV01015320
Cover Note Number	
Driver	
Name of Driver	LIN JIANNING
NRIC No	S7076148C
Date Of Birth	13/05/1970
Occupation	INDOOR
Date Of Driving Pass	11/09/1997
Driving Experience	21 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87220981
Fax Number	
Contact Number	OFFICE-87220981
EMail Address	JIANNINGLIN@GMAIL.COM

Address

NIL

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

...

Insurance Company of Driver's Own Vehicle

.

General Information of the Accident

Type Of Accident

COLLISION - ROUNDABOUT

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

2

involved in the accident

....

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

Passenger 1

NAME:

: LIN PEI RONG

GENDER:

FEMALE

Passenger 2

NAME:

: LUCY LIN

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police?

NO

if Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

I was travelling from Newton Road onto Newton Circle. The traffic was clear. I was on the second lane from the left. When I was in the Newton circle roundabout, I wanted to exit to Bukit Timeh Road. In the middle of Scott's Road exit, this vehicle SLA6956E from the right lane suddenly drove fast and cut onto my lane to exit Scott's Road. This caused the collision on my front right portion and his passenger rear left portion. Damages to my car were on the right front portion. No Injuries were involved.

Attachment(s)

Are accident photos available for attachment?

YES YES

Was there any video captured by Car Camera?

PENDING VIDEO FROM INSURED

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLA6956E

Vehicle Make/Model/Colour

HONDA / VEZEL 1.5X A / WHITE

Details Of Properties

Remarks/ Reasons:

Vehicle Category

PRIVATE CAR

Name of Driver

CHAN ENG LEONG EDWIN

NRIC/Passport Number

S1698061G

Contact Number

97424697

Address


Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan



A CONTRACTOR AND ADMINISTRATION ADMINISTRATION AND	NAME AND ADDRESS OF THE OWNER, AS NOT THE OWNER, THE PARTY OF THE OWNER, THE PARTY OF THE OWNER, THE PARTY OF THE OWNER,	The state of the s	CONTRACTOR OF STREET
ACCIDENT	STATEMENT	(2000 4	haractara
RECUIDER	SIMILMENT	12000 6	

was travelling from Newton Road onto Newton Circle. The traffic was clear. I was on the second lane from the left. When I was in the Newton circle roundabout, I wanted to sit to Bukit Timah Road. In the middle of Scott's Road exit, this vehicle SLA6956E om the right lane suddenly drove fast and cut onto my lane to exit Scott's Road. This aused the collision on my front right portion and his passenger rear left portion. amages to my car were on the right front portion. No injuries were involved.
Taxi Voucher No.:

DECLARATION

IWe declare that the above particulars & information provided above are true in every espect

VERIFIED BY AJAX MARS REPORTING OFFICER -MUHAMMAD FIRZA BIN IDERIS

1-/-

MARS Officer

Registered Owner or Driver's Signature

Job Complete Date/Time

Date/Time:

17 February 2019 at 5:40 PM

17 February 2019 at 5:40 PM

Massive Trading & Auto
Mailing address: Blk 225 #07-579 Ang Mo Kio Ave 1 Singapore 560225

H/p 91082728

Lin Jianning 8 Alexandra View #38-10 Singapore 158747

Vehicle No : SKK 9105 J

Make Year

: Ford Focus

2016

Ave 1 SingaponSurvey 14/2/2019
Not Motheries
Ulling & 28och
4ctors

Qty	Description	Unit Price	Amount
Estimate	Cost Of Repair	4.1	
1 pc 1 pc 1 pc 1 pc 1 pc 1 pc 1 pc	Front o/s headlamp assy Front o/s fender Front bumper Front o/s bumper side retainer Front o/s shock absorber Front o/s lower arm Front o/s kunckle arm	Š	\$850.00 \$650.00 \$1,445.00 \$75.00 \$581.00 x \$833.00 x \$726.00 x
S Nett		Less 15% 201	\$5,160.00 \$774.00 \$4,386.00
1 pc 10 pcs	Front o/s tyre rim / Rear bumper clip	\$2.50	\$350.00 \$25.00 \$375.00
Labour C	harges		
Remove/	renew the above parts including knocking, welding etc.		\$700.00 40
To putty	& spray paint front accident affected portion.		\$700.00 40 \$700.00 40
To check	and reconnect wiring.		\$40.00 2
To spray	anti rust on accident affected portion.	Total	\$100.00 3 2 \$6,301.00

LKK Auto Consultants hence notify the Repairer of the following:

. To resurvey before/after spray painting . To display damaged part(s) during resurvey . Parts prices are subject to confirmation . Third party survey is on a "Without Prejudice" basis. . No illegal modification(s) is allowed . Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status	
Main	18 Feb 2019		19 Feb 2019 16:45 Edit Adj Rpt	S\$2,800.00 Edit Estimates	\$\$2,800.00 View Rpt		Pending for Report Cancel Car	10
,	tain)[R	eference	Claim De	etails	Documents		Show All
CLAIM SU	BFOLDER DE	TAILS			[Created	by insurer]		
Insured:	Chan Eng	Leong Edwin,	ID: S1698061G		102111111111111111111111111111111111111			
Main Claimant:	LIN JIAN	NING, 1D: S70	76148C					
Vehicle Reg. No.:	SKK910	53		Date o		9 14:00 - :59 s and 5 Days Fron	n LTA Reg Date	(Man Yr)]
Claim Type:	TP / 585	570		Policy/ Note N		29071835 (Comprehensive) Coverage: 11/03/2018 - 10/03/2019		
Vehicle Reg. No. (Insured):	SLA69561	ı		Policy (Claim				
				Excess				
Repairer:	Massive T	rading & Auto () Blk 5038 #01-405	, Ang Mo Kio Indus	trial Pk 2, 569541 A	ing Ma Kio - Tel:		
Handling Insurer:	MSIG Ins	urance (Singapo	ore) Pte. Ltd. (HQ)	- Tel: +65 6827 7	888 [Handled by	Pauline Tham -	6594 2545]	
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 62	56-3561 [Handle	ed by KENNETH KO	NG] [Final I	Rpt due 21/0	3/2019]
Adj Asg. Remarks:	Unable to 2728 Anth		ity. OI reported to v	rrong Insurer. TP ag	ree with SJE - assignment	n LKK Auto Consi	ultants Pte Ltd.	contact: 91
ASSOCIAT	ED MAIL RE	CEIVED				Vie	w All Compe	se Case Mai
There are no	mail for this	case.						
ALL ASSO	CIATED TAS	ks⊟			View All	Search Tasks C	reste New Task	Complete
Due Date	Priority	Type Tasi	Group Subjec	t Handler	Assigned By	Completed On	Created C	

Claim Documents

*SKK9105J (585570) [SLA6956E] TP LIN JIANNING Feb 17 2019 2:00PM [Chan Eng Leong Edwin] Massive Trading & Auto

135	Vipad Documents Up	oload Photos Compose New Letter	View	View in Brows	Ser V
Ass	essment Reports		1 per	page V	V
Νo	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnall	Print
1	21/02/19 15:51	Adjuster Immediate Advice	0	Load HTM	
Pho	itos/Images		3 per p	page: V	V
Nα	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	21/02/19 15:53	General View	0	Load JPG	V
2	21/02/19 15:53	General View	0	Load JPG	V
3	21/02/19 15:53	General View	0	Load JPG	Z
4	21/02/19 15:53	General View	0	Load JPG	V
5	21/02/19 15:53	General View	0	Load JPG	V
6	21/02/19 15:53	General View	0	Load 3PG	V
7	21/02/19 15:53	General View	0	Load JPG	V
8	21/02/19 15:53	General View	0	Load JPG	V
9	21/02/19 15:53	General View	0	Load JPG	V
10	21/02/19 15:53	Odometer Reading	0	Load JPG	V
11	21/02/19 15:53	General View	0	Load JPG	150
12	21/02/19 15:53	Chassis Number	0	Load JPG	V
13	21/02/19 15:53	General View	0	Load JPG	8
14	21/02/19 15:53	General View	0	Load JPG	V
Doc	umentation		1 per p	age 🔻	1
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	-
1	19/02/19 11:36	TP PRI NOTICE AND GIA REPORT	0	Load PDF	
2	19/02/19 11:37	tp agree SJE - assign LKK	0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save	Print
There are no document checklists configured.		
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)		
		0
		V
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.		

LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607198R)

51 Ubi Ave 1 #01-25. Pava Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

Date:

22/02/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

29071835

Claimant Vehicle Date of Loss:

SKK9105J

Insured Vehicle No:

SLA6956E

17/02/2019

Nature of Claim:

TP

Claim No: 585570

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SKK9105J

Make & Model:

FORD FOCUS, 1.6 TREND WAGON (A)

Engine No:

DR01501

63833 km

CS/MSG19003189/KSD3Q2

Reg. Date:

12/09/2013 (Man. Year: 2013)

Chassis No: Odometer:

WF0LXXGCBLDR01501

Colour

White

Engine Capacity: 1596 cc

Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Pre-accident Condition:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Engine Modification:

205/55 R16

Front Tyre Size: Front Left Side:

205/55 R16 Continental 7 mm

Rear Tyre Size: Rear Left Side:

Continental 7 mm

Front Right Side:

Continental 7 mm

Rear Right Side:

Continental 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		4,761.00	2,748.60	2,012.40	42.27
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,540.00	850.00	690.00	44.81
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	6,301.00	3,598.60	2,702.40	42.89
	Approved Total (Overridden) (S\$)		2,800.00		
	Nett Amount (S\$)	6,301.00	2,800.00	3,501.00	55.56

INSPECTION

Date of Assignment:

19/02/2019

Date Inspected:

19/02/2019 Inspected At:

Massive Trading & Auto

Blk 5038 #01-405, Ang Mo Kio Industrial

Pk 2

Singapore 569541

Estimated Period of Repair:

4.0 days

Adjuster: KENNETH KONG

Manager:

Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 21 Feb 2019)

Parts: N/A FORD FOCUS 1.6 TREND WAGON (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKK9105J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT O/S HEADLAMP ASSY	Mtg Cracked	850.00 FL	*850.00 FL
2	1		*FRONT O/S FENDER	Bent	650.00 FL	*650.00 FL
3	1		*FRONT BUMPER	Buckled / Dented	1,445.00 FL	*1,392.00 FL
4	1		*FRONT O/S BUMPER SIDE RETAINER	Distorted	75.00 FL	*75.00 FL
5	1		*FRONT O/S SHOCK ABSORBER	Serviceable	581.00 FL	*-FL
6	1		*FRONT O/S LOWER ARM	Serviceable	833.00 FL	*-FL
7	1		*FRONT O/S KNUCKLE ARM	Serviceable	726.00 FL	*-FL
8	1		*FRONT O/S TYRE RIM	Dented	350.00 FS	*350.00 FS
9	10		*REAR BUMPER CLIP	Necessary	25.00 FS	*25.00 FS
F=Fr	anchise	part. S=Spcf	Nett. L=ListItemDisc.			
				Sub Total (S\$)	5,535.00	3,342.00
	- List Item Discount on L Items 15.00/20.00% (S\$)			774.00	593.40	
				Total Parts (S\$)	4,761.00	2,748.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	REMOVE /RENEW THE ABOVE PARTS INCLUDING KNOCKING ,WELDING ETC	New	700.00	400.00
2	TO PUTTY & SPRAY PAINT FRONT ACCIDENT AFFECTED PORTION	New	700.00	400.00
3	TO CHECK AND RECONNECT WIRING	New	40.00	20.00
4	TO SPRAY ANTI RUST ON ACCIDENT AFFECTED PORTION	New	100.00	30.00
	Gross Labou	ır Cost (S\$)	1,540.00	850.00

< END OF ESTIMATES >

Report was unsubmitted during this print-out.