

MOVA Automotive Pte Ltd
Blk 1008, Bukit Merah Lane
3, #01-04/06/08. Singapore
159722

Claim Reference:
Assessment number: CK134097
Version: 1810
Date calculated: 02/19/2019 03:42 PM

Full Report
Registration: SKL7931Z
Printed: 19/02/2019 3:43 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	Tan SG	Currency:	SGD
Claim Reference:		Date of Incident:	2019-02-19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer: VW
 Model: JETTA (162)
 Sub Model: BASE MODEL
 Model Sheet Number: 06 C1 01
 Registration: SKL7931Z
 VIN number:
 Odometer:

Model Specs

ULTRASONIC PARK SYS TWO COAT METALLIC PAINTING OFF VEHICLE

Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
66 76 19 50	R + R L/R WHEELHOUSE SHELL (WHEEL REMOVED)		2.0	9.00
66 76 19 50	R + R R/R WHEELHOUSE SHELL (WHEEL REMOVED)		2.0	9.00
55 90 19 50	R + R BOOT LID (BOOT LID TRIM REMOVED) INCLUDES: ADJUST BOOT LID		5.0	22.50
55 90 55 50	RENEW BOOTLID (BOOTLID REMOVED) INCLUDES: R + R ALL PARTS		5.0	22.50
55 91 20 50)	R + R BOTH BOOTLID HINGES (BOOTLID REMOVED)		4.0	18.00
70 87 19 00	R + R BOOTLID TRIM		2.0	9.00
53 82 19 50	R + R REAR BUMPER CARRIER		2.0	9.00
63 69 19 00	R + R REAR BUMPER COVER (TAILLAMPS REMOVED)		3.0	13.50
63 69 55 53	RENEW REAR BUMPER COVER (REMOVED)		3.0	13.50

MOVA Automotive Pte Ltd
Blk 1008, Bukit Merah Lane
3, #01-04/06/08. Singapore
159722

Claim Reference:
 Assessment number: CK134097
 Version: 1810
 Date calculated: 02/19/2019 03:42 PM

Full Report
 Registration: SKL7931Z
 Printed: 19/02/2019 3:43 PM

Code	Description	WU	Price SGD
	INCLUDES: R + R PARKING AID SENSORS		
NO NUMBER	R + R REAR CARRIER (REAR BUMPER COVER REMOVED)	2.0	9.00
55 55 19 ZAX	R + R REAR LOWER LOCK (LOCK CARRIER COVER REMOVED)	1.0	4.50
70 30 19 50	R + R LUGGAGE BOOT COVER	1.0	4.50
94 31 20 00	R + R BOTH TAIL LAMPS	3.0	13.50
72 49 19 00	R + R REAR SEAT CUSHION	2.0	9.00
NO NUMBER	R + R LEFT REAR WHEEL HOUSE TRIM	1.0	4.50
NO NUMBER	R + R RIGHT REAR WHEEL HOUSE TRIM	1.0	4.50
44 05 19 00	R + R REAR WHEEL (WHEELS)	2.0	9.00
2711	REAR PANEL REPAIR ?	35.0*	157.50
Labour Cost		Hrs	WU
Panel / Mechanical Labour		7.60	76.0
Total of Labour			342.00

Paint

Paint Work		Time Basis 10WU/h	
Code	Description - TWO COAT METALLIC	WU	Price SGD
63 69 61 50	REAR BUMPER NEW PART PAINT S1	13.0	58.50
91 75 61 60	R/OUT ULTRASONIC SEN NEW PART PAINT S1	1.0	4.50
91 75 61 60	L/INN ULTRASONIC SEN NEW PART PAINT S1	1.0	4.50
55 90 61 50	BOOTLID/TAILGATE NEW PART PAINT S1	13.0	58.50
53 05 79 03	REAR PANEL REPAIR PAINT S3	13.0	58.50
53 55 79 04	L/R SIDE PANEL REPAIR PAINT S4	19.0	85.50
53 55 79 04	R/R SIDE PANEL REPAIR PAINT S4	19.0	85.50
91 75 61 52)	ADD/TIME FOR ONE MAIN WORK NEW PART PAINTING S1 FOR PARKING AID SENSOR	4.0	18.00
51 01 71 33	PAINTING PREPARATION WORK STAGE S3 METAL, PLASTIC S3 (PART/ S FITTED)	19.0	85.50
51 01 71 93	PREPARATION FOR PAINT (PLASTIC PARTS) (ASSEMBLY OPERATION)	2.0	9.00
Total Paint		Hrs 10.40	WU 104.0
			Price SGD 468.00

Spare Parts

MOVA Automotive Pte Ltd
Blk 1008, Bukit Merah Lane
3, #01-04/06/08. Singapore
159722

Steve (CLKK) 8322 8813 stevechen@kkkato.com
 20/3/19 2pm
 with projudice
 L/S
 4 days
 Resy Af spy

Claim Reference:
 Assessment number: CK134097
 Version: 1810
 Date calculated: 02/19/2019 03:42 PM

Full Report
 Registration: SKL7931Z
 Printed: 19/02/2019 3:43 PM

Code	Description	Part Number	Supplier	prices as at 2015-06-01 Price SGD
2583	REAR BUMPER	5C6 807 421 / GRU	00	560.00
2607	REAR BUMPER SPOILER	5C6 807 433 / GRU	00	340.00
2609	RR BUMPER FILLING	5C6 807 251	?	90.00
2617	L/R BUMPER GUIDE	5C6 807 393 B	?	60.00
2618	R/R BUMPER GUIDE	5C6 807 394 B	?	60.00
2619	L/R OUT BUMPER BRKT	5C6 813 745	?	45.00
2620	R/R OUT BUMPER BRKT	5C6 813 745	?	45.00
2640	REAR BUMPER SUPPORT	5C6 807 305	?	290.00
2645	RR BUMPER MOULDING	5C6 807 863	?	160.00
2782	R/OUT ULTRASONIC SEN	1S0 919 275 C / GRU	NEC	250.00
2783	L/INN ULTRASONIC SEN	1S0 919 275 C / GRU	NEC	250.00
2787	L/R OUT SENSOR BRKT	5C6 919 491	X	0.00
2788	R/R OUT SENSOR BRKT	5C6 919 491	X	0.00
2789	L/R INN SENSOR BRKT	5C6 919 492	X	0.00
2790	R/R INN SENSOR BRKT	5C6 919 492	X	0.00
2931	BOOTLID/TAILGATE	5C6 827 025 A	X R	850.00
2953	L/BOOTLID HINGE	5C6 827 301 B	X	90.00
2954	R/BOOTLID HINGE	5C6 827 302	X	90.00
2979	REAR BADGE -VW-	5C6 853 630 E / ULM	NEC	65.00
3284	R/R INNER LAMP	5C6 945 094 A	X	140.00
3417	L/R REFLECTOR	5C6 945 105 A	X	38.00
3418	R/R REFLECTOR	5C6 945 106 A	X	38.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			3,461.00
u: Used parts	Addition(+15.00%)			519.15
	Total			3,980.15

Extras

Code	Description	Price SGD
1000	NO PLATE NO PLATE / CUT	35 45.00*
	Total Extras	45.00

MOVA Automotive Pte Ltd
Blk 1008, Bukit Merah Lane
3, #01-04/06/08. Singapore
159722

Claim Reference:
 Assessment number: CK134097
 Version: 1810
 Date calculated: 02/19/2019 03:42 PM

Full Report
Registration: SKL7931Z
Printed: 19/02/2019 3:43 PM

Final Calculation

	SGD	SGD
Parts	3,461.00	
Addition(+15.00%)	519.15	
Total Parts		3,980.15
Labour Time Base 10 WU/h		
Total 76.0 WU X 45.00 SGD/h	342.00	
Total of Labour		<i>391</i> 342.00
Total Of Extras		45.00
Paint Work Time Base 10 WU/h		
Labour Cost 104.0 WU X 45.00 SGD/h	468.00	
Total Paint Including Material		<i>400</i> 468.00
Repair Cost Excludes GST		4,835.15
GST (+7.0%)		338.46
Repair Cost Included GST		5,173.61

Comments

- * - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
-) - WU PARTIAL INCL IN OTHER POSITIONS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: