

Vic



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
50 Woodlands Industrial Park E4, Singapore 737705
FAX Number : 63685192
Estimator Telephone Number : 68562623
Accident Reporting Number : 68562672



Date Generated : 02/04/2019

User ID : PehSuan

Lic Finalized-HJ

Section A - Accident Details

Registration Number	SHC4317A
Case Reference Number	TAX/02/19/2087
Registration Date	6/12/2013
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	SENG BOON HONG
Type of Accident	Side Swipe
Accident Date and Time	16/2/2019 11:15 AM
Accident Reported Date and Time	18/2/2019 10:41 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	24100175
Special Instruction to ARC, if any	DROVE IN / AXA
Prepared Date and Time	19/2/2019 4:31 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Location

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$900.00
Total Spray Cost	\$2,052.00	\$950.00
Total Spare Part Cost	\$5,148.08	\$167.52
Total Other Cost	\$1,065.00	\$80.00
TOTAL COST	\$9,279.08	\$2,097.52
Lump Sum Total	\$9,300.00	\$2,100.00 (L/S)
Number of Repair Days	7.0	5.0
Prepared / Adjusted By	Tuck Foo Kok	Hwee Jie (LKK) / AXA
ARC / Surveyor Sign Off Date	20/02/2019 1:54 PM	20/02/2019 1:11 PM
Signature		
Remarks		L/S REPAIR, PHOTO AFTER PAINT.



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757726
FAX Number: 63655502
Estimator Telephone Number: 69662623
Accident Reporting Number: 64662672

Date Generated : 02/04/2019

User ID : PehSuan

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1903-0038	Invoice Number	
Quotation Date	02.03.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	\$1,014.00	\$900.00
Total Labour	\$1,014.00	\$900.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT DOOR RH	\$378.00	\$200.00
TO RESPRAY VIEW MIRROR	\$180.00	\$0.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$100.00
TO RESPRAY RH REAR DOOR	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$50.00
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$2,052.00	\$950.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$30.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$30.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$0.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$125.00	\$0.00
TO REMOVE & REFIT REAR QUARTER GLASS RH	\$120.00	\$0.00
TO REMOVE / REFIT SEAT	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$1,065.00	\$80.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		67001-47070	DOOR FRT/RH	1.00	\$894.40	100.00	\$0.00	Replace	Repair
			STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace
		69030-47070	DOOR LOCK FRT/RH	0.00	\$575.80	0.00	\$0.00	Replace	Not Given
		81730-52090	MIRROR LAMP RH	0.00	\$65.30	0.00	\$0.00	Replace	Not Given
		879157-4010	COVER, OUTER MIRROR, RH	0.00	\$107.40	0.00	\$0.00	Replace	Not Given

nec
SVC
SVC
SVC

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
00 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63655582
Estimator Telephone Number : 68682823
Accident Reporting Number : 68682872

Date Generated : 02/04/2018

User ID : PohSuan

75851-47900	MOULDING BODY, RH	1.00	\$673.60	100.00	\$0.00	Replace	Repair	✓	
67003-47080	DOOR RR/RH	1.00	\$954.50	100.00	\$0.00	Replace	Repair	✓	
68770-52031	HINGE LOWER RHR, DOOR	0.00	\$52.00	0.00	\$0.00	Replace	Not Given	X	SVC
68750-20121	HINGE UPPER RHR, DOOR	0.00	\$81.70	0.00	\$0.00	Replace	Not Given	X	SVC
68630-47031	CHECK ASSY, RR DOOR	0.00	\$150.30	0.00	\$0.00	Replace	Not Given	X	SVC
69050-47080	DOOR LOCK RR/RH	0.00	\$709.30	0.00	\$0.00	Replace	Not Given	X	SVC
69410-33010	DOOR LOCK STRIKER	0.00	\$40.50	0.00	\$0.00	Replace	Not Given	X	SVC
69211-74020	DOOR OUTER HANDLE RR/RH	0.00	\$69.80	0.00	\$0.00	Replace	Check	X	SVC
61604-47090	FENDER RR/RH	1.00	\$766.60	100.00	\$0.00	Replace	Repair	✓	
	SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	✓	nec
	STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	✓	nec
62710-47130	QUARTER GLASS RR/RH	0.00	\$846.50	0.00	\$0.00	Replace	Not Given	X	SVC
	SEALANT W/SCREEN	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X	SVC
65637-47021	FENDER LINER RR/RH	0.00	\$141.30	0.00	\$0.00	Replace	Check	✓	SVC
42611-47140	WHEEL, DISC	1.00	\$1,490.20	100.00	\$0.00	Replace	Repair	✓	
52159-47905	BUMPER REAR	1.00	\$458.60	100.00	\$0.00	Replace	Repair	✓	
52591-47021	BUMPER SEAL, RR RH	0.00	\$65.70	0.00	\$0.00	Replace	Check	X	SVC
52575-47020	BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Check	X	SVC
	PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace	✓	nec
Total			\$8,424.90		\$209.40				

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

209.40

-20%

167.52
+ 900.00
+ 1030.00

2097.52

LS \$2100/-