

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

19-Feb-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1053 A

1 pc	Radiator top cover	X NN	\$	56.00
1 pc	Front bumper	/ CRA	\$	531.00
1 pc	Front bumper emblem	/ NEC	\$	44.00
1 pc	Front bumper strip	X NN	\$	40.00
1 pc	Bonnet	/ DM	\$	979.00
1 pc	Bonnet grille	/ DM	\$	386.00
			\$	2,036.00
Less 10%			\$	203.60
			\$	1,832.40

S/NETT

1 set	Front bumper clips	/ NEC	\$	48.00
	Sundry	NEC	\$	50.00 20
	To check headlamp wiring		\$	80.00 X
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same		\$	650.00 300
	To putty and spray painting on front bumper, bonnet, bonnet grille		\$	600.00 540
	To apply rustproofing on the repaired and replaced panels		\$	80.00 30

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

KIA Auto Consultants hence notified the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Any supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

K. L. 1004
20/2/19 1630h
3 Rys
P.P.
Before Print p 4th