

ASS. REC. BY: REF: CS/SMO19003197/Jvd3² Special Instruction:

Surveyor: Hwee Jie ASSIGNMENT (Office)
From (Person): Ruth Chua Gek of SMD Date/Time: 20/2/19 @ 11am

Estimated Cost: _____ Bill to: _____

OD TP WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No: SHB 168U Insured: SKT 9596U

at Workshop n/s SMRT Tel: _____

of No. 61 woodlands Ind. Park EQ # 04-04

Policy No: D18MTPV01010673 Claim No: CMTD1900921

Sum Insured: _____ Excess: _____

Make of Vch: _____ D.O.A. 17/02/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS ^{up} H.O.D. Endorsement: _____

Date/Time: 12:15pm @ 20/2/19 Person Contacted: shanti Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SHB 168U - CC3/EQT/7022251/Rlgb3q2 DoA: 18/11/2017 SKT 9596U - X
<u>20/2/19</u>	Send preli revised via merimen
<u>5/4/19</u>	LS \$ 2850 confirmed by email (Red 12,945.14, 829)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Feb 2019		20 Feb 2019 11:00 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	PRICILLA RAJINEE DEVI D/O KANAGALI, ID: S7608433E, Tel: +6597773564, Email: emailrajinee@gmail.com								
Main Claimant:	SMRT TAXIS PTE LTD, Co. Reg. No.: 198905369K								
Vehicle Reg. No.:	SHB168U	Date of Loss:	17/02/2019 11:00 - :59						
Claim Type:	TP / CMTD1900921	Policy/Cover Note No.:	D18MTPV01010673 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKT9596C	Policy No. (Claimant):							
		Excess:							
Repairer:	Smrt Automotive Services Pte Ltd (HQ) No. 61 Woodlands Industrial Park E9, #04-04 Premium Building, 757047 Woodlands - Tel:								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Ruth Chua Gek Tiang - 6329 5153]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 01/03/2019]								
Driver/Custodian (Insured):	PRICILLA RAJINEE DEVI D/O KANAGALI (42 / Female), NRIC: S7608433E, Tel: +6597773564								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sampo Insurance Singapore Pte. Ltd. 50 Raffles Place #05-01/06, Singapore Land Tower Singapore 048623	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Ruth Chua Gek Tiang	Date: 22 Feb 2019
<u>Preliminary Advice</u>	

Insured Vehicle No : SKT9596C	
TP Vehicle No : SHB168U	Accident Date : 17/02/2019
Make : TOYOTA PRIUS	Assignment Date : 20/02/2019
Date of Inspection : 20/02/2019	Est. Duration of Repair : 5.00
Inspection At : SMRT AUTOMOTIVE SERVICES PTE LTD (HQ) NO. 61 WOODLANDS INDUSTRIAL PARK E9, #04-04 PREMIUM BUILDING SINGAPORE 757047	

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$		15,795.14
Revised Amount	:S\$		2,991.44
Check Items (Estimated)	:S\$		1,308.75
Total	:S\$		4,300.19
Lump Sum Repair	:S\$		
Total Loss Consideration			
New for Old Value	:S\$		
Pre-Accident Value	:S\$		
COE / PARF Rebate	:S\$		
Salvage Value	:S\$		
Margin for Repair	:S\$		

Remarks

()		The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
()		The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
(X)		Other comments :The above survey was conducted on a "Without Prejudice" basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/02/2019 11:07
Date Of Accident	17/02/2019 11:30
Exact Location Of Accident	BLK 539 SERANGOON NORTH AVE 4 CP
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB168U
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	

Driver

Name of Driver	MALKIT SINGH S/O JASSA SINGH
NRIC No	S1651795Z
Date Of Birth	18/08/1990
Occupation	OUTDOOR
Date Of Driving Pass	18/08/1990
Driving Experience	28 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Tax Number	
Contact Number	
Mail Address	NOEMAIL

Address	11
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
Have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING ALONG THE CAR PARK OF BLK 539 SERANGOON NORTH AVE 4 TO EXIT THE CAR PARK. SUDDENLY A VEHICLE SKT9596C CAME OUT FROM THE PARKING LOT AND COLLIDED ONTO THE LEFT PORTION OF MY TAXI. AFTER COLLIDING ONTO MY TAXI THIRD PARTY REVERSED BACK TO THE LOT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKT9596C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	PRICILLA RAJINEE DEVI
NRIC/Passport Number	S7608433E
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5369K
Vehicle Details	
Vehicle No.:	SHB168U
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Feb 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2013
Engine No.:	2ZR5914616
Chassis No.:	JTDKN36U005718365
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$33,120.00
Original Registration Date:	20 Dec 2013
First Registration Date:	20 Dec 2013
Transfer Count:	0
Actual ARF Paid:	\$8,368.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Dec 2021
PARF Rebate Amount:	\$5,857.00
Intended COE Rebate Details	
COE Expiry Date:	19 Dec 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$62,740.00
COE Rebate Amount:	\$22,141.00
Total Rebate Amount:	\$27,998.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 22 Feb 2019

OK



Case Details

Case Reference Number : TAX/02/19/2089
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB168U

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-5770-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : Sompoo Insurance Singapore Pte. Ltd
 Accident Date and Time : 17/02/2019 03:30 AM
 Vehicle Age(In Months) : 62

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation				Repair/ Replace	Surveyor Quantity	Surveyor Approval		Remarks
						List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)			Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			DOOR RR/LH	1	954.50	954.50	25.00	715.88	Replace	1	0	Repair	
One Time Key In	Main			PIXEL STICKER	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	NEC
One Time Key In	Main			HINGE LOWER LHR, DOOR	1	72.20	72.20	25.00	54.15	Replace	0	0	Check	
One Time Key In	Main			HINGE UPPER LHR, DOOR	1	81.70	81.70	25.00	61.28	Replace	0	0	Check	
One Time Key In	Main			CHECK ASSY, RR DOOR,	1	150.30	150.30	25.00	112.73	Replace	0	0	Not Give	
One Time Key In	Main			FENDER RR/LH	1	766.80	766.80	25.00	575.10	Replace	1	0	Repair	
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	NEC
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	NEC
One Time Key In	Main			FENDER LINER RR/LH	1	141.30	141.30	25.00	105.98	Replace	0	0	Not Give	
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	0	0	Not Give	

Total Spare Part Cost	7,930.72	Surveyor Total	861.44
Lump Sum Discount (%)	20.00	Lump Sum Dis (%)	20
Final Spare Part Cost	6,239.70	Final Sur Total	689.15

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			BUMPER SIDE RETAINER RR/LH	1	94.80	94.80	25.00	71.10	Replace	0	0	Not Give	
One Time Key In	Main			PIXEL STICKER	1	60.00	60.00	0.00	60.00	Replace	0	0	Not Give	
One Time Key In	Main			BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	0	Repair	
One Time Key In	Main			BUMPER SUPPORT FLH	1	76.40	76.40	25.00	57.30	Replace	0	0	Check	
One Time Key In	Main			FENDER FRT/LH	1	723.40	723.40	25.00	542.55	Replace	1	542.55	Replace	BUC
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace	NEC
One Time Key In	Main			FENDER LINER FRT/LH	1	171.70	171.70	25.00	128.77	Replace	0	0	Check	
One Time Key In	Main			FENDER LINER PAD, FR WHEEL, LH	1	49.30	49.30	25.00	36.97	Replace	0	0	Check	
One Time Key In	Main			FENDER APRON SUB FRT/LH	1	637.80	637.80	25.00	478.35	Replace	0	0	Check	
One Time Key In	Main			PROTECTOR, FRONT FENDER SIDE PANEL LH	1	114.50	114.50	25.00	85.88	Replace	0	0	Check	
One Time Key In	Main		6503707	TYRE	1	126.74	126.74	25.00	95.05	Replace	0	0	Not Give	
One Time Key In	Main			WHEEL DISC, FRONT	1	1,484.20	1,484.20	25.00	1,113.15	Replace	0	0	Not Give	
One Time Key In	Main			CAP SUB-ASSY, WHEEL	1	174.10	174.10	25.00	130.57	Replace	1	130.57	Replace	SCR
One Time Key In	Main			PILLAR, FR BODY, LH	1	363.10	363.10	25.00	272.33	Replace	0	0	Not Give	
One Time Key In	Main			QUARTER GLASS FRT/LH	1	234.90	234.90	25.00	176.18	Replace	0	0	Not Give	

Total Spare Part Cost	7,930.72	Surveyor Total	861.44
Lump Sum Discount (%)	20.00	Lump Sum Dis (%)	20
Final Spare Part Cost	6,239.70	Final Sur Total	689.15

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			SEALANT W/SCREEN	1	37.00	37.00	0.00	37.00	Replace	0	0	Not Give	
One Time Key In	Main			MOULDING BODY, LH	1	673.60	673.60	25.00	505.20	Replace	1	0	Repair	
One Time Key In	Main			DOOR FRT/LH	1	894.40	894.40	25.00	670.80	Replace	1	0	Repair	
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	NEC
One Time Key In	Main			DOOR OUTER HANDLE FRT/LH	1	370.80	370.80	25.00	278.10	Replace	0	0	Check	
One Time Key In	Main			DOOR LOCK FRT/LH	1	575.80	575.80	25.00	431.85	Replace	0	0	Not Give	
One Time Key In	Main			HINGE UPPER LHF, DOOR	1	80.50	80.50	25.00	60.38	Replace	0	0	Check	
One Time Key In	Main			HINGE LOWER LHF, DOOR	1	90.10	90.10	25.00	67.57	Replace	0	0	Check	
One Time Key In	Main			CHECK ASSY, FR DOOR,	1	150.30	150.30	25.00	112.73	Replace	0	0	Not Give	
Total Spare Part Cost									7,930.72				Surveyor Total	861.44
Lump Sum Discount (%)									20.00				Lump Sum Dis (%)	20
Final Spare Part Cost									6,239.70				Final Sur Total	689.15

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR LH PORTION	1,014.00	900	
Total:			1,014.00	900.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	
2	Main	TO RESPRAY FRONT FENDER LH	378.00	200	
3	Main	TO RESPRAY APRON PANEL LH	180.00	0	
Total:			3,168.00	1,150.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
4	Main	RESPRAY WHEEL CAP	180.00	50	
5	Main	TO RESPRAY RIM	180.00	0	
6	Main	TO RESPRAY ROCKER PANEL MOULDING	180.00	100	
7	Main	TO RESPRAY FRONT DOOR LH	378.00	200	
8	Main	TO RESPRAY FRONT PILLAR LH	180.00	0	
9	Main	TO RESRAY REAR DOOR LH	378.00	200	
10	Main	TO RESPRAY REAR FENDER LH	378.00	200	
11	Main	TO RESPRAY REAR BUMPER	378.00	0	
Total:			3,168.00	1,150.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TOWING CHARGE	56.00	0	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	40	
4	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0	
5	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	20	
6	Main	TO REMOVE & REFIX FRONT LHS/RHS QUATER GLASS	120.00	0	
7	Main	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	0	
8	Main	TO TRANSFER DOOR MECHANISM	240.00	0	
9	Main	TO REPLACE SUNDRY PARTS	100.00	0	
10	Main	TO WASH AND VACUUM	60.00	0	
Total:			1,121.00	80.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	6,239.70	689.15


	Estimator Assessment(\$)		Surveyor Assessment(\$)
Total Labour Cost	1,014.00		900.00
Total Spray Painting	3,168.00		1,150.00
Other	1,121.00		80.00
Overall Total	11,542.70	15,795.14	2,819.15
Lump Sum Repair Option			<input checked="" type="checkbox"/>
Lump Sum Total	11,550.00		2,800.00
Surveyor Approved Amount			2,800.00
No of Repair Days*	7		5
Remarks			L/S REPAIR, PHOTO AFTER PAINT.
Surveyor Name			Hwee je
Signature			 25/2/19
Survey Date	20/02/2019		<input type="button" value="Save"/> <input type="button" value="Clear"/>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed.
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Section A - Accident Details	
Registration Number	SHB168U
Case Reference Number	TAX/02/19/2089
Registration Date	20/12/2013
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	MALKIT SINGH S/O JASSA SINGH
Type of Accident	Head To Side
Accident Date and Time	17/2/2019 11:30 AM
Accident Reported Date and Time	18/2/2019 11:21 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	17/2/2019 12:20 PM
Replacement Vehicle issued?	No
Job Card Number	24100177
Special Instruction to ARC, if any	TOWED \$40 / TP
Prepared Date and Time	19/2/2019 1:07 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$900.00
Total Spray Cost	\$3,168.00	\$1,150.00
Total Spare Part Cost	\$6,344.58	\$689.17
Total Other Cost	\$1,121.00	\$120.00
TOTAL COST	\$11,647.58	\$2,859.17
Lump Sum Total	\$11,850.00	\$2,850.00 (L/S)
Number of Repair Days	7.0	5.0
Prepared / Adjusted By	Tuck Foo Kok	Hwee Jie (LKK) / Sampo
ARC / Surveyor Sign Off Date	20/02/2019 3:09 PM	20/02/2019 1:59 PM
Signature		
Remarks	L/S REPAIR, PHOTO AFTER PAINT.	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
 60 Woodlands Industrial Park EA, Singapore 757705
 FAX Number : 63995592
 Estimator Telephone Number : 88552623
 Accident Reporting Number : 8862672

Date Generated : 02/04/2019
 User ID : PohSuan

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1903-0036	Invoice Number	
Quotation Date	02.03.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	\$1,014.00	\$900.00
Total Labour	\$1,014.00	\$900.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
TO RESPRAY APRON PANEL LH	\$180.00	\$0.00
RESPRAY WHEEL CAP	\$180.00	\$50.00
TO RESPRAY RIM	\$180.00	\$0.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$100.00
TO RESPRAY FRONT DOOR LH	\$378.00	\$200.00
TO RESPRAY FRONT PILLAR LH	\$180.00	\$0.00
TO RESRAY REAR DOOR LH	\$378.00	\$200.00
TO RESPRAY REAR FENDER LH	\$378.00	\$200.00
TO RESPRAY REAR BUMPER	\$378.00	\$0.00
Total Spray Painting & Panel Beating	\$3,168.00	\$1,150.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$56.00	\$40.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$60.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$40.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$20.00
TO REMOVE & REFIX FRONT LHS/RHS QUATER GLASS	\$120.00	\$0.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$125.00	\$0.00
TO TRANSFER DOOR MECHANISM	\$240.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$1,121.00	\$120.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		67004-47080	DOOR RRLH	1.00	\$954.50	100.00	\$0.00	Replace	Repair



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
 30 Woodlands Industrial Park E4, Singapore 757706
 FAX Number : 63685552
 Estimator Telephone Number : 69102023
 Accident Reporting Number : 60062072

Date Generated : 02/04/2019
 User ID : PohSuan

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	Notes
			PIXEL STICKER	1.00	\$60.00	0.00	\$60.00	Replace	Replace	✓ NEC
68780-52031			HINGE LOWER LHR, DOOR	0.00	\$72.20	0.00	\$0.00	Replace	Check	X nn
68760-20122			HINGE UPPER LHR, DOOR	0.00	\$81.70	0.00	\$0.00	Replace	Check	X nn
68630-47031			CHECK ASSY, RR DOOR,	0.00	\$150.30	0.00	\$0.00	Replace	Not Given	X nn
61602-47091			FENDER RR/LH	1.00	\$766.80	100.00	\$0.00	Replace	Repair	✓ R
			SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	✓ NEC
			STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	✓ NEC
65638-47021			FENDER LINER RR/LH	0.00	\$141.30	0.00	\$0.00	Replace	Not Given	X nn
52159-47905			BUMPER REAR	0.00	\$458.60	0.00	\$0.00	Replace	Not Given	X nn
52576-47020			BUMPER SIDE RETAINER RR/LH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given	X nn
			PIXEL STICKER	0.00	\$60.00	0.00	\$0.00	Replace	Not Given	X nn
52119-47930			BUMPER FRT	1.00	\$482.00	100.00	\$0.00	Replace	Repair	✓ R nn
52116-47040			BUMPER SUPPORT F/LH	0.00	\$76.40	0.00	\$0.00	Replace	Check	X BUC
53802-47050			FENDER FRT/LH	1.00	\$723.40	25.00	\$542.55	Replace	Replace	✓ 861.46
75374-47051			NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace	✓ NEC -20%
53876-47030			FENDER LINER FRT/LH	0.00	\$171.70	0.00	\$0.00	Replace	Check	X nn
53852-47020			FENDER LINER PAD, FR WHEEL LH	0.00	\$49.30	0.00	\$0.00	Replace	Check	X nn
53702-47050			FENDER APRON SUB FRT/LH	0.00	\$637.80	0.00	\$0.00	Replace	Check	X nn 689.17
53828-47060			PROTECTOR, FRONT FENDER SIDE PANEL LH	0.00	\$114.50	0.00	\$0.00	Replace	Check	X nn +900.00
6503707			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X nn +1270.00
42611-47140 (Frt)			WHEEL DISC. FRONT	0.00	\$1,484.20	0.00	\$0.00	Replace	Not Given	X nn +1270.00
42602-47060			CAP SUB-ASSY, WHEEL	1.00	\$174.10	25.00	\$130.58	Replace	Replace	✓ SCR
61132-47030			PILLAR, FR BODY, LH	0.00	\$363.10	0.00	\$0.00	Replace	Not Given	X nn 2859.17
62120-47021			QUARTER GLASS FRT/LH	0.00	\$234.90	0.00	\$0.00	Replace	Not Given	X nn
			SEALANT W/SCREEN	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X nn 45 \$2850/-
75852-47900			MOULDING BODY, LH	1.00	\$673.60	100.00	\$0.00	Replace	Repair	✓ R
67002-47070			DOOR FRT/LH	1.00	\$894.40	100.00	\$0.00	Replace	Repair	✓ R
			STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace	✓ NEC
69210-74030			DOOR OUTER HANDLE FRT/LH	0.00	\$370.80	0.00	\$0.00	Replace	Check	X nn
69040-47070			DOOR LOCK FRT/LH	0.00	\$575.80	0.00	\$0.00	Replace	Not Given	X nn
68720-15151			HINGE UPPER LHF, DOOR	0.00	\$80.50	0.00	\$0.00	Replace	Check	X nn
68740-12120			HINGE LOWER LHF, DOOR	0.00	\$90.10	0.00	\$0.00	Replace	Check	X nn
68610-47021			CHECK ASSY, FR DOOR,	0.00	\$150.30	0.00	\$0.00	Replace	Not Given	X nn
Total					\$10,492.14		\$861.46			

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

15795.14

Veron Chen (LKKAuto)

From: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis) <YeoPohsuan@smrt.com.sg>
Sent: Friday, 5 April 2019 10:51 AM
To: Hwee Jie (LKK Auto)
Cc: Veron Chen (LKKAuto)
Subject: RE: SHB168U

Hi,

Amount confirmed as per your recommendation, thanks.

Regards
Poh Suan

-----Original Message-----

From: Hwee Jie (LKK Auto) [mailto:hweejie@lkkauto.com]
Sent: Friday, 5 April 2019 8:56 AM
To: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)
Cc: Veron Chen (LKKAuto)
Subject: RE: SHB168U

Hi poh suan,

Finalized L/S \$2,850/- 5days.

Best Regards,
Hwee Jie | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 9180 3151 | Email: Hweejie@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis) [mailto:YeoPohsuan@smrt.com.sg]
Sent: Tuesday, 2 April, 2019 3:02 PM
To: Hwee Jie (LKK Auto)
Cc: SUR; CS A Team; 'Leong Chee kwong'; 'EE SIN GUAN'
Subject: SHB168U

Hi Hwee Jie,

Attached herewith the repair estimate of SHB 168U having Case No: TAX/02/19/2089.

There is no change to the approved amount of \$2,850 @ 5 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Aside Kwong,

Please provide the before / after paint photos as per surveyor's request.

Thanks & Regards

Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)

Sent: Tuesday, 2 April 2019 2:55 PM

To: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)

Subject: Scan Data from FX-D421D6

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Feb 2019		20 Feb 2019 11:00 Edit Adj Rpt	S\$2,850.00 Edit Estimates	S\$2,850.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	PRICILLA RAJINEE DEVI D/O KANAGALINGAM, ID: S7608433E, Tel: +6597773564, Email: emailrajinee@gmail.com	
Main Claimant:	SMRT TAXIS PTE LTD, Co. Reg. No.: 198905369K	
Vehicle Reg. No.:	SHB168U	Date of Loss: 17/02/2019 11:00 - :59 [61 Months and 28 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / CMTD1900921	Policy/Cover Note No.: D18MTPV01010673 (Comprehensive)
Vehicle Reg. No. (Insured):	SKT9596C	Policy No. (Claimant):
		Excess:
Repairer:	Smrt Automotive Services Pte Ltd (HQ) No. 61 Woodlands Industrial Park E9, #04-04 Premium Building, 757047 Woodlands - Tel:	
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Ruth Chua Gek Tiang - 6329 5153]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Final Rpt due 01/03/2019]	
Driver/Custodian (Insured):	PRICILLA RAJINEE DEVI D/O KANAGALI (42 / Female), NRIC: S7608433E, Tel: +6597773564 Email: emailrajinee@gmail.com	
ASSOCIATED MAIL RECEIVED View All Compose Case Mail		
<ul style="list-style-type: none"> • SOMPO_SG (08/05/2019): Please submit survey report (SHB168U) 		
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete		
Due Date	Priority	Type
Task Group	Subject	Handler
Assigned By	Completed On	Created On
Done?		
No results.		

Claim Documents

***SHB168U (CMTD1900921)
[SKT9596C]**

TP

SMRT TAXIS PTE LTD

Feb 17 2019 11:00AM

[PRICILLA RAJINEE DEVI D/O KANAGALINGAM]

Smrt Automotive Services Pte Ltd

<input type="button" value="Upload Documents"/> <input type="button" value="Upload Photos"/> <input type="button" value="Compose New Letter"/>			View	View in Browser ▾
Assessment Reports			1 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)		Thumbnail Print
1	20/02/19 10:59	Accident Statement From:OD - Reg. No: SKT9596C, Claimant: PRICILLA RAJINEE DEVI D/O KANAGALI		Load HTM
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	22/02/19 15:57	Adjuster Immediate Advice		Load HTM
Photos/Images			3 per page ▾	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	25/02/19 09:02	General View		Load JPG <input checked="" type="checkbox"/>
2	25/02/19 09:02	General View		Load JPG <input checked="" type="checkbox"/>
3	25/02/19 09:02	General View		Load JPG <input checked="" type="checkbox"/>
4	25/02/19 09:02	General View		Load JPG <input checked="" type="checkbox"/>
5	25/02/19 09:02	General View		Load JPG <input checked="" type="checkbox"/>
6	25/02/19 09:02	General View		Load JPG <input checked="" type="checkbox"/>
7	25/02/19 09:02	General View		Load JPG <input checked="" type="checkbox"/>
8	25/02/19 09:02	General View		Load JPG <input checked="" type="checkbox"/>
9	25/02/19 09:02	General View		Load JPG <input checked="" type="checkbox"/>
10	25/02/19 09:02	General View		Load JPG <input checked="" type="checkbox"/>
11	25/02/19 09:02	General View		Load JPG <input checked="" type="checkbox"/>
12	25/02/19 09:02	General View		Load JPG <input checked="" type="checkbox"/>
13	25/02/19 09:02	General View		Load JPG <input checked="" type="checkbox"/>
14	25/02/19 09:02	General View		Load JPG <input checked="" type="checkbox"/>
15	25/02/19 09:02	General View		Load JPG <input checked="" type="checkbox"/>
16	25/02/19 09:02	General View		Load JPG <input checked="" type="checkbox"/>
17	25/02/19 09:02	General View		Load JPG <input checked="" type="checkbox"/>
18	25/02/19 09:02	General View		Load JPG <input checked="" type="checkbox"/>
19	25/02/19 09:02	General View		Load JPG <input checked="" type="checkbox"/>
20	25/02/19 09:02	General View		Load JPG <input checked="" type="checkbox"/>
21	25/02/19 09:02	General View		Load JPG <input checked="" type="checkbox"/>
22	25/02/19 09:02	General View		Load JPG <input checked="" type="checkbox"/>
23	25/02/19 09:02	General View		Load JPG <input checked="" type="checkbox"/>
24	25/02/19 09:02	General View		Load JPG <input checked="" type="checkbox"/>
25	25/02/19 09:02	General View		Load JPG <input checked="" type="checkbox"/>
26	25/02/19 09:02	General View		Load JPG <input checked="" type="checkbox"/>
27	25/02/19 09:02	General View		Load JPG <input checked="" type="checkbox"/>
28	25/02/19 09:02	General View		Load JPG <input checked="" type="checkbox"/>
29	25/02/19 09:02	General View		Load JPG <input checked="" type="checkbox"/>
30	25/02/19 09:02	General View		Load JPG <input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)		Thumbnail	Print
31	25/02/19 09:02	General View		Load JPG	<input checked="" type="checkbox"/>
32	25/02/19 09:02	General View		Load JPG	<input checked="" type="checkbox"/>
33	05/04/19 08:53	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
34	05/04/19 08:53	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
35	05/04/19 08:53	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
36	05/04/19 08:53	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)		Thumbnail	Print
1	19/02/19 16:37	TP - SAS		Load PDF	
2	20/02/19 10:59	TP - ASSIGN LKK		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<p>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</p> <hr/> <p>Show Remarks To: <input type="checkbox"/> Handling Insurer</p> <p><small>Note: Remarks are private unless you show it to other parties.</small></p>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19003197/JVD3S2
Date: 09/05/2019

REFERENCE

Handling Insurer: Sompoo Insurance Singapore Pte. Ltd. Policy No: D18MTPV01010673
Claimant Vehicle No : SHB168U **Insured Vehicle No :** SKT9596C
 Date of Loss: 17/02/2019 Nature of Claim: TP Claim No: CMTD1900921

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHB168U**
 Make & Model: TOYOTA PRIUS, 1.8 (A) Engine No: 2ZR5914616
 Reg. Date: 20/12/2013 (Man. Year: 2013) Chassis No: JTDKN36U005718365
 Colour: Maroon Odometer: 857061 km
 Engine Capacity: 1798 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
 Front Left Side: Chilles 6 mm Rear Left Side: Chilles 6 mm
 Front Right Side: Chilles 6 mm Rear Right Side: Chilles 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,617.14	861.46	9,755.68	91.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,178.00	2,170.00	3,008.00	58.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,795.14	3,031.46	12,763.68	80.81
Approved Total (Overridden) (S\$)		2,850.00		
Nett Amount (S\$)	15,795.14	2,850.00	12,945.14	81.96

INSPECTION

Date of Assignment: 20/02/2019
 Date Inspected: 20/02/2019 Inspected At: Smrt Automotive Services Pte Ltd (HQ)
 No. 61 Woodlands Industrial Park E9, #04-04 Premium Building
 Singapore 757047
 Estimated Period of Repair: 5.0 days

Adjuster: ONG HWEE JIE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 08 May 2019)
Parts: 144	TOYOTA PRIUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHB168U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FENDER FRT/LH (DISC 25%)	Buckled	723.40 F	*542.55 F	
2	1		*NAME PLATE (HYBRID) (DISC 25%)	Necessary	51.90 F	*38.93 F	
3	1		*CAP SUB-ASSY, WHEEL (DISC 25%)	Scratched	174.10 F	*130.58 F	
4	1		*PIXEL STICKER (SN)	Necessary	60.00 F	*60.00 F	
5	1		*SMRT LOGO (SN)	Necessary	7.80 F	*7.80 F	
6	1		*STICKER DECAL 6555 8888 (SN)	Necessary	21.60 F	*21.60 F	
7	1		*STICKER DECAL SMRT (DOOR) (SN)	Necessary	60.00 F	*60.00 F	
8	1		*HINGE LOWER LHR, DOOR	Not Necessary	72.20 F	*- F	
9	1		*HINGE UPPER LHR, DOOR	Not Necessary	81.70 F	*- F	
10	1		*CHECK ASSY, RR DOOR	Not Necessary	150.30 F	*- F	
11	1		*FENDER LINER RR/LH	Not Necessary	141.30 F	*- F	
12	1		*BUMPER REAR	Not Necessary	458.60 F	*- F	
13	1		*BUMPER SIDE RETAINER RR/LH	Not Necessary	94.80 F	*- F	
14	1		*PIXEL STICKER	Not Necessary	60.00 F	*- F	
15	1		*BUMPER SUPPORT F/LH	Not Necessary	76.40 F	*- F	
16	1		*FENDER LINER FRT/LH	Not Necessary	171.70 F	*- F	
17	1		*FENDER LINER PAD, FR WHEEL, LH	Not Necessary	49.30 F	*- F	
18	1		*FENDER APRON SUB FRT/LH	Not Necessary	637.80 F	*- F	
19	1		*PROTECTOR, FRONT FENDER SIDE PANEL LH	Not Necessary	114.50 F	*- F	
20	1		*TYRE	Not Necessary	126.74 F	*- F	
21	1		*WHEEL DISC, FRONT	Not Necessary	1,484.20 F	*- F	
22	1		*PILLAR, FR BODY, LH	Not Necessary	363.10 F	*- F	
23	1		*QUARTER GLASS FRT/LH	Not Necessary	234.90 F	*- F	
24	1		*SEALANT W/SCREEN	Not Necessary	37.00 F	*- F	
25	1		*DOOR OUTER HANDLE FRT/LH	Not Necessary	370.80 F	*- F	
26	1		*DOOR LOCK FRT/LH	Not Necessary	575.80 F	*- F	
27	1		*HINGE UPPER LHF, DOOR	Not Necessary	80.50 F	*- F	
28	1		*HINGE LOWER LHF, DOOR	Not Necessary	90.10 F	*- F	
29	1		*CHECK ASSY, FR DOOR,	Not Necessary	150.30 F	*- F	
30	1		*DOOR RR/LH	Repair	954.50 F	*- F	
31	1		*FENDER RR/LH	Repair	766.80 F	*- F	
32	1		*BUMPER FRT	Repair	482.00 F	*- F	
33	1		*MOULDING BODY, LH	Repair	673.60 F	*- F	
34	1		*DOOR FRT/LH	Repair	894.40 F	*- F	
35	1		*SOLAR FILM (SN)	Not Necessary	125.00 F	*- F	
					Total Parts (\$\$)	10,617.14	861.46

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODYWORK.	New	1,014.00	900.00
2	SPRAY PAINT.	New	3,168.00	1,150.00
3	TOWING CHARGE.	New	56.00	40.00
4	TO CHECK WIRING AND SYSTEM FUNCTION.	New	80.00	20.00
5	TO APPLY RUST-PROOFING ON AFFECTED AREA.	New	100.00	40.00
6	TO DO WHEEL ALIGNMENT / TYRE BALANCING.	New	120.00	0.00
7	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	New	120.00	20.00
8	TO REMOVE & REFIX FRONT LHS/RHS QUARTER GLASS.	New	120.00	0.00
9	TO TRANSFER DOOR MECHANISM.	New	240.00	0.00
10	TO REPLACE SUNDRY PARTS.	New	100.00	0.00
11	TO WASH AND VACUUM.	New	60.00	0.00
Gross Labour Cost (S\$)			5,178.00	2,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >