



Section A - Accident Details

Registration Number	SHB168U
Case Reference Number	TAX/02/19/2089
Registration Date	20/12/2013
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	MALKIT SINGH S/O JASSA SINGH
Type of Accident	Head To Side
Accident Date and Time	17/2/2019 11:30 AM
Accident Reported Date and Time	18/2/2019 11:21 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	17/2/2019 12:20 PM
Replacement Vehicle issued?	No
Job Card Number	24100177
Special Instruction to ARC,if any	TOWED \$40 / TP
Prepared Date and Time	19/2/2019 1:07 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Top View

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$900.00
Total Spray Cost	\$3,168.00	\$1,150.00
Total Spare Part Cost	\$6,344.58	\$689.17
Total Other Cost	\$1,121.00	\$120.00
TOTAL COST	\$11,647.58	\$2,859.17
Lump Sum Total	\$11,650.00	\$2,850.00 (L/S)
Number of Repair Days	7.0	5.0
Prepared / Adjusted By	Tuck Foo Kok	Hwee Jie (LKK) / Sompo
ARC / Surveyor Sign Off Date	20/02/2019 3:09 PM	20/02/2019 1:59 PM
Signature		
Remarks	L/S REPAIR, PHOTO AFTER PAINT.	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
 60 Woodlands Industrial Park E4, Singapore 757705
 FAX Number : 63665692
 Estimator Telephone Number : 68652623
 Accident Reporting Number : 68662672

Date Generated : 02/04/2019

User ID : PohSuan

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1903-0036	Invoice Number	
Quotation Date	02.03.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	\$1,014.00	\$900.00
Total Labour	\$1,014.00	\$900.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
TO RESPRAY APRON PANEL LH	\$180.00	\$0.00
RESPRAY WHEEL CAP	\$180.00	\$50.00
TO RESPRAY RIM	\$180.00	\$0.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$100.00
TO RESPRAY FRONT DOOR LH	\$378.00	\$200.00
TO RESPRAY FRONT PILLAR LH	\$180.00	\$0.00
TO RESRAY REAR DOOR LH	\$378.00	\$200.00
TO RESPRAY REAR FENDER LH	\$378.00	\$200.00
TO RESPRAY REAR BUMPER	\$378.00	\$0.00
Total Spray Painting & Panel Beating	\$3,168.00	\$1,150.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$56.00	\$40.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$40.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$20.00
TO REMOVE & REFIX FRONT LHS/RHS QUATER GLASS	\$120.00	\$0.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$125.00	\$0.00
TO TRANSFER DOOR MECHANISM	\$240.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$1,121.00	\$120.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		67004-47080	DOOR RR/LH	1.00	\$954.50	100.00	\$0.00	Replace	Repair <i>f</i>

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
 60 Woodlands Industrial Park E4, Singapore 757705
 FAX Number : 63685592
 Estimator Telephone Number : 68662623
 Accident Reporting Number : 68662672

Date Generated : 02/04/2019
 User ID : PohSuan

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
			PIXEL STICKER	1.00	\$60.00	0.00	\$60.00	Replace	Replace ✓
		68780-52031	HINGE LOWER LHR, DOOR	0.00	\$72.20	0.00	\$0.00	Replace	Check X
		68760-20122	HINGE UPPER LHR, DOOR	0.00	\$81.70	0.00	\$0.00	Replace	Check X
		68630-47031	CHECK ASSY, RR DOOR,	0.00	\$150.30	0.00	\$0.00	Replace	Not Given X
		61602-47091	FENDER RR/LH	1.00	\$766.80	100.00	\$0.00	Replace	Repair R
			SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace ✓
			STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace ✓
		65638-47021	FENDER LINER RR/LH	0.00	\$141.30	0.00	\$0.00	Replace	Not Given X
		52159-47905	BUMPER REAR	0.00	\$458.60	0.00	\$0.00	Replace	Not Given X
		52576-47020	BUMPER SIDE RETAINER RR/LH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given X
			PIXEL STICKER	0.00	\$60.00	0.00	\$0.00	Replace	Not Given X
		52119-47930	BUMPER FRT	1.00	\$482.00	100.00	\$0.00	Replace	Repair R
		52116-47040	BUMPER SUPPORT F/LH	0.00	\$76.40	0.00	\$0.00	Replace	Check X
		53802-47050	FENDER FRT/LH	1.00	\$723.40	25.00	\$542.55	Replace	Replace ✓
		75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace ✓
		53876-47030	FENDER LINER FRT/LH	0.00	\$171.70	0.00	\$0.00	Replace	Check X
		53852-47020	FENDER LINER PAD, FR WHEEL. LH	0.00	\$49.30	0.00	\$0.00	Replace	Check X
		53702-47050	FENDER APRON SUB FRT/LH	0.00	\$637.80	0.00	\$0.00	Replace	Check X
		53828-47060	PROTECTOR, FRONT FENDER SIDE PANEL LH	0.00	\$114.50	0.00	\$0.00	Replace	Check X
6503707			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given X
		42611--47140 (Frt)	WHEEL DISC. FRONT	0.00	\$1,484.20	0.00	\$0.00	Replace	Not Given X
		42602-47060	CAP SUB-ASSY, WHEEL	1.00	\$174.10	25.00	\$130.58	Replace	Replace ✓
		61132-47030	PILLAR, FR BODY, LH	0.00	\$363.10	0.00	\$0.00	Replace	Not Given X
		62120-47021	QUARTER GLASS FRT/LH	0.00	\$234.90	0.00	\$0.00	Replace	Not Given X
			SEALANT W/SCREEN	0.00	\$37.00	0.00	\$0.00	Replace	Not Given X
		75852-47900	MOULDING BODY, LH	1.00	\$673.60	100.00	\$0.00	Replace	Repair R
		67002-47070	DOOR FRT/LH	1.00	\$894.40	100.00	\$0.00	Replace	Repair R
			STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace ✓
		69210-74030	DOOR OUTER HANDLE FRT/LH	0.00	\$370.80	0.00	\$0.00	Replace	Check X
		69040-47070	DOOR LOCK FRT/LH	0.00	\$575.80	0.00	\$0.00	Replace	Not Given X
		68720-15151	HINGE UPPER LHF, DOOR	0.00	\$80.50	0.00	\$0.00	Replace	Check X
		68740-12120	HINGE LOWER LHF, DOOR	0.00	\$90.10	0.00	\$0.00	Replace	Check X
		68610-47021	CHECK ASSY, FR DOOR,	0.00	\$150.30	0.00	\$0.00	Replace	Not Given X
Total					\$10,492.14		\$861.46		

861.46
 -20%
 689.17
 +900.00
 +1270.00

 2859.17
 45 \$2850/-

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									