

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0179/2019/GW
Date : 12-Feb-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no : SJQ80K

AXA Insurance Singapore Pte Ltd

8 Shenton Way
#27-01 AXA Tower
Singapore 068811

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax 6880 4838

Owner's Name : Mr. Chia Herbin
Address : Blk 512 Serangoon North Ave 4
#04-424
Singapore 550512
Telephone : HP +65 98540103
Type of Claim : Third Party Claims
Policy No. : 2100245469-08
Vehicle No : **SGZ 738 K**
Model Code : Q5 2.0 TFSI QU
Model / Year : Jan-11
Engine No : CDN 167630
Chassis No : WAUZZZ8R5BA060175
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Allan Wu
Accident Date : 5-Feb-19
Place of Accident : Outside of 64 PortChescter Ave

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGZ 738 K

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer rhs rear door's multi-lock system and power window devices.	S/N \$ 280.00
2	To remove and transfer rear parking aid. Check function.	S/N \$ 280.00
3	To dismantle and renew rhs rear door and rear bumper. Reinstall all parts removed.	\$ 2,100.00
4	To respray rhs front and rear door, door covers, rhs rear fender, rear bumper and lower spoiler.	\$ 4,300.00
5	To carry out diagnostic check.	S/N \$ 192.00
SUB-TOTAL LABOUR CHARGES		: \$ 7,152.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGZ 738 K

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR DOOR-RH	\$ 2,829.00	
2	REAR OUTER DOOR SEAL-RH	\$ 193.00	
3	BONDING AGENT	\$ 45.00	
4	CLEANING SOLUTION	\$ 65.00	
5	REAR DOOR CATCH-RH	\$ 132.00	
6	REAR DOOR COVER-RH	\$ 311.00	
7	REAR BUMPER	\$ 1,513.00	
8	REAR BUMPER GUIDE SECTION-RH	\$ 49.00	
9	SUNDRIES	\$ 300.00	
SUB-TOTAL SPARE PARTS		: \$ 5,437.00	
TOTAL LABOUR CHARGES		: \$ 7,152.00	
GRAND TOTAL		: \$ 12,589.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant