

Approved
Assigned By

REF: es/FCI19003206/Gtd3n2

Special Instructions

Sub Vehicle

ASSIGNMENT (Office)

CWS

From (Person)

May chua

of

FCI

Date/Time

8:47pm

20/2/19

Estimated Cost

Bill to

OD (TP) WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No

SLB8881T

Insured

SHA 3830B

at Workshop m/s

MBM Wheelpower

Tel

86865188

of

608th Mthg Drive #06-02

Policy No

Claim No

019001137MPSH

Sum Insured

Excess

Make of Veh

(Client's Record)

D.O.A

14/02/2019

CA / REV / REP. / REV 24 HRS

(up)

11am-12pm

21/2/19

H.O.D. Endorsement

Date/Time

11:05am 20/2/19

Person Contacted

Stephanie

Vehicle IN /

OUT

Date/Time

Action/Instruction

(✓)

Estimate

SLB8881T-WA/INC 19002234/13

D.O.A: 4/2/19

SHA 3830B - CC3/ALG 18005290/M1p392

D.O.A: 15/3/18

25/2

Forwarded via email preli advise.

lump sum \$3100/-
(Red: 7702, 71%)

Confirm with Stephanie.

Signature

xnd

REF:

Fci

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

MBM wheel power

of

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SLB888IT

Yr Regn:

03 Jun 2016

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda veezel

C.C.

1496

Colour

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

26200

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

RU11116026

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size:

F:

215 / 60 R16

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

21-02-18

Survey held at

w/s

11:45

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 12 APR 2019

Date/Time, File Pass to?

1) 12/4 Typist

Date/Time, File Return to?

2)

Report Format :

TP

Lump Sum / I.B.I: (\$

3100/-

Days Of Repair:

5

Resurvey No. of Trip:

2

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

) \$ + RS, \$

) Photos

) Others

TOTAL

170

50

50+50

70

390



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19001137MFSH

Date: 25/2/2019

Our Ref: CS/FCI19003206/Gtd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLB 8881T

Please be informed that we had conducted the inspection of the abovementioned vehicle 21/2/2019 at the premises of M/s MBM Wheelpower have the following to report: -

Workshop Estimate Amount	: S\$ 10,802.00
Revised Estimate Amount	: S\$ 3,454.00
"Check" Items Amount	: S\$ 1,966.00
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Guo Qiang

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	15-02-2019	Our Ref No. D19001137MFSH
Accident Date	14-02-2019	Claim Type. Third Party
Insured Vehicle	SHA3830B	Third Party Vehicle. SLB8881T
Survey Location	160 SIN MING DRIVE #06-02 SIN MING AUTOCITY	
Contact Person.	STEPHANIE LIN	
Contact No.	62628888/ 86865188	Fax No. 62509015
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	MBM WHEELPOWER PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Monday, 25 February 2019 2:43 PM
To: Admin-D (LKKAUTO); 'CWS Motor Claims'; assignments
Cc: 'May Chua Hui Chin'; SUR
Subject: RE: SURVEY ASSESSMENT - D19001137MFSH/1
Attachments: PRELI ADVISED SLB 8881T.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SLB 8881T**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 20 February 2019 11:08 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'May Chua Hui Chin' <maychua@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19001137MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer arrange on 21/02/2019.

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 19 February 2019 5:47 PM

Denise Tay (LKKAUTO)


From: stephanie.lin@mbmwheelpower.com.sg
Sent: Thursday, 11 April 2019 12:41 PM
To: Denise Tay (LKKAUTO); Guo Qiang (LKKAUTO)
Cc: danny.ong@mbmwheelpower.com.sg
Subject: RE: SLB8881T - DOA 14/02/2019 - FINALISE

Hi Denise,

Confirmed L/S: \$3100/- 05 Days

Warmest Regards,

Stephanie Lin | Claims Officer



T 6262 8888 | F 6250 9015 | M 8686 5188

Email: stephanie.lin@mbmwheelpower.com.sg

MBM Wheelpower Pte Ltd

160 Sin Ming Drive • #06-02

Sin Ming AutoCity • Singapore 575722

www.mbmwheelpower.com.sg

From: Denise Tay (LKKAUTO) <denisetay@lkkauto.com>
Sent: Thursday, 11 April 2019 12:04 PM
To: stephanie.lin@mbmwheelpower.com.sg; Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>
Cc: danny.ong@mbmwheelpower.com.sg
Subject: RE: SLB8881T - DOA 14/02/2019 - FINALISE

Dear Stephanie,

Re-counter on lump sum offer \$3100

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: stephanie.lin@mbmwheelpower.com.sg <stephanie.lin@mbmwheelpower.com.sg>
Sent: Wednesday, 10 April 2019 1:11 PM
To: Denise Tay (LKKAUTO) <denisetay@lkkauto.com>; Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>
Cc: danny.ong@mbmwheelpower.com.sg
Subject: RE: SLB8881T - DOA 14/02/2019 - FINALISE
Importance: High

****3rd reminder****

Enquire Transfer Fee

You may print this page for reference.

Print

> Back to OneMotoring


Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8614D
Vehicle Details	
Vehicle No.:	SLB8881T
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Feb 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X A
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	L15B4036030
Chassis No.:	RU11116026
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$19,752.00
Original Registration Date:	09 Jun 2016
First Registration Date:	09 Jun 2016
Transfer Count:	0
Actual ARF Paid:	\$9,752.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	08 Jun 2026
PARF Rebate Amount:	\$7,314.00
Intended COE Rebate Details	
COE Expiry Date:	08 Jun 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,300.00
COE Rebate Amount:	\$34,512.00
Total Rebate Amount:	\$41,826.00

The information contained herein is correct as at 22 Feb 2019

OK

MBM WHEELPOWER PTE LTD



Your Ref: SHA3830B
Our Ref: SLB8881T

To: FIRST CAP

CC

Fax

Date: 21/2/2019
From: Stephanie
Fax: 64525333
Contact: 86865188
Make / Model: HONDA VEZEL 1.5
Chassis No.: RU11116026
Engine No.: L15B4036030
Year of Make: 2016
Accident Date: 14 February 2019

ESTIMATE FOR VEHICLE NO.: SLB8881T

DESCRIPTION

TAILGATE / BNC
TAILGATE INNER TRIM BOARD X / CRA
TAILGATE INNER TRIM BOARD CLIPS X / CRA
TAILGATE WEATHER STRIP X / CRA
TAILGATE "HONDA" LOGO X NN
TAILGATE "VEZEL" EMBLEM X MC.
TAIL GATE HINGE LH X
TAIL GATE HINGE RH X
TAIL GATE LOCK X
TAIL GATE STRIKER X NN
TAILGATE LAMP RH X
TAILGATE LAMP LH X
TAIL LAMP RH X
TAIL LAMP LH X
REAR WINDSCREEN MOULDING X MC.
REAR BUMPER X MC.
REAR BUMPER UPP LH COVER X NN
REAR BUMPER UPP RH COVER X NN
REAR BUMPER CLIPS X MC.
REAR BUMPER SIDE RETAINER RH X
REAR BUMPER SIDE RETAINER LH X NN
REAR BUMPER RH REFLECTOR X
REAR BUMPER LH REFLECTOR X
END PANEL X Repair
END PANEL TOP GARNISH X MC
END PANEL TOP GARNISH CLIPS X MC

QTY		List Price
1	\$	1100 ✓ 1,630.00
1	\$	225 ✓ 460.00
10	\$	30(SN) ✓ 60.00
1	\$	165 ✓ 180.00
1	\$	✓ 85.00
1	\$	65 ✓ 90.00
1	\$	✓ 155.00
1	\$	✓ 155.00
1	\$	✓ 180.00
1	\$	✓ 130.00
1	\$	✓ 540.00
1	\$	✓ 540.00
1	\$	✓ 630.00
1	\$	✓ 630.00
1	\$	120 ✓ 150.00
1	\$	863.5 ✓ 1,180.00
1	\$	✓ 290.00
1	\$	✓ 290.00
10	\$	30(SN) ✓ 60.00
1	\$	✓ 85.00
1	\$	✓ 85.00
1	\$	X ✓ 165.00
1	\$	✓ 165.00
1	\$	✓ 950.00
1	\$	100 ✓ 195.00
10	\$	20 ✓ 60.00
Total: \$		9,140.00
LESS 20% \$		(1,828.00)
Parts Total: \$		7,312.00

SPECIAL NETT

BODY SEALANT	X NN	1	\$	40	80.00
WINDSCREEN SEALANT	/ H.	1	\$	40	80.00
REAR BUMPER SENSORS	3/ DM	1	\$	200	400.00
REAR NUMBER PLATE WITH FRAME	X NN	1 SET	\$	X	50.00

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS.	\$	500	500	1,000.00
TO REMOVE & REFIT REAR WINDSCREEN	\$	100	100	150.00
TO REMOVE & REPLACE REAR END PANEL LINING & GARNISH TO FACILITATE REPAIR	\$	60	60	100.00
TO DISMANTLE & TRANSFER TAILGATE FITTINGS & MECHANISM TO NEW TAILGATE / FACILITATE REPAIR	\$	60	60	120.00
TO REALIGN EXHAUST PIPE	\$	NN	X	60.00
TO CONDUCT ALL WHEEL COMPUTERISED ALIGNMENT	\$	NN	X	80.00
TO CHECK & RECONNECT ALL NECESSARY WIRING	\$	30	30	120.00
TO REMOVE & REPLACE BUMPER SENSORS	\$	40	40	100.00
TO APPLY ANTI RUST COATING	\$	40	40	250.00
TO SPRAY PAINT ON THE AFFECTED AREAS	\$	500	500	900.00
Total:	\$	500	500	10,802.00
7% GST:	\$			756.14
Grand Total:	\$			11,558.14

4 Days.

lumpsum repair.

After repair photos.

Gmo Qiao - 82880282

21/2/19.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Mbm wheelpower pte ltd

160 SIN MING DRIVE #06-02

SIN MING AUTOCITY

t62628888 t64525333

Company Registration Number : 200204110W

MBM WHEELPOWER PTE LTD



Your Ref: SHA3830B
Our Ref: SLB8881T

To: FIRST CAP

CC

Fax

Date: 25/3/2019
From: Stephanie
Fax: 64525333
Contact: 86865188
Make / Model: HONDA VEZEL 1.5
Chassis No.: RU11116026
Engine No.: L15B4036030
Year of Make: 2016
Accident Date: 14 February 2019

ESTIMATE FOR VEHICLE NO. : SLB8881T

DESCRIPTION

TAILGATE
TAILGATE INNER TRIM BOARD
TAILGATE INNER TRIM BOARD CLIPS
TAILGATE WEATHER STRIP
TAILGATE "VEZEL" EMBLEM
REAR WINDSCREEN MOULDING
REAR BUMPER
REAR BUMPER CLIPS
REAR BUMPER LH REFLECTOR
END PANEL
END PANEL TOP GARNISH
END PANEL TOP GARNISH CLIPS

QTY		List Price	
1	\$	1100	1,630.00
1	\$	225	460.00
10	\$	30(SN)	60.00
1	\$	165	180.00
1	\$	65	90.00
1	\$	120	150.00
1	\$	202.5	1,180.00
10	\$	30(SN)	60.00
1	\$	/	165.00
1		REPAIR	
1	\$	100	195.00
10	\$	26	60.00
Total: \$			4,230.00
LESS 20% \$			(846.00)
Parts Total: \$			3,384.00

2829.5
20%: 263.6

SPECIAL NETT

BODY SEALANT	1	\$	40.00
WINDSCREEN SEALANT	1	\$	40.00
REAR BUMPER SENSORS	1	\$	200.00

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS.	\$	500.00
TO REMOVE & REFIT REAR WINDSCREEN	\$	100.00
TO REMOVE & REPLACE REAR END PANEL LINING & GARNISH TO FACILITATE REPAIR	\$	60.00
TO DISMANTLE & TRANSFER TAILGATE FITTINGS & MECHANISM TO NEW TAILGATE / FACILITATE REPAIR	\$	60.00
TO CHECK & RECONNECT ALL NECESSARY WIRING	\$	30.00
TO REMOVE & REPLACE BUMPER SENSORS	\$	40.00
TO APPLY ANTI RUST COATING	\$	40.00
TO SPRAY PAINT ON THE AFFECTED AREAS	\$	500.00
Total:	\$	4,994.00
Less 20% Lump Sum	\$	(998.80)
	\$	3,995.20

LUMP SUM REPAIR	\$	4,000.00
------------------------	-----------	-----------------

3937.6
20% 3150



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19003206/Gtd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 16-04-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 3830B	Veh. Inspected	SLB 8881T	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19001137MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	20/02/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	RU11116026	Colour	BLACK	
Odometer	26200	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DUNLOP	6 mm	
L/H Front Tyre	215/60 R16	DUNLOP	6 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/02/2019	Inspection Date	21/02/2019	
Survey held at	MBM WHEELPOWER PTE LTD 176 SIN MING DRIVE #01-15 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLB 8881T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAILGATE	BUCKLED	1,630.00	1,100.00
1	TAILGATE INNER TRIM BOARD	CRACKED	460.00	225.00
1	TAILGATE WEATHER STRIP	TORN	180.00	165.00
1	TAILGATE "HONDA" LOGO	NOT NECESSARY	85.00	-
1	TAILGATE "VEZEL" EMBLEM	NECESSARY	90.00	65.00
1	TAIL GATE HINGE LH	NOT NECESSARY	155.00	-
1	TAIL GATE HINGE RH	NOT NECESSARY	155.00	-
1	TAIL GATE LOCK	NOT NECESSARY	180.00	-
1	TAIL GATE STRIKER	NOT NECESSARY	130.00	-
1	TAILGATE LAMP RH	NOT NECESSARY	540.00	-
1	TAILGATE LAMP LH	NOT NECESSARY	540.00	-
1	TAIL LAMP RH	NOT NECESSARY	630.00	-
1	TAIL LAMP LH	NOT NECESSARY	630.00	-
1	REAR WINDSCREEN MOULDING	NECESSARY	150.00	120.00
1	REAR BUMPER	DEFORMED	1,180.00	863.50
1	REAR BUMPER UPP LH COVER	NOT NECESSARY	290.00	-
1	REAR BUMPER UPP RH COVER	NOT NECESSARY	290.00	-
1	REAR BUMPER SIDE RETAINER RH	NOT NECESSARY	85.00	-
1	REAR BUMPER SIDE RETAINER LH	NOT NECESSARY	85.00	-
1	REAR BUMPER RH REFLECTOR	NOT NECESSARY	165.00	-
1	REAR BUMPER LH REFLECTOR	CRACKED	165.00	165.00
1	END PANEL	TO REPAIR SEE LABOUR	950.00	-
1	END PANEL TOP GARNISH	DEFORMED	195.00	100.00
10	END PANEL TOP GARNISH CLIPS	NECESSARY	60.00	26.00
	LESS 20% DISCOUNT		-1,804.00	-565.90
			7,216.00	2,263.60
10	TAILGATE INNER TRIM BOARD CLIPS (SN)	NECESSARY	60.00	30.00
10	REAR BUMPER CLIPS (SN)	NECESSARY	60.00	30.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 20% DISCOUNT		-24.00	-
			96.00	60.00
	<u>SPECIAL NETT ITEMS</u>			
1	BODY SEALANT (SN)	NECESSARY	80.00	40.00
1	WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	REAR BUMPER SENSORS (SN)	DAMAGED	400.00	200.00
1	SET REAR NUMBER PLATE WITH FRAME (SN)	NOT NECESSARY	50.00	-
			610.00	280.00
	<u>LABOUR</u>			
	TO REMOVE,REFIT & REPAIR AFFECTED DAMAGED PARTS,INCLUDING TO KNOCK-OUT,WELD & STRAIGHTEN ON THE AFFECTED PARTS.INCLUSIVE OF THE REPAIR OF END PANEL.		1,000.00	500.00
	TO REMOVE & REFIT REAR WINDSCREEN.		150.00	100.00
	TO REMOVE & RELACE REAR END PANEL LINING & GARNISH TO FACILIATE REPAIR.		100.00	60.00
	TO DISMANTLE & TRANSFER TAILGATE FITTINGS & MECHANISM TO NEW TAILGATE/FACILIATE REPAIR.		120.00	60.00
	TO REALIGN EXHAUST PIPE.	NOT NECESSARY	60.00	-
	TO CONDUCT ALL WHEEL COMPUTERISED ALIGNMENT.	NOT NECESSARY	80.00	-
	TO CHECK & RECONNECT ALL NECESSARY WIRING.		120.00	30.00
	TO REMOVE & REPLACE BUMPER SENSORS.		100.00	40.00
	TO APPLY ANTI RUST COATING.		250.00	40.00
	TO SPRAY PAINT ON THE AFFECTED AREAS.		900.00	500.00
			2,880.00	1,330.00
	GRAND TOTAL		10,802.00	3,933.60
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,100.00

Report Ref No. CS/FC19003206/Gtd3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.