

ASS. REC. BY

REF: es/FCI 19 003207 / RHD3¹²

Special Instruction

Surveyor

Raru

ASSIGNMENT (Office)

WS

Henry Kao

FCI

Date/Time: 5:50 pm @ 19/2/19

Estimated Cost

Bill to

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLB 980T

Insured

SHB 2100B

at Workshop in/s

Hitiuehi Capital

Tel:

68336282 / 96506439

of

No. 8 Fourth 10c Yung Rd

Policy No:

Claim No:

D19001085MPH

Sum Insured:

Excess:

Make of Veh:

DOA 12/02/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

11:08 am @ 20/2/19

Person Contacted:

Jung Hw

Vehicle

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLB 980T-

SHB 2100B - CS/FCI 18018498 / Dtd 302

DOA: 9/10/18


8/3/2019 @ 11:27 am - revised via preli advise

Part by Part \$50651 (Red: 1956.25: 270%)

John

0399N

Make _____ Date _____
Engine No. _____
Chassis No. _____
Type of Vehicle: SLB 980T
Make/Model: HITACHI CAPTOR
Insured: D. POWER LOK YANAH RN
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____
(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.
Bal. or Market Value: _____
OAC / Recent Repat: _____ Consistent? : Yes or No
GIA / PE Seen: _____ Consistent? : Yes or No
Est. Repair: _____ days: Res.: Yes or No
Lum Sum: _____ %: 3 Val: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____ Vehicle: IN / OUT



SLB 980T 2016 MAR
Type: ☒ Car / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Truck / ☐ Trailer or
Make: TOYOTA VELLFIRE 2.5A 2494
Colour: black AC Insured / Std / Nil / NA
Sp/Reading: 365018 I/Radio: Insured / Std / Nil / NA
EngNo: 3TN6F3DH 208004336
ChNo: _____
Gen. Cond: Good ☒ Fair / Poor / Burnt
Steering: ☒ Good / Jammed / Leaked / Burnt or
Brake: ☒ Good / Jammed / Leaked / Burnt or
Mod: Nil ☒ STD A/Rim or
Tyre Size: F: 295/50ZR18
R: _____
BS / ☒ EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front: _____ Rear: _____
R/Bal: 6 mm R/Bal: 6 mm
L/Bal: 6 mm L/Bal: 6 mm
D.O.A: 12/02/19 D.O.L: 20/02/19
Survey held at: HITACHI
Des. of Damages: Frl / Rear / O/S ☒ N/S / UIC / Rooftop or
The UIC / Chassis frame / Body Structure affected due to collision.

RECEIVED 10 JUN 2019

Date/Time: 14/06/2019
10/6 Typst
Date/Time: 14/06/2019
☐ Preli. Report
☒ Final Report

Days Of Repair: 5
Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp. 15
☐ Interview 15
☐ Tech Insp 15
☐ W.A. 15

Survey Fee:
Transportation
1. 5.00
2. 1.00
3. 1.00
4. 1.00
5. 1.00
6. 1.00
7. 1.00
8. 1.00
9. 1.00
10. 1.00
11. 1.00
12. 1.00
13. 1.00
14. 1.00
15. 1.00
16. 1.00
17. 1.00
18. 1.00
19. 1.00
20. 1.00
21. 1.00
22. 1.00
23. 1.00
24. 1.00
25. 1.00
26. 1.00
27. 1.00
28. 1.00
29. 1.00
30. 1.00
31. 1.00
32. 1.00
33. 1.00
34. 1.00
35. 1.00
36. 1.00
37. 1.00
38. 1.00
39. 1.00
40. 1.00
41. 1.00
42. 1.00
43. 1.00
44. 1.00
45. 1.00
46. 1.00
47. 1.00
48. 1.00
49. 1.00
50. 1.00
51. 1.00
52. 1.00
53. 1.00
54. 1.00
55. 1.00
56. 1.00
57. 1.00
58. 1.00
59. 1.00
60. 1.00
61. 1.00
62. 1.00
63. 1.00
64. 1.00
65. 1.00
66. 1.00
67. 1.00
68. 1.00
69. 1.00
70. 1.00
71. 1.00
72. 1.00
73. 1.00
74. 1.00
75. 1.00
76. 1.00
77. 1.00
78. 1.00
79. 1.00
80. 1.00
81. 1.00
82. 1.00
83. 1.00
84. 1.00
85. 1.00
86. 1.00
87. 1.00
88. 1.00
89. 1.00
90. 1.00
91. 1.00
92. 1.00
93. 1.00
94. 1.00
95. 1.00
96. 1.00
97. 1.00
98. 1.00
99. 1.00
100. 1.00

150
50
50
126
376

Report Format: TP
Temp Sum: 5065



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19001085MFSH

Date: 8/3/2019

Our Ref: CS/FCI19003207/R1td3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLB 980T

Please be informed that we had conducted the inspection of the abovementioned vehicle 20/02/2019 at the premises of M/s Hitachi Capital have the following to report: -

Workshop Estimate Amount	: S\$	<u>6,533.75</u>
Revised Estimate Amount	: S\$	<u>5,702.50</u>
"Check" Items Amount	: S\$	<u>0.00</u>
Market Value	: S\$	<u> </u>
LTA Reimbursement Value	: S\$	<u> </u>
Nett Value	: S\$	<u> </u>

Description of Damage:

The vehicle sustained damages at the n/s portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Rasul

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	13-02-2019	Our Ref No. D19001085MFSH
Accident Date	12-02-2019	Claim Type. Third Party
Insured Vehicle	SHB2100B	Third Party Vehicle. SLB980T
Survey Location	JUN TAIYO SERVICE CENTRE NO 8 FOURTH LOK YANG ROAD	
Contact Person.	NG JIONG HOW	
Contact No.	64663022/ 0	Fax No. 68966591
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	HITACHI CAPITAL ASIA PACIFIC PTE. LTD.	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	HENRY KAO	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Friday, 8 March 2019 11:27 AM
To: Admin-D (LKKAUTO); 'CWS Motor Claims'; assignments
Cc: 'Henry Kao Cai Jie'; SUR
Subject: RE: SURVEY ASSESSMENT - D19001085MFSH/1
Attachments: PRELI ADVISED SLB 980T.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SLB 980T**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 20 February 2019 11:11 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Henry Kao Cai Jie' <HenryKao@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19001085MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 19 February 2019 5:50 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Henry Kao Cai Jie

Denise Tay (LKKAUTO)

From: JiongHow, Ng <jionghow.ng@hcspl.com.sg>
Sent: Monday, 10 June 2019 11:47 AM
To: Denise Tay (LKKAUTO); Vonn, LM Siow
Cc: Jamilah, Binte MohdKassim; SUR
Subject: RE: SLB980T / SHB2100B TP CLAIM FCIL DOA: 12/02/2019 LIABILITY

Hi Denise,

COR confirmed

Thank you

Regards

Ng Jiong How
Motor Claims Advisor
Auto Servicing
Total Vehicle Solutions Department

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre (Automobile Leasing & Workshop)
8 Fourth Lok Yang Road Singapore 629705
t: 6833 6282
e: jionghow.ng@hcspl.com.sg
w: www.hitachi-capital.com.sg

HITACHI
Inspire the Next

DISCLAIMER:

This email and/or any files and/or attachments transmitted are PRIVATE & CONFIDENTIAL and may be LEGALLY PRIVILEGED.
This email is intended solely for the attention and use of the name addressee(s).
If you are not a named addressee, you must not use, disseminate, forward, print or copy this email and all its contents/attachments.
If you have received this email in error, please notify the sender immediately by email and delete it from your system.

From: Denise Tay (LKKAUTO) <denisetay@lkkauto.com>
Sent: Monday, June 10, 2019 10:06 AM
To: JiongHow, Ng <jionghow.ng@hcspl.com.sg>; Vonn, LM Siow <vonnlm.siow@hcspl.com.sg>
Cc: Jamilah, Binte MohdKassim <jamilahbegum@hcspl.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SLB980T / SHB2100B TP CLAIM FCIL DOA: 12/02/2019 LIABILITY

Dear Jiong How,

Any confirmation?

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
 Tel : 64663022 Fax : 68966591
 Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

VEHICLE ESTIMATE

FCIL

ATTN: MOTOR CLAIMS DEPT

QUOTE NO :
 ACCIDENT DATE : 12/02/2019@1255HRS
 VRN : SLB80T
 MODEL : Toyota Vellfire
 TP VRN : SHB2100B

	<u>Qty</u>	<u>S\$ Unit</u>	<u>S\$ Amt</u>	<u>S\$ Labor</u>
<u>PARTS REPLACEMENT</u>				
<u>1. Body Repair</u>				
1 Rear Door LH BA ✓	1	\$ 2,500.00	\$ 2,500.00	
2 Rear Door Protector LH SC ✓	1	\$ 765.00	\$ 765.00	
3 Rear Fender LH repair	1	\$ 1,500.00	\$ 1,500.00	
4 Rear Bumper DE ✓	1	\$ 635.00	\$ 635.00	
5 Rear Bumper Outer Bracket LH/RH free 1pc ✓	1	\$ <u>135.00</u>	\$ 270.00	
6 Rear Bumper Clips ✓	10	\$ 5.50	\$ 55.00	
Discount 25%			\$ (1,431.25)	
TOTAL			\$ 4,293.75	

2. Labor Charges

1 Panel beat, cut, weld, re-align & replace damaged parts of affected area	700 \$ 1,000.00
2 Spray painting on rear portion of affected area	750 \$ 1,000.00
3 Remove & reinstall 2 pieces bumper sensors	\$60 120.00
4 Remove & reinstall rear reverse camera	1pc X 120.00

Sub Total : \$ 2,240.00

Grand Total : \$ 6,533.75
 Add 7% GST : \$ 457.36
 Nett Total : \$ 6,991.11

No. of repair days: 5

Rasul
Hp 90010068
5 days
P/P
20/02/19 @ 1650
Repair b4 paint

7021-25

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No financial modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

CUSTOMER SIGNATURE

Acknowledged by Repairer
 Signature:
 Date:

HITACHI CAPITAL ASIA PACIFIC PTE LTD
 (MANAGER)

No. 8 Fourth Lok Yang Road Singapore 629705
Tel : 64663022 Fax : 68966591
Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

FCIL

ATTN: MOTOR CLAIMS DEPT

QUOTE NO :
ACCIDENT DATE : 12/02/2019@1255HRS
VRN : SLB80T
MODEL : Toyota Vellfire
TP VRN : SHB2100B

1. Body Repair

1 Rear Fender Protector LH	1	\$	325.00	\$	325.00
2 Rear Bumper Cover LH	1	\$	325.00	\$	325.00
Discount 25%				\$	(162.50)
TOTAL				\$	487.50

2. Labor Charges

Sub Total : \$ -

Grand Total	:	\$	487.50
Add 7% GST	:	\$	34.13
Nett Total	:	\$	521.63

No. of repair days: 0

CUSTOMER SIGNATURE

HITACHI CAPTIAL ASIA PACIFIC PTE LTD
(MANAGER)

Parts - \$4090.00
-25% - \$1022.50

\$3068.00

Labour - \$1510.00

\$4578.00

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705

Tel : 64663022 Fax : 68966591

Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

Supp - \$650.00

-25% - \$162.50

\$487.50

Total - \$5065.50

FCIL

ATTN: MOTOR CLAIMS DEPT

5/1/19 20/3/19

B4 spray

1. Body Repair

PARTS REPLACEMENT

	Qty	S\$ Unit	S\$ Amt	S\$ Labor
✓ 1 Rear Door LH BA ✓	1	\$ 2,500.00	\$ 2,500.00 ✓	
✓ 2 Rear Door Protector LH SC ✓	1	\$ 765.00	\$ 765.00 ✓	
3 Rear Fender LH repair	1	\$ 1,500.00	\$ 1,500.00	
✓ 4 Rear Bumper DE ✓	1	\$ 635.00	\$ 635.00 ✓	
✓ 5 Rear Bumper Outer Bracket LH/RH ✓	1	\$ 135.00	\$ 270.00 ✓	
6 Rear Bumper Clips	10	\$ 5.50	\$ 55.00 ✓	

Discount 25%

\$ (1,431.25)

TOTAL \$ 4,293.75

2. Labor Charges

- 1 Panel beat, cut, weld, re-align & replace damaged parts of affected area
- 2 Spray painting on rear portion of affected area
- 3 Remove & reinstall 2 pieces bumper sensors
- 4 Remove & reinstall rear reverse camera

700 \$ 1,000.00
750 \$ 1,000.00
\$60 120.00
\$ X 120.00

Sub Total : \$ 2,240.00

Rasul
Hp 90010068

Grand Total : \$ 6,533.75
Add 7% GST : \$ 457.36
Nett Total : \$ 6,991.11

No. of repair days: 5

5 days

P/P

20/02/19 @ 1650

Repair b4 paint

LKK Auto Consultants hence notify the Repairer of the following:
• To resume work after spray painting
• To display damaged part(s) during recovery
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis

CUSTOMER SIGNATURE

• Supplementary claims must be received and shall be subject to final approval from insurance company
• An invoice to be provided

HITACHI CAPITAL ASIA PACIFIC PTE LTD
(MANAGER)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19003207/R1td3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 11-06-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 2100B	Veh. Inspected	SLB 980T	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19001085MFSH	Excess (\$)	0.00	
Assign From	HENRY KAO	Assign Date	19/02/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA VELLFIRE 2.5 A	c.c	2494	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JTNGF3DH208004336	Colour	BLACK	
Odometer	365018	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	295/50 ZR18	DUNLOP	6 mm	
L/H Front Tyre	295/50 ZR18	DUNLOP	6 mm	
R/H Rear Tyre	295/50 ZR18	DUNLOP	6 mm	
L/H Rear Tyre	295/50 ZR18	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/02/2019	Inspection Date	20/02/2019	
Survey held at	HITACHI CAPITAL (S) PTE LTD JUN TAIYO SERVICE CENTRE NO. 8 FOURTH LOK YANG ROAD SINGAPORE 629705			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLB 980T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR DOOR LH	BENT	2,500.00	2,500.00
1	REAR DOOR PROTECTOR LH	SCRATCHED	765.00	765.00
1	REAR FENDER LH	TO REPAIR SEE LABOUR	1,500.00	-
1	REAR BUMPER	DEFORMED	635.00	635.00
2	REAR BUMPER OUTER BRACKET LH/RH @\$135.00	N/S NECESSARY	270.00	135.00
10	REAR BUMPER CLIPS @\$5.50	NECESSARY	55.00	55.00
1	REAR FENDER PROTECTOR LH (ADDITIONAL)	SCRATCHED	325.00	325.00
1	REAR BUMPER COVER LH (ADDITIONAL)	SCRATCHED	325.00	325.00
	LESS 25% DISCOUNT		-1,593.75	-1,185.00
			4,781.25	3,555.00
	<u>LABOUR</u>			
	PANEL BEAT,CUT,WELD,RE-ALIGN & REPLACE DAMAGED PARTS OF AFFECTED AREA.INCLUSIVE OF THE REPAIR OF REAR FENDER LH.		1,000.00	700.00
	SPRAY PAINTING ON REAR PORTION OF AFFECTED AREA.		1,000.00	750.00
	REMOVE & REINSTALL 2 PIECES BUMPER SENSORS.		120.00	60.00
	REMOVE & REINSTALL REAR REVERSE CAMERA.	NOT NECESSARY	120.00	-
			2,240.00	1,510.00
	GRAND TOTAL		7,021.25	5,065.00
	RECOMMENDED COST OF REPAIRS			5,065.00

Report Ref No. CS/FCI19003207/R1td3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI**

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.