

ASS. REC. BY

REF es/FCI/19003209/Agd3 ⁿ²

Special Instructions

Surveyor

ASSIGNMENT (Office)

CWS

From Person: Merina Chia

of FCI

Date/Time: 5:27pm @ 10/2/19

Estimated Cost:

Bill to:

OD / (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMD 6442T

Insured: SHA 9154E

at Workshop n/s: BW workshop

Tel: 62898800

of 30 Ubi Rd 4

Policy No:

Claim No: D19000993 MP&H

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 06/02/2019

CA / REV / REP. / REV 24 HRS ¹⁰⁵

22/2/19 @ 4pm

H.O.D. Endorsement:

Date/Time: 18:50pm @ 20/2/19

Person Contacted: Justin

Vehicle IN/OUT

Date/Time	Action/Instruction (—) Estimate
	<u>SMD 6442T-X</u>
	<u>SHA 9154E - C/FCI/18011079/R16d3n2</u> <u>DOA: 16/6/18</u>
<u>7/2/19 @ 2:43pm</u>	<u>Informed Merina Chia, we are pending estimate from repairer.</u>
<u>10/4/19 @ 10:41am</u>	<u>revised to Merina Chia by email.</u>
	<u>Final trig @ 1177.50, 3 days (red @ 1178.75, 49%)</u>

REF: FCI

INVESTIGATION

Date: 22/2/19

Insured's Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Inspected Vehicle No.

at Workshop no.

Ref

Insured

Policy No.

Claim No.

Sum Insured

Excess

(Client's Record)

Make of Vch.

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS (ps)

Date:

Person Contacted:

Vehicle IN / OUT

Vch No: SMD6442T.

Date: 2018 August.

Type: ☒ Car / ☐ Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: Toyota Noah Hybrid, cc 1797

Colour: Black / ☐ Insured / ☐ Std / ☐ NI / NASp Reading: 10644. / ☐ Radio Insured / ☐ Std / ☐ NI / NA

Eng/Ho.

Ch/Ho.

ZWR800319228.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ Inorder / ☒ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ Inorder / ☒ Jammed / ☐ Leaked / ☐ Burnt orMod: Nil / ☒ SRim / ☐ STD ARim or

Tyre Size:

F:

195/65R15

R:

195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

06

mm

R/Bal:

06

mm

L/Bal:

06

mm

L/Bal:

06

mm

D.O.A.

D.O.I

22/02/19.

Survey held at

BW.

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear N/S.

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP 1st Cap.

RECEIVED 10 APR 2019

Date/Time: File Pass to?



Preli. Report



Final Report

Date/Time: File Return to?

No

Report Format:

7P

Lump Sum / LB L/C

M7.50

Days Of Repair:

3

Resurvey No. of Trip:

1

Add Fee:



Site Insp: £



Interview: £



Team Insp: £



Work and £

Survey Fee:

Transportation:

1. 5.00

2. 1.00

3. 1.00

4. 1.00

Total

110
50
50
11
221



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19000993MFSH

Date: 10 April 2019

Our Ref: CS/FCI19003209/Aqd3

The Motor Claims Department
MS First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SMD 6442T .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 22/02/2019 at the premises of M/s BW WORKSHOP. and have the following to report:-

Workshop Estimate Amount	: S\$ 2,396.25 .
Revised Estimate Amount	: S\$ 1,217.50 .
"Check" Items Amount	: S\$ - .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages at the rear n/s portion.



Yours faithfully

ADRIAN LING WAI PING
B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	11-02-2019	Our Ref No. D19000993MFSH
Accident Date	06-02-2019	Claim Type. Third Party
Insured Vehicle	SHA9154E	Third Party Vehicle. SMD6442T
Survey Location	30 UBI ROAD 4	
Contact Person.	JUSTIN EE	
Contact No.	52898800/ 0	Fax No. 68582120
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	BW WORKSHOP SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MERINA CHIA SAN SAN	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 10 April 2019 10:41 AM
To: 'CWS Motor Claims'; assignments
Cc: 'Merina Chia San San'; SUR
Subject: RE: SURVEY ASSESSMENT - D19000993MFSH/1
Attachments: CSFCI19003209Aqd3.pdf

Dear Merina,

Enclosed herewith preliminary advice of SMD 6442T.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 25 February 2019 2:43 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Merina Chia San San' <MerinaChia@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000993MFSH/1

Dear Merina,

Please be informed that we have inspected the vehicle SMD 6442T on 22/02/2019.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 20 February 2019 10:52 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Merina Chia San San' <MerinaChia@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000993MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer arrange on 22/02/2019.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 25 February 2019 2:43 PM
To: 'CWS Motor Claims'; assignments
Cc: 'Merina Chia San San'; SUR
Subject: RE: SURVEY ASSESSMENT - D19000993MFSH/1

Dear Merina,

Please be informed that we have inspected the vehicle SMD 6442T on 22/02/2019.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 20 February 2019 10:52 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Merina Chia San San' <MerinaChia@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000993MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer arrange on 22/02/2019.

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 19 February 2019 5:27 PM
To: ASSIGNMENTS@LKKAUTO.COM

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 1250D

Vehicle Details

Vehicle No.: SMD6442T
Vehicle to be Exported: Yes
Intended Deregistration Date: 18 Feb 2019
Vehicle Make: TOYOTA
Vehicle Model: NOAH HYBRID 1.8X CVT
Primary Colour: Black
Manufacturing Year: 2018
Engine No.: 2ZR0B51732
Chassis No.: ZWR800319228
Maximum Power Output: 100.0 kW (134 bhp)
Open Market Value: \$33,636.00
Original Registration Date: 29 Aug 2018
First Registration Date: 29 Aug 2018
Transfer Count: 0
Actual ARF Paid: \$29,091.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 28 Aug 2028
PARF Rebate Amount: \$21,818.00

Intended COE Rebate Details

COE Expiry Date: 28 Aug 2028
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$32,429.00
COE Rebate Amount: \$25,943.00
Total Rebate Amount: \$47,761.00

The information contained herein is correct as at 18 Feb 2019

OK

BW WORKSHOP SERVICES PTE. LTD.

30 UBI ROAD 4 SINGAPORE 408615

TEL: 5289 8800 FAX: 6858 2120

GST REG NO : 201504834E

TP 1st Cap
Xiao Chan.

Estimate

To : **FIRST CAPITAL INSURANCE** DATE : **18/2/2019**
Attn : **Claims Officer**
CC : **1499** VEHICLE NO : **SMD 6442 T**
YEAR : **2018** CHASSIS NO : **ZWR800319228**
MODEL : **TOYOTA NOAH HYBRID 1.8X** PAGE : **1 OF 1**

Please quote the following items listed.

Third Party Claims

S/NO	ITEMS	Qty	Price
1	Rear bumper <i>Rehnd</i>	1	\$650.00
2	Rear bumper reflector - LH <i>re on</i>	1	\$75.00
3	Rear bumper side retainer - LH (Inner) <i>ace</i>	1	\$85.00
4	Rear bumper side retainer - LH (Outter) <i>ace</i>	1	\$145.00
5	Rear bootlid <i>Repair</i>	1	REPAIR
			\$955.00
Discount 25%			\$238.75
TOTAL :			\$716.25

22

650

487.50

BW WORKSHOP SERVICES PTE. LTD.

30 UBI ROAD 4 SINGAPORE 408615

TEL: 5289 8800 FAX: 6858 2120

GST REG NO : 201504834E

Estimate

To : **FIRST CAPITAL INSURANCE** DATE : 18/2/2019
Attn : **Claims Officer**
CC : **1499** VEHICLE NO : **SMD 6442 T**
YEAR : **2018** CHASSIS NO : **ZWR800319228**
MODEL : **TOYOTA NOAH HYBRID 1.8X** PAGE : **1 OF 1**

S/NO	LABOURS	AMOUNT
1	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIT AND TO RENEW AFFECTED PARTS. \$300/ Per Days	\$ 600.00
2	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS. \$280/ Per Panel	\$ 840.00
3	DISCONNECT AND CHECK ELECTRICAL WIRING, HARNESS, WIRE SOCKETS, ETC. REMOVE AND REINSTALL DAMAGED PARTS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	\$ 120.00
4	REMOVE AND REPLACE BUMPER SENSOR.	\$ 120.00

Working Days : 4 Days.

730

NOTE: ALL QUOTED PRICE IS SUBJECT TO 7% GST

TOTAL : \$1,680.00
PARTS TOTAL : \$716.25
GRAND TOTAL : \$2,396.25

Adrian Lj
P/p 22/02/19.

63 days.

total: 1217.50
(P/P)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19003209/Aqd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 11-04-2019		
		Code : FC12		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 9154E	Veh. Inspected	SMD 6442T	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19000993MFSH	Excess (\$)	0.00	
Assign From	MERINA CHIA	Assign Date	19/02/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA NOAH HYBRID	c.c	1797	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	ZWR800319228	Colour	BLACK	
Odometer	10644	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	YOKOHAMA	6 mm	
L/H Front Tyre	195/65 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm	
L/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/02/2019	Inspection Date	22/02/2019	
Survey held at	BW WORKSHOP SERVICES PTE LTD 30 UBI ROAD 4 SINGAPORE 408615			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMD 6442T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DEFORMED	650.00	650.00
1	REAR BUMPER REFLECTOR-LH	NOT NECESSARY	75.00	-
1	REAR BUMPER SIDE RETAINER-LH (INNER)	NOT NECESSARY	85.00	-
1	REAR BUMPER SIDE RETAINER-LH (OUTTER)	NOT NECESSARY	145.00	-
1	REAR BOOTLID (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 25% DISCOUNT		-238.75	-162.50
			716.25	487.50
	LABOUR			
	TO REMOVE,CUT OUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIT AND TO RENEW AFFECTED PARTS.INCLUSIVE OF THE REPAIR OF REAR BOOTLID.		600.00	250.00
	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.		840.00	400.00
	DISCONNECT AND CHECK ELECTRICAL WIRING,HARNESS,WIRE SOCKETS,ETC.REMOVE AND REINSTALL DAMAGED PARTS.TEST AND RECTIFY FOR PROPER FUNCTIONING.		120.00	30.00
	REMOVE AND REPLACE BUMPER SENSOR.		120.00	50.00
			1,680.00	730.00
GRAND TOTAL			2,396.25	1,217.50
RECOMMENDED COST OF REPAIRS				1,217.50

Report Ref No. CS/FCI19003209/Aqd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.