

ASS. REC. BY:

REF:

08/FCI/19003212/T1s d302

Special Instruction:

Surveyor:

CWS

ASSIGNMENT (Office)

From (Person):

Mentira Chica

of

FCI

Date/Time:

11:30am @ 20/2/19

Estimated Cost:

Bill to:

OD / TI / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

SLV 4854T

Insured:

SHB3462A

at Workshop m/s:

Wecmes

Tel:

81261237

of

249 Alexandra Road

Policy No:

Claim No:

D19001168MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

14/2/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

(DS)

H.O.D. Endorsement:

Date/Time:

12:00pm @ 20/2/19

Person Contacted:

Paul

Vehicle-IN

OUT

Date/Time

Action/Instruction

(✓)

Estimate

SLV 4854T-X

SHB 3462A-CCP/AXA/6023043/Alha392

DOA: 1/2/16

20/2/19

@ 16:14 pm. received PA to memo via email

Taufik


REF:

FEL

WORLDWIDE

From: _____ Date: _____
 Estimated Cost: _____
 OIL / TP / WBS / FF RES / FO RES / EVA / HV / MV
 Is it a post-accident file?
 at Work Shop?
 of _____
 Insured?
 Policy No.
 Claim No.
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh:

Vehicle: **SLV 4854T** at Year: **2017 Dec.**
 Type: **Car** / Motorcycle / Bus / Van / Lorry / Truck / Prime Mover /
 Truck / Trailer or
 Make: **Land Rover Range Rover Evoque** Co: **1999**
 Color: **Red** Insured / Std / NI / NA
 Cap. Loading: **16/22** Radio Insured / Std / NI / NA
 Engine: **SALVA2AG2H4224175**
 Cyls: _____
 Gen. Cond: **Good** / Fair / Poor / Burnt
 Steering: **In order** / Jammed / Leaked / Burnt or
 Brake: **In order** / Jammed / Leaked / Burnt or
 Mod: **Nil** / R/Rm / STD / R/Rm or
 Tyre Size: **F: 235/55R19**
 R: **235/55R19**
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: **6** mm Rear: **6** mm
 R/Bal: **6** mm L/Bal: **6** mm
 D.O.A. **4/3/19 or 24/5**
 Survey held at: **Wanar 45 by Mr**
 Des. of Damages: **Front / Rear / O/S / MS / UIC / Rooftop** or
 The UIC / Chassis frame / Body Structure affected due to collision.



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: **4165K**
 IDAC Accident Report: Consistent? Yes or No
 CIA / PI Seen: Consistent? Yes or No
 Est. Repairs: **5** days Res: Yes or No
 Turn time: % 3 Val: Yes or No
 GA / REV / REP / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time: _____ Action / Instruction: _____

03/04/19

Confirmed P/P \$ 17,336.54 @ 5 days with Taufik.
 (\$ 8627.96 Red - 33%)

White \$100,093.

RECEIVED 03 APR 2019

[Signature]
 3/4/2019

Date/Time File Path for
03/04/19
 Typ: **54**
 Date/Time File Return to:

: Prel. Report
 : Final Report

Days Of Repair: **5**

Resurvey No. of Trip: **1**

Survey Fee
 Transportation

Add Fee: Site Insp.
 Interview
 Tech. Insp.
 Witness

Report Format

Lump Sum / UIC: **17,336.54 P/P**

15x15=225

170+225
50
50
54
549

[Handwritten]
 0587
 4/4/19

MOTOR SURVEY ASSIGNMENT

Date 18-02-2019 **Our Ref No.** D19001168MFSH

Accident Date 14-02-2019 **Claim Type.** Third Party

Insured Vehicle SHB3462A **Third Party Vehicle.** SLV4854T

Survey Location BODY AND PAINT DEPT 249 ALEXANDRA ROAD
Contact Person. PAUL ONG
Contact No. 81261237/ 63789336 **Fax No.** 0

Survey Type DIRECT SETTLEMENT:

Appointed Surveyor LKK AUTO CONSULTANTS PTE LTD
Contact Person NA **Fax No.** 68416315
Contact Number. NA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop WEARNES AUTOMOTIVE **Attention.** NIL
PTE LTD

Cc : TP Solicitor NA **TP Solicitor Fax No.** NA

Officer Incharge MERINA CHIA SAN SAN

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, 3 April 2019 11:07 AM
To: 'Paul Ong Qing Yong'; SUR
Cc: Taufikh (LKKAuto)
Subject: RE: SLV4854T Finalise

Sensitivity: Confidential

Dear Paul,

Confirmed final fig \$17,336.54 @ 5 days of repairs before GST.

Final invoice and all supporting documents sent over to First Capital Ins Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Paul Ong Qing Yong [mailto:paul.ong@wearnes.com]
Sent: Tuesday, 2 April 2019 9:21 AM
To: SUR <sur@lkkauto.com>
Cc: 'Taufikh (LKK Auto)' <taufikh@lkkauto.com>
Subject: SLV4854T Finalise
Importance: High
Sensitivity: Confidential

Attached for finalise

Paul Ong
Service Consultant
Bodyshop & Paint



WEARNES

Wearnes Automotive Pte Ltd
249 Alexandra Road Singapore 159935
M (65) 8126 1237 D (65) 6378 9336
www.wearnesauto.com paul.ong@wearnes.com

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 7 March 2019 4:14 PM
To: 'Merina Chia San San'; 'CWS Motor Claims'
Cc: assignments; SUR; Admin-D (LKKAuto)
Subject: RE: SURVEY ASSESSMENT - D19001168MFSH/1
Attachments: SLV 4854T - Preli Advise .pdf

Dear Merina,

Enclosed preliminary revised of vehicle SLV 4854T.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Wednesday, 20 February 2019 12:06 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Merina Chia San San' <MerinaChia@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19001168MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Wednesday, 20 February 2019 11:33 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Merina Chia San San <MerinaChia@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19001168MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19001168MFSH

Date: 07 March 2019

Our Ref: CS/FCI19003212/T1sd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLV 4854T

Please be informed that we had conducted the inspection of the abovementioned vehicle on 04/03/2019 at the premises of M/s Wearnes Automotive Pte Ltd and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 24,264.70</u>
Revised Estimate Amount	: <u>S\$ 15,448.20</u>
"Check" Items Amount	: <u>S\$ 3,089.10</u>
Market Value	: <u>S\$</u>
LTA Reimbursement Value	: <u>S\$</u>
Nett Value	: <u>S\$</u>

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.
Repair days: 5 Days

Yours faithfully,
Mohamad Taufikh
Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/02/2019 08:49
Date Of Accident	14/02/2019 18:35
Exact Location Of Accident	ALONG HOLLAND ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLV4854T
Insured/Policyholder	
Name Of Registered Owner	MEIER WERNER
Passport No/FIN	G5768974P
Email Address	WERNERHMEIER@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90257966
Alternative Phone No	OFFICE-90257966

Vehicle Particulars

Manufacturer	LAND ROVER
Model	EVOQUE-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800005078
Cover Note Number	

Driver

Name of Driver	MEIER JEANNE MARIE BELEN
Passport No/FIN	G5772755T
Date Of Birth	26/02/1969
Occupation	INDOOR
Date Of Driving Pass	12/11/2005
Driving Experience	13 YEARS AND 3 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91014812
Fax Number	

Address	24 GREENLEAF VIEW
Postcode	279263
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Refer to attached

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHB3462A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

(i) processing, handling and/or dealing w ith my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as w ell as on the external cover of envelopes/mail packages); and/or


(v) complying w ith applicable law in administering, processing, handling and/or dealing w ith my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time



Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstance of the Accident

FEB. 14 '19

Holland Road (near Potamika Condo)

6:30

When the car in front of me suddenly stopped and I also stopped on time. And suddenly there was a cab that hit the back of my car with a big impact.

It was traffic during that time and vehicles are moving slow.

IMPORTANT NOTE

Under **General Condition – Conduct of Claim** of the Motor Policy, you have to decide within 21 days of occurrence or discovery of damage whether or not to claim under the policy. Please check your policy for more information.

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time



Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

SERVICE ESTIMATE

95197 - C00001
Mr Meier Werner
24 Greenleaf View

SL: SERVICE SALES - PC

GST Reg.No:M28920628X
Inv.No. . : B&P 0 Page 1
Inv.date. : 16/02/2019
WIP No. . : 54067
Veh.In/Out:
*Tel.No. . : Mobile: 90257966
Reg.No. . : SLV4854T
Reg.date . : 29/12/2017
Mileage .. : 0
Chassis No: SALVA2AG2HH224175

Singapore 279263

Closed by : Paul Ong Qing Yong
Svc Consultant :
Remarks : Mr Meier Werner

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

802	TO REPLACE BOOTLID, REAR BUMPER, TOW COVER REAR, REFLECTOR REAR, ETC	0	3600.00	0		3,600.00	S 2400
800	TO PUTTY SPRAYPAINT ON REAR BOOTLID, REAR BUMPER, ETC	0	3000.00	0		3,000.00	S 2000
802	TO REPLACE REAR WINDSCREEN	0	1200.00	0		1,200.00	S 600
0080	TO INSTALL REAR WINDSCREEN FIL	0	280.00	0		280.00	S ✓
802	TO REMOVE & REFIT REAR BOOTLID	0	500.00	0		500.00	S ✓
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	486.00	0		486.00	S ✓

BUMPER - REAR	1.0 EA	2026.90	2,026.90	S	de	1824.21
BUMPER MOULDING REAR	1.0 EA	259.50	259.50	S	at	233.55
BUMPER MOULDING REAR	1.0 EA	227.20	227.20	S	cut	204.48
EXHAUST FINISHER RH	1.0 EA	709.30	709.30	S	bt ✓	639.37
EXHAUST FINISHER LH	1.0 EA	709.30	709.30	S	bt ✓	639.37
HEAT SHIELD	1.0 EA	115.50	115.50	S	Kim	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Handwritten signature
7/3/19
Tanjung 97495749
UP
4/3/19 @ 245
Resurvey before paint.
sur elkhant...
05 days



WEARNES

SERVICE ESTIMATE

95197 - C00001
Mr Meier Werner
24 Greenleaf View

SL: SERVICE SALES - PC

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 2
Inv.date. : 16/02/2019
WIP No. : 54067
Veh.In/Out:

Singapore 279263

*Tel.No. : Mobile: 90257966

Reg.No. : SLV4854T

Closed by : Paul Ong Qing Yong

Reg.date. : 29/12/2017

Svc Consultant :

Mileage : 0

Remarks : Mr Meier Werner

Chassis No: SALVA2AG2HH224175

Op.No Description Mech Qty Price Disc% Pkg Amount G

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
	BRACKET - BUMPER MOU	1.0	EA	60.90			60.90	S ?
	BRACKET - BUMPER MOU	1.0	EA	68.10			68.10	S ?
	BUMPER BRACKET REAR	1.0	EA	120.40			120.40	S ?
	BUMPER BRACKET REAR	1.0	EA	80.40			80.40	S ?
	BUMPER BEAM REAR EVO	1.0	EA	1225.20			1,225.20	S ?
	BOOT REAR EVO 5D	1.0	EA	3588.20			3,588.20	S out ✓ 3229.38
	WINDSCREEN REAR EVO	1.0	EA	1268.00			1,268.00	S ne ✓ 1141.20
	LLR002238/WINDSCREEN	4.0	EA	5.90			23.60	S ne ✓ 21.24
	D PRIMER GLASS & P	1.0	EA	37.40			37.40	S ne ✓ 33.66
	ADHESIVE AND SEALER	2.0	EA	136.10			272.20	S ne ✓ 244.98
	REAR LOGO 'RANGE' EV	1.0	EA	174.50			174.50	S ne ✓ 157.05
	REAR LOGO 'ROVER' EV	1.0	EA	174.40			174.40	S ne ✓ 156.96
	NAME PLATE	1.0	EA	91.70			91.70	S ne ✓ 82.53
	NAME PLATE - PLASTIC	1.0	EA	202.30			202.30	S ne ✓ 182.07
	PANEL - TAILGATE TRI	1.0	EA	351.70			351.70	S X ne
	COVER - STRIKER	1.0	EA	38.00			38.00	S out ✓ 34.20
	EXHAUST FINISHER RH	1.0	EA	709.30			709.30	S X un.

SERVICE ESTIMATE

95197 - C00001
Mr Meier Werner
24 Greenleaf View

SL: SERVICE SALES - PC

GST Reg.No:M28920628X

Singapore 279263

Inv.No. . : B&P 0 Page 3
Inv.date. : 16/02/2019
WIP No. . : 54067
Veh.In/Out:
*Tel.No. . : Mobile: 90257966
Reg.No. . : SLV4854T
Reg.date. : 29/12/2017
Mileage . : 0
Chassis No: SALVA2AG2HH224175

Closed by : Paul Ong Qing Yong
Svc Consultant :
Remarks : Mr Meier Werner

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

	EXHAUST FINISHER LH	1.0 EA	709.30			709.30	SX un
	LAMP - FOG - REAR RH	1.0 EA	273.90			273.90	SX un
	LAMP - FOG - REAR LH	1.0 EA	249.20			249.20	Saw 224.23
	BODY PANEL SEALANT X	1.0 EA	883.20			883.20	SX un
	ADHESIVE SEALER FL2	1.0 EA	549.10			549.10	S ne 494.19

				Gross Total.	24,264.70	
Labour	Total	9,066.00		Net.....	24,264.70	25964.50
Parts	Total	15,198.70		GST @ 7.0%	1,698.53	
Package	Total	0.00		Total.....	25,963.25	
				Paid.....	0.00	
				Please Pay..	25,963.25	

GST: S=StdRated; 0=OutOfScope; Z=ZeroRated

25964.52

SWP

SERVICE ESTIMATE

0 - F00003 SL: FIRST CAPITAL INSURANCE LTD
 FIRST CAPITAL INSURANCE LTD GST Reg.No:M28920628X
 36 ROBINSON ROAD Inv.No. . : B&P 0 Page 1
 #16-01, CITY HOUSE Inv.date. : 02/04/2019
 SINGAPORE WIP No. . : 54067
 Singapore 068877 Veh.In/Out: 04/03/2019 01/04/2019
 *Tel.No. . :
 Closed by : Paul Ong Qing Yong Reg.No. . : 3LY4854T
 Svc Consultant : ACC Reg.date .: 29/12/2017
 Remarks : Mr Meier Werner Mileage ..: 16,122
 Chassis No: SALVA2AG2HH224175

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	MUFFLER - REAR	1.0 EA	1699.80	10		1,529.82	\$ A BT

		Gross Total.	1,529.82
Labour Total	0.00	Net.....	1,529.82
Parts Total	1,529.82	GST @ 7.0%	107.09
Package Total	0.00	Total.....	1,636.91
		Paid.....	0.00
		Please Pay..	1,636.91

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

SERVICE ESTIMATE

0 - F00003	SL: FIRST CAPITAL INSURANCE LTD	GST Reg.No:M28920628X
FIRST CAPITAL INSURANCE LTD		Inv.No. . . : B&P 0 Page 1
36 ROBINSON ROAD		Inv.date. . : 02/04/2019
#16-01, CITY HOUSE		WIP No. . . : 54067
SINGAPORE		Veh.In/Out: 04/03/2019 01/04/2019
Singapore 068877		*Tel.No. . . :
		Reg.No. . . : SLV4854T
Closed by : Paul Ong Qing Yong		Reg.date . . : 29/12/2017
Svc Consultant : ACC		Mileage .. : 16,122
Remarks : Mr Meier Werner		Chassis No: SALVA2AG2HH224175

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE BOOTLID, REAR BUMPER, TOW COVER REAR, REFLECTOR REAR, ETC	0	2400.00	0		2,400.00	S
800	TO PUTTY SPRAYPAINT ON REAR BOOTLID, REAR BUMPER, ETC	0	2000.00	0		2,000.00	S
802	TO REPLACE REAR WINDSCREEN	0	600.00	0		600.00	S
0080	TO INSTALL REAR WINDSCREEN FIL	0	280.00	0		280.00	S
802	TO REMOVE & REFIT REAR BOOTLID	0	500.00	0		500.00	S
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	486.00	0		486.00	S
	BUMPER - REAR	1.0 EA	2026.90	10		1,824.21	S
	BUMPER MOULDING REAR	1.0 EA	259.50	10		233.55	S
	BUMPER MOULDING REAR	1.0 EA	227.20	10		204.48	S
	BOOT REAR EVO 5D	1.0 EA	3588.20	10		3,229.38	S
	WINDSCREEN REAR EVO	1.0 EA	1268.00	10		1,141.20	S
	LLR002238/WINDSCREEN	4.0 EA	5.90	10		21.24	S

SERVICE ESTIMATE

0 - F00003 SL: FIRST CAPITAL INSURANCE LTD
 FIRST CAPITAL INSURANCE LTD GST Reg.No:M28920628X
 36 ROBINSON ROAD Inv.No. . : B&P 0 Page 2
 #16-01, CITY HOUSE Inv.date. : 02/04/2019
 SINGAPORE WIP No. . : 54067
 Singapore 068877 Veh.In/Out: 04/03/2019 01/04/2019
 *Tel.No. . :
 Reg.No. . : SLV4854T
 Reg.date. : 29/12/2017
 Mileage . : 16,122
 Chassis No: SALVA2AG2HH224175

Closed by : Paul Ong Qing Yong
 Svc Consultant : ACC
 Remarks : Mr Meier Werner

Op.No	Description	Mech Qty	Price Disc%	Pkg Amount	G
	D PRIMER GLASS & P	1.0 EA	37.40/10	33.66	S
	ADHESIVE AND SEALER	2.0 EA	136.10/10	244.98	S
	REAR LOGO 'RANGE' EV	1.0 EA	174.50/10	157.05	S
	REAR LOGO 'ROVER' EV	1.0 EA	174.40/10	156.96	S
	NAME PLATE	1.0 EA	91.70/10	82.53	S
	NAME PLATE - PLASTIC	1.0 EA	202.30/10	182.07	S
	COVER - STRIKER	1.0 EA	38.00/10	34.20	S
	LAMP - FOG - REAR LH	1.0 EA	249.20/10	224.28	S
	ADHESIVE SEALER FL2	1.0 EA	549.10/10	494.19	S
	EXHAUST FINISHER RH ^{PS-1}	1.0 EA	709.30/10	638.37	S
	EXHAUST FINISHER LH ^{PS-1}	1.0 EA	709.30/10	638.37	S
	MUFFLER - REAR ^{Supp}	1.0 EA	1699.80/10	1,529.82	S bt ✓

Gross Total. 17,336.54

Labour Total 6,266.00
 Parts Total 11,070.54
 Package Total 0.00

Net..... 17,336.54
 GST @ 7.0% 1,213.56
 Total..... 18,550.10
 Paid..... 0.00
 Please Pay.. 18,550.10

GST: S=StdRated; O=OutOfScope; Z=ZeroRated



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19003212/T1sd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 15-04-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 3462A	Veh. Inspected	SLV 4854T
Policy No.		Coverage (\$)	0.00
Claim No.	D19001168MFSH	Excess (\$)	0.00
Assign From	MERINA CHIA	Assign Date	20/02/2019
2. Vehicle Particulars & Condition			
Make & Model	LAND ROVER RANGE ROVER EVOQUE	c.c	1999
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	SALVA2AG2HH224175	Colour	RED
Odometer	16122	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	235/55 R19	GOODYEAR	6 mm
L/H Front Tyre	235/55 R19	GOODYEAR	6 mm
R/H Rear Tyre	235/55 R19	GOODYEAR	6 mm
L/H Rear Tyre	235/55 R19	GOODYEAR	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	14/02/2019	Inspection Date	04/03/2019
Survey held at	WEARNES AUTOMOTIVE PTE LTD 249 ALEXANDRA ROAD SINGAPORE 159935		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 4854T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER - REAR (SN)	DEFORMED	2,026.90	1,824.21
1	BUMPER MOULDING REAR (SN)	CUT	259.50	233.55
1	BUMPER MOULDING REAR (SN)	CUT	227.20	204.48
1	EXHAUST FINISHER RH (SN)	BENT	709.30	638.37
1	EXHAUST FINISHER LH (SN)	BENT	709.30	638.37
1	HEAT SHIELD REAR EVO (SN)	NOT NECESSARY	115.50	-
1	BRACKET - BUMPER MOU (SN)	NOT NECESSARY	60.90	-
1	BRACKET - BUMPER MOU (SN)	NOT NECESSARY	68.10	-
1	BUMPER BRACKET REAR (SN)	NOT NECESSARY	120.40	-
1	BUMPER BRACKET REAR (SN)	NOT NECESSARY	80.40	-
1	BUMPER BEAM REAR EVO (SN)	NOT NECESSARY	1,225.20	-
1	BOOT REAR EVO 5D (SN)	CRACKED	3,588.20	3,229.38
1	WINDSCREEN REAR EVO (SN)	NECESSARY	1,268.00	1,141.20
4	LLR002238/WINDSCREEN (SN)	NECESSARY	23.60	21.24
1	*D* PRIMER GLASS & P (SN)	NECESSARY	37.40	33.66
2	ADHESIVE AND SEALER (SN)	NECESSARY	272.20	244.98
1	REAR LOGO 'RANGE' EV (SN)	NECESSARY	174.50	157.05
1	REAR LOGO 'ROVER' EV (SN)	NECESSARY	174.40	156.96
1	NAME PLATE (SN)	NECESSARY	91.70	82.53
1	NAME PLATE - PLASTIC (SN)	NECESSARY	202.30	182.07
1	PANEL - TAILGATE TRI (SN)	NOT NECESSARY	351.70	-
1	COVER - STRIKER (SN)	CUT	38.00	34.20
1	EXHAUST FINISHER RH (SN)	NOT NECESSARY	709.30	-
1	EXHAUST FINISHER LH (SN)	NOT NECESSARY	709.30	-
1	LAMP - FOG - REAR RH (SN)	NOT NECESSARY	273.90	-
1	LAMP - FOG - REAR LH (SN)	CRACKED	249.20	224.28
1	BODY PANEL SEALANT X (SN)	NOT NECESSARY	883.20	-
1	ADHESIVE SEALER FL2 (SN)	NECESSARY	549.10	494.19
1	MUFFLER - REAR (SN) (ADDITIONAL)	BENT	1,529.82	1,529.82
			16,728.52	11,070.54

Report Ref No. CS/FCI19003212/T1sd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REPLACE, BOOTLID, REAR BUMPER, TOW COVER REAR, REFLECTOR REAR, ETC.		3,600.00	2,400.00
	TO PUTTY SPRAYPAINT ON REAR BOOTLID, REAR BUMPER, ETC.		3,000.00	2,000.00
	TO REPLACE REAR WINDSCREEN.		1,200.00	600.00
	TO INSTALL REAR WINDSCREEN FIL.		280.00	280.00
	TO REMOVE & REFIT REAR BOOTLID.		500.00	500.00
	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES.		486.00	486.00
			9,066.00	6,266.00
	GRAND TOTAL		25,794.52	17,336.54
RECOMMENDED COST OF REPAIRS				17,336.54

Report Ref No. CS/FCI19003212/T1sd3e2

MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
Automotive Assessor

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.