



STUTTGART AUTO PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
FINALIZATION COST OF REPAIRS



PORSCHE

China Taiping Insurance (S) Pte Ltd		NAME : Mr Lim Hock Leong		WIP : 42623	
3 Anson Rd, #16-00 Springleaf Tower		ADDRESS : 9 Sennett Road		EXCESS :	
Singapore 079909		Singapore 466784		DATE: 13.02.2019	
ATTN. : MOTOR CLAIMS		TEL :			
FAX :					
VEH NO :	SKQ28B	DATE IN :		CONTACT PERSON :	EVA 63310683
CHASSIS NO :	WP0ZZZ97ZGL002227	MILEAGE :		TYPE OF CLAIM :	TP
MODEL :	Panamera Edition	DATE REG.:	08.01.2016	POLICY NO. :	
NATURE OF WORKS					
S/NO	Parts Description				
	QTY			REVISED	PRICES
1	REAR BUMPER	1	P970-505-951-03-	\$ 2,272.70	\$ 2,272.70
2	REAR BUMPER (LOWER SPOILER)	1	P970-505-611-01-1E0	\$ 929.40	\$ 929.40
3	TAIL PIPE GARNISH LH	1	P970-505-837-00-1E0	\$ 143.30	\$ 143.30
4	TAIL PIPE GARNISH RH	1	P970-505-838-00-1E0	\$ 143.30	\$ 143.30
5	BLIND RIVET	4	P999-190-191-30-	\$ 22.00	\$ 22.00
6	REAR DOOR LH	1	P970-532-011-01-GRV	\$ 3,396.40	\$ 3,396.40
7	REAR DOOR SEAL RR	1	P970-536-535-04-	\$ 92.20	\$ 92.20
8	REAR DOOR SEAL FRT	1	P970-536-531-02-	\$ 84.50	\$ 84.50
9	DOOR TRIM UNIT BOLT	8	P999-073-920-30-	\$ 27.20	\$ 27.20
10	WASHER	8	P999-025-123-30-	\$ 19.20	\$ 19.20
11	P970-536-531-01-/(970-536-53100) ADDITIO	1	970-536-53100	REPEATED	\$ 84.50
12	INSULATION DOOR	1	P997-537-551-00-	\$ 22.40	\$ 22.40
13	ACTIVATOR	1	P000-043-305-31-	\$ -	\$ 179.60
14	DOOR WEATHER STRIP	1	P970-536-275-01-	\$ 281.80	\$ 281.80
15	STONEGUARD FILM LH	1	P970-532-825-03-	\$ 107.00	\$ 107.00
16	SIDE SKIRT	1	P970-559-201-04-G2L		\$ 1,708.30
17	RUBBER LIP	1	P970-559-601-01-1E0	\$ 73.30	\$ 73.30
18	SIDE SKIRT INSERT	10	P999-507-911-40-	\$ 32.00	\$ 32.00
19	SPLASH SHIELD	1	P970-504-133-03-		\$ 397.70
20	DISC WHEEL	1	P970-362-160-08-88Z	\$ 2,709.00	\$ 2,709.00
21	BLIND RIVET	6	P999-190-188-30-	\$ 6.00	\$ 6.00
SUPPLEMENTARY PARTS					
1	REAR DOOR PROTECTIVE FILM LH	1	P970-536-283-01	\$ 40.50	\$ 40.50
2	DOOR INSULATION LOWER	1	P970-536-561-01	\$ 44.60	\$ 44.60
TOTAL PARTS				\$ 10,446.80	\$ 12,816.90
LESS 10%				\$ 1,044.68	\$ 1,281.69
TOTAL PARTS COST				\$ 9,402.12	\$ 11,535.21
Labour Description					
1	TO REMOVE / REPLACE LH REAR DOOR, SIDE SKIRT & REAR BUMPER & TO REPAIR LH REAR FENDER			\$ 5,460.00	\$ 6,240.00
AREAS AFFECTED BY THE ACCIDENT.					

2	TO RESPRAY LH REAR DOOR, SIDE SKIRT & REAR BUMPER & LH REAR FENDER.	\$ 4,050.00	\$ 4,800.00
3	TO CARRY-OUT BODY CAVITY PRESERVATION.	\$ 250.00	\$ 250.00
4	TO REPLACE 1 PC TYRE. 285/40 ZR19	\$ 784.00	\$ 980.00
5	TO MOUNT 1 PC SPORT RIM AND CONDUCT WHEEL BALANCING.	\$ 120.00	\$ 120.00
6	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.	\$ 680.00	\$ 680.00
7	TO TRANSFER THE DOOR MECHANISM.	\$ 780.00	\$ 780.00
8	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 200.00	\$ 200.00
9	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 600.00	\$ 600.00
10	SUNDRIES.	\$ 50.00	\$ 50.00
	SUPPLEMENTARY LABOUR		
1	TO REPAIR LH REAR ARCH PANEL AREA AFFECTED BY THE ACCIDENT	\$ 780.00	\$ 780.00
2	TO RESPRAY LH REAR FENDER ARCH PANEL	\$ 550.00	\$ 550.00
	TOTAL LABOUR	\$ 14,304.00	\$ 16,030.00
	TOTAL PARTS	\$ 9,402.12	\$ 11,535.21
	TOTAL	\$ 23,706.12	\$ 27,565.21
	LESS EXCESS	\$ -	\$ -
	TOTAL AFTER EXCESS	\$ 23,706.12	
	GST 7%	\$ 1,659.43	\$ -
	GRAND TOTAL	\$ 25,365.55	\$ -

NUMBER OF DAYS: 9 WORKING DAYS(EXCLUDE WAITING FOR SURVEY,AUTHORIZATION,PARTS,SAT,SUN & PH)