

ASS. REC. BY:

REF: CS/CTI 19003214/Tlvcbⁿ² Special Instruction

Surveyor

ASSIGNMENT (Office)

From (Person) Elaine chong of CTI Date/Time: 19/10/19 @ 11:42am

Estimated Cost: Till to:

OI / IT / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No: SKQ28B Insured: SLN 6258T

at Workshop no: Truseumkars Tel: 63310683

of 27A Tanjung Perjurn

Policy No: Claim No: SNM19D200585C02/8

Sum Insured: Excess:

Make of Veh: D.O.A. 31/01/2019
(Client's Record) 21/10/19 @ 4pm

CA / REV / REP. / REV 24 HRS

Date/Time: 10:20am @ 20/10/19 Person Contacted: Eva Vehicle INT (III)

Date/Time Action/Instruction (✓) Estimate

SKQ28B - X

SLN 6258T - X

7/5/19 @ 301pm Eva said vehicle waiting for spare parts

7/6/19 @ 1136am Eva said vehicle has not send in for repair

11/6/19 Submit preli report

23/10/19 Final fig \$ 23,706.12 (Red 3859.09, 1490)
9 days


23/10/2019

RECEIVED 24 OCT 2019

Tanji

10/1/19

CT1

10/1/19

2016 Jan

Make of Vehicle
 Insurance Policy No.
 Date of Policy
 Policy No.
 Claim No.
 Date of Loss
 (Client's Record)
 Make of Vehicle

NS	O/S

(Policy Condition)
 Remarks: The veh had commenced its repair at the time of inspection.

Est. or Market Value: \$290K
 IDAG Accident Report: Consistent? Yes or No
 GLA / PR / Sewer: Consistent? Yes or No
 Est. Repairs: days Res: Yes or No
 Loss Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS
 Date Person Contacted Vehicle: IN / OUT

SKG 28B
 Type: Car / Motorcycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Porsche Panamera cc 360S
 Colour: Black
 Sp. Reading: 1226
 Engine: WP02229729L002222
 CTR: 1226
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 255/45 R19
 R: 285/40 R19
 BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: 6 mm
 R/Bal: 6 mm
 L/Bal: 6 mm
 D.O.A: 26/2/19
 Survey held at: Stuttgart
 Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collapse

white. 9162, 022.

RECEIVED 11 JUN 2019

Download File Pass to:
☒ Prel. Report
☐ Final Report

Days Of Repair: 9
 Resurvey No. of Trip: -

Survey Fee:
 Transport:
 1. 1000.00
 2. 1000.00
 3. 1000.00
 4. 1000.00
 5. 1000.00
 6. 1000.00
 7. 1000.00
 8. 1000.00
 9. 1000.00
 10. 1000.00
 11. 1000.00
 12. 1000.00
 13. 1000.00
 14. 1000.00
 15. 1000.00
 16. 1000.00
 17. 1000.00
 18. 1000.00
 19. 1000.00
 20. 1000.00
 21. 1000.00
 22. 1000.00
 23. 1000.00
 24. 1000.00
 25. 1000.00
 26. 1000.00
 27. 1000.00
 28. 1000.00
 29. 1000.00
 30. 1000.00
 31. 1000.00
 32. 1000.00
 33. 1000.00
 34. 1000.00
 35. 1000.00
 36. 1000.00
 37. 1000.00
 38. 1000.00
 39. 1000.00
 40. 1000.00
 41. 1000.00
 42. 1000.00
 43. 1000.00
 44. 1000.00
 45. 1000.00
 46. 1000.00
 47. 1000.00
 48. 1000.00
 49. 1000.00
 50. 1000.00
 51. 1000.00
 52. 1000.00
 53. 1000.00
 54. 1000.00
 55. 1000.00
 56. 1000.00
 57. 1000.00
 58. 1000.00
 59. 1000.00
 60. 1000.00
 61. 1000.00
 62. 1000.00
 63. 1000.00
 64. 1000.00
 65. 1000.00
 66. 1000.00
 67. 1000.00
 68. 1000.00
 69. 1000.00
 70. 1000.00
 71. 1000.00
 72. 1000.00
 73. 1000.00
 74. 1000.00
 75. 1000.00
 76. 1000.00
 77. 1000.00
 78. 1000.00
 79. 1000.00
 80. 1000.00
 81. 1000.00
 82. 1000.00
 83. 1000.00
 84. 1000.00
 85. 1000.00
 86. 1000.00
 87. 1000.00
 88. 1000.00
 89. 1000.00
 90. 1000.00
 91. 1000.00
 92. 1000.00
 93. 1000.00
 94. 1000.00
 95. 1000.00
 96. 1000.00
 97. 1000.00
 98. 1000.00
 99. 1000.00
 100. 1000.00

Add Fee:
☐ Site Insp. 15
☐ Inter. Insp. 15
☐ Photo. Insp. 15
☐ Weighment 15

11/6 - typist
 Report Format:
 Lump Sum / L.R. P.C.

220

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 23 October 2019 4:31 PM
To: jessicahs@eurokars.com.sg; Taufikh (LKKAuto); Admin A
Cc: eva.kok@eurokars.com.sg; janice.syn@porsche.com.sg; rickteo@eurokars.com.sg;
SUR
Subject: RE: Finalization SKQ28B CTI TP

Dear Jessica,

WITHOUT PREJUDICE

Confirmed COR: \$23,706.12 before GST
09 repair days

Kindly send Final invoice and all supporting documents directly to CHINA TAIPING

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: jessicahs@eurokars.com.sg <jessicahs@eurokars.com.sg>
Sent: Monday, 21 October 2019 11:25 AM
To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Cc: eva.kok@eurokars.com.sg; janice.syn@porsche.com.sg; rickteo@eurokars.com.sg
Subject: RE: Finalization SKQ28B CTI TP

Dear Taufikh,

Hope this email finds you well. I am writing to you for follow up with the finalization.

I am hoping we could finalized this case.

Please let us have your confirmation.

Thanks & Regards,
Jessica

From: Jessica Harry Shastri
Sent: 17 October 2019 2:48 PM
To: 'Taufikh (LKKAuto)' <Taufikh@lkkauto.com>; 'Admin A' <admin-a@lkkauto.com>
Cc: Eva Kok <eva.kok@eurokars.com.sg>; Janice Syn <janice.syn@porsche.com.sg>; Rick Teo

<rickteo@eurokars.com.sg>

Subject: RE: Finalization SKQ28B CTI TP

Dear Taufikh,

Please find our Ammended computation attached for your agreement.

COR: \$23,706.12 before GST

09 repair days (not including preparation of estimate, wait for liability/wait for survey/authorization/spare parts, Sat/Sun/PH)

Appreciate your confirmation for this case.

Thank you very much.

Regards,

Jessica Shastri

Admin Executive – Insurance Claims

27A, Tanjong Penjuru

Singapore 609042

Dir: +65 6331 0691 Fax: +65 6331 0690 Email: jessicahs@eurokars.com.sg

Website: www.eurokarsgroup.com

From: Jessica Harry Shastri

Sent: 14 October 2019 2:45 PM

To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>; 'Admin A' <admin-a@lkkauto.com>

Cc: Eva Kok <eva.kok@eurokars.com.sg>; Janice Syn <janice.syn@porsche.com.sg>; Rick Teo <rickteo@eurokars.com.sg>

Subject: Finalization SKQ28B CTI TP

Dear Taufikh,

Please find our computation attached for your agreement.

COR: \$22,299.53 before GST

09 repair days (not including preparation of estimate, wait for liability/wait for survey/authorization/spare parts, Sat/Sun/PH)

Appreciate your confirmation for this case.

Thank you very much.

Regards,

Jessica Shastri

Admin Executive – Insurance Claims

27A, Tanjong Penjuru

Singapore 609042

Dir: +65 6331 0691 Fax: +65 6331 0690 Email: jessicahs@eurokars.com.sg

Website: www.eurokarsgroup.com



PORSCHE

STUTTGART AUTO PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042,
ESTIMATE COST OF REPAIRS



China Taiping Insurance (S) Pte Ltd 3 Anson Rd, #16-00 Springleaf Tower Singapore 079909		NAME : Mr Lim Hock Leong ADDRESS : 9 Sonnett Road Singapore 466784 TEL :		WIP : 42623 EXCESS : DATE: 13.02.2019	
ATTN : MOTOR CLAIMS FAX :					
VEH NO :	SKQ28B	DATE IN :		CONTACT PERSON :	EVA 63310683
CHASSIS NO :	WP0Z2297ZGLD02227	MILEAGE :		TYPE OF CLAIM :	TP
MODEL :	Panamera Edition	DATE REG.:	08.01.2016	POLICY NO. :	

NATURE OF WORKS

S/NO	Parts Description			REVISED	PRICES
	QTY				
1	1	REAR BUMPER	P970-505-951-03-	de ✓	\$ 2,272.70 ✓
2	1	REAR BUMPER (LOWER SPOILER)	P970-505-611-01-1E0	ant ✓	\$ 929.40 ✓
3	1	TAIL PIPE GARNISH LH	P970-505-837-00-1E0	the ✓	\$ 143.30 ✓
4	1	TAIL PIPE GARNISH RH	P970-505-838-00-1E0	the ✓	\$ 143.30 ✓
5	4	BLIND RIVET	P999-190-191-30-	re ✓	\$ 22.00 ✓
6	1	REAR DOOR LH	P970-532-011-01-GRV	h ✓	\$ 3,396.40 ✓
7	1	REAR DOOR SEAL RR	P970-536-535-04-	asi ✓	\$ 92.20 ✓
8	1	REAR DOOR SEAL FRT	P970-536-531-02-	re ✓	\$ 84.50 ✓
9	8	DOOR TRIM UNIT BOLT	P999-073-920-30-	re ✓	\$ 27.20 ✓
10	8	WASHER	P999-025-123-30-	re ✓	\$ 19.20 ✓
11	1	P970-536-531-01-/(970-536-53100) ADDITIO	P970-536-531-02-	REPEATED	\$ 84.50 ✓
12	1	INSULATION DOOR	P997-537-551-00-	re ✓	\$ 22.40 ✓
13	1	ACTIVATOR	P000-043-305-31-	X m ✓	\$ 179.60 ✓
14	1	DOOR WEATHER STRIP	P970-536-275-01-	re ✓	\$ 281.80 ✓
15	1	STONEGUARD FILM LH	P970-532-825-03-	re ✓	\$ 107.00 ✓
16	1	SIDE SKIRT	P970-559-201-04-G2L	Ky ✓	\$ 1,708.30 ✓
17	1	RUBBER LIP	P970-559-601-01-1E0	re ✓	\$ 73.30 ✓
18	10	SIDE SKIRT INSERT	P999-507-911-40-	re ✓	\$ 32.00 ✓
19	1	SPLASH SHIELD	P970-504-133-03-	X m ✓	\$ 397.70 ✓
20	1	DISC WHEEL	P970-362-160-08-88Z	de ✓	\$ 2,709.00 ✓
21	6	BLIND RIVET	P999-190-188-30-	re ✓	\$ 6.00 ✓
TOTAL PARTS					\$ 12,731.80
LESS 10%					\$ 1,273.18
TOTAL PARTS COST					\$ 11,458.62

Labour Description

1	TO REMOVE / REPLACE LH REAR DOOR, SIDE SKIRT & REAR BUMPER & TO REPAIR LH REAR FENDER AREAS AFFECTED BY THE ACCIDENT.	✓	5460	\$ 6,240.00
2	TO RESPRAY LH REAR DOOR, SIDE SKIRT & REAR BUMPER & LH REAR FENDER.	✓	4050	\$ 4,800.00
3	TO CARRY-OUT BODY CAVITY PRESERVATION.	✓		\$ 250.00

4	TO REPLACE 1 PC TYRE. 285/40 ZR19	ISH out ✓ 80%	\$	980.00
5	TO MOUNT 1 PC SPORT RIM AND CONDUCT WHEEL BALANCING.	✓	NETT ✓	\$ 120.00
6	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.	✓	NETT ✓	\$ 680.00
7	TO TRANSFER THE DOOR MECHANISM.	✓	NETT ✓	\$ 780.00
8	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	✓	NETT ✓	\$ 200.00
9	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	✓	NETT ✓	\$ 600.00
10	SUNDRIES.	50	NETT 20	\$ 50.00

TOTAL LABOUR	\$ -	\$ 14,700.00
TOTAL PARTS	\$ -	\$ 11,458.62
TOTAL	27,565.21	\$ 26,158.62
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	\$ -
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

[Signature]
26/1/19 Taylor 97495749
J.W.P.
26/1/19 e/640.
Rising before paint
8-9 days
sure lakanto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



PORSCHE

STUTTGART AUTO PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
FINALIZATION COST OF REPAIRS



China Taiping Insurance (S) Pte Ltd 3 Anson Rd, #16-00 Springleaf Tower Singapore 079909		NAME : Mr Lim Hock Leong		WIP : 42623	
		ADDRESS : 9 Sennett Road Singapore 466784		EXCESS :	
ATTN. : MOTOR CLAIMS		TEL :		DATE: 13.02.2019	
FAX :					
VEH NO :	SKQ28B	DATE IN :		CONTACT PERSON :	EVA 63310683
CHASSIS NO :	WP0ZZZ97ZGL002227	MILEAGE :		TYPE OF CLAIM :	TP
MODEL :	Panamera Edition	DATE REG.:	08.01.2016	POLICY NO. :	
NATURE OF WORKS					
S/NO	Parts Description			REVISED	PRICES
		QTY			
1	REAR BUMPER	1	P970-505-951-03-	\$ 2,272.70	\$ 2,272.70
2	REAR BUMPER (LOWER SPOILER)	1	P970-505-611-01-1E0	\$ 929.40	\$ 929.40
3	TAIL PIPE GARNISH LH	1	P970-505-837-00-1E0	\$ 143.30	\$ 143.30
4	TAIL PIPE GARNISH RH	1	P970-505-838-00-1E0	\$ 143.30	\$ 143.30
5	BLIND RIVET	4	P999-190-191-30-	\$ 22.00	\$ 22.00
6	REAR DOOR LH	1	P970-532-011-01-GRV	\$ 3,396.40	\$ 3,396.40
7	REAR DOOR SEAL RR	1	P970-536-535-04-	\$ 92.20	\$ 92.20
8	REAR DOOR SEAL FRT	1	P970-536-531-02-	\$ 84.50	\$ 84.50
9	DOOR TRIM UNIT BOLT	8	P999-073-920-30-	\$ 27.20	\$ 27.20
10	WASHER	8	P999-025-123-30-	\$ 19.20	\$ 19.20
11	P970-536-531-01-/(970-536-53100) ADDITIO	1	970-536-53100	REPEATED	\$ 84.50
12	INSULATION DOOR	1	P997-537-551-00-	\$ 22.40	\$ 22.40
13	ACTIVATOR	1	P000-043-305-31-	\$ -	\$ 179.60
14	DOOR WEATHER STRIP	1	P970-536-275-01-	\$ 281.80	\$ 281.80
15	STONEGUARD FILM LH	1	P970-532-825-03-	\$ 107.00	\$ 107.00
16	SIDE SKIRT	1	P970-559-201-04-G2L		\$ 1,708.30
17	RUBBER LIP	1	P970-559-601-01-1E0	\$ 73.30	\$ 73.30
18	SIDE SKIRT INSERT	10	P999-507-911-40-	\$ 32.00	\$ 32.00
19	SPLASH SHIELD	1	P970-504-133-03-		\$ 397.70
20	DISC WHEEL	1	P970-362-160-08-88Z	\$ 2,709.00	\$ 2,709.00
21	BLIND RIVET	6	P999-190-188-30-	\$ 6.00	\$ 6.00
TOTAL PARTS				\$ 10,361.70	\$ 12,731.80
LESS 10%				\$ 1,036.17	\$ 1,273.18
TOTAL PARTS COST				\$ 9,325.53	\$ 11,458.62
Labour Description					
1	TO REMOVE / REPLACE LH REAR DOOR, SIDE SKIRT & REAR BUMPER & TO REPAIR LH REAR FENDER			\$ 5,460.00	\$ 6,240.00
	AREAS AFFECTED BY THE ACCIDENT.				
2	TO RESPRAY LH REAR DOOR, SIDE SKIRT & REAR BUMPER & LH REAR FENDER.			\$ 4,050.00	\$ 4,800.00
3	TO CARRY-OUT BODY CAVITY PRESERVATION.			\$ 250.00	\$ 250.00

4	TO REPLACE 1 PC TYRE. 285/40 ZR19	\$ 784.00	\$ 980.00
5	TO MOUNT 1 PC SPORT RIM AND CONDUCT WHEEL BALANCING.	\$ 120.00	\$ 120.00
6	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.	\$ 680.00	\$ 680.00
7	TO TRANSFER THE DOOR MECHANISM.	\$ 780.00	\$ 780.00
8	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 200.00	\$ 200.00
9	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 600.00	\$ 600.00
10	SUNDRIES.	\$ 50.00	\$ 50.00
		TOTAL LABOUR	\$ 12,974.00 \$ 14,700.00
		TOTAL PARTS	\$ 9,325.53 \$ 11,458.62
		TOTAL	\$ 22,299.53 \$ 26,158.62
		LESS EXCESS	\$ - \$ -
		TOTAL AFTER EXCESS	\$ 22,299.53
		GST 7%	\$ 1,560.97 \$ -
		GRAND TOTAL	\$ 23,860.50 \$ -

NUMBER OF DAYS: 9 WORKING DAYS(EXCLUDE WAITING FOR SURVEY,AUTHORIZATION,PARTS,SAT,SUN & PH)



PORSCHE

STUTTGART AUTO PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
FINALIZATION COST OF REPAIRS



China Taiping Insurance (S) Pte Ltd 3 Anson Rd, #16-00 Springleaf Tower Singapore 079909		NAME : Mr Lim Hock Leong ADDRESS : 9 Sennett Road Singapore 466784		WIP : 42623 EXCESS : DATE: 13.02.2019	
ATTN. : MOTOR CLAIMS		TEL :			
FAX :					
VEH NO :	SKQ28B	DATE IN :		CONTACT PERSON :	EVA 63310683
CHASSIS NO :	WPOZZZ97ZGL002227	MILEAGE :		TYPE OF CLAIM :	TP
MODEL :	Panamera Edition	DATE REG.:	08.01.2016	POLICY NO. :	
NATURE OF WORKS					
S/NO	Parts Description			REVISED	PRICES
	QTY				
1	REAR BUMPER	1	P970-505-951-03-	\$ 2,272.70	\$ 2,272.70
2	REAR BUMPER (LOWER SPOILER)	1	P970-505-611-01-1E0	\$ 929.40	\$ 929.40
3	TAIL PIPE GARNISH LH	1	P970-505-837-00-1E0	\$ 143.30	\$ 143.30
4	TAIL PIPE GARNISH RH	1	P970-505-838-00-1E0	\$ 143.30	\$ 143.30
5	BLIND RIVET	4	P999-190-191-30-	\$ 22.00	\$ 22.00
6	REAR DOOR LH	1	P970-532-011-01-GRV	\$ 3,396.40	\$ 3,396.40
7	REAR DOOR SEAL RR	1	P970-536-535-04-	\$ 92.20	\$ 92.20
8	REAR DOOR SEAL FRT	1	P970-536-531-02-	\$ 84.50	\$ 84.50
9	DOOR TRIM UNIT BOLT	8	P999-073-920-30-	\$ 27.20	\$ 27.20
10	WASHER	8	P999-025-123-30-	\$ 19.20	\$ 19.20
11	P970-536-531-01-/(970-536-53100) ADDITIO	1	970-536-53100	REPEATED	\$ 84.50
12	INSULATION DOOR	1	P997-537-551-00-	\$ 22.40	\$ 22.40
13	ACTIVATOR	1	P000-043-305-31-	\$ -	\$ 179.60
14	DOOR WEATHER STRIP	1	P970-536-275-01-	\$ 281.80	\$ 281.80
15	STONEGUARD FILM LH	1	P970-532-825-03-	\$ 107.00	\$ 107.00
16	SIDE SKIRT	1	P970-559-201-04-G2L		\$ 1,708.30
17	RUBBER LIP	1	P970-559-601-01-1E0	\$ 73.30	\$ 73.30
18	SIDE SKIRT INSERT	10	P999-507-911-40-	\$ 32.00	\$ 32.00
19	SPLASH SHIELD	1	P970-504-133-03-		\$ 397.70
20	DISC WHEEL	1	P970-362-160-08-88Z	\$ 2,709.00	\$ 2,709.00
21	BLIND RIVET	6	P999-190-188-30-	\$ 6.00	\$ 6.00
SUPPLEMENTARY PARTS					
1	REAR DOOR PROTECTIVE FILM LH	1	P970-536-283-01	\$ 40.50	\$ 40.50
2	DOOR INSULATION LOWER	1	P970-536-561-01	\$ 44.60	\$ 44.60
TOTAL PARTS				\$ 10,446.80	\$ 12,816.90
LESS 10%				\$ 1,044.68	\$ 1,281.69
TOTAL PARTS COST				\$ 9,402.12	\$ 11,535.21
Labour Description					
1	TO REMOVE / REPLACE LH REAR DOOR, SIDE SKIRT & REAR BUMPER & TO REPAIR LH REAR FENDER			\$ 5,460.00	\$ 6,240.00
AREAS AFFECTED BY THE ACCIDENT.					

2	TO RESPRAY LH REAR DOOR, SIDE SKIRT & REAR BUMPER & LH REAR FENDER.	\$ 4,050.00	\$ 4,800.00
3	TO CARRY-OUT BODY CAVITY PRESERVATION.	\$ 250.00	\$ 250.00
4	TO REPLACE 1 PC TYRE. 285/40 ZR19	\$ 784.00	\$ 980.00
5	TO MOUNT 1 PC SPORT RIM AND CONDUCT WHEEL BALANCING.	\$ 120.00	\$ 120.00
6	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.	\$ 680.00	\$ 680.00
7	TO TRANSFER THE DOOR MECHANISM.	\$ 780.00	\$ 780.00
8	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 200.00	\$ 200.00
9	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 600.00	\$ 600.00
10	SUNDRIES.	\$ 50.00	\$ 50.00
SUPPLEMENTARY LABOUR			
1	TO REPAIR LH REAR ARCH PANEL AREA AFFECTED BY THE ACCIDENT	\$ 780.00	\$ 780.00
2	TO RESPRAY LH REAR FENDER ARCH PANEL	\$ 550.00	\$ 550.00
TOTAL LABOUR		\$ 14,304.00	\$ 16,030.00
TOTAL PARTS		\$ 9,402.12	\$ 11,535.21
TOTAL		\$ 23,706.12	\$ 27,565.21
LESS EXCESS		\$ -	\$ -
TOTAL AFTER EXCESS		\$ 23,706.12	
GST 7%		\$ 1,659.43	\$ -
GRAND TOTAL		\$ 25,365.55	\$ -

NUMBER OF DAYS: 9 WORKING DAYS(EXCLUDE WAITING FOR SURVEY,AUTHORIZATION,PARTS,SAT,SUN & PH)



PORSCHE

STUTTGART AUTO PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
SUPPLEMENTARY



China Taiping Insurance (S) Pte Ltd 3 Anson Rd, #16-00 Springleaf Tower Singapore 079909		NAME : Mr Lim Hock Leong ADDRESS : 9 Sennett Road Singapore 466784		WIP : 42623 EXCESS : DATE: 15.10.2019	
ATTN.: MOTOR CLAIMS FAX :		TEL :			
VEH NO :	SKQ28B	DATE IN :		CONTACT PERSON :	EVA 63310683
CHASSIS NO :	WP0ZZZ97ZGL002227	MILEAGE :		TYPE OF CLAIM :	TP
MODEL :	Panamera Edition	DATE REG.:	08.01.2016	POLICY NO. :	

NATURE OF WORKS

S/NO	Parts Description			REVISED	PRICES
	QTY				
1	REAR DOOR PROTECTIVE FILM LH	1	P970-536-283-01-	✓	\$ 40.50
2	DOOR INSULATION LOWER	1	P970-536-561-01-	✓	\$ 44.60
TOTAL PARTS					\$ 85.10
LESS 10%					\$ 8.51
TOTAL PARTS COST					\$ 76.59
Labour Description					
1	TO REPAIR LH REAR ARCH PANEL			✓	\$ 780.00
	AREAS AFFECTED BY THE ACCIDENT.				
2	TO RESPRAY LH REAR FENDER ARCH PANEL			✓	\$ 550.00
TOTAL LABOUR					\$ - \$ 1,330.00
TOTAL PARTS					\$ - \$ 76.59
TOTAL					\$ - \$ 1,406.59
LESS EXCESS					\$ - \$ -
TOTAL AFTER EXCESS					\$ - \$ -
GST 7%					\$ - \$ -
GRAND TOTAL					\$ - \$ -

- THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.
- TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.
- THIS IS ONLY AN ESTIMATE BASED ON PARTS AVAILABILITIES AT CURRENT LOCAL SINGAPORE WAREHOUSE. IF THERE IS A NEED TO INCLUDE AIRFREIGHT PARTS , WE WILL INFORM DULY.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119003214/T1VD3N2

Date: 24/10/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN1801021800
Claimant Vehicle No :	SKQ28B	Insured Vehicle No :	SLN6258T
Date of Loss:	31/01/2019	Nature of Claim:	TP
		Claim No:	SNM19D200585C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKQ28B	Engine No:	011391
Make & Model:	PORSCHE PANAMERA V6, 3.6 PDK E5 (A)	Chassis No:	WP0ZZZ97ZGL002227
Reg. Date:	08/01/2016 (Man. Year: 2015)	Odometer:	12260 km
Colour:	Black		
Engine Capacity:	3605 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/45R19	Rear Tyre Size:	285/40R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,565.21	10,236.12	2,329.09	18.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,000.00	13,470.00	1,530.00	10.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	27,565.21	23,706.12	3,859.09	14.00
+ GST 7.00/7.00% (\$\$)	1,929.56	1,659.43	270.13	14.00
Nett Amount (\$\$)	29,494.77	25,365.55	4,129.22	14.00

INSPECTION

Date of Assignment:	21/02/2019	Inspected At:	Stuttgart Auto Pte Ltd (HQ)
Date Inspected:	26/02/2019		27A Tanjong Penjuru
			Singapore 609042
Estimated Period of Repair:	9.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Oct 2019)
Parts:	144	PORSCHE PANAMERA V6 3.6 PDK E5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKQ28B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,272.70 FL	*2,272.70 FL
2	1		*REAR BUMPER (LOWER SPOILER)	Cut	929.40 FL	*929.40 FL
3	1		*TAIL PIPE GARNISH LH	Necessary	143.30 FL	*143.30 FL
4	1		*TAIL PIPE GARNISH RH	Bent	143.30 FL	*143.30 FL
5	4		*BLIND RIVET	Necessary	22.00 FL	*22.00 FL
6	1		*REAR DOOR LH	Bent	3,396.40 FL	*3,396.40 FL
7	1		*REAR DOOR SEAL RR	Necessary	92.20 FL	*92.20 FL
8	1		*REAR DOOR SEAL FRT	Necessary	84.50 FL	*84.50 FL
9	8		*DOOR TRIM UNIT BOLT	Necessary	27.20 FL	*27.20 FL
10	8		*WASHER	Necessary	19.20 FL	*19.20 FL
11	1		*P970-536-531-01-/(970-536-53100) ADDITIO	Repeated	84.50 FL	*- FL
12	1		*INSULATION DOOR	Necessary	22.40 FL	*22.40 FL
13	1		*ACTIVATOR	Not Necessary	179.60 FL	*- FL
14	1		*DOOR WEATHER STRIP	Necessary	281.80 FL	*281.80 FL
15	1		*STONE GUARD FILM LH	Necessary	107.00 FL	*107.00 FL
16	1		*SIDE SKIRT	Repair	1,708.30 FL	*- FL
17	1		*RUBBER LIP	Necessary	73.30 FL	*73.30 FL
18	10		*SIDE SKIRT INSERT	Necessary	32.00 FL	*32.00 FL
19	1		*SPLASH SHIELD	Not Necessary	397.70 FL	*- FL
20	1		*DISC WHEEL	Dented	2,709.00 FL	*2,709.00 FL
21	6		*BLIND RIVET	Necessary	6.00 FL	*6.00 FL
22	1		*SUNDRIES	Necessary	50.00 FS	*50.00 FS
23	1		*TYRE 285/40 ZR19 (80%)	Cut	980.00 FS	*784.00 FS
24	1		*REAR DOOR PROTECTIVE FILM LH	Necessary	40.50 FL	*40.50 FL
25	1		*DOOR INSULATION LOWER	Necessary	44.60 FL	*44.60 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,846.90	11,280.80
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,281.69	1,044.68
Total Parts (\$\$)	12,565.21	10,236.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE/REPLACE LH REAR DOOR,SIDE SKIRT & REAR BUMPER & TO REPAIR LH REAR FENDER AREAS AFFECTED BY THE ACCIDENT	New	6,240.00	5,460.00
2	TO RESPRAY LH REAR DOOR,SIDE SKIRT & REAR BUMPER & LH REAR FENDER	New	4,800.00	4,050.00
3	TO CARRY-OUT BODY CAVITY PRESERVATION	New	250.00	250.00
4	TO MOUNT 1PC SPORT RIM AND CONDUCT WHEEL BALANCING	New	120.00	120.00
5	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT	New	680.00	680.00
6	TO TRANSFER THE DOOR MECHANISM	New	780.00	780.00
7	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	200.00	200.00
8	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	600.00	600.00
9	TO REPAIR LH REAR ARCH PANEL AREAS AFFECTED BY THE ACCIDENT	New	780.00	780.00
10	TO RESPRAY LH REAR FENDER ARCH PANEL	New	550.00	550.00
Gross Labour Cost (S\$)			15,000.00	13,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >