

## STUTTGART AUTO PTE LTD 27A TANJONG PENJURU, SINGAPORE 609042 SUPPLEMENTARY



## PORSCHE

China Taiping Insurance (S) Pte Ltd  3 Anson Rd, #16-00 Springleaf Tower Singapore 079909  ATTN.: MOTOR CLAIMS FAX:			NAME: Mr Lim Hock Leong ADDRESS: 9 Sennett Road Singapore 466784  TEL:		WIP: 42623 EXCESS: DATE: 15.10.2019				
VEH NO: SKQ28B		DATE IN:		CONTACT PERSON :	EVA	1	63310683		
CHASSIS NO :		WP0ZZZ97ZGL002227	MILEAGE :		TYPE OF CLAIM:		TP		
MODEL:		Panamera Edition	DATE REG.:	08.01.2016	POLICY NO. :				
				NATURE OF WO	DRKS				
s/NO	Parts Description								
	QTY					REVISED		PRICES	
1 2 2	REAR DOOR	PROTECTIVE FILM LH		1	P970-536-283-01-	New	\$	40.50	
	DOOR INSULATION LOWER 1 P970-536-561-01-					iu/	\$	44.60	
	TOTAL PARTS					+	\$	85.10	
	LESS 10%						\$	8.51	
	TOTAL PARTS COST						\$	76.59	
	<u>Labour Description</u>								
	TO REPAIR LH REAR ARCH PANEL						\$	780.00	
	AREAS AFFECTED BY THE ACCIDENT.						Ť	70000	
	TO RESPRAY LH REAR FENDER ARCH PANEL.						\$	550.00	
							Ĺ		
					TOTAL LABOUR	\$ -	\$	1,330.00	
					TOTAL PARTS	\$ -	\$	76.59	
					TOTAL	\$ -	\$	1,406.59	
					LESS EXCESS	\$ -	\$	- ·	
					TOTAL AFTER EXCESS	\$ -			
					GST 7%	\$ -	\$	-	
					GRAND TOTAL	\$ -	\$		

- 1 THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE
  BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL
  BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.
- 2 TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.
- 3 THIS IS ONLY AN ESTIMATE BASED ON PARTS AVAILABILITIES AT CURRENT LOCAL SINGAPORE WAREHOUSE. IF THERE IS A NEED TO INCLUDE AIRFREIGHT PARTS, WE WILL INFORM DULY.