

ASSIGNMENT

REF: CS/AIG/19003215/kqdb (Type of Instruction)

CAUSE NO: menmen

Kenneth

ASSIGNMENT (OFFICE)

From (Person)

Azlan

at

AIG

Date/Time:

19/12/19 @ 3:02pm

Estimated Cost

Bill to

OD / TP / WS / TP RES / OD RES / EVA / INV / MV TCS

To Inspect Vehicle No:

GBE70022

Insured

SLB 59072

at Workshop no:

Insurance Auto

Tel:

9008 9959

of

Blk 5038 AMK Ave 3 #01-405

Policy No:

0999994822

Claim No:

592035361856

Sum Insured

Excess

Make of Vch:
(Client's Record)

D.O.A

18/2/19

CA / REV / REP. / REV 24 HRS

H.O.B. Enforcement

Date/Time:

10:07am @ 20/12/19

Person Contacted

Mr. YEO

Vehicle

TP DIT

Date/Time	Action/Instruction (✓) Estimate
	<u>GBE70022 - X</u>
	<u>SLB 59072 - X</u>

ASS. REC. BY:

REF: AIG1

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Insurance Agency Hoc
of Amk

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: GBE 7002 Z Yr Regn: 05, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: Toy Hige c.c. 2882

Colour: M. Silver A/C: Insured / Std / NI / NA

Sp. Reading: 102939 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTI-H702P4C0189862

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 195R 15X8

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Kapsen

Front

Rear

R/Bal. 9 mm

R/Bal. 9 mm

L/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 18/2/19

D.O.I. 20/2/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

cls Acc body

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>1</u>	<u>File pass to</u>
<u>26/2/19</u>	<u>C1 Day @ 2300 (red @ 4139.93, 64%), confirmed with Mr Yeo.</u>
RECEIVED 26 FEB 2019	

Date/Time, File Pass to?

: Prell. Report

Days Of Repair: 5

Resurvey No. of Trlp: _____

1) 28/2 2019

: Final Report

Date/Time, File Return to?

2)

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech Invs (\$ _____)

: Weekend (\$ _____)

Survey Fee:

Transportation:

\$ - RS - SI

Phone

Others

TOTAL

Report Format: MER-TP

Lump Sum / I.B.K. (\$) 2300

Empty box for recording fees and totals.

- Pre repair inspection request - GBE7002Z VS SLB5907Z (OI) DOA 18/02/2019

From: Azlan, Syazairdina
To: admin-a@lkkauto.com, assignments@lkkauto.com
Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Chan, Yoke Shi, Kaur, Baljit, Hor, Yinrul
Sent: 19/2/2019 3:22:36 PM
Attachments:  90164(NQA).pdf

Hi,

Please refer to the enclosed request from **CHEONGHOH LAW CORPORATION**.

Claim no : 5920353618SG003
Case Owner : ANGIE GEOK LING GAN

If you have any queries/concerns, please let us know.
Kindly assist to assign Kenneth Kong as Single Joint Expert as requested.

Thanks and regards,

Syaza Irdina Azlan
AIG
Express Claims Adjuster II, Singapore FNOL, Claims Operations – Auto
SG Claims Operations | AIG Shared Services

Syazairdina.Azlan@aig.com | www.aig.sg

From: Cheonghoh Law [mailto:mail@cheonghoh.sg]
Sent: Tuesday, February 19, 2019 2:55 PM
To: Azlan, Syazairdina
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Chan, Yoke Shi; Kaur, Baljit; Hor, Yinrul
Subject: Re: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLB5907Z AND GBE7002Z ON 18/02/2019

Dear Sir/ Madam,

We refer to the above matter and to your email of even date.

Our client hereby nominate Kenneth Kong of LKK Auto Consultants Pte Ltd of your said letter to conduct the pre-repair survey of the damages to our client's vehicle arising out of the above mentioned accident.

Please be informed that our client's vehicle, GBE 7002Z is currently laying at our client's workshop, Insurance's Auto at Blk 5038 Ang Mo Kio Ave 3 #01-405 Ang Mo Kio Industrial Park 2 Singapore 569541. Kindly contact the person in charge Mr Yeo at 9008 9959 before your surveyor attending at the said workshop.

Thanks & regards,
Melody
CHEONGHOH LAW CORPORATION
Blk 53 Chin Swee Road #03-05 Singapore 160053
T: 6337 8700 | F: 6337 3700 | E: mail@cheonghoh.sg

On 19 Feb 2019, at 9:09 AM, Azlan, Syazairdina <Syazairdina.Azlan@aig.com> wrote:

<logo.jpeg>

<lock.gif>

This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยของข้อมูลที่เข้ารหัส เพื่ออ่านเนื้อหาก็เปิดไฟล์นี้แทน

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려

면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

[Click here](#) by 2019-02-26 09:10 +08 to read your message.
After that, open the attachment.

[More info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the address. Please notify the sender if you have received this email in error or simply delete it

Secured by Proofpoint Encryption. Copyright © 2009-2017 Proofpoint, Inc. All rights reserved

<SecureMessageAtt.html>

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Syzairdina Azlan@aicg.com

To: mail@cheonghoh.sg

Cc: Andy-SY.Fong@aicg.com ,Lee-

Ying.Chin@aicg.com ,NoorMariesa.AbuKassim@aicg.com ,ShengYang.Lim@aicg.com ,Aashweenjeetkaur.Mithoosingh@aicg.com ,yokeshi.chan@aicg.com ,Baljit.Kaur@aicg.com ,Yinrul.Hor@aicg.com

Subject: AIGENCRYPT - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLB5907Z AND GBE7002Z ON 18/02/2019

Date: Tue, 19 Feb 2019 01:09:45 +0000

Without Prejudice

Your Reference : LCH.my/AMK07-90164.19
Our Reference : SLB5907Z

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards,

Syaza Irdina Azlan

AIG

Express Claims Adjuster II, Singapore FNOL, Claims Operations – Auto
SG Claims Operations | AIG Shared Services

Syazairdina.Azlan@aig.com | www.aig.sg

From: Chan, Yoke Shi

Sent: Tuesday, February 19, 2019 7:44 AM

To: Azlan, Syazairdina

Cc: Lim, Sheng Yang; Abu Kassim, Noor Mariesa

Subject: FW: Notice of Accident - Traffic accident involving GBE 7002 Z and SLB 5907 Z (your insured) on 18 February 2019 at/along Upper Cross Street towards CTE; Our ref: LCH.my/AMK07-90164.19

From: Cheonghoh Law [<mailto:mail@cheonghoh.sg>]

Sent: Monday, February 18, 2019 6:03 PM

To: Abu Kassim, Noor Mariesa; Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Lim, Sheng Yang; Md Ishak, Mohd Imran; Chan, Yoke Shi; Supramaniam, Darshene

Subject: Notice of Accident - Traffic accident involving GBE 7002 Z and SLB 5907 Z (your insured) on 18 February 2019 at/along Upper Cross Street towards CTE; Our ref: LCH.my/AMK07-90164.19

Dear Sir/ Madam,

Please see attached Notice of Accident for your attention and reply.

Thanks & regards,

Melody

CHEONGHOH LAW CORPORATION

Blk 53 Chin Swee Road #03-05 Singapore 160053

T: 6337 8700 | F: 6337 3700 | E: mail@cheonghoh.sg

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	19/02/2019 10:00
Date Of Accident	18/02/2019 09:30
Exact Location Of Accident	UPPER CROSS ST TWDS CTE
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	GBE700Z
Insured/Policyholder	
Name Of Registered Owner	KAM KEE & SONS ELECTRIC CONTRACTOR
Co Reg No	06638600D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97519918
Alternative Phone No	OFFICE-97519918
Vehicle Particulars	
Manufacturer	TOYOTA
Model	HIACE
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5087850392-01
Cover Note Number	
Driver	
Name of Driver	LOKE CHEE FOO
NRIC No	S1532011G
Date Of Birth	07/11/1962
Occupation	INDOOR
Date Of Driving Pass	16/03/1986
Driving Experience	32 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97519918
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 34 UPP CROSS ST #18-148
Postcode	050034
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN - CIRCUMSTANCES OF THE ACCIDENT.


Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLB5907Z
Vehicle Make/Model/Colour	HONDA AIRWAVE
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	KWEK KIAT BENG
NRIC/Passport Number	S1588300F
Contact Number	98788962
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along Upper Cross St towards CTE on the extreme right lane of 4 lanes road. Approaching the front of court, a vehicle SLB 59072 suddenly came out from the slip road without stopping and collided against my right side of my van. My right side of my van was damaged.

DECLARATION
 聲明
 肥父子電器工程
 KAI KEE & SONS' ELECTRICAL CONTRACTOR
 Blk 32 New Market Road #02-1036
 People's Park Singapore 050032
 Tel: 6534 1240 Fax: 6532 6798

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Insurance's Auto

Blk 5038 #01-405, Ang Mo Kio Ind. Park 2
 Singapore 569541.
 Email: insurancesauto@hotmail.com / Fax:64455393.
 Tel: 90089959

Not Asbestos
L1 Bump @ 2300k
Respray After Paint

Kam Kee & Sons Electric Contractor
 32 New Market Road #02-1036
 Singapore 050032.

Vehicle No : GR3745L
 Chassis No : JTFHT02P400189862
 Make : Toyota Hiace
 Year : 2015

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey & inform after work commencing
- To disclose damaged parts, serial numbers
- Parts prices are subject to confirmation
- Third party survey is on a "without prejudice" basis
- No illegal modifications allowed
- Supplementary items (material, labour, etc) is subject to final cost from the repairer

Acknowledged by Repairer
 Signature: _____
 Date: _____

5 days

QTY	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1	Rear Fender RH	<i>1308.10</i>	<i>Rn \$1,849.20 ✓</i>
1	Fender Center Sliding Guide LH		<i>Sn \$213.00 X</i>
1	Rear Fender Inner Shield RH		<i>Sn \$126.00 X</i>
1 set	Rear Fender Inner Shield Clips		<i>nn \$40.00 X</i>
1	Sliding Door RH		<i>n \$906.30 X</i>
1	Sliding Door Lower Guide RH		<i>Sn \$103.30 X</i>
1	Sliding Door Weather Strip RH		<i>Sn \$289.30 X</i>
1	Sliding Door Lock LH		<i>n \$215.00 ✓</i>
1	Rear Bumper	<i>411.60</i>	<i>Sn \$653.00 ✓</i>
1	Rear Bumper Side Retainer RH		<i>Sn \$35.00 X</i>
1 set	Rear Bumper Clips		<i>nn \$30.00 ✓</i>
1	Rear Absorber RH		<i>Sn \$280.00 X</i>
1	Rear Tail Lamp RH	<i>241.85</i>	<i>Ln \$277.20 ✓</i>
			<u>\$4,677.24</u>
		Less 25%	\$1,169.31
			\$3,507.93

Labour Charges

To remove and replaced damaged parts including straightening repositioning replacement parts.

700
 \$900.00
350
 \$1,000.00

Supply Paint Material and necessary items. To respray replaced

and other affected panels

Reconnect wiring at the damage section and check for proper functions.

\$50.00 201

To carry out antirust treatment on affected panels.

\$100.00 301

To remove and refit roof lining to facilitate repair.

\$200.00 1001

To remove/replace rear LH under carriage

na \$200.00 X

Special Nett Item

Rear Tyre

r2 \$200.00 X

Rear Bumper Reverse Sensor

r2 \$280.00 X

Grand Total :

\$6,437.93

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Feb 2019 Edit Reg		19 Feb 2019 00:00 Edit Adj Rpt	S\$2,300.00 Edit Estimates	S\$2,300.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by adjuster]
Insured:	LCRF PTE LTD, Co. Reg. No.: 201624597K			
Main Claimant:	-			
Vehicle Reg. No.:	GBE7002Z	Date of Loss:	18/02/2019 00:00 - :59 [35 Months and 17 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / 5920353618SG	Policy/Cover Note No.:	0999994822 (Comprehensive)	
Vehicle Reg. No. (Insured):	SLB5907Z	Policy No. (Claimant):		
		Excess:		
Repairer:	Insurance Auto (HQ) BLK 134 PASIR RIS ST 11 #04-253 (510134) MAILING ADDRESS, BLK 5038 ANG MO KIO INDUSTRIAL PARK ZN#01-405 (569541), 569541 Ang Mo Kio - Tel:			
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Gan, Angie-GL] Angiegeokling.Gani@aig.com			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 01/03/2019]			

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
• AIG_5G (21/02/2019): Request to upload TP GIA Report		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

*GBE7002Z (5920353618SG)
[SLB5907Z]
TP

-
Feb 18 2019 12:00AM
[LCRF PTE LTD]
Insurance Auto

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View	View in Browser
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/02/19 11:05	General View		<input checked="" type="checkbox"/>
2	27/02/19 11:05	General View		<input checked="" type="checkbox"/>
3	27/02/19 11:05	General View		<input checked="" type="checkbox"/>
4	27/02/19 11:05	General View		<input checked="" type="checkbox"/>
5	27/02/19 11:05	General View		<input checked="" type="checkbox"/>
6	27/02/19 11:05	General View		<input checked="" type="checkbox"/>
7	27/02/19 11:05	General View		<input checked="" type="checkbox"/>
8	27/02/19 11:05	General View		<input checked="" type="checkbox"/>
9	27/02/19 11:05	General View		<input checked="" type="checkbox"/>
10	27/02/19 11:05	General View		<input checked="" type="checkbox"/>
11	27/02/19 11:05	General View		<input checked="" type="checkbox"/>
12	27/02/19 11:05	General View		<input checked="" type="checkbox"/>
13	27/02/19 11:05	General View		<input checked="" type="checkbox"/>
14	27/02/19 11:05	Odometer Reading		<input checked="" type="checkbox"/>
15	27/02/19 11:05	Chassis Number		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/02/19 17:20	Singapore Accident Statement		<input type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	21/02/19 09:19	OI GIA REPORT		<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG19003215/KQD3Q2
Date: 04/03/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 0999994822	
Claimant Vehicle No : GBE7002Z	Insured Vehicle No : SLB5907Z	
Date of Loss: 18/02/2019	Nature of Claim: TP	Claim No: 5920353618SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBE7002Z		Engine No: 1KD2590536
Make & Model: TOYOTA HIACE, 3.0 (A)		Chassis No: JTFHT02P400189862
Reg. Date: 01/03/2016 (Man. Year: 2016)		Odometer: 102939 km
Colour: Metallic Silver		
Engine Capacity: 2982 cc		
Market Value/New Car Price: N/A		
Sum Insured (S\$): Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable): Yes	Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes	Engine Modification: No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15X8	Rear Tyre Size: 195 R15X8	
Front Left Side: KAPSEN 9 mm	Rear Left Side: KAPSEN 9 mm	
Front Right Side: KAPSEN 9 mm	Rear Right Side: KAPSEN 9 mm	

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,242.97	1,493.66	2,749.31	64.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,450.00	1,400.00	1,050.00	42.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,692.97	2,893.66	3,799.31	56.77
Approved Total (Overridden) (S\$)		2,300.00		
Nett Amount (S\$)	6,692.97	2,300.00	4,392.97	65.64

INSPECTION

Date of Assignment: 19/02/2019		
Date Inspected: 20/02/2019	Inspected At:	Insurance Auto (HQ) BLK 134 PASIR RIS ST 11 #04-253 (510134) MAILING ADDRESS, BLK 5038 ANG MO KIO INDUSTRIAL PARK 2N#01-405 (569541) Singapore 569541
Estimated Period of Repair: 5.0 days		

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER RH	Bent	1,849.20 FL	*1,308.10 FL
2	1		*FENDER CENTER SLIDING GUIDE LH	Serviceable	213.00 FL	*- FL
3	1		*REAR FENDER INNER SHIELD RH	Serviceable	126.00 FL	*- FL
4	1		*SET REAR FENDER INNER SHIELD CLIPS	Not Necessary	40.00 FL	*- FL
5	1		*SLIDING DOOR RH	Repair	906.30 FL	*- FL
6	1		*SLIDING DOOR LOWER GUIDE RH	Serviceable	103.30 FL	*- FL
7	1		*SLIDING DOOR WEATHER STRIP RH	Serviceable	289.30 FL	*- FL
8	1		*SLIDING DOOR LOCK LH	Repair	215.00 FL	*- FL
9	1		*REAR BUMPER	Cut	653.00 FL	*411.60 FL
10	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	35.00 FL	*- FL
11	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
12	1		*REAR ABSORBER RH	Serviceable	280.00 FL	*- FL
13	1		*REAR TAIL LAMP RH	Cut	277.20 FL	*241.85 FL
14	1		*REAR TYRE	Serviceable	200.00 FS	*- FS
15	1		*REAR BUMPER REVERSE SENSOR	Serviceable	280.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,497.30	1,991.55
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,254.33	497.89
Total Parts (\$\$)	4,242.97	1,493.66

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REPLACED DAMAGED PARTS INCLUDING STRAIGHTENING REPOSITIONING REPLACEMENT PARTS	New	900.00	700.00
2	SUPPLY PAINT MATERIAL AND NECESSARY ITEMS .TO RESPRAY REPLACED AND OTHER AFFECTED PANELS	New	1,000.00	550.00
3	RECONNECT WIRING AT THE DAMAGE SECTION AND CHECK FOR PROPER FUNCTIONS	New	50.00	20.00
4	TO CARRY OUT ANTIRUST TREATMENT ON AFFECTED PANELS	New	100.00	30.00
5	TO REMOVE AND REFIT ROOF LINING TO FACILITATE REPAIR	New	200.00	100.00
6	TO REMOVE/REPLACE REAR LH UNDER CARRIAGE	New	200.00	0.00
Gross Labour Cost (S\$)			2,450.00	1,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >