

200 m.

INS. CASE OWNER: CC6/LPC1900 32177 **ASSIGNMENT** **LOK** **IDAC**

Surveyor: **WJ** DOI: **WJ/19** Date / Time: **WJ/19** Registered in Merimen: **WJ/19**

Pro-assign / CCU / FTE: **GBA 4407**

Insured Vehicle No.: _____ Claim No.: _____

Name of Insured: _____ Policy No.: _____

Insured Tel No.: _____ HP: _____ Make / Model: _____

Excess Sec II \$5: _____ D.O.A.: **14/7/19** Place of Accident: _____

Is driver the owner? (YES / NO) Nature of Accident: _____

If NO, Driver Name / Age: _____ TP GIA REPORT: YES / NO

Driver Tel No.: _____ (V/L: YES / NO) Insured Liability: _____ Final ? Yes / No

ym 7683

INSRS: **WSP: 1 km** INSRS: _____ INSRS: _____ INSRS: _____

Tel: **WMA** Tel: _____ Tel: _____ Tel: _____

Liability: _____ Liability: _____ Liability: _____ Liability: _____

RMKS: _____ RMKS: _____ RMKS: _____ RMKS: _____

Date/Time	STAGE	DATE/PIC
	Non-Reporting Ir (1st)	
	Non-Reporting Ir (2nd)	
	Non-Reporting Ir (Final)	
	Notification Ir (if non-pickup)	
	Call Of	
	After call Ir to Of	
	Documentation Check List: Handler Typist	
	Notification Ir (if non-pickup)	
	After call Ir to Of	
	Authorisation To Act	
	Release Voucher	
	Final Repair Bill	
	Car Rental Invoice	
	Towing Invoice	
	LTA / GIA	
	Medical Bill	
	PIR	
	Mandate/Reject Instruction	
	LOD	
	Payment Breakdown Form	
	Post-Repair Photos	
	Others	

PRELIMINARY ADVICE Date/Time: _____ Sent By: _____

FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: **OMJ**

Repair Cost: **\$5,250.00** (6 days) Reduction: **5%** Email: ☒ Call: ☐

FINAL SETTLEMENT Date/Time: **04.09.19** Confirm with: **ADUNE** Email: ☐ Call: ☐

Final Liability: **\$100** (Agreed / Assessed) BOLA S/N No.: **27** If NO or B 28, Ass. Lia: _____

Repair Cost: **\$5,250.00** **OLD REPAIR ENDED BY**

Loss of Rental (LOR): **\$5** (days)

Loss of Use (LOU): **\$5** (\$150 x 10 days)

Loss of Income (LOI): **\$5** (\$5 x 10 days)

LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ (Tick only one)

GIA/LTA Search: **\$5**

Medical: **\$5**

Disbursement: **\$5** (e.g. Tow/Independent)

Legal Cost: **\$5**

Total: **\$5,250.00** Global Sum \$5: _____

FINAL PAYMENT Date/Time: **04.09.19** Confirm with: **ADUNE** Email: ☐ Call: ☐

Payee 1: **\$5,250.00** Name 1: **LES KUNN TWA MOTOR SERVICE**

Payee 2: (Strike if N.A.) **\$5** Name 2: _____

Payee 3: (Strike if N.A.) **\$5** Name 3: _____

Hwa Jie

REF: LPC

Date: 21/2/19

Sub No: YM 7683 T Date: 24 Dec 2007

Type: M/Car / M/Cycle / Bus / Van / Truck / Taxi / Prime Mover /

Truck / Trailer or

Make: Mitsubishi FE83 Qty: 2977

Colour: White A/C: Insured / STD / N/A

Sp/Reading: 422/90 (Std): Insured / Std / N/A

Engine:

Chin: FE83BEA70627

Gen. Cond: Good / Fair / Poor / BurntSteering: Good / Jammed / Leaked / Burnt /Brake: Good / Jammed / Leaked / Burnt /Mod: Nil / STD / STD A/Rin. or

Tyre Size: F: 7.00-12

R: -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUM /

TOYO / YOKO or Swallow

Front: R/Rat: 7 mm

L/Rat: 7 mm

D.O.A. 14/2/19 D.O.I. 21/2/19

Survey held at Lee Kuan Hwa

Des. of Damages: F/R / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

1. Insured Code:

2. (1) WS / TP RES / QO RES / EVA / RV / MV

3. Insured Vehicle No:

YM 7683 K

4. Insured Description:

Lee Kuan Hwa

5. Date:

24 Sungai Kadut St. 4

6. Amount:

7. Policy No:

8. Name:

9. Name:

10. Insured:


Excess:

11. Motor of Veh:

10:30am
owner waiting

(Policy Condition)

Remarks: The veh had commenced its repair at the time of inspection.



Est. or Market Value:

IDAC Accident Report: Consistent? - Yes or No

GIA / PIR Seen: Consistent? - Yes or No

Est. Repairs: 6 days Res: Yes or No

Loss Limit: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Date / Time: Action / Instruction

42.4520 (520) 5513 5.7.1

Initial Date: File Path: 1/1

☐ Prel. Report

2/

☐ Final Report

Initial Date: File Path: 2/2

3/

Report Format:

Lump Sum / L.B. / C.

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp. 15☐ Interview 15☐ Tech. Insp. 15☐ Witness 15

Survey Fee:

Transportation:

1. 10.00 12

1. 11.40

1. 10.00

1. 11.40

P. 11.40





Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC4/LPC19003217/Jhb3

Date: 22.02.2019

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

YM7683T

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 21.02.2019 at the premises of M/s Lee Kuan Hwa Motor Service and have the following to report:-

Workshop Estimate Amount	: S\$	10,763.00
Revised Estimate Amount	: S\$	6,948.00
"Check" Items Amount	: S\$	385.00
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 6 days

Yours faithfully,

HWEE JIE
Licensed Appraiser

LEE KUAN HWA MOTOR SERVICE

Mailing Add: 39, Westwood Ave Singapore 648719
 Workshop: 24, Sungei Kadut Street 4 Singapore 729050
 Tel: 6269 9192 Fax: 6269 2239 H/P: 9631 1712
 Business Reg. No: 36463500B

M/s: **Lonpac Insurance Bhd**
 300, Beach Road
 #17-04/07 The Concourse
 Singapore 199555

Date 19.02.2019

Motor Claim Dept

Vehicle number : YM 7683 T
 Make/Model : MITSUBISHI FE83BE0SRDEA
 Date of accident : 14.02.2019
 Claim Type : TP Claim

Accident involving YM 7683 T & GBA 440 J along Boon Lay Way on 14.02.2019.

Re: Estimate

1.	2 pcs	Rear door	BVC /	\$	1,600.00✓
2.	2 / 8 pcs	Rear door hinges LH RH	(2) BT / @50 x ✓	\$	300.00 x 100
3.	2 pcs	Rear door lock LH RH	SVC x	\$	400.00
4.	2 pcs	Rear lamp LH RH	LRA /	\$	360.00✓
5.	1 pcs	Rear lamp bracket	(LH) BT /	\$	120.00✓
6.	1 pc	Rear box lower panel	Repair x	\$	500.00
7.	1 pc	Rear cross member	BD /	\$	450.00✓
8.	1 pc	Rear number plate	DEF /	\$	30.00✓
9.	1 pc	Rear number plate lamp	LRA /	\$	28.00✓
10.	1 / 2 pcs	Rear box side bar (Big)	LH RH Repair x DV / CW ✓	\$	600.00 x 300
11.	1 pc	Rear box side bar (Small)	LH BT /	\$	280.00✓
12.	1 pc	Rear bumper	DEF /	\$	400.00✓
13.	2 pcs	Rear bumper bracket LH RH	BT /	\$	200.00✓
14.	8 pcs	Rear box U clip bracket LH RH	BT /	\$	400.00✓
15.	1 pc	Rear box front cross member	NN x	\$	500.00
16.	1 pc	Air filter pipe RH	2 x	\$	385.00
Sub-Total				\$	6,553.00

李光華 摩托修理

LEE KUAN HWA MOTOR SERVICE
 39, Westwood Avenue, Singapore 648719
 TEL: 6269 9192 FAX: 6269 2239 H/P: 9631 1712

LEE KUAN HWA MOTOR SERVICE

Mailing Add: 39, Westwood Ave Singapore 648719
Workshop: 24, Sungei Kadut Street 4 Singapore 729050
Tel: 6269 9192 Fax: 6269 2239 H/P: 9631 1712
Business Reg. No: 36463500B

M/s: **Lonpac Insurance Bhd**
300, Beach Road
#17-04/07 The Concourse
Singapore 199555

Date 19.02.2019

Motor Claim Dept

Vehicle number : YM 7683 T
Make/Model : MITSUBISHI FE83BE0SRDEA
Date of accident : 14.02.2019
Claim Type : TP Claim

Accident involving YM 7683 T & GBA 440 J along Boon Lay Way on 14.02.2019.

Re: Estimate

To Wiring Services	\$ 80 200.00 ✓
To Remove & Refix Rear Box Labour Charges	\$ 400 800.00 ✓
To Change Rear Box Cross Member	\$ 200 800.00 ✓
To Repair & Replace Labour Charges	1000 \$ 1,300.00 ✓
To Logo Writing	\$ 260.00 ✓
To Putty & Spray Painting	\$ 600 850.00 ✓
Total	\$ 10,763.00

Yours Faithfully,

李光華 廖曉輝
LEE KUAN HWA MOTOR SERVICE
39, Westwood Avenue, Singapore 648719
TEL: 6269 9192 FAX: 6269 2239 H/P: 9631 1712

KKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Hwee Jia - LKK

21/2/19

L/S 6 days.



Shu Pei (LKKAuto)


From: ONG LI LI <llong@lonpac.com>
Sent: Friday, 22 February 2019 4:03 PM
To: Shu Pei (LKKAuto)
Cc: MT_Claim_SG; Admin A; Vic (LKKAuto)
Subject: RE: Our Ref: 19/19/19/VC05/021426 Acciden involving YM 7683 T & GBA 440 J along Jalan Boon lay Way on 14.02.2019 . [External Confidential]
Attachments: GBA440J 140219.PDF

Lonpac External - Confidential

Dear Shu Pei

Please see attached for our Insured's GIA report.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

From: Shu Pei (LKKAuto) [mailto:shupeil@lkkauto.com]
Sent: Friday, 22 February, 2019 3:49 PM
To: ONG LI LI
Cc: MT_Claim_SG; Admin A; Vic (LKKAuto)
Subject: RE: Our Ref: 19/19/19/VC05/021426 Acciden involving YM 7683 T & GBA 440 J along Jalan Boon lay Way on 14.02.2019 . [External Confidential]

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle YM 7683T at M/s Lee Kuan Hwa Motor Service on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:

- TP estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Vic and he can be contacted at DID: 6841 2096.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Wednesday, 20 February 2019 10:43 AM

To: 'ONG LI LI' <llong@lonpac.com>; assignments <assignments@lkkauto.com>

Cc: 'MT_Claim_SG' <mt_claim@lonpac.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: Our Ref: 19/19/19/VC05/021426 Acciden involving YM 7683 T & GBA 440 J along Jalan Boon lay Way on 14.02.2019 . [External Confidential]

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: ONG LI LI [<mailto:llong@lonpac.com>]

Sent: Wednesday, 20 February 2019 9:14 AM

To: Lee Kuan Hwa <kuanhwa@singnet.com.sg>; MT_Claim_SG <mt_claim@lonpac.com>; assignments@lkkauto.com;
Admin-D (LKKAuto) <admin-d@lkkauto.com>

Subject: RE: Our Ref: 19/19/19/VC05/021426 Acciden involving YM 7683 T & GBA 440 J along Jalan Boon lay Way on 14.02.2019 . [External Confidential]

Lonpac External - Confidential

Without Prejudice

Dear Siew Chen

You may liaise with LKK Auto Consultants Pte Ltd for survey and assessment of liability.

Dear Catherine/Nivitha

FYA


Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

From: Lee Kuan Hwa [mailto:kuanhwa@singnet.com.sg]

Sent: Wednesday, 20 February, 2019 9:09 AM

To: MT_Claim_SG

Cc: GERALD POH WEE BIN

Subject: Acciden involving YM 7683 T & GBA 440 J along Jalan Boon lay Way on 14.02.2019 .

Dear Gerald Poh,

Our vehicle: YM 7683 T

Attached the GIA report.

We refer to the above matter and please be informed that we are making T.P claim against your insured GBA 440 J.

Kindly create a T.P claim for this case

Please advise on the officer-In-Charge & Liability

Kindly arrange survey for this case

Thank you.

Best Regards,

Siew Chen

Lee Kuan Hwa Motor Service

39, Westwood Ave,

Singapore 729050.

Tel: 6269 9192 Fax: 6269 2239



This email has been checked for viruses by AVG antivirus software.
www.avg.com



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC4/LPC19003217/Jeb3n2	
300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Date : 22-10-2019	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBA 440J	Veh. Inspected	YM 7683T
	Policy No.	Z19VC05001635	Coverage (\$)	0.00
	Claim No.	19/19/19/VC05/021426	Excess (\$)	0.00
	Assign From	ONG LI LI	Assign Date	20/02/2019
2. Vehicle Particulars & Condition				
	Make & Model	MITSUBISHI FE83	c.c	2977
	Engine No.	HIDDEN	Year of Reg.	2007
	Chassis No.	FE83BEA10621	Colour	WHITE
	Odometer	422190	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	7.00-16	SWALLOW	7 mm
	L/H Front Tyre	7.00-16	SWALLOW	7 mm
	R/H Rear Tyre	7.00-16	SWALLOW	7 mm
	L/H Rear Tyre	7.00-16	SWALLOW	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
	DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	14/02/2019	Inspection Date	21/02/2019
	Survey held at	24 SUNGEI KADUT ST. 4		
	Repairer	LEE KUAN HWA MOTOR SERVICE		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.			
	B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YM 7683T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
2	REAR DOOR	BUCKLED	1,600.00	1,600.00
6	REAR DOOR HINGE LH RH	BENT (2 PCS ONLY)	300.00	100.00
2	REAR DOOR LOCK LH RH	SERVICEABLE	400.00	-
2	REAR LAMP LH RH	CRACKED	360.00	360.00
1	REAR LAMP BRACKET LH	BENT	120.00	120.00
1	REAR BOX LOWER PANEL	TO REPAIR SEE LABOUR	500.00	-
1	REAR CROSS MEMBER	DENTED	450.00	450.00
1	REAR NUMBER PLATE	DEFORMED	30.00	30.00
1	REAR NUMBER PLATE LAMP	CRACKED	28.00	28.00
2	REAR BOX SIDE BAR (BIG) LH/RH	N/S DENTED	600.00	300.00
1	REAR BOX SIDE BAR (SMALL) LH	BENT	280.00	280.00
1	REAR BUMPER	DEFORMED	400.00	400.00
2	REAR BUMPER BRACKET LH RH	BENT	200.00	200.00
8	REAR BOX U CLIP BRACKET LH RH	BENT	400.00	400.00
1	REAR BOX FRONT CROSS MEMBER	NOT NECESSARY	500.00	-
1	AIR FILTER PIPE RH	NOT NECESSARY	385.00	-
	LESS 10% DISCOUNT		-	-426.80
			6,553.00	3,841.20
LABOUR				
	TO WIRING SERVICES.		200.00	80.00
	TO REMOVE & REFIX REAR BOX LABOUR CHARGES. INCLUSIVE OF THE REPAIR OF REAR BOX LOWER PANEL.		800.00	400.00
	TO CHARGE REAR BOX CROSS MEMBER .		800.00	400.00
	TO REPAIR & REPLACE LABOUR CHARGES.		1,300.00	1,000.00
	TO LOGO WRITING.		260.00	260.00
	TO PUTTY & SPRAY PAINTING.		850.00	600.00
			4,210.00	2,740.00
GRAND TOTAL			10,763.00	6,581.20

Report Ref No. CC4/LPC19003217/Jeb3n2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,250.00
---	--	--	----------

Report Ref No. CC4/LPC19003217/Jeb3n2

ONG HWEE JIE
Automotive Assessor

HO LEONG CHUAN
Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.