

15/9/2010

INS. CASE OWNER:

CC 3 / CTI1900

LKK:

IDAC:

Surveyor:

Kawin

DOI:

ASSIGNMENT

12/12/19

Date / Time:

12/12/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SJD 7645D

Name of Insured:

UM Jian Qun

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

18/12/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

UM Jian Qun

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

SWMG 010085802

Policy No.:

0MP5W301081800

Make / Model:

Honda

Place of Accident:

Beach rd TMS Bp

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SH 8503x



INSRS:

WSP:

Tel:

Liability:

RMKS:

code
us

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

SH 8503x -

SJD 7645D - 15/12/19 - 18/12/19

12/4/19

FILE PASS TO TYPE MANDATE

5/3/19

FILE PASS TO LSP TO CLOSE

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

Confirm by:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

S\$

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed)

BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost: (w/gst)

S\$

5269.45

Loss of Rental (LOR):

S\$

575.00

(5 days) x \$115

Loss of Use (LOU):

S\$

-

(S x days)

Loss of Income (LOI):

S\$

250.00

(S 50 x 5 days)

LOR only

LOU only

LOR + LOU

LOR + LOU

LOR + LOU

[Tick only one]

GIA/LTA Search

S\$

7.49

Medical:

S\$

-

Disbursement:

S\$

-

(e.g. Tow/ Independent)

Legal Cost

S\$

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$400

Total:

S\$

6101.44

Global Sum S\$: 6100.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

6100.00

Name 1:

Comfort Delgro Engineering Pte Ltd

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

UM 5/12/19



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your ref: To Be Advised
Our ref: CC3/CTI19003218/K1pb3

Date: 20.02.2019

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SH8503X


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 19.02.2019 at the premises of M/s ComfortDelGro Engineering Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	7,856.58
Revised Estimate Amount	: S\$	4,910.64
"Check" Items Amount	: S\$	103.12
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4 days

Yours faithfully,

KALVIN ANG
Licensed Appraiser

Date/Time: 18.02.2019 16:09

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO.: 305269745

COMFORT TRANSPORTATION PTE LTD
7010045
383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755


REGN NO.: SH 8503X	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL I-40	DATE/TIME IN 18.02.2019 12:15
YR OF MANU 09.06.2016	TARGET DATE
CHASSIS CODE KMHLB41UMGU090123	COMPLETION DATE/TIME:

JNT CARD NO:

Accident Date: 18.02.2019
NATURE: 3P 18.02.19

JOB DESCRIPTION

S/NO LABOR CODE DESCRIPTION



& PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

ment Slip

Exit Pass

SH 8503X

LIMITS

Vehicle No.:

SH 8503X

ce Advisor

Signature/Date

Name of Service Advisor

Date

to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

China Taiping (P/P)

TS

VEHICLE NO : SH 8503X

DATE 19/2/2019

MAKE :

LKK - Kalvin

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid ✓			\$ 2,174.90
	Boot Lid Lock Upper ✕			\$ 102.60
	Boot Lid Lock Lower ✕			\$ 31.70
	Boot Lid 'H' Emblem ✓			\$ 28.70
	Boot Lid CRDI Plate ✓			\$ 27.90
	Bootlid Moulding ✕			\$ 85.00
	Bootlid i40 Emblem ✓			\$ 27.90
	Bootlid Lower Garnish ✕ repair			\$ 227.90
	Rear Bumper ✓			\$ 553.00
	Rear Bumper Reinforcement ✓			\$ 428.40
	Rear Bumper Reinforcement Bracket (LH/RH) ✓		\$ 80.30	\$ 160.60
	Rear Bumper Clip 10 pcs ✓			\$ 22.00
	Rear Bumper Bracket ?		\$ 35.60	\$ 71.20
	Rear Bumper Sponge ✓			\$ 103.50
	Rear Bumper Under Cover ✓			\$ 228.00
	Tail Lamp (LH/RH) ✕		\$ 697.80	\$ 1,395.60
	Rear Panel ✕ repair			\$ 526.70
	Rear Panel Garnish ?			\$ 57.70
	Rear Panel Lower Panel ✕ repair			\$ 89.40
	Fuel Lid Cover ✓			\$ 70.90
	rear fender (RH) ✕ repair			\$ 17.60
	Clamp - Spare Tire			
	SUB TOTAL			\$ 6,413.60
	LESS 20%			\$ 1,282.72
	DISCOUNTED TOTAL			\$ 5,130.88
	Boot Lid Comfort Logo & Tel No. Sticker ✓			\$ 30.00
	Rear Bumper Reverse Sensor ✕			\$ 135.70
				\$ 165.70
	Labour Charge			
	Panel Beating-Repair Fender			\$ 1,200.00
	Spray Painting Charge			\$ 1,200.00
	Wiring Charge			\$ 30.00
	Tuff Kote			\$ 50.00
	Remove/Refix Reverse Sensor			\$ 80.00
	TOTAL LABOUR			\$ 2,560.00
	ESTIMATE TOTAL			\$ 7,856.58
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Knownledged by Repairer

Signature:

Date:

Ka lun (LKK)
 19/2/19 1050h
 4 hrs
 P/P
 Before Paint p/h

Nett
 Nett

800
 1000
 ✕
 ✕

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

China Taiping (P/P)

TS

VEHICLE NO : SH 8503X

DATE 19/2/2019

MAKE :

LKK - Kalvin

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid <i>Beut</i>			\$ 2,174.90
	Boot Lid Lock Upper <i>X on</i>			\$ 102.60
	Boot Lid Lock Lower <i>X sub</i>			\$ 31.70
	Boot Lid 'H' Emblem <i>in</i>			\$ 28.70
	Boot Lid CRDI Plate <i>in</i>			\$ 27.90
	Bootlid Moulding <i>X on</i>			\$ 85.00
	Bootlid i40 Emblem <i>in</i>			\$ 27.90
	Bootlid Lower Garnish <i>X repair</i>			\$ 227.90
	Rear Bumper <i>Beut</i>			\$ 553.00
	Rear Bumper Reinforcement <i>in</i>			\$ 428.40
	Rear Bumper Reinforcement Bracket (LH/RH) <i>Beut</i>		\$ 80.30	\$ 160.60
	Rear Bumper Clip 10 pcs <i>in</i>			\$ 22.00
	Rear Bumper Bracket <i>Beut</i>		\$ 35.60	\$ 71.20
	Rear Bumper Sponge <i>in</i>			\$ 103.50
	Rear Bumper Under Cover <i>in</i>			\$ 228.00
	Tail Lamp (LH/RH) <i>X on</i>		\$ 697.80	\$ 1,395.60
	Rear Panel <i>X repair</i>			\$ 526.70
	Rear Panel Garnish <i>X on</i>			\$ 57.70
	Rear Panel Lower Panel <i>scrub</i>			\$ 89.40
	Fuel Lid Cover <i>wiring</i>			\$ 70.90
	<i>rear fender (RH) X repair</i>			
	SUB TOTAL			\$ 6,413.60
	LESS 20%			\$ 1,282.72
	DISCOUNTED TOTAL			\$ 5,130.88
	Boot Lid Comfort Logo & Tel No. Sticker <i>in</i>			\$ 30.00 Nett
	Rear Bumper Reverse Sensor <i>X on</i>			\$ 135.70 Nett
				\$ 165.70
	Labour Charge			
	Panel Beating-Repair Fender			\$ 1,200.00 <i>800</i>
	Spray Painting Charge			\$ 1,200.00 <i>1000</i>
	Wiring Charge			\$ 30.00 <i>X on</i>
	Tuff Kote			\$ 50.00 <i>20</i>
	Remove/Refix Reverse Sensor			\$ 80.00 <i>X on</i>
	TOTAL LABOUR			\$ 2,560.00
	ESTIMATE TOTAL			\$ 7,856.58

LKK Auto Consignments Pte Ltd
 the Repairer of the vehicle
 • To survey and estimate the damage
 • To display damaged parts and materials
 • Parts prices are subject to the
 • Third party survey is on a
 • No illegal modification is allowed
 • Supplementary item(s) must be approved
 is subject to final approval from the

Kalvin
 Signature:
 Date: 19/2/19 1050h
 4 hrs
 P/P
 De for Panel p/h

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

VEHICLE	:	SH 8503X	TYPE OF CLAIM :	TP
MODEL	:	I-40	SURVEY BY :	LKK-KALVIN
JOB NO	:	305269745	DATE	19.02.19

[illegible]

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 22.02.2019

Time: 15:16:56

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305269745
 REGN NO : SH 8503X
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 09.06.2016
 DATE/TIME IN : 18.02.2019 12:15
 ACCIDENT DATE : 18.02.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0577-G	BOOTLID	1	2,174.90	20.00	1,739.92
0002	04-01-0103-0800-G	BOOTLID EMBLEM-H	1	28.70	20.00	22.96
0003	04-01-0103-0786-G	BOOTLID EMBLEM-CRDI	1	27.90	20.00	22.32
0004	04-01-0103-0787-G	BOOTLID EMBLEM-I40	1	27.90	20.00	22.32
0005	04-01-0103-0579-G	REAR BUMPER	1	553.00	20.00	442.40
0006	04-01-0103-0740-G	REAR BUMPER REINFORCEMENT	1	428.40	20.00	342.72
0007	04-01-0103-0743-G	REAR BUMPER REIN-BRKT RH	1	80.30	20.00	64.24
0008	04-01-0103-0742-G	REAR BUMPER REIN-BRKT LH	1	80.30	20.00	64.24
0009	04-01-0101-0111-G	REAR BUMPER CLIPS	10 L	22.00	20.00	17.60
0010	04-01-0103-0739-G	REAR BUMPER SPONGE	1	103.50	20.00	82.80
0011	04-01-0103-0738-G	REAR BUMPER UNDER COVER	1	228.00	20.00	182.40
0012	04-01-0103-0817-G	FUEL LID COVER	1	70.90	20.00	56.72
0013	28-01-0103-0005-A	BOOTLID COMFORTDELGRO	1	20.00		20.00

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305269745
REGN NO : SH 8503X
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 09.06.2016
DATE/TIME IN : 18.02.2019 12:15
ACCIDENT DATE : 18.02.2019


JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0014 28-01-0103-0006-A BOOTLID 65521111	1	10.00			10.00
0015 04-01-0103-0695-G SPARE TYRE FASHENER **	1	17.60	20.00		14.08

SUB-TOTAL : 3,104.72

JOB NATURE

0000 PB	PANEL BEATING	800.00
0001 SP	SPRAYPAINT CHARGE	1000.00
0002 20-00	TUFF COAT ON AFFECTED PARTS.	20.00
SUB-TOTAL :		1,820.00

TOTAL : 4,924.72


MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE : AUTHORIZED : YES / NO

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

Our Job Ref No : 305269745
Date : 22/02/19

FINALIZATION FORM

To : LKK
Attn : KALVIN ANG
Vehicle Reg No. : SH 8503X

Fax :
Date of Accident : 18-Feb-19

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-


1. The repair job shall bill to: CHINA TAIPING --- SJD7645D
2. The finalized amount shall be:
 - (a) Spare Parts after List discount \$3,104.72
 - (b) Labour Charges \$1,820.00
 - Total for Part-By-Part Repair Cost \$4,924.72**
 - (c.) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost

3. Estimated normal period for repairs: 4 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : LIM T S
Tel : 62148398
Fax : 65468156

Signature : 
Name : KALVIN
Date : 22/2/19

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees	-----			
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/CTI19003218/K1pb3

04 APRIL 2019

LIM JIAN QIANG
183 SPRINGSIDE AVENUE
SINGAPORE 786036

Dear Sir/Madam,

ACCIDENT INVOLVING SJD 7645D AND SH 8503X ON 18/02/2019

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, China Taiping Insurance (Singapore) Pte Ltd to deal with the third party claim against your policy.

We have received a claim from SH 8503X against your motor insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in your favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please call us if you have further queries.

Yours faithfully,

CHEW HSIAO TONG
Case Handler
DID: 6742 3197
FAX: 6741 4108
EMAIL: chewht@lkkauto.com

c.c. *China Taiping Insurance (Singapore) Pte Ltd*
(Motor Claims Dept)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI19003218/K1pb3n2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 10-07-2019	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJD 7645D	Veh. Inspected	SH 8503X
Policy No.	DMPCSN3020281800	Coverage (\$)	0.00
Claim No.	SNM19D0200858C02/5	Excess (\$)	0.00
Assign From		Assign Date	19/02/2019
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KMHLB41UMGU090123	Colour	BLUE
Odometer	267459	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/60 R16	HANKOOK	7 mm
L/H Front Tyre	205/60 R16	HANKOOK	7 mm
R/H Rear Tyre	205/60 R16	HANKOOK	7 mm
L/H Rear Tyre	205/60 R16	HANKOOK	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	18/02/2019	Inspection Date	19/02/2019
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 8503X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOOT LID	BENT	2,174.90	2,174.90
1	BOOT LID LOCK UPPER	SERVICEABLE	102.60	-
1	BOOT LID LOCK LOWER	SERVICEABLE	31.70	-
1	BOOT LID 'H' EMBLEM	NECESSARY	28.70	28.70
1	BOOT LID CRDI PLATE	NECESSARY	27.90	27.90
1	BOOTLID MOULDING	SERVICEABLE	85.00	-
1	BOOTLID I40 EMBLEM	NECESSARY	27.90	27.90
1	BOOTLID LOWER GARNISH	TO REPAIR SEE LABOUR	227.90	-
1	REAR BUMPER	DEFORMED	553.00	553.00
1	REAR BUMPER REINFORCEMENT	CRACKED	428.40	428.40
2	REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @\$80.30	BENT	160.60	160.60
10	REAR BUMPER CLIP	NECESSARY	22.00	22.00
2	REAR BUMPER BRACKET @\$35.60	SERVICEABLE	71.20	-
1	REAR BUMPER SPONGE	TORN	103.50	103.50
1	REAR BUMPER UNDER COVER	CRACKED	228.00	228.00
2	TAIL LAMP (LH/RH) @\$697.80	SERVICEABLE	1,395.60	-
1	REAR PANEL	TO REPAIR SEE LABOUR	526.70	-
1	REAR PANEL GARNISH	SERVICEABLE	57.70	-
1	REAR PANEL LOWER PANEL	TO REPAIR SEE LABOUR	89.40	-
1	FUEL LID COVER	MISSING	70.90	70.90
1	REAR FENDER (RH) (NPA)	TO REPAIR SEE LABOUR	-	-
1	SPARE TYRE FASHENER (ADDITIONAL) LESS 20% DISCOUNT	CRACKED	17.60	17.60
			-1,286.24	-768.68
			5,144.96	3,074.72
SPECIAL NETT ITEMS				
1	BOOT LID COMFORT LOGO & TEL NO.STICKER (SN)	NECESSARY	30.00	30.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER REVERSE SENSOR (SN)	NOT NECESSARY	135.70	-
			165.70	30.00
	LABOUR			
	PANEL BEATING-REPAIR FENDER .INCLUSIVE OF THE REPAIR OF BOOTLID LOWER GARNISH,REAR PANEL,REAR PANEL LOWER PANEL AND REAR FENDER (RH) .		1,200.00	800.00
	SPRAY PAINTING CHARGE.		1,200.00	1,000.00
	WIRING CHARGE.	NOT NECESSARY	30.00	-
	TUFF KOTE.		50.00	20.00
	REMOVE/REFIX REVERSE SENSOR .	NOT NECESSARY	80.00	-
			2,560.00	1,820.00
GRAND TOTAL			7,870.66	4,924.72
RECOMMENDED COST OF REPAIRS				4,924.72

Report Ref No. CC3/CTI19003218/K1pb3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.