

Tanpoh

REF

51

Accident

SHC 7169R

2016 Aug

Team
Estimated Cost
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No
At Workshop No
Insured
Policy No
Claim No
Sum Insured
Excess
(Client's Record)
Make of Veh

N/S	O/S

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Est. or Market Value:
IDAC Accident Report Consistent? : Yes or No
GIA / PP Seen Consistent? : Yes or No
Est. Repairs: 2 days Res.: Yes or No
Lump Sum: 181 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date Person Contacted:

Vehicle: IN / OUT

Vehicle No
Type: M/Car / M/Cycle / Bus / Van / Lorry
Truck / Trailer or
Make: Hyundai 140
Colour: Yellow
Sp Reading: 250452
Eng No: KM HCS414mg 4093566
C/No
Gen Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Mod: R/S / Rim / STD A/Rim or
Tyre Size: F: 205 / 60 R14.
R: 205 / 60 R14.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Hankook

Front R/Bal. 6 mm
L/Bal. 6 mm
D.O.A.
Rear R/Bal. 6 mm
L/Bal. 6 mm
D.O.A.

Survey held at CONE Agency
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

P/P & 1,322.40 (Red & 731.22 / 35.61%)

Date/Time: File Pass to?

☐ : Preli. Report
☐ : Final Report

By

Date/Time: C6: Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Interpretation

Report Format:

Lump Sum / LB to

Add Fee: ☐ Site Trip - \$

☐ Interview - \$

☐ Transport - \$

☐ Refreshment - \$

1 x 1 x 1

1 x 1 x 1

1 x 1 x 1

1 x 1 x 1

1 x 1 x 1



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/CTI19003222/T1fb3

Date: 20.02.2019

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHC7169R


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 15.02.2019 at the premises of M/s ComfortDelGro Engineering Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	2,053.62
Revised Estimate Amount	: S\$	1,322.40
"Check" Items Amount	: S\$	561.22
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 2 days

Yours faithfully,

MOHD. TAUFIKH
Licensed Appraiser

China Taiping (P/B)
LKK -

TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010070
 ADDRESS : CITYCAB PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65551188

JOB NO : 305269089
 REGN NO : SHC7169R
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 25.08.2016
 DATE/TIME IN : 15.02.2019 12:40
 ACCIDENT DATE : 15.02.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0579-G	REAR BUMPER	1	553.00	20.00	442.40	de ✓
0002 04-01-0103-0738-G	REAR BUMPER UNDER COVER	1	228.00	20.00	182.40	de ✓
0003 04-01-0103-0739-G	REAR BUMPER SPONGE	1	103.50	20.00	82.80	? X } nn
0004 04-01-0103-0740-G	REAR BUMPER BEAM	1	428.40	20.00	342.72	? X } nn
0005 04-01-0101-0111-G	REAR BUMPER CLIPS	10	22.00	20.00	17.60	nei ✓
0006 09-01-9999-0068-A	REVERSE SENSOR	1	135.70	2.00	135.70	? X nn

SUB-TOTAL : 1,203.62

JOB NATURE

0000 20-05	Rear Fender Adv.Sticker RH/LH	200.00	nei ✓
0001 20-05	Rear Bumper Adv.Sticker	50.00	nei ✓
0002 PB	PANEL BEATING	240.00	200
0003 SP	SPRAYPAINT CHARGE	240.00	200
0004 L	R/I REVERSE SENSOR	120.00	30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taiping 97495745 / 67418434
 02 days
 WP 15/2/19 @ 420pm
 part by part
 Resurvey before paint
 taiping @ lkkauto.com

COMFORTDELGRO ENGINEERING PTE LTD

Date: 15.02.2019

REPAIR ESTIMATE

China Taiping (P/P)
LKK-

Time: 15:54:18

Page: 2

12 IS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305269089
REGN NO : SHC7169R
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 25.08.2016
DATE/TIME IN : 15.02.2019 12:40
ACCIDENT DATE : 15.02.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

SUB-TOTAL : 850.00

TOTAL : 2,053.62

Limf

MVA NAME & SIGNATURE
DATE :


AUTHORISED : YES / NO

SURVEYOR NAME & SIGNATURE
DATE :

Team: ARC Repair TP(CFSO)1	JOB CARD	Sales Order:	JC NO.: 305269089
OMER	REGN NO.: SHC7169R	MILEAGE	
IS: CITYCAB PTE LTD	MAKE: HYUNDAI	FUEL	
OMER NO. 7010070	MODEL: I-40	E.....1/2.....F	
LESS 383 SIN MING DRIVE	YR OF MANU. 25.08.2016	DATE/TIME IN 15.02.2019 12:40	
Singapore SINGAPORE 575717	CHASSIS CODE: KMHLB41UMGU093566	TARGET DATE	
65551188 (P) (O)	COMPLETION DATE/TIME:		
DUNT CARD NO			

JOB DESCRIPTION

Accident Date: 15.02.2019
NATURE: 3P 15.02.19

S/NO	LABOR CODE	DESCRIPTION
		

BOOKED & PASSED OUT BY: _____		CUSTOMER'S SIGNATURE _____	
SERVICE ADVISOR _____			
Acknowledgement Slip		Exit Pass	
No.: SHC7169R	LIMITS	Vehicle No.: SHC7169R	
Service Advisor _____	Signature/Date _____	Name of Service Advisor _____	Date _____
Returned to Service Reception upon collection		To be kept by Security Guard	

Poh Kin (LKKAUTO)

From: William Tan Thoo Seng <williamtan@cdge.com.sg>
Sent: Thursday, 18 April 2019 12:04 PM
To: Poh Kin (LKKAUTO)
Cc: Admin A
Subject: Re: RTA involving vehicle nos. GBH 9776U, SHC 7169R and other on 15.02.2019

Without Prejudice.

Dear Poh Kin

We are glad to accept your global offer.

Kindly forward your D.V. .

Thank you.

Best Regards
William Tan
Claims Department | ComfortDelgro Engineering Pte Ltd
Off : 62148737 | Fax : 62141843

From: Poh Kin (LKKAUTO) <pohkin@lkkauto.com>
Sent: Thursday, 18 April 2019 11:32:41 AM
To: William Tan Thoo Seng
Cc: Admin A
Subject: RTA involving vehicle nos. GBH 9776U, SHC 7169R and other on 15.02.2019

'WITHOUT PREJUDICE' SAVE AS TO COSTS

Our Ref: CC3/CTI19003222/T1fb3
Your Ref: CC9020431/ SHC7169R/WT(st)

Dear William,

We refer to above matter.

Towards an amicable settlement and without admission of liability to our Insured's part, we offer settlement at global sum of **\$1,990.00**(all in) on this matter.

kindly confirm acceptance.

Your prompt reply will be very much appreciated.

Poh Kin (LKKAUTO)

From: Poh Kin (LKKAUTO)
Sent: Thursday, 18 April 2019 11:33 AM
To: William Tan Thoo Seng
Cc: Admin A
Subject: RTA involving vehicle nos. GBH 9776U, SHC 7169R and other on 15.02.2019

Importance: High

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Our Ref: CC3/CTI19003222/T1fb3
Your Ref: CC9020431/ SHC7169R/WT(st)

Dear William,

We refer to above matter.

Towards an amicable settlement and without admission of liability to our Insured's part, we offer settlement at global sum of **\$1,990.00**(all in) on this matter.

kindly confirm acceptance.

Your prompt reply will be very much appreciated.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI19003222/T1fb3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 27-05-2019



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBH 9776U	Veh. Inspected	SHC 7169R
Policy No.	DMCVSN1835081800	Coverage (\$)	0.00
Claim No.	SNM19D200820	Excess (\$)	0.00
Assign From		Assign Date	15/02/2019

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KMHLB41UMGU093566	Colour	YELLOW
Odometer	250452	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	HANKOOK	6 mm
L/H Front Tyre	205/60 R16	HANKOOK	6 mm
R/H Rear Tyre	205/60 R16	HANKOOK	6 mm
L/H Rear Tyre	205/60 R16	HANKOOK	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	15/02/2019	Inspection Date	15/02/2019
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 7169R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	553.00	553.00
1	REAR BUMPER UNDER COVER	DEFORMED	228.00	228.00
1	REAR BUMPER SPONGE	NOT NECESSARY	103.50	-
1	REAR BUMPER BEAM	NOT NECESSARY	428.40	-
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
	LESS 20% DISCOUNT		-266.98	-160.60
			1,067.92	642.40
<u>SPECIAL NETT ITEMS</u>				
1	REVERSE SENSOR (SN)	NOT NECESSARY	135.70	-
2	REAR FENDER ADV STICKER RH/LH (SN)	NECESSARY	200.00	200.00
1	REAR BUMPER ADV STICKER (SN)	NECESSARY	50.00	50.00
			385.70	250.00
<u>LABOUR</u>				
	PANEL BEATING.		240.00	200.00
	SPRAYPAINT CHARGE.		240.00	200.00
	R/I REVERSE SENSOR.		120.00	30.00
			600.00	430.00
GRAND TOTAL			2,053.62	1,322.40
RECOMMENDED COST OF REPAIRS				1,322.40

Report Ref No. CC3/CTI19003222/T1fb3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.