



TRANS EUROKARS PTE LTD



FINALISED COST OF REPAIRS

FWD SINGAPORE PTE LTD		NAME : Ms Ho Wei Har	WIP : 43510
6 TEMASEK BOULEVAED		ADDRESS : Blk 564 Ang Mo Kio Ave 3	EXCESS : \$ 500.00
#18-01 SUNTEC TOWER 4		#06-3469	DATE: 19-Feb-19
SINGAPORE 038986		Singapore 560564	
ATTN. :	MOTOR CLAIMS	TEL : 93226008	
FAX :			

VEH NO :	SLA3388P	DATE IN :		CONTACT PERSON :	Jess 63957874
CHASSIS NO :	JM6BM42A8G0328325	MILEAGE :		TYPE OF CLAIM :	OWN DAMAGED CLAIM
MODEL :	MAZDA3	DATE REG.:	18-Jan-16	POLICY NO. :	

NATURE OF WORKS

Parts Description

NO		QTY		REVISED	PRICES
1	FRONT BUMPER	1	MBHR3-50-031BBB	\$ 1,031.70	\$ 1,031.70
2	RETAINER RHS	1	MBHN1-50-0T1F	\$ 18.70	\$ 18.70
3	BRACKET RHS	1	MBHN1-50-152		\$ 15.10
4	FRONT REINFORCEMENT	1	MB45A-50-070A		\$ 444.50
5	CHROME RHS, FOGLAMP	1	MBJE1-50-C12		\$ 106.70
6	COVER RHS, FOGLAMP	1	MBJE1-50-C11A	\$ 46.40	\$ 46.40
7	STIFF'A', FRONT BUMPER	1	MBHN1-50-0S0B		\$ 83.70
8	CLIP, FRONT BUMPER	12	MC274-50-133	\$ 42.00	\$ 42.00
9	FASTENER, FRONT BUMPER	2	MB45A-56-146A	\$ 5.60	\$ 5.60
10	GROMMET, FRONT BUMPER	2	MGHP9-50-0Z5	\$ 5.40	\$ 5.40
11	RIVET, FRONT BUMPER	4	MTK21-50-355	\$ 34.80	\$ 34.80
12	RIVET, FRONT BUMPER	6	MS51S-51-833	\$ 22.80	\$ 22.80
13	CHROME RHS	1	MBHN1-50-7J1A		\$ 176.70
14	FRONT GRILLE	1	MBJE1-50-712B		\$ 581.60
15	BRACKET RHS, FRONT GRILLE	1	MBHN1-50-153		\$ 15.10
16	PIN LOCATOR, FRONT GRILLE	2	MKD45-50-1K5A		\$ 5.40
17	GROMMET, FRONT GRILLE	2	MKD45-50-ES1	\$ 5.40	\$ 5.40
18	RIVET, FRONT GRILLE	2	MEA01-50-037	\$ 15.20	\$ 15.20
19	PLATE SET, FRONT REINFORCEMENT	1	MBHN3-50-1C0		\$ 92.70
20	FASTENER, PLATE SET	4	MGD7A-50-EA1		\$ 12.00
21	PLATE SEAL RHS	1	MBHN1-50-1U1A		\$ 35.60
22	FASTENER, PLATE SEAL	4	MKD45-50-EA1		\$ 10.00
23	HEADLAMP RHS	1	MBHT6-51-031A	\$ 2,245.00	\$ 2,245.00
24	HID CONTROL UNIT	1	MBHN3-51-0H3		\$ 895.50
25	GASKET, CONTROL UNIT	1	MC236-51-0B2		\$ 13.60
26	CLIP, HEADLAMP	2	MFB01-50-133C		\$ 7.60
27	RIVET, HEADLAMP	1	MB092-51-833	\$ 3.30	\$ 3.30
28	LAMP RHS, SIDE TURN	1	MB45A-51-350A		\$ 157.30
29	FOGLAMP RHS	1	MTK21-51-680A		\$ 351.40
30	BRACKET RGS, FOGLAMP	1	MBHR1-51-684A		\$ 17.30
31	WASHER TANK	1	MGHP9-67-481		\$ 104.00

32	COVER RHS, HEADLAMP WASHER	1	MBHT4-51-8G1 27	\$ 75.40	\$ 75.40	
33	CLAMP, ACUTATOR	1	MTK33-51-829	\$ 16.40	\$ 16.40	
34	ACTUATOR RHS, HEADLAMP WASHER	1	MBHT4-51-82X	\$ 242.40	\$ 242.40	
35	FRONT FENDER RHS	1	MB45A-52-111B		\$ 333.90	
36	STAY RHS, FENDER	1	MB4YA-52-10Y		\$ 39.90	
37	MUDGUARD RHS	1	MB45A-56-130H		\$ 97.00	
38	FASTENER, MUDGUARD	15	MB45A-56-146A		\$ 42.00	
				TOTAL PARTS	\$ 3,810.50	\$ 7,449.10
				LESS 10%	\$ 381.05	\$ 744.91
				TOTAL PARTS COST	\$ 3,429.45	\$ 6,704.19

Labour Description

1		TO REPLACE FRONT BUMPER. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	\$ 660.00	\$ 1,260.00
2		TO RESPRAY FRONT BUMPER AND FRONT FENDER RH.	\$ 945.00	\$ 1,200.00
3	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.		\$ 250.00
4	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 150.00	\$ 250.00
5	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 180.00	\$ 350.00
6	MZ-BR-SUNDRI	SUNDRIES.	\$ 10.00	\$ 100.00

TOTAL LABOUR	\$ 1,945.00	\$ 3,410.00
TOTAL PARTS	\$ 3,429.45	\$ 6,704.19
TOTAL	\$ 5,374.45	\$ 10,114.19
LESS EXCESS	\$ 500.00	\$ -
TOTAL AFTER EXCESS	\$ 4,874.45	
GST 7%	\$ 341.21	\$ -
GRAND TOTAL	\$ 5,215.66	\$ -

REMARKS:

4 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)