

REP: es/FCI19003237/ugd3 ⁰²
 ASS. REF. NO. Marina
 SURVEYOR CWS
 FROM (PERSON) Meina Chia of FCI Date/Time 3:32pm @ 20/2/19
 Estimated Cost: Bill to:
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS
 To inspect Vehicle No. SGF1026E Insured: SHC0164A
 at Workshop m/s Tom Lim Motor Tel: 68585151
 of 51 Defunct Lane 10
 Policy No. Claim No. D19001191MP&H
 Sum Insured: Excess:
 Make of Veh: D.O.A. 18/2/19
 (Client's Record) 25/2/19
 CA / REV / REP. / REV 24 HRS (DS)
 Date/Time: 3:41pm @ 20/2/19 Person Contacted: Cayman Vehicle IN / OUT: (OUT)

Date/Time	Action/Instruction (✓) Estimate	Insp: 1 Defunct Lane 6
	SGF1026E - CCG/AIG/14014965/1193W2	DVA: 6/8/19
	SHC0164A - NS/INC/14002240/YCBC3	DVA: 4/2/19
<u>28/1/19 @ 12:01pm</u>	<u>Notified to Meina Chia by email.</u>	

REF: FCI

STATEMENT

Date: 05/12/19

1. Sampled Code

2. TP / WS / TP RES / OD RES / EVA / INV / MV

3. Reported Vehicle No

SGF 1026E

4. Work shop name

Tan Lim Motor

5.

1 Defunct June 6

Insured

Policy No

Claim No

Sum Insured

Excess

(Client's Record)

Make of Vehicle

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Est. or Market Value

14k.

DAC Accident Report

Consistent? : Yes or No

GM / PR Seen

Consistent? : Yes or No

Est. Repairs

4

days

Res.: Yes or No

Est. Sum

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date

Person Contacted

24rs hls

Date / Time

Action / Instruction

Loc 30-3-201 LTA10374 net 3626

26/2/19

confund L/S \$2000 with cayan
cred \$4288 + 60%

Vehicle No: SGF1026E 3 06

Type: M/Car / B/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make

Hyundai Matrix 1599

Colour

Blue

APC

Insured / Std / NI / NA

Sp Reading

326624

TT/Adler Insured / Std / NI / NA

Eng/No

C/No

KMHPN81CR64250440

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size

F:

R:

195/55-R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Silverstone

Front

6

mm

Rear

6

mm

R/Bal

R/Bal

L/Bal

6

mm

L/Bal

6

mm

D.O.A.

18/2/19

D.O.I

25/2/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 05 MAR 2019

MV: \$14K (EST) - LTA: \$10,374 = Net value: 3626

Date/Time, File Pass to?

☐

Preli. Report

05/3/19

☐

Final Report

Date/Time, File Return to?

Days Of Repair:

4

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

1. Site Insp. (\$)

1. Interview (\$)

1. Tech. Insp. (\$)

1. Weekend (\$)

Total

Add Fee:

☐

Site Insp. (\$)

☐

Interview (\$)

☐

Tech. Insp. (\$)

☐

Weekend (\$)

Report Format:

TP

Lump Sum / TP / TS

2800

150

50

50

61

311



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19001191MFSH

Date: 28 February 2019

Our Ref: CS/FC119003237/Uqd3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SGF 1026E .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 25/02/2019 at the premises of M/s TAN LIM MOTOR, and have the following to report:-

Workshop Estimate Amount	: S\$ 7,088.00 .
Revised Estimate Amount	: S\$ 3,558.72 .
"Check" Items Amount	: S\$ - .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:
The vehicle sustained damages
at the n/s body.



Yours faithfully

CHUA KANG SENG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	18-02-2019	Our Ref No. D19001191MFSH
Accident Date	18-02-2019	Claim Type. Third Party
Insured Vehicle	SHC0164A	Third Party Vehicle. SGF1026E
Survey Location	51 DEFU LANE 10	
Contact Person.	CAYMEN	
Contact No.	68585151/ 0	Fax No. 68580877
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TAN LIM MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MERINA CHIA SAN SAN	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 28 February 2019 12:01 PM
To: 'CWS Motor Claims'; assignments
Cc: 'Merina Chia San San'; SUR
Subject: RE: SURVEY ASSESSMENT - D19001191MFSH/1
Attachments: CSFC119003237Uqd3.pdf

Dear Merina,

Enclosed herewith preliminary advice of SGF 1026E.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 20 February 2019 5:34 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Merina Chia San San' <MerinaChia@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19001191MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 20 February 2019 3:32 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Merina Chia San San



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

Find out more



matrix

Price Range

Depreciation

> 10 year

Vehicle Type



Submit

Advanced Search

Home » Used Cars » Direct Owners » Hyundai Matrix 1.8A FL (COE till 04/2021)

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Vehicle Number Plates

BUY & SELL
Your AUSPICIOUS & UNIQUE Vehicle No.

Do you know? We are Singapore's **BIGGEST PLAYER** with the most vehicle plate numbers for sale!

[Click here to see all Auspicious Numbers!](#)

Hyundai Matrix 1.8A FL (COE till 04/2021)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

DIRECT OWNER

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price **\$18,000**

Depreciation \$8,300 /yr

Reg Date 28-Apr-2006
(2yrs 2mths 2days COE left)

Manufactured 2005

Mileage 181,000 km (14.1k /yr)

Transmission Auto

Engine Cap 1,795 cc

Road Tax \$1,264 /yr

Power 90.2 kW (120 bhp)
View specs of the Hyundai Matrix (2007-2009)

Curb Weight 1,295 kg

Features Airbags, CD Radio, Reverse Sensors Etc.

Accessories Alloy Rims, Overhead Rail.

Description In Good Working Condition With Fairly Low Mileage For Its Age. Selling Only Because I Am Moving Overseas. One Owner Car - 01 Transfer Was From My Wife To Me. Car Available Available From Around 6th March Onwards.

COE \$23,725

OMV \$12,668

ARF \$13,935

Dereg Value \$10,296 as of today (change)

No. of Owners 2

Type of Veh Hatchback

Category COE Car, Direct Owner Sale.

Availability Available

DIRECT OWNER

Add to Shortlist

Add to Compare

Add a Note

Posted on: 13-Feb-2019 | Last Updated on: 20-Feb-2019

Tags: Hyundai Matrix, hyundai matrix, 2006 Hyundai Matrix, 2006 hyundai matrix, Hyundai, Matrix, matrix, Used Hyundai

Upfront Payment

» more Financial info

Transfer Fee \$25

Down Payment \$5,400 (change)

Maximum 70% Loan

1st Instalment \$524



Seller Information

Contact Person(s) Kelvin Lee

Contact No. 94746211

Enquiry Contact Seller

ESSENTIAL TRANSACTION FORMS

- * Indemnity form
- * Sales agreement
- * Receipt
- * Hand-over form
- * Ownership Transfer



GET HELP WITH PAPERWORK



sgCarMart Connect handles your transaction paperwork - send us your completed Sales Agreement, and we'll help with **Car Loans, Insurance, Payments & Ownership Transfer**. FREE for all sgCarMart Advertised Vehicles.

Upload your Sales Agreement

Read our 8 Step Guide for Direct Buyers & Sellers

Useful Services



Afraid of lemons? Request to have this car evaluated professionally.

Vehicle Evaluation

Find out the market value for your car. Get a free Car Valuation.



DBS TREASURES PRIVATE CLIENT

Compare

RENEW
YOUR COE1.99%*P.A
ONLYMONEY8MAX
LEASING
MEMBER OF MONEYMAX FINANCIAL SERVICES LTD.

matrix

Price Range

Depreciation

> 10 year

Vehicle Type



Submit

Advanced
Search

Home » Used Cars » Car Search » Hyundai Matrix 1.6A FL (COE till 01/2021)

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Hyundai Matrix 1.6A FL (COE till 01/2021)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

CONSIGNMENT



Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price \$19,800

Depreciation \$10,350 /yr

Reg Date 24-Jan-2006
(1yr 10mths 29days COE left)

Manufactured 2005

Mileage 195,000 km (14.9k /yr)

Transmission Auto

Engine Cap 1,599 cc

Road Tax \$967 /yr

Power 76.0 kW (101 bhp)
View specs of the Hyundai Matrix (2007-2009)

Curb Weight 1,269 kg

Features Powerful And Responsive 4 Cylinders 16 Valves DOHC VVT Engine, Smooth 4 Speed Auto Transmission, Dual Airbags, Climatic Control Air Conditioning.

Accessories Leather Seats, Sport Rims, Multi Function Steering Wheel, Factory Fitted Audio System, Knockdown Seats.

Description Consignment Unit, Low Fuel Consumption And Low Maintenance. Call Now For Viewing And Test Drive!

COE \$28,317

OMV \$12,840

ARF \$14,124

Dereg Value \$10,830 as of today (change)

No. of Owners 1

Type of Veh Hatchback

Category COE Car, Consignment Car

Availability Available

CONSIGNMENT

Add to Shortlist

Add to Compare

Add a Note

Posted on: 14-Feb-2019 | Last Updated on: 22-Feb-2019

Tags: Hyundai Matrix, hyundai matrix, 2006 Hyundai Matrix, 2006 hyundai matrix, Hyundai, Matrix, matrix, Used Hyundai

Owner Consignment Car

This car is for sale by direct owner via a consignment agent. Consignment agents help to market, sell and handle all documentation on the car seller's behalf.

- » List of owner consignment cars
- » List of consignment agents



Location Map

Seller Information

Company

Car Search

- » dealer's pricelist
- » 53 vehs sold | 183 vehs available

Address

18 Sin Ming Lane #04-02
Search cars nearby this location

Location

Midview City

Office No

62620728

Contact Person(s)

Kelvin	97593539
Justin	91827511
Rachel	91126538
Lester	96192666

Engine Oil

FREE
ENGINE OIL
SERVICE PACKAGE
worth \$98Participating Brands:
YOKOHAMA
DUNLOP
PirelliDBS TREASURES
PRIVATE CLIENT

Compare

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 7696G

Vehicle Details

Vehicle No.: SGF1026E

Vehicle to be Exported: No

Intended Deregistration Date: 26 Feb 2019

Vehicle Make: HYUNDAI

Vehicle Model: MATRIX FL A

Primary Colour: Silver

Manufacturing Year: 2005

Engine No.: G4ED5273160

Chassis No.: KMHPN81CR6U250440

Maximum Power Output: 76.0 kW (101 bhp)

Open Market Value: \$12,264.00

Original Registration Date: 31 Mar 2006

First Registration Date: 31 Mar 2006

Transfer Count: 1

Actual ARF Paid: \$13,491.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 30 Mar 2021

COE Category: E - Open Category

COE Period(Years): 5

PQP Paid: \$24,771.00

COE Rebate Amount: \$10,374.00

Total Rebate Amount: \$10,374.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 25 Feb 2019

OK



Date of Accident : 18 February 2019

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Mr Lim Seng Sang

Date : 20 February 2019

Chassis No : KMHPN81CR6U250440

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	n/s front fender <i>30d/600</i>	\$ 337.00
02	1 pc	front fender protector <i>cu7</i>	\$ 21.80
03	1 pc	n/s front door <i>30d/600/gal</i>	\$ 897.30
04	1 pc	n/s front door protector <i>grom</i>	\$ 36.70
05	1 pc	n/s front door lock <i>in</i>	\$ 121.50
06	1 pc	front door weatherstrip <i>1ec</i>	\$ 85.60
07	1 pc	n/s front door window glass channel weatherstrip <i>11</i>	\$ 95.10
08	1 pc	n/s front door window frame sticker - rear <i>nei</i>	\$ 15.00
09	1 pc	n/s front door window frame sticker - front <i>nei</i>	\$ 15.00
10	1 pc	front door hinge top <i>2</i>	\$ 56.40
11	1 pc	front door hinge bottom <i>2</i>	\$ 56.40
12	1 pc	n/s rear door <i>20/200</i>	\$ 791.20
13	1 pc	n/s rear door window frame sticker front <i>nei</i>	\$ 15.00
14	1 pc	n/s rear door window frame sticker rear <i>nei</i>	\$ 15.00
15	1 pc	n/s rear door protector <i>grom</i>	\$ 31.00
16	1 pc	n/s rear door weatherstrip <i>nei</i>	\$ 75.30
17	1 pc	n/s front door outer weatherstrip moulding <i>11</i>	\$ 23.50
18	1 pc	n/s rear door outer weatherstrip moulding <i>11</i>	\$ 23.50
19	1 pc	n/s rear fender <i>2</i>	\$ 1,682.00
20	1 pc	rear bumper <i>2</i>	\$ 400.20
21	8 pc	rear bumper clips @ \$3.50 <i>11</i>	\$ 28.00
			\$ 4,822.50
		Less 20 %	\$ 964.50
			\$ 3,858.00
		<u>SPECIAL NETT ITEMS</u>	
22	1 pc	n/s rear wheel rim <i>2</i>	\$ 350.00
			\$ 350.00
		<u>LABOUR & MISC. CHARGES</u>	
01		To transfer of tyre, rim and on wheel balancing.	\$ 11 60.00
02		To check steering geometry and computer wheel alignment.	\$ 80.00
03		To rust-proofing of the affected areas.	\$ 80.00
04		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 11 80.00
05		To reinstall of rear bumper parking sensor.	\$ 11 80.00
06		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,000.00



陳林摩打私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

MS FCIL Insured's Veh No : SHC164A
Date of Accident : 18 February 2019

Mr Lim Seng Sang

Date : 20 February 2019

Estimate To Repair SGF1026E - Hyundai MATRIX FLA
Chassis No : KMHPN81CR6U250440

S/No	Quantity	Description	Amount
07		LABOUR & MISC. CHARGES	
		Putty and spray painting of the affected portion.	\$ 1,500.00
			\$ 2,880.00
		Total	\$ 7,088.00

1000

358.72
246.

LKK Auto Consultants hence notify the Repainter of the following:

- To resurvey before spray painting
- To disclose damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repainter:

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19003237/Uqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 05-03-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 164A	Veh. Inspected	SGF 1026E	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19001191MFSH	Excess (\$)	0.00	
Assign From	MERINA CHIA	Assign Date	20/02/2019	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI MATRIX (A)	c.c	1599	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	KMHPN81CR6U250440	Colour	BLUE	
Odometer	326624	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/55 R15	SILVERSTONE	6 mm	
L/H Front Tyre	195/55 R15	SILVERSTONE	6 mm	
R/H Rear Tyre	195/55 R15	SILVERSTONE	6 mm	
L/H Rear Tyre	195/55 R15	SILVERSTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/02/2019	Inspection Date	25/02/2019	
Survey held at	1 DEFU LANE 6			
Repairer	TAN LIM MOTOR PTE LTD			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGF 1026E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	N/S FRONT FENDER	BADLY DENTED	337.00	337.00
1	FRONT FENDER PROTECTOR	CUT	21.80	21.80
1	N/S FRONT DOOR	BADLY DENTED / BENT	897.30	897.30
1	N/S FRONT DOOR PROTECTOR	GRAZED	36.70	36.70
1	N/S FRONT DOOR LOCK	NOT NECESSARY	121.50	-
1	FRONT DOOR WEATHERSTRIP	NECESSARY	85.60	85.60
1	N/S FRONT DOOR WINDOW GLASS CHANNEL WEATHERSTRIP	NOT NECESSARY	95.10	-
1	N/S FRONT DOOR WINDOW FRAME STICKER-REAR	NECESSARY	15.00	15.00
1	N/S FRONT DOOR WINDOW FRAME STICKER-FRONT	NECESSARY	15.00	15.00
1	FRONT DOOR HINGE TOP	TO REPAIR SEE LABOUR	56.40	-
1	FRONT DOOR HINGE BOTTOM	TO REPAIR SEE LABOUR	56.40	-
1	N/S REAR DOOR	DENTED / BENT	791.20	791.20
1	N/S REAR DOOR WINDOW FRAME STICKER FRONT	NECESSARY	15.00	15.00
1	N/S REAR DOOR WINDOW FRAME STICKER REAR	NECESSARY	15.00	15.00
1	N/S REAR DOOR PROTECTOR	GRAZED	31.00	31.00
1	N/S REAR DOOR WEATHERSTRIP	NECESSARY	75.30	75.30
1	N/S FRONT DOOR OUTER WEATHERSTRIP MOULDING	NOT NECESSARY	23.50	-
1	N/S REAR DOOR OUTER WEATHERSTRIP MOULDING	NOT NECESSARY	23.50	-
1	N/S REAR FENDER	TO REPAIR SEE LABOUR	1,682.00	-
1	REAR BUMPER	TO REPAIR SEE LABOUR	400.20	-
8	REAR BUMPER CLIPS @\$3.50	NOT NECESSARY	28.00	-
	LESS 20% DISCOUNT		-964.50	-467.18
			3,858.00	1,868.72
SPECIAL NETT ITEMS				
1	N/S REAR WHEEL RIM (SN)	TO REPAIR SEE LABOUR	350.00	-
			350.00	-

Report Ref No. CS/FCI19003237/Uqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO TRANSFER OF TYRE,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	60.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		80.00	60.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		80.00	80.00
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMMINGS,GARNISH AND OTHER,TL ENABLE REPAIR.	NOT NECESSARY	80.00	-
	TO REINSTALL OF REAR BUMPER PARKING SENSOR.	NOT NECESSARY	80.00	-
	PANEL BEATING,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF FRONT DOOR HINGE TOP,FRONT DOOR HINGE BOTTOM,N/S REAR FENDER,REAR BUMPER AND N/S REAR WHEEL RIM.		1,000.00	550.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,500.00	1,000.00
			2,880.00	1,690.00
	GRAND TOTAL		7,088.00	3,558.72
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,800.00

Report Ref No. CS/FCI19003237/Uqd3n2

MARKET VALUE: \$14,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$10,374.00=NETT VALUE: \$3,626.00

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.