

W.S. REC. BY:

REF: CS/FCI19003240/Kqcbn2

Special Instructions

Surveyor

Kenneth

ASSIGNMENT (Office)

cus

From (Person)

Eileen Lee

of

FCI

Date/Time

3:23pm @ 20/2/19

Estimated Cost:

Bill to:

OD TP PWS/TP RES / OD RES / EVA / INV / MYTCS

To Inspect Vehicle No.

SHCS256K

Insured

SH 9128P

at Workshop m/s

Transcab

Tel.

6287 6666

of

No 2 Amk St - G3

Policy No.

Claim No.

D19001199MFSH

Sum Insured

Excess:

Make of Veh:

D.O.A.

14/2/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

'DS'

H.O.D. Endorsement

Date/Time

3:27pm @ 20/2/19

Person Contacted

Zhenwei

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate	
	<u>SHCS256K - NA/INC180226SS/24</u>	<u>DoA: 14/2/18</u>
	<u>SH 9128P - NS/INC18019178/Klvbn2</u>	<u>DoA: 21/10/18</u>
<u>21/02/19 @ 5:24pm</u>	<u>Revised to Eileen Lee by email.</u>	

ASS. REC. BY:

REF:

FC21

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC 5256K Yr Regn: 02, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry (Taxi) Prime Mover /

Truck / Trailer or

Make: Renault Latitude C.C. 1995

Colour: M. White / Red A/C: Insured / Std / NI / NA

Sp. Reading: 416223 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VFIABL15AUC 276875

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: M / S/Rlm / STD A/Rlm or

Tyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Giti

Front

R/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 14/2/19

Rear

R/Bal. 8 mm

L/Bal. 8 mm

D.O.I. 20/2/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Acc body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 File pass to

895.00 (Red 631798.85, 97%) Labour Only

no lump sum.

RECEIVED 25 FEB 2019

Date/Time, File Pass to?

1) 25/2/2019

Date/Time, File Return to?

2)

☐ : Prel. Report☐ : Final Report

Days Of Repair: 2

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Fixtures

Others

TOTAL

Report Format: TP

Lump Sum / I.B.I. (\$ 995)

350



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19001199MFSH

Date: 21 February 2019

Our Ref: CS/FCI19003240/Kqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 5256K .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 20/02/2019 at the premises of M/s TRANS-CAB, and have the following to report:-

Workshop Estimate Amount	: S\$ 32,793.85 .
Revised Estimate Amount	: S\$ 995.00 .
"Check" Items Amount	: S\$ - .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages at the n/s rear body.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	18-02-2019	Our Ref No. D19001199MFSH
Accident Date	14-02-2019	Claim Type. Third Party
Insured Vehicle	SH9128P	Third Party Vehicle. SHC5256K
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	KEK ZHEWEI	
Contact No.	62876666/ 0	Fax No. 62571330
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 21 February 2019 5:24 PM
To: 'CWS Motor Claims'; assignments
Cc: 'Eileen Lee'; SUR
Subject: RE: SURVEY ASSESSMENT - D19001199MFSH/1
Attachments: CSFCI19003240Kqd3.pdf

Dear Eileen,

Enclosed herewith preliminary advice of SHC 5256K.

Best Regards,

Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 20 February 2019 5:32 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Eileen Lee' <EileenLee@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19001199MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 20 February 2019 3:23 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Eileen Lee <EileenLee@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19001199MFSH/1

PARE/COE Rebate Enrolling

Enquire PARF/COE Rebate for Registered Vehicle

Message

The information contained herein is correct as at 15 Feb 2019

[illegible]

Trans-cab Auto Services Pte Ltd

AAD1902-104

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5256K*Not Authored**LD 8995.00**Direct settle*

Vehicle No.:

SHC 5256K

Chassis No.:

VF1ABL15AUC276875

Vehicle Make:

RENAULT

Vehicle Model:

LATITUDE

Date of Accident :

14.2.2019

Third Party Insurer :

FCIL

Date of Registration :

19/2/2014

PART**LIST**

1	DOOR PANEL REAR LH	\$	<i>11</i> 2,844.66
1	DOOR GUIDE REAR LH	\$	<i>12</i> 176.82
1	DOOR HINGE UPPER LH	\$	<i>11</i> 274.50
1	DOOR HINGE LOWER LH	\$	<i>11</i> 300.55
1	DOOR CHECK REAR LH	\$	<i>12</i> 203.06
1	DOOR LOCK REAR LH	\$	<i>11</i> 908.75
1	DOOR HANDLE OUTER REAR LH	\$	<i>12</i> 126.49
1	DOOR HANDLE CAP REAR LH	\$	<i>12</i> 35.52
1	DOOR HANDLE SEAL REAR LH	\$	<i>12</i> 7.89
1	DOOR HANDLE COVER REAR LH	\$	<i>12</i> 13.22
1	DOOR HANDLE MODULE REAR LH	\$	<i>12</i> 133.60
1	DOOR REGULATOR REAR LH	\$	<i>12</i> 1,135.10
1	DOOR REGULATOR MOTOR REAR LH	\$	<i>12</i> 893.75
1	DOOR REGULATOR NUT REAR LH	\$	<i>12</i> 12.43
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	<i>12</i> 6.31
1	DOOR FINISHER REAR LH	\$	<i>12</i> 423.10
1	DOOR MOULDING REAR LH	\$	<i>12</i> 176.82
1	DOOR MOULDING CLIP L70Y	\$	<i>12</i> 5.92
1	DOOR MOULDING SCREW L70Y	\$	<i>12</i> 6.91
1	DOOR CASING REAR LH	\$	<i>12</i> 1,509.06
1	DOOR WATER SHIELD REAR LH	\$	<i>12</i> 30.39
1	DOOR CASING CLIP	\$	<i>12</i> 12.63
1	DOOR CASING LIGHT L70Y	\$	<i>12</i> 48.74
1	DOOR FINISHER INNER REAR LH	\$	<i>12</i> 323.44
1	DOOR FINISHER BRACKET INNER REAR LH	\$	<i>11</i> 46.97
1	DOOR FINISHER BRACKET INNER REAR LH	\$	<i>11</i> 20.33
1	DOOR FINISHER BRACKET INNER REAR LH	\$	<i>11</i> 20.33
1	DOOR FINISHER BRACKET INNER REAR LH	\$	<i>11</i> 20.33
1	DOOR GRAB HANDLE REAR LH	\$	<i>12</i> 210.96

X

Trans-cab Auto Services Pte Ltd**AAD1902-104**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5256K

1	DOOR BLIND REAR LH	\$	741.80	}
1	DOOR WHEATHESTRIIP REAR LH	\$	410.66	
1	DOOR SEAL REAR LH	\$	162.02	
1	DOOR GLASS RUNNER SEAL REAR LH	\$	229.31	
1	DOOR WAIST SEAL OUTER REAR LH	\$	334.69	
1	DOOR WAIST SEAL INNER REAR LH	\$	115.64	
1	FENDER PANEL REAR LH	\$	3,299.13	
1	FENDER PANEL INNER TRIM REAR	\$	671.45	
1	WHEELARCH REAR LH	\$	543.47	
1	DOOR MIRROR ASSY LH	\$	1,483.40	
1	ROCKER PANEL INNER GARNISH LH	\$	466.51	
1	ROCKER PANEL INNER LH	\$	1,024.79	
1	ROCKER PANEL CENTER LH	\$	990.25	
1	FRONT DOOR PANEL LH	\$	2,844.66	
		\$	23,246.36	
		10% \$	2,324.64	
		\$	20,921.72	

Special Nett

1SET	FRAME FULL SUPPORT PANEL CLIP	\$	70.00	X
2	FRAME FULL SUPPORT PANEL NUT	\$	20.00	X
2	FRAME FULL SUPPORT PANEL STUD	\$	30.00	X
1SET	WHEELARCH CLIP FRT LH	\$	30.50	X
1	FRONT DOOR STICKER 'Trans-cab'	\$	80.00	605M
1	FRONT DOOR STICKER 'Chassis'	\$	50.00	155M
1	REAR DOOR STICKER '6555 3333'	\$	80.00	605M
1	DOOR CHECK BOLT	\$	22.69	}
1	DOOR GUIDE SCREW	\$	10.85	
1	DOOR HINGE BOLT	\$	10.85	
1	DOOR HINGE NUT RH	\$	14.60	
1	DOOR CHECK BOLT	\$	22.69	
1	DOOR CHECK NUT	\$	3.75	
1	DOOR LOCK SCREW L70Y	\$	6.12	
1	DOOR CATCH SCREW L70Y	\$	10.06	
		TOTAL \$	462.13	

TOTAL PARTS \$ 21,383.85

Trans-cab Auto Services Pte Ltd

AAD1902-104

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5256K

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,200.00	2001
Putty and spray painting of the affected portion.	\$	4,200.00	6601
To rust-proofing of the affected areas.	\$	nn 170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To Check Electrical Lighting Concerned.	\$	nn 170.00	X
To transfer of front fender fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of front door fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	nn 380.00	X

TOTAL \$ 11,410.00**Over All Total \$ 32,793.85****LUMP SUM (REPAIR DAY)****20 DAYS**

2 days

LKK Auto Consultants hence notify
the Repairer to confirm
• To resurvey before/after spray painting
• To resurvey before/after part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19003240/Kqd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 25-02-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 9128P	Veh. Inspected	SHC 5256K	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19001199MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	20/02/2019	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	VF1ABL15AUC276875	Colour	METALLIC WHITE / RED	
Odometer	416223	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	GITI	8 mm	
L/H Front Tyre	215/60 R16	GITI	8 mm	
R/H Rear Tyre	215/60 R16	GITI	8 mm	
L/H Rear Tyre	215/60 R16	GITI	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/02/2019	Inspection Date	20/02/2019	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5256K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	DOOR PANEL REAR LH	TO REPAIR SEE LABOUR	2,844.66	-
1	DOOR GUIDE REAR LH	SERVICEABLE	176.82	-
1	DOOR HINGE UPPER LH	TO REPAIR SEE LABOUR	274.50	-
1	DOOR HINGE LOWER LH	TO REPAIR SEE LABOUR	300.55	-
1	DOOR CHECK REAR LH	SERVICEABLE	203.06	-
1	DOOR LOCK REAR LH	TO REPAIR SEE LABOUR	908.75	-
1	DOOR HANDLE OUTER REAR LH	SERVICEABLE	126.49	-
1	DOOR HANDLE CAP REAR LH	SERVICEABLE	35.52	-
1	DOOR HANDLE SEAL REAR LH	SERVICEABLE	7.89	-
1	DOOR HANDLE COVER REAR LH	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE REAR LH	SERVICEABLE	133.60	-
1	DOOR REGULATOR REAR LH	SERVICEABLE	1,135.10	-
1	DOOR REGULATOR MOTOR REAR LH	SERVICEABLE	893.75	-
1	DOOR REGULATOR NUT REAR LH	SERVICEABLE	12.43	-
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	SERVICEABLE	6.31	-
1	DOOR FINISHER REAR LH	SERVICEABLE	423.10	-
1	DOOR MOULDING REAR LH	SERVICEABLE	176.82	-
1	DOOR MOULDING CLIP L70Y	NOT NECESSARY	5.92	-
1	DOOR MOULDING SCREW L70Y	NOT NECESSARY	6.91	-
1	DOOR CASING REAR LH	SERVICEABLE	1,509.06	-
1	DOOR WATER SHIELD REAR LH	SERVICEABLE	30.39	-
1	DOOR CASING CLIP	NOT NECESSARY	12.63	-
1	DOOR CASING LIGHT L70Y	SERVICEABLE	48.74	-
1	DOOR FINISHER INNER REAR LH	SERVICEABLE	323.44	-
1	DOOR FINISHER BRACKET INNER REAR LH	TO REPAIR SEE LABOUR	46.97	-
1	DOOR FINISHER BRACKET INNER REAR LH	TO REPAIR SEE LABOUR	20.33	-

Report Ref No. CS/FCI19003240/Kqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR FINISHER BRACKET INNER REAR LH	TO REPAIR SEE LABOUR	20.33	-
1	DOOR FINISHER BRACKET INNER REAR LH	TO REPAIR SEE LABOUR	20.33	-
1	DOOR GRAB HANDLE REAR LH	SERVICEABLE	210.96	-
1	DOOR BLIND REAR LH	SERVICEABLE	741.80	-
1	DOOR WEATHERSTRIP REAR LH	SERVICEABLE	410.66	-
1	DOOR SEAL REAR LH	SERVICEABLE	162.02	-
1	DOOR GLASS RUNNER SEAL REAR LH	SERVICEABLE	229.31	-
1	DOOR WAIST SEAL OUTER REAR LH	SERVICEABLE	334.69	-
1	DOOR WAIST SEAL INNER REAR LH	SERVICEABLE	115.64	-
1	FENDER PANEL REAR LH	TO REPAIR SEE LABOUR	3,299.13	-
1	FENDER PANEL INNER TRIM REAR	SERVICEABLE	671.45	-
1	WHEELARCH REAR LH	SERVICEABLE	543.47	-
1	DOOR MIRROR ASSY LH	SERVICEABLE	1,483.40	-
1	ROCKER PANEL INNER GARNISH LH	SERVICEABLE	466.51	-
1	ROCKER PANEL INNER LH	TO REPAIR SEE LABOUR	1,024.79	-
1	ROCKER PANEL CENTER LH	TO REPAIR SEE LABOUR	990.25	-
1	FRONT DOOR PANEL LH	TO REPAIR SEE LABOUR	2,844.66	-
	LESS 10% DISCOUNT		-2,324.64	-
			20,921.72	-
	SPECIAL NETT ITEMS			
1	SET FRAME FULL SUPPORT PANEL CLIP (SN)	NOT NECESSARY	70.00	-
2	FRAME FULL SUPPORT PANEL NUT (SN)	NOT NECESSARY	20.00	-
2	FRAME FULL SUPPORT PANEL STUD (SN)	NOT NECESSARY	30.00	-
1	SET WHEELARCH CLIP FRT LH (SN)	NOT NECESSARY	30.50	-
1	FRONT DOOR STICKER "TRANS-CAB" (SN)	NECESSARY	80.00	60.00
1	FRONT DOOR STICKER "CHASSIS" (SN)	NECESSARY	50.00	15.00
1	REAR DOOR STICKER "6555 3333" (SN)	NECESSARY	80.00	60.00
1	DOOR CHECK BOLT (SN)	NOT NECESSARY	22.69	-
1	DOOR GUIDE SCREW (SN)	NOT NECESSARY	10.85	-

Report Ref No. CS/FCI19003240/Kqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR HINGE BOLT (SN)	NOT NECESSARY	10.85	-
1	DOOR HINGE NUT RH (SN)	NOT NECESSARY	14.60	-
1	DOOR CHECK BOLT (SN)	NOT NECESSARY	22.69	-
1	DOOR CHECK NUT (SN)	NOT NECESSARY	3.75	-
1	DOOR LOCK SCREW L70Y (SN)	NOT NECESSARY	6.12	-
1	DOOR CATCH SCREW L70Y (SN)	NOT NECESSARY	10.06	-
			462.11	135.00
	LABOUR			
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION.REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF DOOR PANEL REAR LH,DOOR HINGE UPPER LH,DOOR HINGE LOWER LH,DOOR LOCK REAR LH,DOOR FINISHER BRACKET INNER REAR LH,FENDER PANEL REAR LH,ROCKER PANEL INNER LH,ROCKER PANEL CENTER LH AND FRONT DOOR PANEL LH.		4,200.00	200.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		4,200.00	660.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF FRONT BUMPER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.	NOT NECESSARY	170.00	-
	TO TRANSFER OF FRONT FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF FRONT DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-

Report Ref No. CS/FCI19003240/Kqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER OF REAR DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
			11,410.00	860.00
GRAND TOTAL			32,793.83	995.00
RECOMMENDED COST OF REPAIRS				995.00

Report Ref No. CS/FCI19003240/Kqd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.