

PRELIMINARY ADVICE		Date/Time:	Send By:	Program:	Post-Repair Photos:	Others:
FINALIZATION		Date/Time:	Confirm with:	Confirm by:		
Repair Cost:	PIP	SS 8,124.90	(5 days) Reduction:	%	Email	Call
FINAL SETTLEMENT		Date/Time:	Confirm with:	Email	Call	
Final Liability:	%	100 (Agreed)	Assessed	BOLA S/N No.:	28 (3cc, 0.001)	NO or B 28, Ass. Lia:
Repair Cost:	(w/loss)	SS 8,693.64				(3VEH (C.C. 0.010 2ND VEH)
Loss of Rental (LOR):	(w/loss)	SS 299.60	(4 days) X \$70			
Loss of Use (LOU):	SS	-	(S - x - days)			
Loss of Income (LOI):	SS	-	(S - x - days)			
LOR only <input checked="" type="checkbox"/>	LOU only <input type="checkbox"/>	LOR + LOU <input type="checkbox"/>	LOR + LO <input type="checkbox"/>	[Tick only one]		
GI/ALTA Search:	SS	-				
Medical:	SS	-				1) Claim status: Normal/Reject/Private Settle
Disbursement:	SS	-	(e.g. Tow/ Independent)			2) Report Format: TP
Legal Cost:	SS	-				3) Survey fee: \$320
Total:	SS	8,993.24	Global Sum SS:			
FINAL PAYMENT		Date/Time:	Confirm with:	Email	Call	
Payee 1:	SS	8,693.64	Name 1:	PERFORMANCE MOTOR LIMITED		
Payee 2: (Strike if N.A.)	SS	299.60	Name 2:	OW TONG MUI		
Payee 3: (Strike if N.A.)	SS		Name 3:			

10

2016. July

SE 678B

Type: Q / W / S / D / M / L / T / A / N / B

Truck / Trailer or _____

Make: Hwy 216D Year: 1996

Color: White Body: Insured / Std / HI / HA

Eqs Description: 99667 Liability: Insured / Std / HI / HA

Engine: _____

CID#: WB A2B32000 V 260061

Fuel: Good / Poor / Full / Empty

Steering: Good / Jammed / Locked / Burnt or _____

Brakes: Good / Jammed / Locked / Burnt or _____

Mod: Nil / STD / STD Affin or _____

Type Size: 205/60R16

R: _____

A diagram of a roof truss structure. It consists of a horizontal base with a vertical line passing through its center, labeled with a large 'X'. Two diagonal lines extend from the top of the vertical line to the left and right edges of the base, forming a triangular shape. The left side of the triangle is labeled 'M5' and the right side is labeled 'D5'.

DS / DUN / EXNOVA / GY / FS / LZA / MC / OHTSO / PR / SAM /
 TOYO / YOKO or *Casimiro*
 Front *C* Rear *C*
 P/Bal. *6* mm P/Bal. *6* mm
 L/Bal. *6* mm L/Bal. *6* mm
 D.O.A. D.O.A.
pm L. *4/5/19.*
 Summary field at
 Desc. of Damages: Frt / *(Rear)* / O/B / H/S / MC / Roadtop or

Metodo IPI / CRII
Joseph

The IAC / Chassis frame / Body Structure affected due to collision.

PIP ~~\$ 811~~ 8124.90 Cred \$ 2750-30/ 250

January 1992

Add Fees:	<input type="text"/>	Auto Insp. (%)
	<input type="text"/>	Impost/gov. (%)
	<input type="text"/>	Tax on bus. (%)
	<input type="text"/>	Other Income (%)

Environ Monit Assess (2015) 189:1–13

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No. M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 439185
Tel. 63190888 (AfterSales)
Fax. 63449773

311, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/538 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

20 FEB 2019

Estimate No. : b1 50183
Date Estimated : 19/02/2019
Prepared By : Joseph Yaguel

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Ow Tong Mui
262D Compassvale Street
#06-151

SINGAPORE 544262

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLE6075B	V260061	28/07/2016	216d CAT	0

DESCRIPTION

Replacing rear bumper panel and attachments, tailgate,
etc to knock out dents caused by the accident

Spray rear bumper and tailgate

To remove and install boot compartment carpet and garnish
to facilitate repairs.

To replace rear windscreen glass.

To conduct water leak tests.

To supply and install front or rear windscreen solar film.

To check electrical wiring systems and lightings at the
rear section for proper function.

To carry out body cavity preservation.
(Per panel).

Sundries

To supply rear emboss number plate.

VALUE

1700 ~~1770~~ 2,550.00

1730 1,923.00

un X 130? 271.00

487 574.00

63 75.00

un X 451 531.00

150-177.00

600 118.00

un X 800? 150.00

67 un X 83.00

Total Labour 1: 6,452.00

DESCRIPTION

QTY PRIC

VALUE

TRUNK LID 1 1,204.35
REAR BUMPER PANEL PRIMED (PDC) 1 1,029.50
RR BUMPER LH SIDE GUIDE 1 49.05
RR BUMPER RH SIDE GUIDE 1 49.05
REAR BUMPER CARRIER 1 458.10
REAR WINDOW ESG 1 654.35
TRUNK LID SEALING 1 97.85
DECOUPING RING PDC TORQUE CONVERTER 4 5.05

67 1,204.35

de 1,029.50

? 49.05

? 49.05

? 458.10

? 654.35

143 97.85

un 20.20



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 436180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 50183
Date Estimated : 19/02/2019
Prepared By : Joseph Yaguel

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLE6075B	V260061	28/07/2016	216d CAT	0

DESCRIPTION	QTY	PRIC	VALUE
(DG) CLEANER R1 (100ML)	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	2	131.55	263.10
(DG/SL) GLASS PRIMER 30ML (VP206)	1	27.85	27.85
Total Parts :			3,879.55

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before repair.
- To display damaged parts.
- Parts prices are subject to contract.
- Third party survey for "Without Prejudice" basis.
- No illegal modification(s) is allowed.
- Supplemental work is subject to approval.

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____
Date&Time: 11/3/19 11:45 Excess S\$ _____
Surveyor's Name: Tanjun Sign: [Signature]
Surveyor's Tel: 97495264 Authorised Yes / No _____
Authorised Date _____ Time _____
RESURVEY PARTS PHOTO BY SURVEYOR (Yes/No) PM: Yes / No _____
Surveyor's E-mail: tanjun@lkk.com.sg
No. of Working Days Recommend: 5 days



Labour 1	:	6,452.00
Parts	:	3,879.55
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	723.21
Grand Total	:	11,054.76

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401599W, GST Reg. No. M2-0020081-J



SUPPLEMENTARY

Estimate No. : b1 50183
Date Estimated : 19/02/2019
Prepared By : Joseph Yaguel

Page No. :

REPAIR FOR -
Ow Tong Mui
262D Compassvale Street
#06-151

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

SINGAPORE 544262

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLE6075B	V260061	28/07/2016	216d CAT	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
# To supply rear emboss number plate *	83.00		83.00 ✓
# To transfer lock mechanism from old to new trunk lid include conducting checks on new trunk lid central locking system for proper function	451.00	✓	451.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET NUT M6 *	2.55	3.00	✓	7.65 ✓
# EXPANDING NUT *	1.00	2.00	✓	2.00 ✓

Total Labour : 534.00
Total Parts : 9.65
Total Labour & Parts : 543.65

10875.20

Performance Motors Limited

A member of the Ginec Derby Group
Co. Reg. No. 197401539W, GST Reg. No. M2-0020081-R



FINAL REPORT

Estimate No. : b1 50183
Date Estimated : 19/02/2019
Prepared By : Joseph Yaguel

Page No. :

REPAIR FOR -
Ow Tong Mui
262D Compassvale Street
#06-151

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

SINGAPORE 544262

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLE6075B	V260061	28/07/2016	216d CAT	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
* To replace rear bumper and attachments, trunk lid and attachments include knocking out dents caused by the accident	1700.00		1,700.00 ✓
To spray paint rear bumper and trunk lid	1730.00		1,730.00 ✓
* To remove and install rear windscreen glass to facilitate repairs	574.00		574.00 ✓
* To conduct water leak tests	75.00		75.00 ✓
To check electrical wiring systems and lightings at the rear section for proper function	150.00		150.00 ✓
To carry out body cavity preservation (Per panel)	100.00		100.00 ✓
# To supply rear emboss number plate *	83.00	(M)	83.00 ✓ <i>change</i>
# To transfer lock mechanism from old to new trunk lid include conducting checks on new trunk lid central locking system for proper function	451.00	(M)	451.00 ✓
Sundries	80.00		80.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET NUT M6 *	2.55	3.00		7.65 (M) ✓
TRUNK LID	1,204.35	1.00		1,204.35 ✓
REAR BUMPER PANEL PRIMED (PDC)	1,029.50	1.00		1,029.50 ✓
# EXPANDING NUT *	1.00	2.00		2.00 (M) ✓
REAR BUMPER CARRIER	458.10	1.00		458.10 ✓
TRUNK LID SEALING	143.00	1.00		143.00 ✓
DECOUPING RING PDC TORQUE CONVERTER	5.05	4.00		20.20 ✓
(DG) CLEANER R1 (100ML)	26.15	1.00		26.15 ✓
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	131.55	2.00		263.10 ✓
(DG/SL) GLASS PRIMER 30ML (VP206)	27.85	1.00		27.85 ✓

Performance Motors Limited

A member of the Smeets Group
Co. Reg. No. 157401559W. GST Reg. No. M3-0029081-X



FINAL REPORT

SUPPLEMENTARY ITEMS

Total Labour :	4,943.00
Total Parts :	3,181.90
Total Labour & Parts :	8,124.90
Deduction for Excess :	0.00
Total Repair Costs less Excess:	8,124.90
GST @7%:	568.74
Grand Total :	8,693.64

Hsiao Tong (LKKAUTO)

From: PBSP <pml-pbsp@sime-darby.com.sg>
Sent: Monday, 22 April 2019 6:12 PM
To: Taufikh (LKKAUTO); Hsiao Tong (LKKAUTO)
Subject: FINAL REPORT/ SLE6075B
Attachments: Final Report SLE6075B.pdf; Final Report SLE6075B_2.pdf

Dear Sirs

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 4,943.00

Total Parts : 3,181.90

Total Labour & Parts : 8,124.90

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

Hsiao Tong (LKKAUTO)

From: Hsiao Tong (LKKAUTO)
Sent: Saturday, 2 March 2019 9:24 AM
To: 'PBSP'
Cc: Admin A; CS A Team
Subject: RE: REQUEST FOR DIRECT SETTLEMENT - SLE6075B & SLK5619H ON 18/02/2019
***LKK REF:CC3/AIG19003244/pb3

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

Please note that all finalisation subject insurer's approval.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Thursday, 28 February 2019 9:30 AM
To: Shu Pei (LKKAUTO) <shupe@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Subject: Re: REQUEST FOR DIRECT SETTLEMENT - SLE6075B & SLK5619H ON 18/02/2019
***LKK REF:CC3/AIG19003244/eb3

Dear Sirs,

Kindly reply on liability.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: PBSP
Sent: Monday, 25 February 2019 11:01:50 AM
To: Shu Pei (LKKAuto)
Cc: 甯琨 ☺; CS A Team
Subject: Re: REQUEST FOR DIRECT SETTLEMENT - SLE6075B & SLK5619H ON 18/02/2019
***LKK REF:CC3/AIG19003244/eb3

Dear Shu Pei,

Kindly reply on liability.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: Shu Pei (LKKAuto) <shupe@lkkauto.com>
Sent: Wednesday, 20 February 2019 6:12:39 PM
To: PBSP
Cc: 甯琨 ☺; CS A Team
Subject: RE: REQUEST FOR DIRECT SETTLEMENT - SLE6075B & SLK5619H ON 18/02/2019
***LKK REF:CC3/AIG19003244/eb3

Dear Caroline,

We refer to the below email.

Please be informed that we are currently pending for our insured's report.

Kindly note that for liability, claim negotiation and settlement, please contact Asher at 6841 6051.

Our respective case handler will look into the matter and revert to you in due course.

Thank you

To check availability of the case handler , you may contact the undersigned.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP <pml-pbsp@sime-darby.com.sg>

Sent: Wednesday, 20 February 2019 5:32 PM

To: CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: REQUEST FOR DIRECT SETTLEMENT - SLE6075B & SLK5619H ON 18/02/2019

Dear Sirs,

We refer to the above matter.

We have instructions from our client to seek repair cost and loss of use/car rental from you through Direct Settlement.

Attached is the estimates and supporting documents for your consideration.

Please let us have your confirmation that you agree that liability is clear and we may proceed with Direct Settlement.

If Direct Settlement is approved, kindly let us have your offer for LOU / rental.

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Saturday, 2 March 2019 9:23 AM
To: 'Insurance LCR SG'; 'Eileen, May Hwee Yap'
Subject: ACCIDENT INVOLVING SLK 5619H(AIG) /SLE 6075B/ OTHERS ON 18/02/2019

Your Ref: **SLK 5619H**
Our Ref: CC3/LCR19003244/pb3

Dear Sirs/Madam,

ACCIDENT INVOLVING SLK 5619H(AIG) /SLE 6075B/ OTHERS ON 18/02/2019

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

We have received a claim from SLE 6075B against your insurance policy.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please call us if you have further queries.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong (LKKAUTO)

From: Hsiao Tong (LKKAUTO)
Sent: Tuesday, 23 April 2019 3:28 PM
To: PBSP
Cc: Taufikh (LKKAUTO)
Subject: RE: FINAL REPORT/ SLE6075B *LKK REF: CC3/LCR19003244/T1pb3
Attachments: Final Report SLE6075B.pdf

Without Prejudice

Dear Sirs/Mdm,

(Per panel)			
#	To supply rear emboss number plate *	(no damage)	
		83.00	83.00

According to surveyor, there was no damage to the rear number plate.

For COR, recommended amount at **P/P \$8,041.90(before GST)** with **5 repair days**.

Kindly confirm.

**** Kindly forward your LOD with all the relevant documents(ie: final repair bill, authorisation to act, rental receipt) to us (LKK) for our necessary action.**

Please note that all the finalisation subject to insurer approval.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP <pml-pbsp@sime-darby.com.sg>
Sent: Monday, 22 April 2019 6:12 PM
To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>
Subject: FINAL REPORT/ SLE6075B

Dear Sirs

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 4,943.00

Total Parts : 3,181.90

Total Labour & Parts : 8,124.90

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

Hsiao Tong (LKKAUTO)

From: Keith Leo Chi Yung <keith.leo.chiyung@simerdarby.com.sg>
Sent: Thursday, 16 May 2019 2:02 PM
To: Hsiao Tong (LKKAUTO); PBSP; Yaguel Renan Joseph Estoria
Cc: Taufikh (LKKAUTO)
Subject: RE: FINAL REPORT/ SLE6075B *LKK REF: CC3/LCR19003244/T1pb3
Attachments: RE: FINAL REPORT/ SLE6075B *LKK REF: CC3/LCR19003244/T1pb3

Dear Hsiao Tong

Taufikh approved the number plate replacement. Please refer to email attached.

Warm Regards

Keith Leo
Body & Paint
DDI: 6319 0172
FAX: 6479 4601



"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

From: Hsiao Tong (LKKAUTO) [mailto:chewht@lkkauto.com]
Sent: Thursday, 16 May, 2019 1:58 PM
To: PBSP <pml-pbsp@simerdarby.com.sg>; Yaguel Renan Joseph Estoria <yaguel.renan.joseph@simerdarby.com.sg>; Keith Leo Chi Yung <keith.leo.chiyung@simerdarby.com.sg>
Cc: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Subject: RE: FINAL REPORT/ SLE6075B *LKK REF: CC3/LCR19003244/T1pb3

Without Prejudice

Dear Sirs/Mdm,

Further to your below email.

Kindly advise.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement."

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP <pml-pbsp@simedarby.com.sg>

Sent: Tuesday, 23 April 2019 3:58 PM

To: Yaguel Renan Joseph Estoria <yaguel.renan.joseph@simedarby.com.sg>; Keith Leo Chi Yung <keith.leo.chiyung@simedarby.com.sg>

Cc: Taufikh (LKKAuto) <Taufikh@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: Re: FINAL REPORT/ SLE6075B *LKK REF: CC3/LCR19003244/T1pb3

Dear Keith and Joseph

Please advise ASAP about the number plate.

Thank you.

Regards,
Caroline

From: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Sent: Tuesday, 23 April 2019 3:27:51 PM

To: PBSP

Cc: Taufikh (LKKAuto)

Subject: RE: FINAL REPORT/ SLE6075B *LKK REF: CC3/LCR19003244/T1pb3

Without Prejudice

Dear Sirs/Mdm.

(Per panel)			
#	To supply rear emboss number plate *	(no damage)	
		83.00	83.00

According to surveyor, there was no damage to the rear number plate.

For COR, recommended amount at P/P \$8,041.90(before GST) with 5 repair days.

Kindly confirm.

** Kindly forward your LOD with all the relevant documents(ie: final repair bill, authorisation to act, rental receipt) to us (LKK) for our necessary action.

Please note that all the finalisation subject to insurer approval.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP <pml-pbsp@simedarby.com.sg>

Sent: Monday, 22 April 2019 6:12 PM

To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: FINAL REPORT/ SLE6075B

Dear Sirs

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 4,943.00

Total Parts : 3,181.90

Total Labour & Parts : 8,124.90

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby

disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

Hsiao Tong (LKKAUTO)

From: Yaguel Renan Joseph Estoria <yaguel.renan.joseph@simedarby.com.sg>
Sent: Thursday, 2 May 2019 12:00 PM
To: PBSP; Keith Leo Chi Yung
Cc: Cresendo Lurca Lagman
Subject: RE: FINAL REPORT/ SLE6075B *LKK REF: CC3/LCR19003244/T1pb3


Dear Keith,

Taufikh came today and I showed him the rear number plate photo.

Supplementary approved. Thanks

Best Regards,

Joseph Yaguel
Customer Service Adviser
Performance Motors Limited
Body & Paint Department
Mobile: 91165199
DID : 63190149
Fax : 64743229



<https://www.pml-bmw.com.sg/en/all-models/x-series/X5/2018/bmw-x5-at-a-glance.html>

From: Yaguel Renan Joseph Estoria
Sent: Tuesday, 30 April, 2019 2:58 PM
To: PBSP <pml-pbsp@simedarby.com.sg>; Keith Leo Chi Yung <keith.leo.chiyung@simedarby.com.sg>
Cc: Cresendo Lurca Lagman <cresendo.lagman@simedarby.com.sg>
Subject: RE: FINAL REPORT/ SLE6075B *LKK REF: CC3/LCR19003244/T1pb3

Dear All,

Called and message Taufikh, asking for supplementary.

Ill update you once he replies.

Best Regards,

Joseph Yaguel
Customer Service Adviser
Performance Motors Limited
Body & Paint Department
Mobile: 91165199
DID : 63190149
Fax : 64743229

2019 MEETS THE ALL-NEW BMW X5.

Find out more



<https://www.pml-bmw.com.sg/en/all-models/x-series/X5/2018/bmw-x5-at-a-glance.html>

From: PBSP

Sent: Tuesday, 30 April, 2019 11:17 AM

To: Keith Leo Chi Yung <keith.leo.chiyung@simedarby.com.sg>; Yaguel Renan Joseph Estoria <yaguel.renan.joseph@simedarby.com.sg>

Cc: Cresendo Llorca Lagman <cresendo.lagman@simedarby.com.sg>

Subject: Re: FINAL REPORT/ SLE6075B *LKK REF: CC3/LCR19003244/T1pb3

Dear All

Gentle reminder

Thank you.

Regards,
Caroline

From: Keith Leo Chi Yung

Sent: Tuesday, 23 April 2019 7:28:14 PM

To: Yaguel Renan Joseph Estoria

Cc: Cresendo Llorca Lagman; PBSP

Subject: RE: FINAL REPORT/ SLE6075B *LKK REF: CC3/LCR19003244/T1pb3

Dear Joseph

Please confirm before you go on leave

Warm Regards

Keith Leo
Body & Paint
DDI: 6319 0172
FAX: 6479 4601

DRIVE THE ALL-NEW BMW 3 SERIES.

Find out more



"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

From: PBSP

Sent: Tuesday, 23 April, 2019 4:25 PM

To: Keith Leo Chi Yung <keith.leo.chiyung@simedarby.com.sg>; Yaguel Renan Joseph Estoria <yaguel.renan.joseph@simedarby.com.sg>

Subject: Re: FINAL REPORT/ SLE6075B *LKK REF: CC3/LCR19003244/T1pb3

Dear All

As per surveyor's marking, surveyor disagreed with the replacement. Please see attached for your reference.

Please advise.

Thank you.

Regards,
Caroline

From: Keith Leo Chi Yung

Sent: Tuesday, 23 April 2019 4:16:36 PM

To: PBSP; Yaguel Renan Joseph Estoria

Subject: RE: FINAL REPORT/ SLE6075B *LKK REF: CC3/LCR19003244/T1pb3

Dear Joseph

Was the rear number plate damaged as a result of damage? Did surveyor approve?

Warm Regards

Keith Leo
Body & Paint
DDI: 6319 0172
FAX: 6479 4601



"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

From: PBSP

Sent: Tuesday, 23 April, 2019 3:58 PM

To: Yaguel Renan Joseph Estoria <yaguel.renan.joseph@simedarby.com.sg>; Keith Leo Chi Yung <keith.leo.chiyung@simedarby.com.sg>

Cc: Taufikh (LKKAuto) <Taufikh@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: Re: FINAL REPORT/ SLE6075B *LKK REF: CC3/LCR19003244/T1pb3

Dear Keith and Joseph

Please advise ASAP about the number plate.

Thank you.

Regards,
Caroline

From: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Sent: Tuesday, 23 April 2019 3:27:51 PM

To: PBSP

Cc: Taufikh (LKKAuto)

Subject: RE: FINAL REPORT/ SLE6075B *LKK REF: CC3/LCR19003244/T1pb3

Without Prejudice

Dear Sirs/Mdm,

(Per panel)			
#	To supply rear emboss number plate *	(no damage)	
		83.00	83.00

According to surveyor, there was no damage to the rear number plate.

For COR, recommended amount at P/P \$8,041.90(before GST) with 5 repair days.

Kindly confirm.

** Kindly forward your LOD with all the relevant documents(ie: final repair bill, authorisation to act, rental receipt) to us (LKK) for our necessary action.

Please note that all the finalisation subject to insurer approval.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP <pml-pbsp@simedarby.com.sg>

Sent: Monday, 22 April 2019 6:12 PM

To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: FINAL REPORT/ SLE6075B

Dear Sirs

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 4,943.00

Total Parts : 3,181.90

Total Labour & Parts : 8,124.90

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Tuesday, 20 August 2019 10:20 AM
To: Chew.Mavis@aig.com
Cc: Admin A
Subject: SEEK MANDATE AIG REF: TP / 2393986570SG [ACCIDENT INVOLVING SLK5619H (OI) & SLE6075B (TP) / OTHERS ON 18/02/2019]

Tracking:	Recipient	Delivery
	Chew.Mavis@aig.com	
	Admin A	
	Meikwan@lkkauto.com	Delivered: 20/8/2019 10:20 AM
	olivialau@lkkauto.com	Delivered: 20/8/2019 10:20 AM
	shupei@lkkauto.com	Delivered: 20/8/2019 10:20 AM

AIG Ref: TP / 2393986570SG
LKK Ref: CC3/LCR19003244/T1KB3Q2

Dear Sir/Madam,

ACCIDENT INVOLVING SLK5619H (OI) & SLE6075B (TP) /OTHERS ON 18/02/2019

We refer to the above matter.

This is a 3 vehicle chain collision, our Insured vehicle is second vehicle. We are of the opinion that BOLA 28 is applicable.

We seek your approval to offer to Third Party repairer, "**PERFORMANCE MOTORS LIMITED** " as follows: -

	Claimed Amount	Revised Amount
1. Cost of Repair (w/GST)	\$ 11,595.96	\$ 8,693.64
2. Loss of Rental (4 days x \$70.00)	\$ 299.60	\$ 299.60 (4 days x \$70)
Total	\$ 11,895.56	\$ 8,993.24

**5 days recommendation for repair

All the relevant documents had been uploaded in Merimen.

Kindly let us have your mandate in Merimen.

Best Regards,
Khanchna | Case Handler
LKK Auto Consultants Pte Ltd

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Tuesday, 20 August 2019 11:10 AM
To: PBSP; Hsiao Tong (LKKAuto)
Cc: Admin A
Subject: RE: LOD REMINDER - SLE6075B & SLK5619H ON 18/02/2019 *LKK REF:CC3/LCR19003244/T1kb3

Without Prejudice
(save as to costs)

Dear Sirs/Mdm,

We refer to the above matter.

We confirm settlement as follows: -

1. Cost of Repair (w/GST)	\$ 8,693.64
2. Loss of Rental (4 days x \$70.00)	\$ 299.60
Total	\$ 8,993.24

We will proceed to do the necessary accordingly and close file.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,
Khanchna | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841 2360 | email: Khanchna@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Sent: Friday, 19 July 2019 12:27:50 PM
To: PBSP <pml-pbsp@simedarby.com.sg>
Cc: Khanchna (LKK Auto) <khanchna@lkkauto.com>; 甯珺 @ <admin-a@lkkauto.com>
Subject: RE: LOD REMINDER - SLE6075B & SLK5619H ON 18/02/2019 *LKK REF:CC3/LCR19003244/T1kb3

Without Prejudice

Dear Sirs/Mdm,

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**AIG THIRD PARTY EXPRESS SETTLEMENT
FOR ACCIDENTS ON OR AFTER 1ST JUNE 2008
(PAYMENT BREAKDOWN)**

Vehicle No:	SLE6075B	Model:	
Date of Accident:	18.02.2019		

Global Sum Settlement:	<input type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	: \$	11,054.76
Final Repair Cost	: \$	8,693.64
Loss of Use	: \$	--
Rental (if any)	: \$	299.60
LTA / GIA Search Fee	: \$	--
Others	: \$	--
	: \$	--
Final Settlement Sum	: \$	8,993.24

days at \$ per day

4 days

Is Third Party Workshop GIA Registered? ☐ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Application: Yes / No
BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks

Payment Instruction: Payee's Breakdown			
1)	Performance Motor Limited	: \$	8,693.64
2)	Ow Tong Mui	: \$	299.60
3)		: \$	

Signed by appointed surveyor

Date

Please attach all the supporting documents to the form.

Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act;
Survey Report; Medical Report / Bill (if any)

EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
tel 65 6223 9433 | fax 65 6224 3903 | www.eqinsurance.com.sg
reg no. 1978-00490-N

**CERTIFICATE OF INSURANCE**

ROAD TRANSPORT ACT 1987 (MALAYSIA)

THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES 1959 (FEDERATION OF MALAYSIA)

THE MOTOR VEHICLES(THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP.189 OF THE REVISED EDITION)

(REPUBLIC OF SINGAPORE)

THE MOTOR VEHICLES(THIRD-PARTY RISKS AND COMPENSATION) RULES 1996 EDITION(REPUBLIC OF SINGAPORE)

OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF

PRIVATE CAR**Comprehensive Premier****Certificate No. : DMPPHQ18-004210****1. Index Mark and Registration Number of Vehicles**

SLE6075B

2. Name of Policyholder

OW TONG MUI

3. Effective Date of the Commencement of Insurance for the purpose of the Act

28/07/2018

4. Date of Expiry of Insurance

27/07/2019

5. Person or Classes of persons entitled to drive*

(a) The Policyholder

(b) Any other person who is driving on the Policyholder's order or with his permission.

Premier Plan - Any Workshop

Form: MX2


Excess:

Insured&Named Driver S\$500.00(Section 1 - Own Damage)

Unnamed Driver S\$1,000.00(Section 1 - Own Damage)

YEIDR Additional S\$3,000.00

WindScreen S\$100.00

EQ Insurance-MARS Motor
Accident Help Center**6311 3211**

* Provided that the person driving is permitted in accordance with the licensing or other laws or regulation to drive the Motor Vehicle or has been permitted and is not disqualified by order of Court of Law or by reason of any enactment enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act has not been cancelled at the time of accident loss or damage.

6. Limitation as to use*

Use for social, domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover:

(a) use for hire or reward

(b) use for racing, pace-making, reliability trials or speed testing

(c) use for the carriage of goods (other than samples) in connection with any trade or business

(d) use for any purpose in connection with the Motor Trade

*Limitations rendered inoperative by Section 8 of the Motor vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or and Amendment, Act or Acts passed in substitution thereof.

Hire Purchase :

A000038/Simply Cars Pte Ltd
Date of Issue : 20/06/2018 15:38Authorised Signatory
EQ Insurance Company Limited**Note**

Young, Elderly &/or Inexperience Driver (YEIDR) refers to any person authorized to drive who is below 26 years old or above 70 years old and/or the holder of a qualified driving licence of less than 2 years duration.

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S0164233B



Name

OW TONG MUI



欧宗美

Race

CHINESE

Date of Birth

13-05-1950

Sex

F

Country of Birth

SINGAPORE

S0164233B

0952207



NRIC No. S0164233B



Blood Group Date of issue

AB+

02-05-1993

APT BLK 262D COMPASSVALE STREET #06-151
SINGAPORE 544262

NRIC No: S0164233B

Date: 31-05-2000 No: 3756302

REPUBLIC OF SINGAPORE DRIVING LICENCE

Portrait photo of a man with glasses.

License Number: **S1713034Z**

Name: **QUAKE KHEOK SENG BERNARD**

Birth Date: **27 Jun 1965**

Issue Date: **03 Aug 2017**

Barcode: 002710079J

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S1713034Z

Portrait photo of a man.

Name: **QUAKE KHEOK SENG BERNARD**

Race: **CHINESE**

Date of birth: **27-06-1965**

Sex: **M**

Country of birth: **SINGAPORE**

Barcode: S1713034Z

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor cars with unladen weight \leq 3000kg with \leq 7 passengers, exclusive of driver; and other motor vehicles with unladen weight \leq 2500kg 04 Nov 1989

NP 428A



4167818

Barcode

NRIC No: **S1713034Z**

Fingerprint image

Date of issue: **30-01-2008**

Address: **APT BLK 262D COMPASSVALE STREET
#06-151
SINGAPORE 544262**

Print Received Message

This mail is associated with :

***SLE6075B (2393986570SG)
[SLK5619H]**

TP
OW TONG MUI
Feb 18 2019 7:00AM
[LCRF PTE LTD]
Performance Motors Limited

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 20/08/2019 10:42 AM,
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$8993.24) - SLE6075B - Claim Handler: Chew, Mavis

Approved:8993.24.

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Saturday, 2 March 2019 9:23 AM
To: 'Insurance LCR SG'; 'Eileen, May Hwee Yap'
Subject: ACCIDENT INVOLVING SLK 5619H(AIG) /SLE 6075B/ OTHERS ON 18/02/2019

Your Ref: **SLK 5619H**
Our Ref: CC3/LCR19003244/pb3

Dear Sirs/Madam,

ACCIDENT INVOLVING SLK 5619H(AIG) /SLE 6075B/ OTHERS ON 18/02/2019

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

We have received a claim from SLE 6075B against your insurance policy.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please call us if you have further queries.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)




AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, Ow Tong Mui ("the third party claimant")
of 262D Compassvale Street #06-151 S(544262) (address),
owner of SLE 6075B (vehicle no.) hereby authorize
Performance Motors Ltd
("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SLE 6075B that was
damaged pursuant to the accident which occurred on 18/2/19 (date) along
SLE / Woodlands (location)
involving vehicle no/s SLK 561914 ("the accident").


I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 20 day of AUGUST (month) 20 19 (year)



Signed by "the third party claimant"

PERFORMANCE MOTORS LIMITED
303 Woodlands Road
Singapore Post Centre
Singapore 738941
TEL: 6360100 (Sales)
6360111 (Admin)


Signed by "the workshop"



RELEASE VOUCHER
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

"We/I, Performance Motors Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte. Ltd. LKK Auto Consultants Pte Ltd ("name of surveyor") with respect to the amount claimed for S\$ 8,693.64 (repair costs), S\$ 294.60 (loss of use/rental) S\$ - (search fees) for vehicle no. SLE 6075B that was damaged pursuant to the accident which occurred on 18/12/19 (date) along SLE / Woodlands (location) involving vehicle no/s SLK 561914 ✓.

This is pursuant to the inspection conducted on 11/3/19 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Qin Tang Mui ("third party claimant") of vehicle no. SLE 6075B to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte. Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SLE 6075B (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 20 day of August (month) 20 19 (year)



MTU

Signed by AIG appointed surveyor

Chopped & Signed by "the workshop"

PERFORMANCE MOTORS LIMITED
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941
TEL: 63190100 (Sales)
63190111 (After sales)



103, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449771

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64786601 (AfterSales)
64786624 (Motorrad)

HT

SERVICE TAX INVOICE

Repair Order No. : B1 1343879

Date IN : 11/03/2019

Motor Claim Advisor: Joseph Yaguel

Page No. : 1 of 2

Invoice Number : 2102981 / WSB

Invoice Date : 24/05/2019

Payment Terms : 30 Days From Invoice

Invoice By : Toh Jing Xuan

- CUSTOMER INFORMATION -

Mdm Ow Tong Mui
262D Compassvale Street
#06-151

SINGAPORE 544262

- INVOICE TO - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLE6075B	V260061	28/07/2016	216D CAT	99669

- - - - LABOUR 1 - - - -

	NETT
To replace rear bumper and attachments, trunklid and attachments including knock out dented area caused by the accident.	1,700.00
To respray rear bumper and trunk lid.	1,730.00
To remove and install rear windscreen glass to facilitate repairs.	574.00
To conduct water leak tests.	75.00
To check electrical wiring systems and lightings at the rear section for proper function.	150.00
To carry out body cavity preservation.	100.00
To transfer lock mechanism from old to new trunk lid including conduct checks on new trunk lid central locking system for proper function.	451.00
Sundries.	80.00
INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.	0.00
DATE OF ACCIDENT : 18.02.2019. 3RD PARTY CAR : SLK5619H.	
YOUR REF NO : NIL.	
VEHICLE WAS SURVEYED BY MR TAUFIKH FROM LKK AUTO ON 11.03.2019 AT 11:45AM. AUTHORISED REPAIR BY MS CHEW HSIAO TONG FROM LKK AUTO ON 02.03.2019 VIA EMAIL.	
PROPOSE CAR RENTAL = \$299.60. THE AMOUNT IS SUBJECTED TO INSURANCE COMPANY CONFIRMATION.	0.00

Total Labour 1: **4,860.00**

- - - - PARTS - - - -

	Qty	Retail Price	NETT
REAR BUMPER PANEL PRIMED (PDC)	1	1,029.50	1,029.50
DECOUPING RING PDC TORQUE CONVERTER	4	5.05	20.20
(DG) CLEANER R1 (100ML)	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	2	131.55	263.10
(DG/SL) GLASS PRIMER 30ML (VP206)	1	27.85	27.85
TRUNK LID	1	1,204.35	1,204.35
TRUNK LID SEALING	1	143.00	143.00
REAR BUMPER CARRIER	1	458.10	458.10
EXPANDING NUT	2	1.00	2.00

103, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770290, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)**SERVICE TAX INVOICE**Repair Order No. : **B1 1343879**Date IN : **11/03/2019**Motor Claim Advisor: **Joseph Yaguel**Page No. : **2 of 2**Invoice Number : **2102981 / WSB**Invoice Date : **24/05/2019**Payment Terms : **30 Days From Invoice**Invoice By : **Toh Jing Xuan**

BLIND RIVET NUT M6

3 2.55 7.65

Total Parts : **3,181.90**

- - - - L A B O U R 2 - - - -

NETT

To supply rear silver emboss lettering black base number
plate with bracket.

83.00

Total Labour 2: **83.00**Labour Charges : **4,863.00**
Parts Charges : **3,181.90**
Lubricant/Misc : **80.00**Total Labour & Parts Charges : **S\$ 8,124.90**
Less Insurance Excess : **S\$ 0.00**
Invoice Total Amount Exclude GST : **S\$ 8,124.90**
GST @ 7% : **S\$ 568.74**
Invoice Total Amount Include GST : **S\$ 8,693.64**

Computer generated invoice. No signature is required.

Amount Payable Include GST : **S\$ 8,693.64**

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.



**SIME DARBY SERVICES PTE LTD**

Thrifty International Licensee

305 Alexandra Road, #03-01

Vantage Automotive Centre, Singapore 159942

p (65) 6447.3388 f (65) 6345.7247

Co. Reg. No. 197501065W GST Reg. No. M2-0021986-4

TO BE PAID BY

PAYMENT : MC - XXXXXXXXXXXX9628

HIRER'S DETAILS

TITLE : MR
 NAME : QUAKE KHEOK SENG BERNARD
 ADDRESS : BLK 262D COMPASSVALE STREET
 #06-151
 544262
 SINGAPORE

NRIC/PASSPORT NO. : S1713034Z ISSUE : 30/01/2008

ISSUED BY : SINGAPORE

LICENSE : S1713034Z EXPIRY : 12/12/2299

ISSUED BY : SINGAPORE

NATIONALITY : SINGAPOREAN D.O.B. : 27/08/1965

FREQUENT FLYER NO.

LOCAL CONTACT : 98158759

HOTEL**COMPANY'S DETAILS****NAME****ADDRESS****IMPORTANT NOTICE**

- Hirer is liable for all traffic fines including admin fees that are issued by Singapore or Malaysia authorities for a grace period of 12 months from the date of car return.
- A security deposit depending on the respective car group rented will be withheld on the Hirer's credit card.
- Any accident has to be reported within the next working day to Sime Darby Services Pte Ltd. In the event of failure to report, hirer shall be liable for any costs incurred by Sime Darby Services Pte Ltd or claims made by the other party.
- Smoking, durians and pets are not allowed in the vehicle. An additional 3 day's rental would be imposed if smoking and durian smell/pet's fur is detected upon car return.
- Hirer must inform Sime Darby Services Pte Ltd in advance for vehicle drop-off in Thrifty Malaysia renting location. A one-way rental fee and Malaysia surcharge are applicable as stated in our One Way Rental policy.
- Hirer is responsible for any missing items/car accessories or loss of keys will be charged accordingly.
- The excess do not cover i) Car accessories ii) Loss of key iii) Vandalism iv) Alcohol/intoxicants/drugs.
- Vehicles are prohibited to be driven into Thailand.
- Strictly no key-drop services allowed, security deposit will be forfeited.

The vehicle is rented subject to all terms and conditions on this page and on the reverse side whether printed or handwritten. Hirer represents that they have read, understand and agree with the conditions of the rental agreement. The hirer authorises all amounts due under the rental agreement to be charged to the hirer's credit card shown on this form.

x

Hirer

x

Additional Driver

ADDITIONAL DRIVERS:

RENTAL AGREEMENT NUMBER : 55005453
 RENTAL LOCATION : SHORT TERM-HQ (SIN55)-THRIFTY

CHECKOUT

UNIT # / REGN NO. : 00003031 / SL56978Y
 MAKE & MODEL : HYUNDAI Elantra 1.5
 CAR GROUP GIVEN : G CHARGE : F
 KILOMETER OUT : 36,746
 PETROL LEVEL OUT : FULL
 DATE & TIME OUT : 11/03/2019 09:00
 DUE DATE & TIME IN : 18/03/2019 09:00
 CHECKIN LOCATION : SHORT TERM-HQ (SIN55)-THRIFTY

RENTAL RATES

AS: INSURANCE CLAIMS RATES 2017

DAILY @ S\$ 70.00

EXTRA DAY @ S\$ 70.00

EXTRA HOUR @ S\$ 14.00

TOTAL: S\$ 299.60**FOR RATES TO APPLY**

MINIMUM 24 HOURS.
 CAR MUST BE RETURNED TO RENTING LOCATION
 ON THE DUE DATE

INSURANCE

BY INITIALS, THE HIRER
 INCLUSIVE LDW
 NON-WAIVERABLE DAMAGE EXCESS: S\$ 1,500.00 (SIN USE)

DECLINES PAI @ S\$ 5.00 PER DAY

DECLINES WSC @ S\$ 5.00 PER DAY

THIS CAR IS FOR SINGAPORE USE ONLY. THERE IS NO INSURANCE
 COVERAGE FOR USE OUTSIDE SINGAPORE

OTHER CHARGES

FUEL SERVICES @ S\$2.70 / LITRE

CASH & CHEQUE DEPOSIT**REMARKS**

BMW OWNER: SLE6075B
 \$100/DAY 1600CC
 PML CSA: JOSEPH

HI RESERVATION

RES. ID# : SD000005522
 Nur Ezham Omar

TACO#
 REF SRC: PHONE

Printed on : 10-Apr-2019 16:08
 Entered by: Nur Ezham Omar



TAX INVOICE

Invoice No. 55 - 513295

Page 1 of 1

MR QUAKE KHEOK SENG BERNARD

BLK 262D COMPASSVALE STREET #06-151
544262 SINGAPORE

SIME DARBY SERVICES PTE LTD

Thrifty International Licensee

305 Alexandra Road, #03-01
Vantage Automotive Centre, Singapore 159942
p (65) 6447.3388 f (65) 6345.7247
Co. Reg. No. 197501065W GST Reg. No. M2-0021986-4

INVOICE DATE : 15-MAR 2019

R.A. No. 55005453 / Nur Ezham Omar

TITLE	: MR	KILOMETER OUT/IN	: 36746 / 37315
AUTHORIZED DRIVER	: QUAKE KHEOK SENG BERNARD	KILOMETER DRIVEN	: 569
NRIC/PASSPORT NO.	: S17130342	PETROL LEVEL OUT/IN	: FULL / FULL
MAKE & MODEL	: HYUNDAI ELANTRA 1.6	DATE & TIME OUT	: 11-MAR 2019 09:00
CAR REGISTRATION NO.	: SL5697BY / UNIT #: 0003031	DATE & TIME IN	: 15-MAR 2019 16:50
CAR GROUP GIVEN	: G	CHECK IN LOCATION	: SHORT TERM-HQ (SIN55)-THRIFTY
CAR GROUP CHARGED	: F	NO. OF DAY(S) CHARGED	: 4 DAY(S) 8 HOUR(S)

DESCRIPTION	UNIT PRICE (SGD)	UNIT	AMOUNT BEFORE GST (SGD)	GST @ 7%	AMOUNT (SGD)
INSURANCE CLAIMS RATES 2017					
4 DAY(S) @ \$70.00 / DAY			280.00	19.60	299.60
5 HOUR(S) @ \$14.00 / HOUR			70.00	4.90	74.90
WAIVE DUE TO CUSTOMER'S CAR RETURN LATE			-70.00	-4.90	-74.90
SUB-TOTAL			280.00	19.60	299.60
REMARKS: BMW OWNER: SLE6075B \$100/DAY 1600CC PML CSA: JOSEPH		TOTAL (SGD) :	280.00	19.60	299.60
* ITEMS NOT SUBJECT TO GST					
		MC XXXXXXXXXXXX9628			-299.60
		BALANCE DUE			0.00

NOTE:

I / WE HEREBY AGREE TO THE TERMS AND CONDITIONS AND BE HELD LIABLE FOR ALL AMOUNT DUE UNDER THIS AGREEMENT: ALL TRAFFIC FINES INCLUDING ADMIN FEES INCURRED DURING PERIOD OF HIRE; ANY COSTS INCURRED BY SIME DARBY SERVICES PTE LTD FOR MY FAILURE TO REPORT ANY ACCIDENT WITHIN 24 HOURS. FINAL CHARGES IS SUBJECT TO FULL INSPECTION OF THE VEHICLE BY A COMPANY REPRESENTATIVE.

HIRER'S AND/OR ADDITIONAL DRIVER'S SIGNATURE

Printed on 10-Apr-2019

16:06

Entered by Joe Rahman



...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING





Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Feb 2019 Edit Reg		04 Mar 2019 00:00 Edit Adj Rpt	\$58,124.90 Edit Estimates	\$58,124.90 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: LCRF PTE LTD , Co. Reg. No.: 201624597K									
Main Claimant: OW TONG MUI , ID: 501642338									
Vehicle Reg. No.: SLE6075B		Date of Loss: 18/02/2019 07:00 - :59 [30 Months and 21 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 2393986570SG		Policy/Cover Note No.: 0999994809 (Comprehensive)							
Vehicle Reg. No. (Insured): SLK5619H		Policy No. (Claimant): DMPPHQ18-004210							
		Excess:							
Repairer: Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chew, Mavis] Chew.Mavis@aig.com									
Claimant's Insurer: EQ Insurance Company Ltd (HQ) - Tel: 6223 9433									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 01/03/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG_EXPRESS (20/08/2019): Alert - Adj Mandate Approved (\$58993.24) - SLE6075B - Claim Handler: Chew, Mavis									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLE6075B (2393986570SG)
 [SLK5619H]
 TP
 OW TONG MUI
 Feb 18 2019 7:00AM
 [LCRF PTE LTD]
 Performance Motors Limited

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page		<input checked="" type="checkbox"/>			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print			
1	(Draft)	Third Party Express Settlement – Payment Breakdown													1	Edit				
Photos/Images															3 per page		<input checked="" type="checkbox"/>			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print			
1	20/08/19 10:01	Odometer Reading													1	Load JPG	<input checked="" type="checkbox"/>			
2	20/08/19 10:01	Chassis Number													1	Load JPG	<input checked="" type="checkbox"/>			
3	20/08/19 10:01	General View													1	Load JPG	<input checked="" type="checkbox"/>			
4	20/08/19 10:01	General View													1	Load JPG	<input checked="" type="checkbox"/>			
5	20/08/19 10:01	General View													1	Load JPG	<input checked="" type="checkbox"/>			
6	20/08/19 10:01	General View													1	Load JPG	<input checked="" type="checkbox"/>			
7	20/08/19 10:01	General View													1	Load JPG	<input checked="" type="checkbox"/>			
8	20/08/19 10:01	General View													1	Load JPG	<input checked="" type="checkbox"/>			
9	20/08/19 10:01	General View													1	Load JPG	<input checked="" type="checkbox"/>			
10	20/08/19 10:01	General View													1	Load JPG	<input checked="" type="checkbox"/>			
11	20/08/19 10:01	General View													1	Load JPG	<input checked="" type="checkbox"/>			
12	20/08/19 10:01	General View													1	Load JPG	<input checked="" type="checkbox"/>			
13	20/08/19 10:01	General View													1	Load JPG	<input checked="" type="checkbox"/>			
14	20/08/19 10:01	General View													1	Load JPG	<input checked="" type="checkbox"/>			
15	20/08/19 10:01	General View													1	Load JPG	<input checked="" type="checkbox"/>			
16	20/08/19 10:01	General View													1	Load JPG	<input checked="" type="checkbox"/>			
17	20/08/19 10:01	General View													1	Load JPG	<input checked="" type="checkbox"/>			
18	20/08/19 10:02	Reinspection Photo													1	Load JPG	<input checked="" type="checkbox"/>			
19	20/08/19 10:02	Reinspection Photo													1	Load JPG	<input checked="" type="checkbox"/>			
20	20/08/19 10:02	Reinspection Photo													1	Load JPG	<input checked="" type="checkbox"/>			
21	20/08/19 10:02	Reinspection Photo													1	Load JPG	<input checked="" type="checkbox"/>			
22	20/08/19 10:02	Reinspection Photo													1	Load JPG	<input checked="" type="checkbox"/>			
23	20/08/19 10:02	Reinspection Photo													1	Load JPG	<input checked="" type="checkbox"/>			
24	20/08/19 10:02	Reinspection Photo													1	Load JPG	<input checked="" type="checkbox"/>			
25	20/08/19 10:02	Reinspection Photo													1	Load JPG	<input checked="" type="checkbox"/>			
26	20/08/19 10:02	Reinspection Photo													1	Load JPG	<input checked="" type="checkbox"/>			
27	20/08/19 10:02	Reinspection Photo													1	Load JPG	<input checked="" type="checkbox"/>			
Documentation															1 per page		<input checked="" type="checkbox"/>			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print			
1	20/02/19 18:10	TP EST & GIA REPORT													1	Load PDF				
2	12/03/19 18:27	TP ESTIMATE- MARKED													1	Load PDF				
3	20/08/19 10:13	EMAIL TO OI													1	Load PDF				
4	20/08/19 10:16	Final Repair Invoice, rental invoice and supporting documents													1	Load PDF				
5	27/08/19 09:44	WORKSHOP INVOICE													1	Load PDF				

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
6	27/08/19 09:44	LKK Auto Consultants Pte Ltd (HQ) AUTHORISATION TO ACT FORM	 Load PDF	
7	27/08/19 09:44	Release Voucher	 Load PDF	
8	27/08/19 09:44	RENTAL RECEIPT	 Load PDF	
No	Finalized On		Thumbnail	Print
1	21/02/19 08:17	AIG Asia Pacific Insurance Pte. Ltd. (SG) OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLK5619H (Insd veh)	Model:	BMW 216D 1.5 D ACTIVE
	SLE6075B (TP veh)		TOURER (F45) D/AB LED (A)
Date of Accident:	18/02/2019		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	11,595.96
Final Repair Cost	:	\$	8,693.64
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	299.60 4 days
LTA / GIA Search Fee	:	\$	0.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	8,993.24

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____(%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ ~~No~~ BOLA Scenario No: _____

BOLA Liability: _____100_____(%) Assessed Liability (*): _____0_____(%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	:	\$ 8,693.64
2)	Ow Tong Mui	:	\$ 299.60

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

27 Aug
2019

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co Reg No: 199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/LCR19003244/T1KB3Q2

Date: 27/08/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994809
Claimant Vehicle No : SLE6075B **Insured Vehicle No :** SLK5619H
 Date of Loss: 18/02/2019 Nature of Claim: TP Claim No: 2393986570SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLE6075B**
 Make & Model: BMW 216D, 1.5 D Active Tourer (F45) D/AB LED (A) Engine No: 31119531B37C15A
 Reg. Date: 28/07/2016 (Man. Year: 2016) Chassis No: WBA2B32000V260061
 Colour: White Odometer: 99669 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
 Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
 Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,167.35	3,344.90	822.45	19.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,670.00	4,780.00	1,890.00	28.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,837.35	8,124.90	2,712.45	25.03
+ GST 7.00/7.00% (S\$)	758.61	568.74	189.87	25.03
Nett Amount (S\$)	11,595.96	8,693.64	2,902.32	25.03
+ Car Rental (4.0 x S\$70.00/day + 7.00% GST) (S\$)		299.60		
Nett Liability (S\$)		8,993.24		

INSPECTION

Date of Assignment: 04/03/2019
 Date Inspected: 04/03/2019 Inspected At: Performance Motors Limited (Alexandra)
 303 Alexandra Road, Sime Darby
 Performance Centre
 Singapore 159941
 Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
2	1		*REAR EMBOSS NUMBER PLATE	Bent	83.00 FS	*83.00 FS
3	1		*TRUNK LID	Bent	1,204.35 FS	*1,204.35 FS
4	1		*REAR BUMPER PANEL PRIMED (PDC)	Deformed	1,029.50 FS	*1,029.50 FS
5	1		*RR BUMPER LH SIDE GUIDE	Not Necessary	49.05 FS	*- FS
6	1		*RR BUMPER RH SIDE GUIDE	Not Necessary	49.05 FS	*- FS
7	1		*REAR BUMPER CARRIER	Bent	458.10 FS	*458.10 FS
8	1		*REAR WINDOW ESG	Not Necessary	654.35 FS	*- FS
9	1		*TRUNK LID SEALING	Necessary	143.00 FS	*143.00 FS
10	4		*DECOUPING RING PDC TORQUE CONVERTER	Necessary	20.20 FS	*20.20 FS
11	1		*(DG) CLEANER R1 (100ML)	Necessary	26.15 FS	*26.15 FS
12	2		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Necessary	263.10 FS	*263.10 FS
13	1		*(DG/SL) GLASS PRIMER 30ML (VP206)	Necessary	27.85 FS	*27.85 FS
14	3		*BLIND RIVET NUT M6	Necessary	7.65 FS	*7.65 FS
15	2		*EXPANDING NUT	Necessary	2.00 FS	*2.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	4,167.35	3,344.90
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW TRUNK LID INCLUDE CONDUCTING CHECKS ON NEW TRUNK LID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION	New	451.00	451.00
2	REPLACING REAR BUMPER PANEL AND ATTACHMENTS ,TAILGATE ,ETC TO KNOCK OUT DENTS CAUSED BY THE ACCIDENT	New	2,550.00	1,700.00
3	SPRAY REAR BUMPER AND TAILGATE	New	1,923.00	1,730.00
4	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS	New	271.00	0.00
5	TO REPLACE REAR WINDSCREEN GLASS	New	574.00	574.00
6	TO CONDUCT WATER LEAK TESTS	New	75.00	75.00
7	TO SUPPLY AND INSTALL FRONT OR REAR WINDSCREEN SOLAR FILM	New	531.00	0.00
8	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
9	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
Gross Labour Cost (S\$)			6,670.00	4,780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >