

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

20 FEB 2019

Estimate No. : b1 50183
Date Estimated : 19/02/2019
Prepared By : Joseph Yaguel

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Ow Tong Mui
262D Compassvale Street
#06-151

SINGAPORE 544262

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLE6075B	V260061	28/07/2016	216d CAT	0

DESCRIPTION

Replacing rear bumper panel and attachments, tailgate,
etc to knock out dents caused by the accident

1770 2,550.00

Spray rear bumper and tailgate

1730 1,923.00

To remove and install boot compartment carpet and garnish
to facilitate repairs.

230 ? 271.00

To replace rear windscreen glass.

487 574.00

To conduct water leak tests.

63 75.00

To supply and install front or rear windscreen solar film.

451 531.00

To check electrical wiring systems and lightings at the
rear section for proper function.

150- 177.00

To carry out body cavity preservation.
(Per panel).

600 118.00

Sundries

? 150.00

To supply rear emboss number plate.

X 83.00

Total Labour 1: **6,452.00**

DESCRIPTION

TRUNK LID
REAR BUMPER PANEL PRIMED (PDC)
RR BUMPER LH SIDE GUIDE
RR BUMPER RH SIDE GUIDE
REAR BUMPER CARRIER
REAR WINDOW ESG
TRUNK LID SEALING
DECOUPING RING PDC TORQUE CONVERTER

QTY	PRIC
1	1,204.35
1	1,029.50
1	49.05
1	49.05
1	458.10
1	654.35
1	97.85
4	5.05

VALUE

bf 1,204.35
de 1,029.50
? 49.05
? 49.05
? 458.10
? 654.35
ni 97.85
ni 20.20



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 50183**
Date Estimated : **19/02/2019**
Prepared By : **Joseph Yaguel**

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLE6075B	V260061	28/07/2016	216d CAT	0

DESCRIPTION	QTY	PRICE	VALUE
(DG) CLEANER R1 (100ML)	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	2	131.55	263.10
(DG/SL) GLASS PRIMER 30ML (VP206)	1	27.85	27.85
Total Parts :			3,879.55

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after repairing
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary work/modification is subject to quotation

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____
Date&Time 11/3/19 2:45 Excess S\$ _____
Surveyor's Name Tan Jiah Sign [Signature]
Surveyor's Tel 97495744 Authorised Yes / No _____
Authorised Date _____ Time _____
RESURVEY PARTS PHOTO BY SURVEYOR (Yes / No) Yes PML Yes / No _____
Surveyor's E-mail tanjiah@lkkauto.com
No. of Working Days Recommend 5 days



Labour 1	:	6,452.00
Parts	:	3,879.55
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	723.21
Grand Total	:	11,054.76

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **