

# FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6841 9095 Email: [focus.autopetltd@yahoo.com.sg](mailto:focus.autopetltd@yahoo.com.sg)

GST:201004495R RCB NO:201004495R

not Authorised  
h/h  
26/2/19  
H/S  
Hdy.  
to be phoned up

M/S : INDIA INTERNATIONAL INSURANCE PTE LTD

64 CECIL STREET  
#04-#05 IOB BUILDING  
SINGAPORE 049711

TEL: 6347 6100

FAX: 6224 4174

ATTN: Motor Claim Department

Your Ref No: WC6560Y

Claim Type: Third Party

Accident Date: 11-02-2019

TP Veh Reg No: PC4032B

Estimate No: EST0000826

Date: 14 Feb 2019

Policy No: O2036012

Veh Reg No: WC6560Y

Make/Model: ISUZU CYH52S

Chassis No: JALCYH52SD7000447

Engine No: 6WG1419891

Reg. Date: 02-12-2013

## Estimate Repair Cost to Vehicle No :WC6560Y

PAGE:1/1

| Description                             | U/Price    | Quantity | List Price<br>S\$ | Amount<br>S\$ |
|-----------------------------------------|------------|----------|-------------------|---------------|
| ISUZU CYH52S                            |            |          |                   |               |
| List Price                              |            |          |                   |               |
| 1 Front Bumper                          | 2,843.0000 | 1 PC     | 2,843.00          |               |
| 2 Front Bumper Top Rubber               | 296.0000   | 1 PC     | 296.00            |               |
| 3 Front Bumper Side Bracket LH          | 90.0000    | 2 PC     | 180.00            |               |
| 4 Front Bumper Lamp LH                  | 70.0000    | 1 PC     | 70.00             |               |
| 5 Front Corner Panel LH                 | 489.0000   | 1 PC     | 489.00            |               |
| 6 Front Side Mirror Bracket LH          | 298.0000   | 1 PC     | 298.00            |               |
| 7 Front Side Mirror LH                  | 110.0000   | 2 PC     | 220.00            |               |
| 8 Front Side Mirror Support Bar LH      | 95.0000    | 1 PC     | 95.00             |               |
| 9 Front Headlamp Cover LH               | 385.0000   | 1 PC     | 385.00            |               |
| 10 Front Step Panel Garnish Top LH      | 346.0000   | 1 PC     | 346.00            |               |
| 11 Front Aluminium Plate LH             | 298.0000   | 1 PC     | 298.00            |               |
| 12 Front Aluminium Plate Support Bar LH | 490.0000   | 1 PC     | 490.00            |               |
| 13 Front Aluminium Plate Garnish LH     | 320.0000   | 1 PC     | 320.00            |               |
| 14 Front Door Garnish LH                | 367.0000   | 1 PC     | 367.00            |               |
|                                         |            |          | 6,697.00          |               |
|                                         | Less 15%   |          | 1,004.55          | 5,692.45      |
| Labour                                  |            |          |                   |               |
| 15 Panel Beating                        | 1,200.0000 | 1 PC     | 1,200.00          |               |
| 16 Check Wiring                         | 60.0000    | 1 PC     | 60.00             |               |
| 17 Spray Painting                       | 800.0000   | 1 PC     | 800.00            |               |
|                                         |            |          | 2,060.00          | 2,060.00      |

Total S\$ 7,752.45

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND SEVEN HUNDRED FIFTY TWO AND CENTS FORTY FIVE ONLY

LKK Auto Consultants hence notify  
the Repairer of the following:

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

For FOCUS AUTO PTE LTD

Focus Auto Pte Ltd

No 1 Kaki Bukit Ave 6 Auto Bay

#02-50 Singapore 417883

Tel: 66349695

AUTHORISED SIGNATURE